

Submit 3 Copies to Appropriate District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-25427
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 23286

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 OIL WELL GAS WELL OTHER

2. Name of Operator
ECLIPSE OIL & GAS, INC.

3. Address of Operator
P.O. BOX 15122, ODESSA, TX 79768

4. Well Location
 Unit Letter N : 660 Feet From The SOUTH Line and 2130 Feet From The WEST Line
 Section 1 Township 12S Range 32E NMPM LEA County

7. Lease Name or Unit Agreement Name
TENNECO SUNSHINE

8. Well No. 003

9. Pool name or Wildcat
BAGLEY PERMO PENN. NORTH

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4314.5" GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

#1. CIBP @ 9145 CAP W/20' cmt.	#7. 50 sks of cement 50' In & out of 8 5/8 CSG. Cut Woc & tag	Cut off wellhead & anchors & BGL Install dry hole marker.
#2. 25 sks. @ 6155'		
#3. 25 sks. @ 3850' WOC & tag.	#8. 75 sks of cement @ 353' WOC & tag	Well to be circ. W/10# brine W/25# of gel per bbl.
#4. Cut & remove 5 1/2 CSG. = or - 3600'		
5. 25 sks of cmt. @ 50' IN & 50' out of 5 1/2 csg. Cut WOC & tag.	#9. 10 sks surface plug	
6. Cut & remove 8 5/8 If any free.		

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Richard Beeson TITLE PRESIDENT DATE 5-21-98

TYPE OR PRINT NAME RICHARD BEESON TELEPHONE NO. 915-550-8818

(This space for State Use)

APPROVED BY CHRIS WILLIAMS TITLE DISTRICT I SUPERVISOR DATE JUN 01 1998

CONDITIONS OF APPROVAL, IF ANY:

