

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name N/A
2. Name of Operator Walter Oil & Gas Corporation	8. Farm or Lease Name D. P. Peck Estate
3. Address of Operator 240 Main Bldg., 1212 Main Street, Houston, Texas 77002	9. Well No. 1
4. Location of Well UNIT LETTER F, 1890 FEET FROM THE North LINE AND 2105 FEET FROM THE West LINE, SECTION 26 TOWNSHIP 12 S RANGE 37 E NMPM.	10. Field and Pool, or Wildcat Gladiola, S.W.
15. Elevation (Show whether DF, RT, GR, etc.) 3882.5' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PBTD: 9820' MW: 8.6 ppg

Plug and abandon well as per following procedure:

1. Pull rods, pump and tubing. Set 5-1/2" WL bridge plug @ 9650'. Set 35' (5 sx) cement plug on top of bridge plug.
2. Pull ±7000' 5-1/2" casing. Set 100' (50 sx) cement plug in and out 5-1/2" casing (50' in and 50' out).
3. Set 100' (50 sx) cement plug at 9-5/8" shoe @ 4469' (50' in and 50' out).
4. Set 100' (50 sx) cement plug at top of salt.
5. Set 10 sx cement plug at surface with marker.
6. Will commence plugging operations after permit approval.

APPROVED FOR THE CDD
DATE APPROVED

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Kim Burkett TITLE Regulatory Coordinator DATE August 28, 1985
Kim Burkett

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

SEP - 8 1985

RECEIVED

AUG 30 1985

G.C.D.
HOBBY OFFICE