

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name Rose Eaves
3. Address of Operator P. O. Box 1920, Hobbs, New Mexico 88231	9. Well No. #1
4. Location of Well UNIT LETTER <u>N</u> <u>660'</u> FEET FROM THE <u>South</u> LINE AND <u>1980'</u> FEET FROM THE <u>West</u> LINE, SECTION <u>35</u> TOWNSHIP <u>16S</u> RANGE <u>38E</u> N.M.P.M.	10. Field and Pool, or Wildcat Knowles-Devonian
15. Elevation (Show whether DF, RT, CR, etc.) 3712' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pull rods, pump and tubing. Spot ³⁵ sx cement plug fr. 12,209' to 12,354' in 7-5/8" casing. Shoot 7-5/8" casing and spot 40 sx cement plug in and out of 7-5/8" casing stub. Spot 40 sx cement plug fr. 4750-4850', 10-3/4" casing @ 4804'. Cut and pull 10-3/4" OD casing, if salt section exposed spot 25 sx cement plug top and bottom. Spot 75 sx cement plug in and out of 13-3/8" casing 246-310'. Spot 10 sx plug at surface w/dry-hole marker.

*Need 25sx plugs at following Formations
tops if exposed:
Tubb - 8070'
Glorieta - 6425'*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED G. O. Webb *G. O. Webb* TITLE District Superintendent DATE 12-29-69

APPROVED BY *[Signature]* TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: