

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
OG-5121

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name New Mexico "DG" State
3. Address of Operator P. O. Box 728 - Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>J</u> <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>18</u> TOWNSHIP <u>17-S</u> RANGE <u>35-E</u> NMPM.	10. Field and Pool, or Wildcat Midway San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 3804' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The following work on subject well has been completed:

1. Pulled rods, pump and 2-3/8" OD tubing.
2. Spotted 30 sx plug over perforations 5053' to 5270'.
3. Cut and pulled 3505' of 4-1/2" OD, 11.6# J-55 casing.
4. Spotted 25 sx cement plug in 4-1/2" casing stub from 3470' to 3580'.
5. Filled hole with mud.
6. Spotted 20 sx plug at surface.
7. Installed 4" Dry Hole Marker extending 4' above ground level.
8. Clean location. Plug and abandon.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *J. Schreff* TITLE Assistant District Superintendent DATE December 28, 1970

APPROVED BY *John W. Runyan* TITLE Geologist DATE MAR 26 1971

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 20 1970

**OIL CONSERVATION COMM.
HOBBES, N. M.**