



June 11, 2025

State of New Mexico
Energy, Minerals, and Natural Resources Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Re: Oilfield Water Logistics Fulfer Produced Water Recycling Facility C-147 Extension

To Whom It May Concern:

On behalf of Oilfield Water Logistics, ENVIROTECH ENGINEERING & CONSULTING, INC. respectfully submits the enclosed C-147 form and summary of monthly inspections and leak detection for the Fulfer Containment and Recycling Facility. For original site plans and submittals, please refer to the facility's original registration application, OCD Registration number 1RF-023, received October 10th, 2017. In accordance with NMAC 19.15.34.10 RECYCLING CONTAINMENTS, Oilfield Water Logistics wishes to seek a one-year extension to the facility.

NMAC 19.15.34.10 RECYCLING CONTAINMENTS

C. Registered recycling containments may be operated for five years from the date on which the registration is filed with the division. The operator may extend the allowed time on an annual basis thereafter with division approval if, 30 days prior to the registration expiration, the operator files a form C-147 with an attached summary showing all monthly inspections at the containment, including the monitoring of the leak detection system, showing the containment's integrity has not been compromised.

Should you have any questions or require additional information, please do not hesitate to contact me at your convenience.

Sincerely,
ENVIROTECH ENGINEERING & CONSULTING, INC.

Mitchell Ratke, P.E.
Senior Project Engineer, Energy Infrastructure



Enclosures:

Updated C-147 Form
Summary of Monthly Inspections and Leak Detection Reports

025097-00

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-147
Revised April 3, 2017

Recycling Facility and/or Recycling Containment

Type of Facility: ☒ Recycling Facility ☒ Recycling Containment*
Type of action: ☒ Permit ☐ Registration
☐ Modification ☒ Extension
☐ Closure ☐ Other (explain) _____

*** At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.**

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.
 Operator: OWL SWD Operating, LLC (For multiple operators attach page with information) OGRID #: 308339
 Address: 8201 Preston Road Dallas, TX 75225
 Facility or well name (include API# if associated with a well): OWL Fulfer Recycling Facility and Containment
 OCD Permit Number: 1RF-23 (For new facilities the permit number will be assigned by the district office)
 U/L or Qtr/Qtr _____ Section 25 Township 25S Range 36E County: Lea
 Surface Owner: ☐ Federal ☐ State ☒ Private ☐ Tribal Trust or Indian Allotment

2.
☒ **Recycling Facility:**
 Location of recycling facility (if applicable): Latitude 32.097730 Longitude -103.219018 NAD83
 Proposed Use: ☒ Drilling* ☒ Completion* ☒ Production* ☒ Plugging*
**The re-use of produced water may NOT be used until fresh water zones are cased and cemented*
☐ Other, *requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.*
☒ Fluid Storage
☐ Above ground tanks ☒ Recycling containment ☐ Activity permitted under 19.15.17 NMAC explain type _____
☐ Activity permitted under 19.15.36 NMAC explain type: _____ ☐ Other explain _____
☐ For multiple or additional recycling containments, attach design and location information of each containment
☐ **Closure Report (required within 60 days of closure completion):** ☐ Recycling Facility Closure Completion Date: _____

3.
☒ **Recycling Containment:**
☐ Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)
 Center of Recycling Containment (if applicable): Latitude 32.097730 Longitude -103.219018 NAD83
☐ For multiple or additional recycling containments, attach design and location information of each containment
☒ Lined ☐ Liner type: Thickness _____ mil ☒ LLDPE ☒ HDPE ☐ PVC ☐ Other _____
☐ String-Reinforced 40 mil (secondary)
60 mil (primary)
 Liner Seams: ☒ Welded ☒ Factory ☒ Other Field Welds Volume: 500,000 bbl Dimensions: L 625 x W 400 x D 18
☐ Recycling Containment Closure Completion Date: _____

4.

Bonding:

- ☒ Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)
- ☐ Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ _____ (work on these facilities cannot commence until bonding amounts are approved)
- ☐ Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

Fencing:

- ☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet
- ☒ Alternate. Please specify Chain Link Game Fence

6.

Signs:

- ☒ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers
- ☐ Signed in compliance with 19.15.16.8 NMAC

7.

Variances:

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

Check the below box only if a variance is requested:

☒ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

If a Variance is requested, it must be approved prior to implementation.

8.

Siting Criteria for Recycling Containment

Instructions: The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

General siting**Ground water is less than 50 feet below the bottom of the Recycling Containment.**

NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells

☐ Yes ☒ No
☐ NA

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.

☐ Yes ☒ No
☐ NA

- Written confirmation or verification from the municipality; written approval obtained from the municipality

Within the area overlying a subsurface mine.

☐ Yes ☒ No

- Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division

Within an unstable area.

☐ Yes ☒ No

- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map

Within a 100-year floodplain. FEMA map

☐ Yes ☒ No

Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

☐ Yes ☒ No

- Topographic map; visual inspection (certification) of the proposed site

Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.

☐ Yes ☒ No

- Visual inspection (certification) of the proposed site; aerial photo; satellite image

Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.

☐ Yes ☒ No

- NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site

Within 500 feet of a wetland.

☐ Yes ☒ No

- US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site

9.

Recycling Facility and/or Containment Checklist:

Instructions: Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.

- ☒ Design Plan - based upon the appropriate requirements.
- ☒ Operating and Maintenance Plan - based upon the appropriate requirements.
- ☒ Closure Plan - based upon the appropriate requirements.
- ☒ Site Specific Groundwater Data -
- ☒ Siting Criteria Compliance Demonstrations –
- ☒ Certify that notice of the C-147 (only) has been sent to the surface owner(s)

10.

Operator Application Certification:

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): David Grounds Title: Vice President of Regulatory Compliance
Signature: David Grounds Date: 05/03/2024
e-mail address: David.Grounds@pilotwater.com Telephone: 817-897-0135

11.

OCD Representative Signature: Victoria Venegas Approval Date: 06/23/2025

Title: Environmental Specialist OCD Permit Number: 1RF-23

- ☒ OCD Conditions _____
- ☒ Additional OCD Conditions on Attachment _____

**New Mexico Recycling Facility Weekly Inspection****Location****Submitted By**  [Steven Anderson](#)*Location was not collected for this report.***Surrogate**  [Steven Anderson](#)**Started On** May 1 2024, 3:03pm**Submitted On** May 1 2024, 3:06pm (2 minutes)**Weather** NaN°,**Version** V1 (latest)**Updated** May 1 2024, 3:06pm**Report No.** 40187822**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS****Date** May 1st 2024**Area** [New Mexico](#)**Recycle Facility** [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION****Read and record the fluid height of staff gauges** 9' 6"**Does the pond surface show visible oil?** No**Visually inspect containments liner** No rips or tears**Check leak detection system for any evidence of a loss of integrity of the primary liner** Good**SUMMARY****# of Action Item(s)** 0**Inspector** [Steven Anderson](#)**Signature**A handwritten signature in blue ink, appearing to be "S. Anderson", written over a horizontal line.

Generated Friday, June 14th 2024, 8:50am CDT

powered by  KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Fernando Sanchez](#)*Location was not collected for this report.*

Surrogate

[Fernando Sanchez](#)**Started On** May 14 2024, 4:07pm**Submitted On** May 15 2024, 9:05am (17 hours)**Weather** NaN°,**Version** V1 (latest)**Updated** May 15 2024, 9:05am**Report No.** 40795243**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS****Date** May 7th 2024**Area** [New Mexico](#)**Recycle Facility** [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION****Read and record the fluid height of staff gauges** 9.5 ft**Does the pond surface show visible oil?** No**Visually inspect containments liner** Liner in good condition**Check leak detection system for any evidence of a loss of integrity of the primary liner** All looks good**SUMMARY****# of Action Item(s)** 0**Inspector** [Fernando Sanchez](#)**Signature**

A handwritten signature in blue ink, appearing to read "F. Sanchez", written over a horizontal line.



New Mexico Recycling Facility Weekly Inspection

Submitted By  [Fernando Sanchez](#)

Surrogate  [Fernando Sanchez](#)

Started On May 15 2024, 9:34am

Submitted On May 15 2024, 9:40am (5 minutes)


Weather 75°, clear

Version V1 (latest)

Updated May 15 2024, 9:40am

Report No. 40797252

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date May 15th 2024

Area [New Mexico](#)

Recycle Facility [FULFER_RECYCLE_FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 12.5ft

Does the pond surface show visible oil? No

Visually inspect containments liner Liner in good condition


Check leak detection system for any evidence of a loss of integrity of the primary liner No issues

SUMMARY

of Action Item(s) 0

Inspector [Fernando Sanchez](#)

Signature

**New Mexico Recycling Facility Weekly Inspection****Submitted By**  [James Smith](#)**Surrogate**  [James Smith](#)**Started On** May 29 2024, 10:46am**Submitted On** May 29 2024, 10:48am (2 minutes)**Weather** 70°, cloudy**Version** V1 (latest)**Updated** May 29 2024, 10:48am**Report No.** 41379583**Location****New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS****Date** May 29th 2024**Area** [New Mexico](#)**Recycle Facility** [JAVELINA_RECYCLE_FACILITY](#)**WEEKLY INSPECTION****Read and record the fluid height of staff gauges** N/A**Does the pond surface show visible oil?** Yes**Visually inspect containments liner** Good**Check leak detection system for any evidence of a loss of integrity of the primary liner** LDS powered on, was pumping fluid out as of a week ago.**SUMMARY****# of Action Item(s)** 0**Inspector** [James Smith](#)**Signature**

A handwritten signature in blue ink, appearing to read "James Smith", written over a horizontal line.

**New Mexico Recycling Facility Weekly Inspection****Location**Submitted By  [Steven Anderson](#)*Location was not collected for this report.*Surrogate  [Steven Anderson](#)

Started On June 6 2024, 4:13pm

Submitted On June 6 2024, 4:14pm (55 seconds)

Weather NaN°,

Version V1 (latest)

Updated June 6 2024, 4:14pm

Report No. 41773552

New Mexico Recycling Facility Weekly Inspection**GENERAL DETAILS**Date *None*Area [New Mexico](#)Recycle Facility [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 13'8"

Does the pond surface show visible oil? Yes

Visually inspect containments liner Good

Check leak detection system for any evidence of a loss of integrity of the primary liner Good

SUMMARY

of Action Item(s) 0

Inspector [Steven Anderson](#)Signature 

Generated Friday, June 14th 2024, 8:45am CDT

powered by  KPA

**New Mexico Recycling Facility Weekly Inspection****Location****Submitted By**  [Steven Anderson](#)*Location was not collected for this report.***Surrogate**  [Steven Anderson](#)**Started On** June 24 2024, 10:38am**Submitted On** June 24 2024, 10:39am (2 minutes)**Weather** NaN°,**Version** V1 (latest)**Updated** June 24 2024, 10:40am**Report No.** 42527296**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS****Date** June 11th 2024**Area** [New Mexico](#)**Recycle Facility** [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION****Read and record the fluid height of staff gauges** 13'8"**Does the pond surface show visible oil?** No**Visually inspect containments liner** Good**Check leak detection system for any evidence of a loss of integrity of the primary liner** Good**SUMMARY****# of Action Item(s)** 0**Inspector** [Steven Anderson](#)**Signature**

A handwritten signature in blue ink, appearing to read "Steven Anderson", written over a horizontal line.



New Mexico Recycling Facility Weekly Inspection

Submitted By  [Mario Nevarez](#)

Surrogate  [Mario Nevarez](#)

Started On June 14 2024, 10:15am

Submitted On June 14 2024, 10:16am (a minute)


Weather 84°, clear

Version V1 (latest)

Updated June 14 2024, 10:16am

Report No. 42120957

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date June 14th 2024

Area [New Mexico](#)

Recycle Facility [FULFER_RECYCLE_FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges N/A

Does the pond surface show visible oil? No

Visually inspect containments liner Yes good

Check leak detection system for any evidence of a loss of integrity of the primary liner Checked good

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

**New Mexico Recycling Facility Weekly Inspection****Location**Submitted By  [Steven Anderson](#)*Location was not collected for this report.*Surrogate  [Steven Anderson](#)

Started On June 24 2024, 10:40am

Submitted On June 24 2024, 10:41am (a minute)

Weather NaN°,

Version V1 (latest)

Updated June 24 2024, 10:41am

Report No. 42527820

New Mexico Recycling Facility Weekly Inspection**GENERAL DETAILS**

Date June 18th 2024

Area [New Mexico](#)Recycle Facility [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 14'2

Does the pond surface show visible oil? Yes

Visually inspect containments liner Good

Check leak detection system for any evidence of a loss of integrity of the primary liner Good no leaks

SUMMARY

of Action Item(s) 0

Inspector [Steven Anderson](#)

Signature

A handwritten signature in blue ink, appearing to be "S. Anderson", written over a horizontal line.

Generated Wednesday, July 3rd 2024, 11:08am CDT

powered by  KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Steven Anderson](#)*Location was not collected for this report.*

Surrogate

[Steven Anderson](#)**Started On** June 24 2024, 10:41am**Submitted On** June 24 2024, 10:43am (2 minutes)**Weather** NaN°,**Version** V1 (latest)**Updated** June 24 2024, 10:43am**Report No.** 42527971**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS****Date** June 24th 2024**Area** [New Mexico](#)**Recycle Facility** [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION****Read and record the fluid height of staff gauges** 13'8**Does the pond surface show visible oil?** Yes**Visually inspect containments liner** Good**Check leak detection system for any evidence of a loss of integrity of the primary liner** Good no leaks**SUMMARY****# of Action Item(s)** 0**Inspector** [Steven Anderson](#)**Signature**

A handwritten signature in blue ink, appearing to be "S. Anderson", written over a horizontal line.

Generated Wednesday, July 3rd 2024, 11:06am CDT

powered by KPA



New Mexico Recycling Facility Monthly Inspection

Location

Submitted By  [Mario Nevarez](#)

Location was not collected for this report.

Surrogate  [Mario Nevarez](#)

Started On	June 4 2024, 5:09pm
Submitted On	July 1 2024, 5:57pm (a month)
Weather	NaN°,
Version	V1 (latest)
Updated	July 1 2024, 5:57pm
Report No.	42863796

New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date	July 1st 2024 5:55 PM
Area	New Mexico
Recycle Facility	FULFER_RECYCLE_FACILITY

INLET AST

Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	N/A
Is bird netting in good condition?	None
Is there any evidence of cracking or subsidence of the pad around the AST?	N/A
Is there oil to be skimmed?	N/A

EFFLUENT AST

Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	N/A
Is there any evidence of cracking or subsidence of the pad around the AST?	N/A

SOUTH POND

Is there fluid in the leak detection system?	No
--	----

Are pond level markers visible?	Yes
Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes

TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY

# of Action Item(s)	0
Inspector	Mario Nevarez

Signature



Generated Tuesday, July 2nd 2024, 2:56pm CDT

powered by  KPA

**New Mexico Recycling Facility Weekly Inspection****Location**Submitted By  [Steven Anderson](#)*Location was not collected for this report.*Surrogate  [Steven Anderson](#)

Started On July 3 2024, 9:47pm

Submitted On July 3 2024, 9:48pm (a minute)

Weather NaN°,

Version V1 (latest)

Updated July 3 2024, 9:48pm

Report No. 42976291

New Mexico Recycling Facility Weekly Inspection**GENERAL DETAILS**

Date July 3rd 2024

Area [New Mexico](#)Recycle Facility [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 12'6

Does the pond surface show visible oil? No

Visually inspect containments liner Good with no rips or tears

Check leak detection system for any evidence of a loss of integrity of the primary liner Good

SUMMARY

of Action Item(s) 0

Inspector [Steven Anderson](#)

Signature

A handwritten signature in blue ink, appearing to read "Steven Anderson", written over a horizontal line.



Generated Friday, July 5th 2024, 8:25am CDT


powered by  KPA

**New Mexico Recycling Facility Weekly Inspection****Location****Submitted By**  [Fernando Sanchez](#)*Location was not collected for this report.***Surrogate**  [Fernando Sanchez](#)**Started On** July 10 2024, 8:25am**Submitted On** July 10 2024, 8:27am (2 minutes)**Weather** NaN°,**Version** V1 (latest)**Updated** July 10 2024, 8:27am**Report No.** 43186360**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS****Date** July 10th 2024**Area** [New Mexico](#)**Recycle Facility** [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION****Read and record the fluid height of staff gauges** 11ft**Does the pond surface show visible oil?** No**Visually inspect containments liner** Liner in good condition**Check leak detection system for any evidence of a loss of integrity of the primary liner** All good**SUMMARY****# of Action Item(s)** 0**Inspector** [Fernando Sanchez](#)**Signature**

A handwritten signature in blue ink, appearing to be "F. Sanchez", written over a horizontal line.




New Mexico Recycling Facility Weekly Inspection		Location
Submitted By	 Fernando Sanchez	Location was not collected for this report.
Surrogate	 Fernando Sanchez	
Started On	July 15 2024, 8:45am	
Submitted On	July 15 2024, 8:48am (3 minutes)	
Weather	NaN°,	
Version	V1 (latest)	
Updated	July 15 2024, 8:48am	
Report No.	43392144	

New Mexico Recycling Facility Weekly Inspection	
GENERAL DETAILS	
Date	July 15th 2024
Area	New Mexico
Recycle Facility	FULFER_RECYCLE_FACILITY
WEEKLY INSPECTION	
Read and record the fluid height of staff gauges	10ft
Does the pond surface show visible oil?	No
Visually inspect containments liner	Liner in working condition
Check leak detection system for any evidence of a loss of integrity of the primary liner	No issues
SUMMARY	
# of Action Item(s)	0
Inspector	Fernando Sanchez
Signature	



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By  [Fernando Sanchez](#)

Location was not collected for this report.

Surrogate  [Fernando Sanchez](#)

Started On	July 25 2024, 2:59pm
Submitted On	July 25 2024, 3:04pm (5 minutes)
Weather	NaN°,
Version	V1 (latest)
Updated	July 25 2024, 3:04pm
Report No.	43889944

New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date	July 25th 2024
Area	New Mexico
Recycle Facility	FULFER_RECYCLE_FACILITY

WEEKLY INSPECTION


Read and record the fluid height of staff gauges	9ft
Does the pond surface show visible oil?	No
Visually inspect containments liner	No issues
Check leak detection system for any evidence of a loss of integrity of the primary liner	No issues

SUMMARY

# of Action Item(s)	0
Inspector	Fernando Sanchez

Signature



**New Mexico Recycling Facility Weekly Inspection****Submitted By**  [Fernando Sanchez](#)**Surrogate**  [Fernando Sanchez](#)**Started On** July 30 2024, 3:08pm**Submitted On** July 30 2024, 3:16pm (9 minutes)**Weather** 95°, clear**Version** V1 (latest)**Updated** July 30 2024, 3:17pm**Report No.** 44095047**Location****New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS****Date** July 30th 2024**Area** [New Mexico](#)**Recycle Facility** [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION****Read and record the fluid height of staff gauges** 9ft**Does the pond surface show visible oil?** No**Visually inspect containments liner** Liner in good condition**Check leak detection system for any evidence of a loss of integrity of the primary liner** No issues**SUMMARY****# of Action Item(s)** 0**Inspector** [Fernando Sanchez](#)**Signature**

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Steven Anderson](#)*Location was not collected for this report.*

Surrogate

[Steven Anderson](#)**Started On** August 5 2024, 12:04pm**Submitted On** August 5 2024, 12:06pm (2 minutes)**Weather** NaN°,**Version** V1 (latest)**Updated** August 5 2024, 12:06pm**Report No.** 44347183**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS****Date** August 5th 2024**Area** [New Mexico](#)**Recycle Facility** [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION****Read and record the fluid height of staff gauges** 8' 6"**Does the pond surface show visible oil?** No**Visually inspect containments liner** Everything is good**Check leak detection system for any evidence of a loss of integrity of the primary liner** Good**SUMMARY****# of Action Item(s)** 0**Inspector** [Steven Anderson](#)**Signature**

A handwritten signature in blue ink, appearing to be "S/A", written over a horizontal line.

Generated Wednesday, August 7th 2024, 8:21am CDT

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**Submitted By  [Steven Anderson](#)*Location was not collected for this report.*Surrogate  [Steven Anderson](#)

Started On August 19 2024, 2:28pm

Submitted On August 19 2024, 2:29pm (51 seconds)

Weather NaN°,

Version V1 (latest)

Updated August 19 2024, 2:29pm

Report No. 45000580

New Mexico Recycling Facility Weekly Inspection**GENERAL DETAILS**

Date August 5th 2024

Area [New Mexico](#)Recycle Facility [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 9'

Does the pond surface show visible oil? No

Visually inspect containments liner Good

Check leak detection system for any evidence of a loss of integrity of the primary liner Good

SUMMARY

of Action Item(s) 0

Inspector [Steven Anderson](#)Signature 

Generated Monday, August 19th 2024, 3:29pm CDT

powered by  KPA

**New Mexico Recycling Facility Weekly Inspection****Location****Submitted By**[Steven Anderson](#)*Location was not collected for this report.***Surrogate**[Steven Anderson](#)**Started On** August 19 2024, 2:29pm**Submitted On** August 19 2024, 2:29pm (35 seconds)**Weather** NaN°,**Version** V1 (latest)**Updated** August 19 2024, 2:30pm**Report No.** 45000834**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS****Date** August 12th 2024**Area** [New Mexico](#)**Recycle Facility** [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION****Read and record the fluid height of staff gauges** 9.5'**Does the pond surface show visible oil?** No**Visually inspect containments liner** Good**Check leak detection system for any evidence of a loss of integrity of the primary liner** Good**SUMMARY****# of Action Item(s)** 0**Inspector** [Steven Anderson](#)**Signature**

A blue ink handwritten signature, appearing to be "S. Anderson", written over a horizontal line.

Generated Monday, August 19th 2024, 3:28pm CDT

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Steven Anderson](#)*Location was not collected for this report.*

Surrogate

[Steven Anderson](#)**Started On** August 19 2024, 2:30pm**Submitted On** August 19 2024, 2:30pm (39 seconds)**Weather** NaN°,**Version** V1 (latest)**Updated** August 19 2024, 2:30pm**Report No.** 45000903**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS****Date** August 19th 2024**Area** [New Mexico](#)**Recycle Facility** [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION****Read and record the fluid height of staff gauges** 10.5'**Does the pond surface show visible oil?** No**Visually inspect containments liner** Good**Check leak detection system for any evidence of a loss of integrity of the primary liner** Good**SUMMARY****# of Action Item(s)** 0**Inspector** [Steven Anderson](#)**Signature**

A blue ink handwritten signature, appearing to be "SA", written over a horizontal line.

Generated Monday, August 19th 2024, 3:27pm CDT

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Steven Anderson](#)*Location was not collected for this report.*

Surrogate

[Steven Anderson](#)**Started On** August 27 2024, 9:44am**Submitted On** August 27 2024, 9:45am (42 seconds)**Weather** NaN°,**Version** V1 (latest)**Updated** August 27 2024, 9:45am**Report No.** 45381409**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS****Date** August 27th 2024**Area** [New Mexico](#)**Recycle Facility** [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION****Read and record the fluid height of staff gauges** 12'9"**Does the pond surface show visible oil?** No**Visually inspect containments liner** Good**Check leak detection system for any evidence of a loss of integrity of the primary liner** Good**SUMMARY****# of Action Item(s)** 0**Inspector** [Steven Anderson](#)**Signature**

A handwritten signature in blue ink, appearing to be "S. Anderson", written over a horizontal line.

Generated Tuesday, August 27th 2024, 9:46am CDT

powered by KPA



New Mexico Recycling Facility Monthly Inspection

Submitted By



[Mario Nevarez](#)

Surrogate



[Mario Nevarez](#)

Started On September 3 2024, 9:33am

Submitted On September 3 2024, 9:35am (2 minutes)


Weather 64°, rain

Version V1 (latest)

Updated September 3 2024, 9:35am

Report No. 45662783

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date September 3rd 2024 9:33 AM

Area [New Mexico](#)

Recycle Facility [FULFER_RECYCLE_FACILITY](#)

INLET AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is bird netting in good condition? None

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

Is there oil to be skimmed? N/A

EFFLUENT AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible?	Yes
---------------------------------	-----

Is pond level sensor working?	Yes
-------------------------------	-----

Is there any visible damage to the pond liner?	No
--	----

Any migratory birds or wildlife discovered in the pond?	No
---	----

Is bird deterrent working?	Yes
----------------------------	-----

Is there any evidence of cracking or subsidence around the pond berm?	No
---	----

Is there any erosion on the outside of the berm?	No
--	----

Is life vest and related pond safety equipment in working condition?	Yes
--	-----

Is pond aeration system functional?	Yes
-------------------------------------	-----

TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
---	-----

Is there any evidence of spills or soil staining that have not been cleaned up?	No
---	----

Any migratory birds or wildlife discovered in the facility?	No
---	----

Are there any holes found in the containment liner?	No
---	----

Any evidence of erosion on the outside slope of the facility?	No
---	----

SUMMARY

# of Action Item(s)	0
---------------------	---

Inspector	None
-----------	------




Signature



Generated Tuesday, September 10th 2024, 12:38pm CDT

powered by  KPA




New Mexico Recycling Facility Weekly Inspection		Location
Submitted By	 Fernando Sanchez	
Surrogate	 Fernando Sanchez	
Started On	September 6 2024, 10:48am	
Submitted On	September 6 2024, 10:49am (a minute)	
Weather	72°, cloudy	
Version	V1 (latest)	
Updated	September 6 2024, 10:49am	
Report No.	45842524	

New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS	
Date	September 6th 2024
Area	New Mexico
Recycle Facility	FULFER_RECYCLE_FACILITY

WEEKLY INSPECTION	
Read and record the fluid height of staff gauges	13ft 9in
Does the pond surface show visible oil?	No
Visually inspect containments liner	Liner looks to be in good condition
Check leak detection system for any evidence of a loss of integrity of the primary liner	All good

SUMMARY	
# of Action Item(s)	0
Inspector	Fernando Sanchez

Signature 

**New Mexico Recycling Facility Weekly Inspection****Location****Submitted By**  [Fernando Sanchez](#)*Location was not collected for this report.***Surrogate**  [Fernando Sanchez](#)**Started On** September 16 2024, 9:41am**Submitted On** September 16 2024, 9:42am (59 seconds)**Weather** NaN°,**Version** V1 (latest)**Updated** September 16 2024, 9:42am**Report No.** 46264729**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS****Date** September 9th 2024**Area** [New Mexico](#)**Recycle Facility** [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION****Read and record the fluid height of staff gauges** 13ft 9in**Does the pond surface show visible oil?** No**Visually inspect containments liner** Liner looks to be in good condition**Check leak detection system for any evidence of a loss of integrity of the primary liner** All good**SUMMARY****# of Action Item(s)** 0**Inspector** [Fernando Sanchez](#)**Signature**

A handwritten signature in blue ink, appearing to read "Fernando Sanchez", written over a horizontal line.

**New Mexico Recycling Facility Weekly Inspection****Location****Submitted By**  [Fernando Sanchez](#)*Location was not collected for this report.***Surrogate**  [Fernando Sanchez](#)**Started On** September 16 2024, 9:42am**Submitted On** September 16 2024, 9:46am (4 minutes)**Weather** NaN°,**Version** V1 (latest)**Updated** September 16 2024, 9:46am**Report No.** 46264999**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS****Date** September 16th 2024**Area** [New Mexico](#)**Recycle Facility** [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION****Read and record the fluid height of staff gauges** 11ft 6in**Does the pond surface show visible oil?** No**Visually inspect containments liner** Liner looks to be in good condition**Check leak detection system for any evidence of a loss of integrity of the primary liner** All good**SUMMARY****# of Action Item(s)** 0**Inspector** [Fernando Sanchez](#)**Signature**

A handwritten signature in blue ink, appearing to read "Fernando Sanchez", written over a horizontal line.

**New Mexico Recycling Facility Weekly Inspection****Location****Submitted By**  [Fernando Sanchez](#)*Location was not collected for this report.***Surrogate**  [Fernando Sanchez](#)**Started On** September 23 2024, 12:27pm**Submitted On** September 23 2024, 12:29pm (2 minutes)**Weather** NaN°,**Version** V1 (latest)**Updated** September 23 2024, 12:29pm**Report No.** 46599137**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS****Date** September 23rd 2024**Area** [New Mexico](#)**Recycle Facility** [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION****Read and record the fluid height of staff gauges** 11ft**Does the pond surface show visible oil?** No**Visually inspect containments liner** Liner seems to be in good condition**Check leak detection system for any evidence of a loss of integrity of the primary liner** All goos**SUMMARY****# of Action Item(s)** 0**Inspector** [Fernando Sanchez](#)**Signature**

A handwritten signature in blue ink, appearing to read "Fernando Sanchez", written over a horizontal line.



New Mexico Recycling Facility Weekly Inspection

Submitted By  [Fernando Sanchez](#)

Surrogate  [Fernando Sanchez](#)

Started On September 30 2024, 11:59am

Submitted On September 30 2024, 12:02pm (3 minutes)


Weather 81°, clear

Version V1 (latest)

Updated September 30 2024, 12:02pm

Report No. 46937802

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date September 30th 2024

Area [New Mexico](#)

Recycle Facility [FULFER_RECYCLE_FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 10 ft 6in

Does the pond surface show visible oil? No

Visually inspect containments liner Liner looks to be in good condition

Check leak detection system for any evidence of a loss of integrity of the primary liner All good

SUMMARY

of Action Item(s) 0

Inspector [Fernando Sanchez](#)

Signature

Generated Friday, October 4th 2024, 8:18am CDT

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

June 11 2025, 11:06am

Submitted On

June 11 2025, 11:07am (2 minutes)

Weather

70°, cloudy

Version


V1 (latest)

Updated

June 11 2025, 11:07am

Report No.

60483777



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

October 1st 2024

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector


[Mario Nevarez](#)

Signature




New Mexico Recycling Facility Monthly Inspection

Submitted By



Mario Nevarez

Surrogate



Mario Nevarez

Started On

October 7 2024, 10:34am

Submitted On

October 7 2024, 10:36am (2 minutes)

Weather

71°, clear

Version

V1 (latest)


Updated

October 7 2024, 10:36am

Report No.

47285219

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS	
Date	October 7th 2024 9:34 AM MDT
Area	New Mexico
Recycle Facility	FULFER_RECYCLE_FACILITY
INLET AST	
Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	N/A
Is bird netting in good condition?	N/A
Is there any evidence of cracking or subsidence of the pad around the AST?	N/A
Is there oil to be skimmed?	N/A
EFFLUENT AST	
Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	N/A
Is there any evidence of cracking or subsidence of the pad around the AST?	N/A
SOUTH POND	
Is there fluid in the leak detection system?	No

Are pond level markers visible?	Yes
---------------------------------	-----

Is pond level sensor working?	Yes
-------------------------------	-----

Is there any visible damage to the pond liner?	No
--	----

Any migratory birds or wildlife discovered in the pond?	No
---	----

Is bird deterrent working?	Yes
----------------------------	-----

Is there any evidence of cracking or subsidence around the pond berm?	No
---	----

Is there any erosion on the outside of the berm?	No
--	----

Is life vest and related pond safety equipment in working condition?	Yes
--	-----

Is pond aeration system functional?	Yes
-------------------------------------	-----

TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
---	-----

Is there any evidence of spills or soil staining that have not been cleaned up?	No
---	----

Any migratory birds or wildlife discovered in the facility?	No
---	----

Are there any holes found in the containment liner?	No
---	----


Any evidence of erosion on the outside slope of the facility?	No
---	----

SUMMARY

# of Action Item(s)	0
---------------------	---

Inspector	Mario Nevarez
-----------	-------------------------------

Signature



Generated Monday, October 14th 2024, 9:07am CDT

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On June 11 2025, 11:08am

Submitted On June 11 2025, 11:09am (44 seconds)


Weather 70°, cloudy

Version V1 (latest)

Updated June 11 2025, 11:09am

Report No. 60483864

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date October 8th 2024

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

Generated Wednesday, June 11th 2025, 12:46pm CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Nevarez](#)*Location was not collected for this report.*

Surrogate

[Mario Nevarez](#)**Started On** October 15 2024, 9:38am**Submitted On** October 15 2024, 9:42am (4 minutes)**Weather** NaN°,**Version** V1 (latest)**Updated** October 15 2024, 9:42am**Report No.** 47660976**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS****Date** October 15th 2024**Area** [New Mexico](#)**Recycle Facility** [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION****Read and record the fluid height of staff gauges** 13**Does the pond surface show visible oil?** No**Visually inspect containments liner** Yes no issues to report**Check leak detection system for any evidence of a loss of integrity of the primary liner** No issues to report**SUMMARY****# of Action Item(s)** 0**Inspector** [Mario Nevarez](#)**Signature**

A handwritten signature in blue ink, consisting of a stylized, overlapping set of loops and lines, positioned above a horizontal line.



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On June 11 2025, 11:10am

Submitted On June 11 2025, 11:11am (40 seconds)


Weather 70°, cloudy

Version V1 (latest)

Updated June 11 2025, 11:11am

Report No. 60483996

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date October 22nd 2024

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

Generated Wednesday, June 11th 2025, 12:50pm CDT.

powered by KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By  [Mario Nevarez](#)Surrogate  [Mario Nevarez](#)

Started On June 11 2025, 11:11am

Submitted On June 11 2025, 11:11am (32 seconds)


Weather 70°, cloudy

Version V1 (latest)

Updated June 11 2025, 11:11am

Report No. 60484041

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date October 29th 2024

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature



New Mexico Recycling Facility Monthly Inspection

Submitted By  [Mario Nevarez](#)

Surrogate  [Mario Nevarez](#)

Started On November 5 2024, 1:28pm

Submitted On November 5 2024, 1:30pm (a minute)


Weather 65°, clear

Version V1 (latest)

Updated November 5 2024, 1:30pm

Report No. 48690996

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date November 5th 2024 12:28 PM MST

Area [New Mexico](#)

Recycle Facility [FULFER_RECYCLE_FACILITY](#)

INLET AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is bird netting in good condition? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

Is there oil to be skimmed? N/A

EFFLUENT AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

SOUTH POND

Is there fluid in the leak detection system? No



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

June 11 2025, 11:12am

Submitted On

June 11 2025, 11:13am (a minute)

Weather

70°, cloudy

Version


V1 (latest)

Updated

June 11 2025, 11:13am

Report No.

60484153



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

November 5th 2024

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature

Are pond level markers visible?	Yes
Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes

TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY

# of Action Item(s)	0
Inspector	Mario Nevarez



Signature





Generated Wednesday, November 6th 2024, 8:01am CST

powered by  KPA



New Mexico Recycling Facility Weekly Inspection		Location
Submitted By	 Fernando Sanchez	Location was not collected for this report.
Surrogate	 Fernando Sanchez	
Started On	November 6 2024, 10:03am	
Submitted On	November 6 2024, 10:08am (6 minutes)	
Weather	NaN°,	
Version	V1 (latest)	
Updated	November 6 2024, 10:08am	
Report No.	48740227	

New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS	
	<div>NOTES</div> <div>Outer sides of pond need dirt work. Signs of erosion</div>
<div></div>	
Date	November 6th 2024
Area	New Mexico
Recycle Facility	FULFER_RECYCLE_FACILITY
WEEKLY INSPECTION	
Read and record the fluid height of staff gauges	12ft 9in
Does the pond surface show visible oil?	No
Visually inspect containments liner	Liner appears to be in good condition . Dirt on the side of ponds has clear erosion. Needs to get some dirt work done.

**Check leak detection system
for any evidence of a loss of
integrity of the primary liner**

All good

SUMMARY

of Action Item(s)

0

Inspector

[Fernando Sanchez](#)




Signature

A handwritten signature in blue ink, appearing to be 'FS', written over a horizontal line.

Generated Wednesday, November 6th 2024, 10:41am CST

powered by  KPA



New Mexico Recycling Facility Weekly Inspection		Location
Submitted By	 Mario Nevarez	
Surrogate	 Mario Nevarez	
Started On	November 14 2024, 11:35am	
Submitted On	November 14 2024, 11:37am (2 minutes)	
Weather	62°, clear	
Version	V1 (latest)	
Updated	November 14 2024, 11:37am	
Report No.	49143624	

New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS	
Date	November 14th 2024
Area	New Mexico
Recycle Facility	FULFER_RECYCLE_FACILITY
WEEKLY INSPECTION	
Read and record the fluid height of staff gauges	Completed
Does the pond surface show visible oil?	No
Visually inspect containments liner	Complete
Check leak detection system for any evidence of a loss of integrity of the primary liner	Completed
SUMMARY	
# of Action Item(s)	0
Inspector	Mario Nevarez

Signature 



New Mexico Recycling Facility Weekly Inspection

Submitted By  [Fernando Sanchez](#)

Surrogate  [Fernando Sanchez](#)

Started On November 18 2024, 9:42am

Submitted On November 18 2024, 9:45am (3 minutes)


Weather 50°, wind

Version V1 (latest)

Updated November 18 2024, 9:45am

Report No. 49296246

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date November 15th 2024

Area [New Mexico](#)

Recycle Facility [FULFER_RECYCLE_FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 12ft 9in

Does the pond surface show visible oil? No

Visually inspect containments liner Liner looks good

NOTES

Dirt around the pond on the sides is eroded


Check leak detection system for any evidence of a loss of integrity of the primary liner All good

SUMMARY

of Action Item(s) 0

Inspector [Fernando Sanchez](#)

Signature

A handwritten signature in blue ink, appearing to be 'JLS', is written over a horizontal line.

Generated Tuesday, November 19th 2024, 7:55am CST

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On June 11 2025, 11:13am

Submitted On June 11 2025, 11:14am (41 seconds)


Weather 70°, cloudy

Version V1 (latest)

Updated June 11 2025, 11:14am

Report No. 60484215

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date November 19th 2024

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On June 11 2025, 11:15am

Submitted On June 11 2025, 11:15am (31 seconds)


Weather 70°, cloudy

Version V1 (latest)

Updated June 11 2025, 11:15am

Report No. 60484271

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date November 26th 2024

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

Generated Wednesday, June 11th 2025, 12:52pm CDT.

powered by KPA



New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On June 6 2025, 5:10pm

Submitted On June 11 2025, 11:18am (5 days)

Weather 70°, cloudy

Version V1 (latest)

Updated June 11 2025, 11:18am

Report No. 60484469

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date December 1st 2024 11:15 AM

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

INLET AST

Is there fluid in the leak detection system? No

Any migratory birds or wildlife discovered in the AST? No

Is bird netting in good condition? Yes

Is there any evidence of cracking or subsidence of the pad around the AST? No

Is there oil to be skimmed? No

EFFLUENT AST

Is there fluid in the leak detection system? No

Any migratory birds or wildlife discovered in the AST? No

Is there any evidence of cracking or subsidence of the pad around the AST? No

SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible? Yes



New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On June 6 2025, 5:10pm

Submitted On June 11 2025, 11:18am (5 days)


Weather 70°, cloudy

Version V1 (latest)

Updated June 11 2025, 11:18am

Report No. 60484469

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date December 1st 2024 11:15 AM

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

INLET AST

Is there fluid in the leak detection system? No

Any migratory birds or wildlife discovered in the AST? No

Is bird netting in good condition? Yes

Is there any evidence of cracking or subsidence of the pad around the AST? No

Is there oil to be skimmed? No

EFFLUENT AST

Is there fluid in the leak detection system? No

Any migratory birds or wildlife discovered in the AST? No

Is there any evidence of cracking or subsidence of the pad around the AST? No

SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible? Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes


TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY

# of Action Item(s)	0
Inspector	Mario Nevarez

Signature



Generated Wednesday, June 11th 2025, 12:53pm CDT.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By  [Steven Anderson](#)

Location was not collected for this report.

Surrogate  [Steven Anderson](#)

Started On December 19 2024, 7:57am

Submitted On December 19 2024, 8:03am (5 minutes)

Weather NaN°,

Version V1 (latest)

Updated December 19 2024, 8:03am

Report No. 50742422

New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date December 4th 2024

Area [New Mexico](#)

Recycle Facility [FULFER_RECYCLE_FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 13'

Does the pond surface show visible oil? No

Visually inspect containments liner Everything is good

Check leak detection system for any evidence of a loss of integrity of the primary liner Everything is good

SUMMARY

of Action Item(s) 1

Action Item Report [VIEW](#)

ACTION ITEMS

1

Item	Berm has wash out spots and needs filled and repacked
Lease/Location	BOBCAT SWD
Responsible Persons	None
Target Date	February 1st 2025
Picture	None

Inspector [Steven Anderson](#)

Signature



Generated Thursday, December 19th 2024, 8:43am CST

powered by  KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Steven Anderson](#)*Location was not collected for this report.*

Surrogate

[Steven Anderson](#)**Started On** December 19 2024, 8:03am**Submitted On** December 19 2024, 8:04am (a minute)**Weather** NaN°,**Version** V1 (latest)**Updated** December 19 2024, 8:04am**Report No.** 50742521**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS****Date** December 11th 2024**Area** [New Mexico](#)**Recycle Facility** [FULFER_RECYCLE_FACILITY](#)**WEEKLY INSPECTION****Read and record the fluid height of staff gauges** 13'**Does the pond surface show visible oil?** No**Visually inspect containments liner** Everything is good**Check leak detection system for any evidence of a loss of integrity of the primary liner** Everything is good**SUMMARY****# of Action Item(s)** 0**Inspector** [Steven Anderson](#)**Signature**

A blue ink handwritten signature, appearing to be "SA", written over a horizontal line.



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On June 11 2025, 11:18am

Submitted On June 11 2025, 11:19am (45 seconds)


Weather 70°, cloudy

Version V1 (latest)

Updated June 11 2025, 11:19am

Report No. 60484520

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date December 18th 2024

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes


TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY

# of Action Item(s)	0
Inspector	Mario Nevarez

Signature




Generated Wednesday, June 11th 2025, 12:53pm CDT.

powered by  KPA




New Mexico Recycling Facility Weekly Inspection

Submitted By

 [Fernando Sanchez](#)

Surrogate

 [Fernando Sanchez](#)

Started On

January 11 2025, 9:41am

Submitted On

January 11 2025, 9:45am (4 minutes)

Weather

33°, clear

Version

V1 (latest)


Updated

January 11 2025, 9:45am

Report No.

51607520

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

NOTES
Erosion on soil around pond



Date

January 10th 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER_RECYCLE_FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

12' 2"

Does the pond surface show visible oil?

No

Visually inspect containments liner

No issues

Check leak detection system for any evidence of a loss of integrity of the primary liner

All looks good

SUMMARY

of Action Item(s) 0

Inspector [Fernando Sanchez](#)

Signature



Generated Monday, January 13th 2025, 1:04pm CST

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By  [Fernando Sanchez](#)

Surrogate  [Fernando Sanchez](#)

Started On January 23 2025, 2:35pm

Submitted On January 23 2025, 2:37pm (2 minutes)

Weather 43°, clear

Version V1 (latest)

Updated January 23 2025, 4:02pm

Report No. 52201879

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date January 15th 2025

Area [New Mexico](#)

Recycle Facility [FULFER_RECYCLE_FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 12' 2"

Does the pond surface show visible oil? No

Visually inspect containments liner Liner seems to be in good condition

Check leak detection system for any evidence of a loss of integrity of the primary liner All good

SUMMARY

of Action Item(s) 0

Inspector [Fernando Sanchez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Submitted By  [Fernando Sanchez](#)

Surrogate  [Fernando Sanchez](#)

Started On January 29 2025, 8:22am

Submitted On January 29 2025, 8:27am (5 minutes)


Weather 39°, cloudy

Version V1 (latest)

Updated January 29 2025, 8:27am

Report No. 52504608

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date January 23rd 2025

Area [New Mexico](#)

Recycle Facility [FULFER_RECYCLE_FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 11ft

Does the pond surface show visible oil? No

Visually inspect containments liner Liner looks to be in good condition

Check leak detection system for any evidence of a loss of integrity of the primary liner No issues

SUMMARY

NOTES

Soil around pond has real bad erosion.



of Action Item(s)

0

Inspector

[Fernando Sanchez](#)

Signature

A handwritten signature in blue ink, appearing to read "F. Sanchez", written over a horizontal line.

Generated Tuesday, February 4th 2025, 12:22pm CST

powered by  KPA




New Mexico Recycling Facility Weekly Inspection

Submitted By  [Fernando Sanchez](#)

Surrogate  [Fernando Sanchez](#)

Started On February 5 2025, 12:36pm
Submitted On February 5 2025, 12:39pm (2 minutes)
Weather 70°, clear
Version V1 (latest)
Updated February 5 2025, 12:39pm
Report No. 52951979

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date January 30th 2025
Area [New Mexico](#)
Recycle Facility [FULFER_RECYCLE_FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 10ft
Does the pond surface show visible oil? No
Visually inspect containments liner Liner looks to be in good condition
Check leak detection system for any evidence of a loss of integrity of the primary liner All good

SUMMARY

of Action Item(s) 0
Inspector [Fernando Sanchez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By

[Steven Anderson](#)

Location was not collected for this report.

Surrogate

[Steven Anderson](#)

Started On

February 12 2025, 8:46am

Submitted On

February 12 2025, 8:48am (2 minutes)

Weather

NaN°

Version

V1 (latest)

Updated

February 12 2025, 8:48am

Report No.

53326135

New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

February 5th 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

11'6"

Does the pond surface show visible oil?

No

Visually inspect containments liner

Everything looks good

Check leak detection system for any evidence of a loss of integrity of the primary liner

Good

SUMMARY

of Action Item(s)

0

Inspector

[Steven Anderson](#)

Signature

Generated Friday, February 21st 2025, 12:09pm CST.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Steven Anderson](#)*Location was not collected for this report.*

Surrogate

[Steven Anderson](#)

Started On February 12 2025, 8:49am

Submitted On February 12 2025, 8:50am (45 seconds)

Weather NaN°,

Version V1 (latest)

Updated February 12 2025, 8:50am

Report No. 53326260

New Mexico Recycling Facility Weekly Inspection**GENERAL DETAILS**

Date February 12th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 12'

Does the pond surface show visible oil? No

Visually inspect containments liner Good

Check leak detection system for any evidence of a loss of integrity of the primary liner Good

SUMMARY

of Action Item(s) 0

Inspector [Steven Anderson](#)

Signature

A handwritten signature in blue ink, appearing to be "S. Anderson", written over a horizontal line.

Generated Friday, February 21st 2025, 12:07pm CST.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Steven Anderson](#)*Location was not collected for this report.*

Surrogate

[Steven Anderson](#)

Started On February 26 2025, 11:01am

Submitted On February 26 2025, 11:01am (47 seconds)

Weather NaN°,

Version V1 (latest)

Updated February 26 2025, 11:02am

Report No. 54112301

New Mexico Recycling Facility Weekly Inspection**GENERAL DETAILS**

Date February 19th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 15'

Does the pond surface show visible oil? No

Visually inspect containments liner Good

Check leak detection system for any evidence of a loss of integrity of the primary liner Good

SUMMARY

of Action Item(s) 0

Inspector [Steven Anderson](#)

Signature

A handwritten signature in blue ink, appearing to be "SA", written over a horizontal line.

Generated Friday, March 21st 2025, 9:52am CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Steven Anderson](#)*Location was not collected for this report.*

Surrogate

[Steven Anderson](#)

Started On February 26 2025, 11:02am

Submitted On February 26 2025, 11:02am (37 seconds)

Weather NaN°,

Version V1 (latest)

Updated February 26 2025, 11:02am

Report No. 54112342

New Mexico Recycling Facility Weekly Inspection**GENERAL DETAILS**

Date February 26th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 13'

Does the pond surface show visible oil? No

Visually inspect containments liner Good

Check leak detection system for any evidence of a loss of integrity of the primary liner Good

SUMMARY

of Action Item(s) 0

Inspector [Steven Anderson](#)

Signature

A handwritten signature in blue ink, appearing to be "S. Anderson", written over a horizontal line.

Generated Friday, March 21st 2025, 9:53am CDT.

powered by KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Fernando Sanchez](#)

Surrogate

[Fernando Sanchez](#)

Started On March 10 2025, 12:18pm

Submitted On March 10 2025, 12:31pm (13 minutes)


Weather 63°, clear

Version V1 (latest)

Updated March 10 2025, 12:31pm

Report No. 54839840

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date March 6th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 12ft

Does the pond surface show visible oil? No

Visually inspect containments liner Liner looks to be in good condition

Check leak detection system for any evidence of a loss of integrity of the primary liner No evidence to suggest loss of integrity

SUMMARY

of Action Item(s) 0

Inspector [Fernando Sanchez](#)

Signature

Generated Friday, March 21st 2025, 9:55am CDT.

powered by KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Fernando Sanchez](#)

Surrogate

[Fernando Sanchez](#)

Started On

March 31 2025, 4:14pm

Submitted On

March 31 2025, 4:16pm (a minute)

Weather

77°, clear

Version

V1 (latest)


Updated

March 31 2025, 4:16pm

Report No.

56131699

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

March 13th 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

12ft

Does the pond surface show visible oil?

No

Visually inspect containments liner

Liner looks to be in good condition

Check leak detection system for any evidence of a loss of integrity of the primary liner

No evidence of loss of integrity

SUMMARY

of Action Item(s)

0

Inspector

[Fernando Sanchez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Fernando Sanchez](#)

Surrogate

[Fernando Sanchez](#)

Started On

March 31 2025, 4:16pm

Submitted On

March 31 2025, 4:17pm (a minute)

Weather

77°, clear

Version

V1 (latest)


Updated

March 31 2025, 4:17pm

Report No.

56131818

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

March 20th 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

12ft

Does the pond surface show visible oil?

No

Visually inspect containments liner

Liner looks to be in good condition

Check leak detection system for any evidence of a loss of integrity of the primary liner

No evidence of loss of integrity

SUMMARY

of Action Item(s)

0

Inspector

[Fernando Sanchez](#)

Signature

None

Generated Tuesday, April 1st 2025, 12:50pm CDT.

powered by KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Fernando Sanchez](#)

Surrogate

[Fernando Sanchez](#)

Started On

March 31 2025, 4:18pm

Submitted On

March 31 2025, 4:19pm (a minute)

Weather

73°, clear

Version

V1 (latest)


Updated

March 31 2025, 4:19pm

Report No.

56131873

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

March 27th 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

12ft

Does the pond surface show visible oil?

No

Visually inspect containments liner

Liner looks to be in good condition

Check leak detection system for any evidence of a loss of integrity of the primary liner

No evidence of loss of integrity

SUMMARY

of Action Item(s)

0

Inspector

[Fernando Sanchez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

June 11 2025, 11:21am

Submitted On

June 11 2025, 11:22am (46 seconds)

Weather

70°, cloudy

Version

V1 (latest)


Updated

June 11 2025, 11:22am

Report No.

60484717

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

April 1st 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature



New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On June 11 2025, 11:19am

Submitted On June 11 2025, 11:21am (2 minutes)


Weather 70°, cloudy

Version V1 (latest)

Updated June 11 2025, 11:21am

Report No. 60484654

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date April 1st 2025 11:19 AM

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

INLET AST

Is there fluid in the leak detection system? No

Any migratory birds or wildlife discovered in the AST? No

Is bird netting in good condition? Yes

Is there any evidence of cracking or subsidence of the pad around the AST? No

Is there oil to be skimmed? No

EFFLUENT AST

Is there fluid in the leak detection system? No

Any migratory birds or wildlife discovered in the AST? No

Is there any evidence of cracking or subsidence of the pad around the AST? No

SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible? Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes


TREATMENT FACILITY

Is fencing and cattleguard in good condition?	None
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY

# of Action Item(s)	0
Inspector	Mario Nevarez

Signature



Generated Wednesday, June 11th 2025, 12:54pm CDT.

powered by  KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

June 11 2025, 11:21am

Submitted On

June 11 2025, 11:22am (46 seconds)

Weather

70°, cloudy

Version

V1 (latest)

Updated

June 11 2025, 11:22am

Report No.

60484717

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date

April 1st 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature

A handwritten signature in blue ink, consisting of a stylized 'M' and 'N' intertwined, written over a horizontal line.

Generated Wednesday, June 11th 2025, 12:55pm CDT.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

June 11 2025, 11:22am

Submitted On

June 11 2025, 11:22am (29 seconds)

Weather

70°, cloudy

Version


V1 (latest)

Updated

June 11 2025, 11:22am

Report No.

60484750



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

April 8th 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On June 11 2025, 11:24am

Submitted On June 11 2025, 11:25am (38 seconds)


Weather 70°, cloudy

Version V1 (latest)

Updated June 11 2025, 11:25am

Report No. 60484944

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date April 14th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

Generated Wednesday, June 11th 2025, 12:57pm CDT.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Lopez](#)

Surrogate

[Mario Lopez](#)

Started On April 23 2025, 11:25am

Submitted On April 23 2025, 11:29am (3 minutes)


Weather 72°, cloudy

Version V1 (latest)

Updated April 23 2025, 11:29am

Report No. 57569948

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date April 23rd 2025

Area [West Texas](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 12' pond

Does the pond surface show visible oil? No

Visually inspect containments liner Liner looks good

Check leak detection system for any evidence of a loss of integrity of the primary liner Working

SUMMARY

of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

Generated Wednesday, April 23rd 2025, 11:29am CDT.

powered by KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On June 11 2025, 11:25am

Submitted On June 11 2025, 11:26am (28 seconds)


Weather 70°, cloudy

Version V1 (latest)

Updated June 11 2025, 11:26am

Report No. 60485039

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date April 29th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

Generated Wednesday, June 11th 2025, 12:55pm CDT.

powered by  KPA



New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Lopez](#)

Surrogate

[Mario Lopez](#)

Started On May 7 2025, 4:06pm

Submitted On May 7 2025, 4:08pm (2 minutes)

Weather 74°, clear

Version V1 (latest)

Updated May 7 2025, 4:08pm

Report No. 58493004

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date May 7th 2025 4:06 PM CDT

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

INLET AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? No

Is bird netting in good condition? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? No

Is there oil to be skimmed? No

EFFLUENT AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? No

Is there any evidence of cracking or subsidence of the pad around the AST? No

SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible? Yes

Is pond level sensor working?	N/A
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	No
Is there any evidence of cracking or subsidence around the pond berm?	None
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	No

TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY

# of Action Item(s)	0
Inspector	Mario Lopez

Signature



Generated Tuesday, May 13th 2025, 9:04am CDT.

powered by  KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On

May 12 2025, 10:20am

Submitted On

May 12 2025, 10:23am (3 minutes)

Weather

NaN°,

Version

V1 (latest)

Updated

May 12 2025, 10:23am

Report No.

58718829

New Mexico Recycling Facility Weekly Inspection**GENERAL DETAILS**

Date

May 12th 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges

12'6"

Does the pond surface show visible oil?

No

Visually inspect containments liner

All look good

Check leak detection system for any evidence of a loss of integrity of the primary liner

no leaks

SUMMARY

of Action Item(s)

0

Inspector

[Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "ML", written over a horizontal line.

Generated Tuesday, May 13th 2025, 9:03am CDT.

powered by KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Fernando Sanchez](#)

Surrogate

[Fernando Sanchez](#)

Started On

May 14 2025, 4:28pm

Submitted On

May 14 2025, 4:32pm (4 minutes)

Weather

93°, clear

Version

V1 (latest)

Updated

May 14 2025, 4:32pm

Report No.

58897176

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

May 14th 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

12ft 1in

NOTES

Aerator pump was not running. Got in touch with electricians so they can trouble shoot. They will be looking into it

Does the pond surface show visible oil?

No

Visually inspect containments liner

Liner looks to be in good condition

Check leak detection system for any evidence of a loss of integrity of the primary liner

No evidence of integrity loss

SUMMARY

of Action Item(s)

0

Inspector

[Fernando Sanchez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Fernando Sanchez](#)

Surrogate

[Fernando Sanchez](#)

Started On May 22 2025, 2:10pm

Submitted On May 22 2025, 2:17pm (7 minutes)


Weather 96°, clear

Version V1 (latest)

Updated May 22 2025, 2:17pm

Report No. 59355622

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date May 22nd 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 12ft 1in

Does the pond surface show visible oil? No

Visually inspect containments liner Liner looks to be in working condition

Check leak detection system for any evidence of a loss of integrity of the primary liner No evidence of loss of integrity but aerator pump is not running. Was told it was an issue on xcel a side causing insufficient power for pump panel. No eta from xcel at this time

SUMMARY

of Action Item(s) 0

Inspector [Fernando Sanchez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On

May 26 2025, 9:34am

Submitted On

May 26 2025, 9:45am (11 minutes)

Weather

NaN°,

Version

V1 (latest)

Updated

May 26 2025, 9:45am

Report No.

59484554

New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

May 26th 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

12'

Does the pond surface show visible oil?

No

Visually inspect containments liner

Liner looks in good condition no visible damage

Check leak detection system for any evidence of a loss of integrity of the primary liner

N/A

SUMMARY

of Action Item(s)

1

1 Action Item Report [VIEW](#)

ACTION ITEMS

Item There's several wash outs around the pond from heavy rains.




Lease/Location [FULFUR RECYCLE FACILITY](#)

Responsible Persons **FOLLOW-UPS**
Assigned to Nathan Ford on 5/26/25, Due 6/5/25

Please fix the washouts around the pond, see attached pictures. - by [Mario Lopez](#) on 5/26/25

Target Date June 5th 2025

Picture



Inspector

[Mario Lopez](#)

Signature

A handwritten signature in blue ink, consisting of several sharp, angular strokes, written over a horizontal line.

Generated Tuesday, May 27th 2025, 10:58am CDT.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Fernando Sanchez](#)

Surrogate

[Fernando Sanchez](#)

Started On May 28 2025, 1:07pm

Submitted On May 28 2025, 1:18pm (11 minutes)


Weather 78°, clear

Version V1 (latest)

Updated May 28 2025, 1:18pm

Report No. 59653440

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date None

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 11ft 10in

Does the pond surface show visible oil? No

Visually inspect containments liner Liner looks to be in working condition

Check leak detection system for any evidence of a loss of integrity of the primary liner

No evidence of loss of integrity.
Still waiting on xcel to resolve incoming power issues to be able to run aerator pump.

SUMMARY

of Action Item(s) 0

Inspector [Fernando Sanchez](#)

Signature

Generated Friday, May 30th 2025, 9:22am CDT.

powered by KPA

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Monday, June 23, 2025 11:25 AM
To: David Grounds; Shelly Cowden
Subject: 1RF-23 – OWL FULFER RECYCLING FACILITY AND CONTAINMENT [fOY1728349023]
Attachments: C-147 1RF-23 – OWL FULFER RECYCLING FACILITY AND CONTAINMENT [fOY1728349023] 06.23.2025.pdf

1RF-23 – OWL FULFER RECYCLING FACILITY AND CONTAINMENT [fOY1728349023]

Good morning, Mr. Grounds.

NMOCD has reviewed the determination of registration/permit annual extension request for 1RF-23 – OWL FULFER RECYCLING FACILITY AND CONTAINMENT [fOY1728349023] received from [308339] OWL SWD OPERATING, LLC on 6/17/2025, Application ID **475911**. The registration/permit annual extension request is approved with the following conditions of approval:

- 1RF-23 – OWL FULFER RECYCLING FACILITY AND CONTAINMENT [fOY1728349023] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of June 26, 2025. The new registration/permit expiration date is June 26, 2026.
- [308339] OWL SWD OPERATING, LLC will continue to operate, maintain, and close the 1RF-23 - OWL Fulfer Recycling Facility and Containment, ID [fOY1728349023] in compliance with 19.15.34 NMAC, to include but not limited to the performance of weekly inspections regardless of fluid levels in the containment; recording of detailed inspection reports; removal of debris, foreign objects and oil from the containment; and monthly reporting of recycling and reuse of produced water, drilling fluids, and liquid oil field waste via from C-148.
- [308339] OWL SWD OPERATING, LLC will maintain a liquid level in the containment that is at least equal to the weight of the liner plus 20%. [308339] OWL SWD OPERATING, LLC may maintain a higher liquid level if they choose.
- If less than 20% of the total fluid capacity is utilized every consecutive six months, operation of the facility is considered ceased and notification of cessation of operations should be sent electronically form through the OCD Online. An extension to extend the cessation of operations, not to exceed six months, may be submitted using a C-147 form via OCD Online.
- The recycling containment is bonded pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC. Water reuse and recycling from 1RF-23 – OWL FULFER RECYCLING FACILITY AND CONTAINMENT [fOY1728349023] is limited to wells owned or operated by [308339] OWL SWD OPERATING, LLC.
- A minimum of 3-feet freeboard must be maintained in the recycling containment at all times.
- [308339] OWL SWD OPERATING, LLC will comply with 19.15.29 NMAC Releases in the event of any release of produced water or other oil field wastes at 1RF-23 – OWL FULFER RECYCLING FACILITY AND CONTAINMENT [fOY1728349023]. [308339] OWL SWD OPERATING, LLC will comply with all other OCD rules.
- [308339] OWL SWD OPERATING, LLC must perform weekly inspections of the containment and leak detection system.
- If [308339] OWL SWD OPERATING, LLC, wishes to extend the registration/permit past June 26, 2026, a registration/permit extension request must be submitted to OCD. Extension requests are reviewed on a case-by-case basis and evaluated on their merit and are considered for a maximum length of one year.
- Additional requests must be submitted to OCD through the OCD Online system on Form C-147 as an Extension request and should include a formal extension request letter, a summary of the prior registration/permit period inspection reports, and the copies of the detailed inspection records for the prior permit period. The extension request should be submitted no later than May 26, 2026.

Please let me know if you have any questions.

Best regards,

Victoria Venegas ● Environmental Specialist Advanced
EMNRD - Oil Conservation Division
506 W. Texas Ave. Artesia, NM 88210
575.909.0269 | Victoria.Venegas@emnrd.nm.gov

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oecd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 475911

CONDITIONS

Operator: OWL SWD OPERATING, LLC 20 Greenway Plaza Houston, TX 77046	OGRID: 308339
	Action Number: 475911
	Action Type: [C-147] Water Recycle Long (C-147L)

CONDITIONS

Created By	Condition	Condition Date
vvenegas	1RF-23 – OWL FULFER RECYCLING FACILITY AND CONTAINMENT [fOY1728349023] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of June 26, 2025. The new registration/permit expiration date is June 26, 2026. If [308339] OWL SWD OPERATING, LLC, wishes to extend the registration/permit past June 26, 2026, a registration/permit extension request must be submitted to OCD no later than May 26, 2026.	6/23/2025