



Enduring Resources IV, LLC

Main Office- 6300 S. Syracuse Way Suite 525 Centennial, CO 80111

Field Office- 200 Energy Court Farmington, NM 87401

Field Office: 505.636.9720 | Main Office: 303.573.1222

September 8, 2025

Enduring Resources, LLC

WLU 2309-24N – 3RF-29

Recycling Facility/Containment

Permit Extension Request for 19.15.34 NMAC

New Mexico Oil Conservation Division

Attn: Victoria Venegas

Enduring Resources is requesting a permit extension for the WLU 2309-24N (3RF-29) Water Recycling Facility. In accordance with 19.15.34.10.C NMAC, »Registered.recycling.containments.may.be.operated.for.five.years.from.the.date.on.which.the.registration.is.filed.with.the.division;.The.operator.may.extend.the.allowed.time.on.an.annual.basis.thereafter.with.division.approval.if.96.days.prior.to.the.registration.expiration.the.operator.files.a.form.C_709with.an.attached.summary.showing.all.monthly.inspections.at.the.containment.including.the.monitoring.of.the.leak.detection.system.showing.the.containment's.integrity.has.not.been.compromised;

The original facility permit was approved on October 14, 2018. The five-year approval period ended on October 14, 2023. Enduring submitted a one-year extension that was approved until October 14, 2025. Enduring is now requesting an extension to operate through October 14, 2026. At that time Enduring will determine if additional annual extensions will be filed. Enduring has included records for the weekly inspections at this facility that have occurred since the last permit extension request (October 2024 through August 2025). There has been no indication that the leak detection system's integrity is compromised. Enduring will continue to operate the facility per regulations in 19.15.34 NMAC.

Thank You,

Heather Huntington

Regulatory Specialist

Enduring Resources, LLC

hhuntington@enduringresources.com

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-147
Revised April 3, 2017

Recycling Facility and/or Recycling Containment

Type of Facility: ☒ Recycling Facility ☒ Recycling Containment*
Type of action: ☐ Permit ☐ Registration
☐ Modification ☒ Extension 10/14/25-10/24/26
☐ Closure ☐ Other (explain) _____

* At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.

Operator: Enduring Resources IV, LLC (For multiple operators attach page with information) OGRID #: 372286
Address: 200 Energy Court, Farmington, New Mexico 87401
Facility or well name (include API# if associated with a well): WLU 2309-24N Water Recycle Facility / Containment
OCD Permit Number: #3RF-29 (For new facilities the permit number will be assigned by the district office)
U/L or Qtr/Qtr SE/4 SW/4 & SW/4 Section 24 Township 23N Range 9W County: San Juan
Surface Owner: ☒ Federal ☐ State ☐ Private ☐ Tribal Trust or Indian Allotment

2.

☒ **Recycling Facility:**

Location of recycling facility (if applicable): Latitude 36.205958 Longitude 107.740891 NAD83

Proposed Use: ☒ Drilling* ☒ Completion* ☒ Production* ☒ Plugging *

*The re-use of produced water may NOT be used until fresh water zones are cased and cemented

☐ Other, requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.

☒ Fluid Storage

☒ Above ground tanks ☒ Recycling containment ☐ Activity permitted under 19.15.17 NMAC explain type _____

☐ Activity permitted under 19.15.36 NMAC explain type: _____ ☐ Other explain _____

☐ For multiple or additional recycling containments, attach design and location information of each containment

☐ **Closure Report (required within 60 days of closure completion):** ☐ Recycling Facility Closure Completion Date: _____

3.

☒ **Recycling Containment:**

☐ Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)

Center of Recycling Containment (if applicable): Latitude 36.205958 Longitude 107.740891 NAD83

☐ For multiple or additional recycling containments, attach design and location information of each containment

☒ Lined ☐ Liner type: Thickness 60 mil ☐ LLDPE ☒ HDPE ☐ PVC ☐ Other _____

☒ String-Reinforced

Liner Seams: ☒ Welded ☐ Factory ☐ Other _____ Volume: 265,385 bbl Dimensions: L 350' x W 400' x D 25'

☐ Recycling Containment Closure Completion Date: _____

4.

Bonding:

- ☒ Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)
- ☐ Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ _____ (work on these facilities cannot commence until bonding amounts are approved)
- ☐ Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

Fencing:

- ☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet
- ☒ Alternate. Please specify 8 foot chain link fence

6.

Signs:

- ☒ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers
- ☐ Signed in compliance with 19.15.16.8 NMAC

7.

Variances:

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

Check the below box only if a variance is requested:

- ☐ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

If a Variance is requested, it must be approved prior to implementation.

8.

Siting Criteria for Recycling Containment

Instructions: The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

General siting**Ground water is less than 50 feet below the bottom of the Recycling Containment.**

NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells

☐ Yes ☒ No
☐ NA

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.

☐ Yes ☒ No
☐ NA

- Written confirmation or verification from the municipality; written approval obtained from the municipality

Within the area overlying a subsurface mine.

☐ Yes ☒ No

- Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division

Within an unstable area.

☐ Yes ☒ No

- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map

Within a 100-year floodplain. FEMA map

☐ Yes ☒ No

Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

☐ Yes ☒ No

- Topographic map; visual inspection (certification) of the proposed site

Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.

☐ Yes ☒ No

- Visual inspection (certification) of the proposed site; aerial photo; satellite image

Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.

☐ Yes ☒ No

- NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site

Within 500 feet of a wetland.

☐ Yes ☒ No

- US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site

9.

Recycling Facility and/or Containment Checklist:

Instructions: Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.

- ☐ Design Plan - based upon the appropriate requirements.
- ☐ Operating and Maintenance Plan - based upon the appropriate requirements.
- ☐ Closure Plan - based upon the appropriate requirements.
- ☐ Site Specific Groundwater Data -
- ☐ Siting Criteria Compliance Demonstrations –
- ☒ **Certify that notice of the C-147 (only) has been sent to the surface owner(s)**

10.

Operator Application Certification:

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): Heather Huntington Title: Regulatory Specialist
Signature: Heather Huntington Date: 09/10/25
e-mail address: hhuntington@enduringresources.com Telephone: 505-636-9751

11.

OCD Representative Signature: Victoria Venegas Approval Date: 10/10/2025
Title: Environmental Specialist OCD Permit Number: 3RF-29
☒ OCD Conditions
☒ Additional OCD Conditions on Attachment

From: [Heather Huntington](#)
To: [Jeff Tafoya](#)
Subject: Enduring Resources WLU 2309-24N Notice of Permit Extension 2025
Date: Monday, September 8, 2025 2:26:00 PM

Good morning Mr. Tafoya,

Enduring Resources is requesting an extension of the operating permit from NMOCD for the WLU 2309-24N Water Recycling Facility. In accordance with 19.15.34.10.A NMAC, Enduring Resources is required to notify the surface owner of the request, which in this case is BLM. The requested extension is in accordance with 19.15.34.10.C NMAC, "Registered recycling containments may be operated for five years from the date on which the registration is filed with the division. The operator may extend the allowed time on an annual basis thereafter with division approval if, 30 days prior to the registration expiration, the operator files a form C-147 with an attached summary showing all monthly inspections at the containment, including the monitoring of the leak detection system, showing the containment's integrity has not been compromised." The original facility permit was approved on October 14, 2018. The five year approval periods ended on October 14, 2023. Enduring submitted a one-year extension that was approved through October 14, 2025. Enduring is now requesting an extension to operate through October 14, 2026. At that time Enduring will determine if additional annual extensions will be filed. There have been no indications that the leak detection system integrity is compromised. Enduring will continue to operate the facility per regulations in 19.15.34 NMAC. This email is the surface owner notification of this permit extension request. Please let me know if you have any questions.

Thank you,

Heather Huntington
Enduring Resources Regulatory Specialist
505-636-9751

Work Orders

#112024 - Weekly Pond Inspections



Created On Date10-06-2024 06:17:31 MST

Updated On11-08-2024 10:18:25 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	Yes
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
7'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
Yes	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	
No	

Upper Leak Detection

Water Present in ULD? No	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 5.0	

Lower Leak Detection

Water Present in (LLD)? Yes	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft) 0.0	Height of Water in (LLD) 0.0
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterrents are present and in working order Yes	Visual Bird Deterrents are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	10-06-2024 06:17:31 MST		11-08-2024 10:18:20 MST	Danny Montoya	11-03-2024 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of several fluid, overlapping strokes. The signature is positioned in the upper left quadrant of the page, below the 'Signature' label and a horizontal line.

Work Orders

#112457 - Weekly Pond Inspections



Created On Date	Updated On
10-13-2024 06:02:06 MST	11-14-2024 11:13:23 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
5'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	
No	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 5.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft) 0.0	Height of Water in (LLD) 0.0
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterrents are present and in working order Yes	Visual Bird Deterrents are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	10-13-2024 06:02:06 MST		11-14-2024 11:13:15 MST	Danny Montoya	11-10-2024 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of several loops and a long horizontal stroke.

Work Orders

#112839 - Weekly Pond Inspections



Created On Date	Updated On
10-20-2024 06:00:08 MST	11-20-2024 10:15:42 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
6'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
Yes	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	
No	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 3.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft) 0.0	Height of Water in (LLD) 0.0
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterrents are present and in working order Yes	Visual Bird Deterrents are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A


Comments

Technician / Employee Comments
Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	10-20-2024 06:00:08 MST		11-20-2024 10:15:35 MST	Danny Montoya	11-17-2024 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink. It features a large, sweeping loop on the left side, followed by a horizontal line that extends to the right. Below the horizontal line, there are two vertical strokes, possibly representing the letters '11' or 'II'.

Work Orders

#113412 - Weekly Pond Inspections



Created On Date	Updated On
10-27-2024 06:00:22 MST	11-25-2024 10:34:13 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
6	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
Yes	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	
No	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft)
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft)
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 5.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	10-27-2024 06:00:22 MST		11-25-2024 10:34:05 MST	Danny Montoya	11-24-2024 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of several loops and a long horizontal stroke.

Work Orders

#116799 - Weekly Pond Inspections



Created On Date	Updated On
11-03-2024 06:00:16 MST	12-05-2024 12:37:00 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
10'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
Yes	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD?	Total Depth of (ULD) (ft)
No	99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD	
0.0	

Lower Leak Detection

Water Present in (LLD)?	Total Depth of (LLD) (ft)
No	95.5
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
0.0	0.0
Gallons of Water Removed (LLD)	
0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order	Visual Bird Deterants are present and in working order
Yes	Yes
Facility was inspected, and no evidence of bird mortality was found	If evidence of bird mortality was found, HSE was notified
Yes	N/A


Comments

Technician / Employee Comments
Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	11-03-2024 06:00:16 MST		12-05-2024 12:36:54 MST	Danny Montoya	12-01-2024 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink. It features a large, sweeping horizontal stroke that curves upwards at the left end and downwards at the right end. Below this main stroke, there are several smaller, more complex strokes, including a vertical line on the left and a series of loops and curves on the right, suggesting a stylized name or set of initials.

Work Orders

#117547 - Weekly Pond Inspections



Created On Date	Updated On
11-10-2024 06:00:18 MST	12-09-2024 12:51:10 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
13'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
Yes	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft) 0.0	Height of Water in (LLD) 0.0
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterrents are present and in working order Yes	Visual Bird Deterrents are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	11-10-2024 06:00:18 MST		12-09-2024 12:51:04 MST	Danny Montoya	12-08-2024 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of several fluid, overlapping strokes. The signature is positioned in the upper left quadrant of the page, below the 'Signature' label and a horizontal line.

Work Orders

#119136 - Weekly Pond Inspections



Created On Date	Updated On
11-17-2024 06:00:18 MST	12-17-2024 10:06:54 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
13'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
Yes	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	11-17-2024 06:00:18 MST		12-17-2024 10:06:48 MST	Danny Montoya	12-15-2024 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink. It features a large, elongated, teardrop-shaped loop on the left side. A horizontal line extends from the middle of this loop towards the right. Below the horizontal line, there is a smaller, more complex loop that crosses itself, resembling a stylized 'R' or a cursive flourish. The signature ends with a short horizontal stroke on the right.

Work Orders

#119671 - Weekly Pond Inspections



Created On Date	Updated On
11-24-2024 06:00:09 MST	01-02-2025 10:26:54 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
17'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
Yes	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	
Yes	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft)
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 50.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft)
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterrents are present and in working order Yes	Visual Bird Deterrents are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	11-24-2024 06:00:09 MST		11-24-2024 06:00:09 MST		12-22-2024 06:00:00 MST	Danny Montoya	P	Assigned	
def	12-23-2024 08:05:08 MST	Kristi Baldwin	12-23-2024 08:05:08 MST	Kristi Baldwin	12-23-2024 08:04:57 MST	Jeff Sarvash	P	Assigned	

Signature

A handwritten signature in black ink, consisting of a large, loopy initial 'R' followed by a horizontal line extending to the right.

Work Orders

#121459 - Weekly Pond Inspections



Created On Date	Updated On
12-01-2024 06:00:16 MST	01-02-2025 10:30:11 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
14'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
Yes	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	
Yes	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft)
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 10.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft)
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	12-01-2024 06:00:16 MST		01-02-2025 10:30:05 MST	Danny Montoya	12-29-2024 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of several fluid, overlapping loops and curves. The signature is positioned in the upper left quadrant of the page, below the 'Signature' label and a horizontal line.

Work Orders

#122230 - Weekly Pond Inspections



Created On Date12-08-2024 06:00:12 MST

Updated On01-10-2025 09:52:51 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
13 3/4'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? No	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft) 0.0	Height of Water in (ULD) 0.0
Gallons of Water Removed ULD 0.8	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 0.0
Depth to Water in (LLD) (ft) 0.0	Height of Water in (LLD) 0.0
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A


Comments

Technician / Employee Comments
Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	12-08-2024 06:00:12 MST		01-10-2025 09:52:45 MST	Danny Montoya	01-05-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of several overlapping loops and a horizontal stroke across the middle.

Work Orders

#122753 - Weekly Pond Inspections



Created On Date	Updated On
12-15-2024 06:00:14 MST	01-17-2025 12:12:51 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
13 1/2'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft) 0.0	Height of Water in (LLD) 0.0
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	12-15-2024 06:00:14 MST		01-17-2025 12:12:39 MST	Danny Montoya	01-12-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of several overlapping loops and curves, positioned on the left side of the page.

Work Orders

#123142 - Weekly Pond Inspections



Created On Date	Updated On
12-22-2024 06:00:09 MST	01-24-2025 13:08:35 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
13 3/4'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 15.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	12-22-2024 06:00:09 MST		01-24-2025 13:08:30 MST	Danny Montoya	01-19-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of several loops and a long horizontal stroke.

Work Orders

#123551 - Weekly Pond Inspections



Created On Date	Updated On
12-29-2024 06:00:10 MST	01-30-2025 10:43:58 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
13 3/4'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD?	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 5.0	

Lower Leak Detection

Water Present in (LLD)?	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	12-29-2024 06:00:10 MST		01-30-2025 10:43:52 MST	Danny Montoya	01-26-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, sweeping loop on the left and a smaller, more complex loop on the right, connected by a horizontal line.

Work Orders

#125926 - Weekly Pond Inspections



Created On Date01-05-2025 06:00:18 MST

Updated On02-07-2025 12:03:26 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
13'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	01-05-2025 06:00:18 MST		02-07-2025 12:03:21 MST	Danny Montoya	02-02-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, loopy capital letter 'L' with a horizontal crossbar, followed by a smaller, stylized lowercase letter 'd' or 't'.

Work Orders

#126657 - Weekly Pond Inspections



Created On Date01-12-2025 06:00:07 MST

Updated On02-14-2025 11:39:15 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
11'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD?	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)?	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments
Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	01-12-2025 06:00:07 MST		02-14-2025 11:39:08 MST	Danny Montoya	02-09-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, sweeping loop on the left and a smaller, more defined loop on the right, connected by a horizontal stroke.

Work Orders

#127631 - Weekly Pond Inspections



Created On Date01-19-2025 06:00:14 MST

Updated On02-20-2025 12:32:51 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
11 1/2'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	01-19-2025 06:00:14 MST		02-20-2025 12:32:45 MST	Danny Montoya	02-16-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, stylized 'L' shape with a horizontal bar and a small loop at the bottom right.

Work Orders

#128368 - Weekly Pond Inspections



Created On Date01-26-2025 06:00:09 MST

Updated On02-27-2025 19:23:15 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
11'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	01-26-2025 06:00:09 MST		02-27-2025 19:23:09 MST	Danny Montoya	02-23-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, rounded, looped shape with a horizontal line crossing it, and a smaller, more complex shape to the right.

Work Orders

#130584 - Weekly Pond Inspections



Created On Date	Updated On
02-02-2025 06:00:21 MST	03-08-2025 06:46:03 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
11'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
Yes	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 35.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	02-02-2025 06:00:21 MST		02-02-2025 06:00:21 MST		03-02-2025 06:00:00 MST	Danny Montoya	P	Assigned	

Signature

A handwritten signature in black ink, featuring a large, sweeping loop on the left side and a horizontal line extending to the right, ending in a small, closed loop.

Work Orders

#131238 - Weekly Pond Inspections



Created On Date02-09-2025 06:00:10 MST

Updated On03-14-2025 12:07:43 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
11'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
Yes	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 6.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	02-09-2025 06:00:10 MST		03-14-2025 12:07:36 MST	Danny Montoya	03-09-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, stylized capital 'A' with a horizontal bar that loops around the right side of the letter.

Work Orders

#131762 - Weekly Pond Inspections



Created On Date	Updated On
02-16-2025 06:00:07 MST	03-21-2025 12:32:11 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
60	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	
Yes	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 105.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 60.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 0.0
Depth to Water in (LLD) (ft) 0.0	Height of Water in (LLD) 0.0
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A


Comments

Technician / Employee Comments
Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	02-16-2025 06:00:07 MST		03-21-2025 12:32:05 MST	Danny Montoya	03-16-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, stylized loop at the top and a series of smaller, connected loops below it.

Work Orders

#132277 - Weekly Pond Inspections



Created On Date	Updated On
02-23-2025 06:00:11 MST	03-27-2025 11:51:56 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
11'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
Yes	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	
Yes	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	02-23-2025 06:00:11 MST		03-27-2025 11:51:50 MST	Danny Montoya	03-23-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, sweeping loop at the top, followed by a horizontal line, and then two smaller, curved strokes at the bottom.

Work Orders

#135222 - Weekly Pond Inspections



Created On Date	Updated On
03-02-2025 06:00:09 MST	04-04-2025 12:54:04 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
11 1/12'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
Yes	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	
No	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 5.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	03-02-2025 06:00:09 MST		04-04-2025 12:53:57 MST	Danny Montoya	03-30-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, stylized capital letter 'A' with a horizontal crossbar and a small loop at the bottom left.

Work Orders

#137998 - Weekly Pond Inspections



Created On Date	Updated On
03-09-2025 06:00:17 MST	04-13-2025 19:55:03 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
11 1/2'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	
No	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft)
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 6.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft)
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	03-09-2025 06:00:17 MST		03-09-2025 06:00:17 MST		04-06-2025 06:00:00 MST	Danny Montoya	P	Assigned	

Signature

A handwritten signature in black ink, consisting of a large, stylized 'L' shape with a horizontal stroke extending to the right and a vertical stroke curving upwards and back to the left, forming a loop.

Work Orders

#139059 - Weekly Pond Inspections



Created On Date	Updated On
03-18-2025 09:31:05 MST	04-17-2025 11:53:07 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
12'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
Yes	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	
No	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	03-18-2025 09:31:05 MST		04-17-2025 11:53:00 MST	Danny Montoya	04-13-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, stylized capital letter 'A' with a horizontal stroke extending to the right and a small loop at the end.

Work Orders

#142027 - Weekly Pond Inspections



Created On Date03-30-2025 06:00:31 MST

Updated On05-02-2025 12:20:30 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
13'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
Yes	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	03-30-2025 06:00:31 MST		05-02-2025 12:16:42 MST	Danny Montoya	04-27-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink. It features a large, rounded, looped initial on the left, followed by a horizontal line that extends to the right. Below the horizontal line, there are several smaller, curved strokes that appear to be part of the signature's base or a flourish.

Work Orders

#140618 - Weekly Pond Inspections



Created On Date03-23-2025 06:00:20 MST

Updated On05-02-2025 12:24:28 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	
Inspected By (auto-populated if you select Yes)	Permit Number
	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
12 1/2'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
Yes	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified Yes

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	03-23-2025 06:00:20 MST		05-02-2025 12:24:21 MST	Danny Montoya	04-20-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, sweeping loop followed by a horizontal line and a small flourish.

Work Orders

#144802 - Weekly Pond Inspections



Created On Date04-06-2025 06:01:18 MST

Updated On05-23-2025 11:56:48 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
14'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	04-06-2025 06:01:19 MST		05-12-2025 07:42:15 MST	Danny Montoya	05-04-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of several loops and a long horizontal stroke.

Work Orders

#145614 - Weekly Pond Inspections



Created On Date04-13-2025 06:00:33 MST

Updated On05-23-2025 11:56:51 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
14'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	04-13-2025 06:00:33 MST		05-16-2025 11:54:45 MST	Danny Montoya	05-11-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, stylized 'A' or 'R' shape with a horizontal line crossing it, and a smaller, looped shape below it.

Work Orders

#146113 - Weekly Pond Inspections



Created On Date04-20-2025 06:00:58 MST

Updated On05-23-2025 12:02:08 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
14 1/2	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
Yes	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	04-20-2025 06:00:58 MST		05-23-2025 12:02:03 MST	Danny Montoya	05-18-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, stylized 'L' shape with a horizontal bar extending to the right and a vertical line extending upwards from the right end of the bar.

Work Orders

#146668 - Weekly Pond Inspections



Created On Date	Updated On
04-27-2025 06:00:29 MST	06-03-2025 14:24:14 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
15'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
Yes	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? No	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)? Yes	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	04-27-2025 06:00:29 MST		04-27-2025 06:00:29 MST		05-25-2025 06:00:00 MST	Danny Montoya	P	Assigned	

Signature

A handwritten signature in black ink, consisting of a large, sweeping loop that crosses itself, with a horizontal line extending to the right and a small hook at the end.

Work Orders

#150994 - VFD for pond aerators faulted on thermal overload.



Created On Date	Updated On
05-26-2025 11:05:49 MST	06-09-2025 05:33:48 MST

Basic Info

Job Status
New

Work Order Information

Brief Description
VFD for pond aerators faulted on thermal overload.

Work Description

Assigned Team
I&E South

Asset Information

Route Lybrook 5	Associated Pad WLU 2309-24N FEDERAL SWD 001 PAD
Asset WLU 2309-24N WRF PAD	Facility Type WRF
Map Link	

Additional Information

Technician / Employee Comments
SPR- T/S aerator, P&S called out for Tuesday morning 5/26. Rebuilt aerator blew out a seal, waiting on P&S to rebuild/repair both aerators

Requester Information

Requested On 05-26-2025 11:04:53 MST	Requester Email ajolly@enduringresources.com
Created By Alec Jolly	Requester Phone

Work Orders

#149006 - Weekly Pond Inspections



Created On Date05-04-2025 06:00:32 MST

Updated On06-03-2025 14:13:39 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
15'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.2	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	05-04-2025 06:00:32 MST		06-03-2025 14:13:32 MST	Danny Montoya	06-01-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, stylized 'R' or 'B' shape with a horizontal line crossing it, and a smaller, more complex shape below it.

Work Orders

#149530 - Weekly Pond Inspections



Created On Date05-11-2025 06:00:34 MST

Updated On06-16-2025 12:47:04 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
15'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
Yes	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	05-11-2025 06:00:34 MST		06-16-2025 12:46:58 MST	Danny Montoya	06-08-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, loopy initial 'R' followed by a series of smaller, connected loops and a final horizontal stroke.

Work Orders

#150631 - Weekly Pond Inspections



Created On Date05-25-2025 06:00:32 MST

Updated On06-27-2025 11:35:53 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
18 1/2	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? No	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 0.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	05-25-2025 06:00:32 MST		06-27-2025 11:35:44 MST	Danny Montoya	06-22-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, stylized loop at the top, followed by a horizontal line, and then two distinct, rounded shapes at the bottom.

Work Orders

#150203 - Weekly Pond Inspections



Created On Date05-18-2025 06:00:20 MST

Updated On06-25-2025 13:51:13 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	Yes
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	Yes

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
16'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
Yes	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 5.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	05-18-2025 06:00:20 MST		06-20-2025 12:01:38 MST	Danny Montoya	06-15-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, stylized capital letter 'L' with a horizontal stroke extending to the right and a small loop at the end.

Work Orders

#164578 - Weekly Pond Inspections



Created On Date08-03-2025 06:00:32 MST

Updated On09-05-2025 13:00:57 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	Yes
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	Yes

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
9'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	08-03-2025 06:00:32 MST		08-03-2025 06:00:32 MST		08-31-2025 06:00:00 MST	Danny Montoya	P	Assigned	

Signature

A handwritten signature in black ink, consisting of a large, stylized 'L' shape with a horizontal line extending to the right and a vertical line extending upwards, forming a loop.

Work Orders

#161439 - Weekly Pond Inspections



Created On Date07-27-2025 06:00:38 MST

Updated On08-29-2025 13:25:19 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
7 3/4'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 105.1
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	07-27-2025 06:00:38 MST		08-29-2025 13:25:10 MST	Danny Montoya	08-24-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, loopy initial 'R' followed by a horizontal line and a small loop at the end.

Work Orders

#160641 - Weekly Pond Inspections



Created On Date	Updated On
07-20-2025 06:01:03 MST	08-26-2025 19:25:59 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
9'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 4.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	07-20-2025 06:01:03 MST		08-26-2025 19:25:53 MST	Danny Montoya	08-17-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, stylized capital letter 'R' with a horizontal crossbar, and a smaller, stylized capital letter 'A' positioned below and to the left of the 'R'.

Work Orders

#160194 - Weekly Pond Inspections



Created On Date07-13-2025 06:00:34 MST

Updated On08-15-2025 13:18:01 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
12'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 8.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	07-13-2025 06:00:34 MST		08-15-2025 13:17:55 MST	Danny Montoya	08-10-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of several loops and a long horizontal stroke.

Work Orders

#159613 - Weekly Pond Inspections



Created On Date07-06-2025 06:00:50 MST

Updated On08-08-2025 10:19:53 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
15'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 10.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	07-06-2025 06:00:50 MST		08-08-2025 10:19:46 MST	Danny Montoya	08-03-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, stylized capital letter 'R' with a horizontal crossbar and a small loop at the bottom left.

Work Orders

#164194 - Weekly Pond Inspections



Created On Date	Updated On
08-01-2025 10:48:06 MST	08-01-2025 10:48:13 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	
Section	Township
Range	County
State	Latitude
Longitude	Map Link

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	Yes
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
19	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawl of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 10.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System


Audio Bird Deterrents are present and in working order Yes	Visual Bird Deterrents are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Signature



Work Orders

#164193 - Weekly Pond Inspections



Created On Date08-01-2025 10:47:01 MST

Updated On08-01-2025 10:47:13 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	
Section	Township
Range	County
State	Latitude
Longitude	Map Link

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	Yes
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
19	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawl of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 10.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterrents are present and in working order Yes	Visual Bird Deterrents are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Signature



Work Orders

#162652 - Weekly Pond Inspections



Created On Date	Updated On
07-30-2025 12:19:24 MST	08-13-2025 07:43:48 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	
Section	Township
Range	County
State	Latitude
Longitude	Map Link
	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	Yes
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
19	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 10.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterrents are present and in working order Yes	Visual Bird Deterrents are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Signature



Work Orders

#156681 - Weekly Pond Inspections



Created On Date	Updated On
06-22-2025 06:00:29 MST	08-01-2025 11:55:46 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	Yes
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
19	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 10.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	06-22-2025 06:00:29 MST		08-01-2025 10:46:57 MST	Danny Montoya	07-20-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, loopy initial 'L' followed by a horizontal stroke and a small loop at the end.

Work Orders

#157581 - Weekly Pond Inspections



Created On Date	Updated On
06-29-2025 06:00:20 MST	08-01-2025 10:47:49 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
17'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.4
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 10.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 99.1
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	06-29-2025 06:00:20 MST		08-01-2025 10:39:03 MST	Danny Montoya	07-27-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of a large, stylized 'L' shape with a horizontal line extending from the middle and a small loop at the end.

Work Orders

#156119 - Weekly Pond Inspections



Created On Date06-15-2025 06:00:41 MST

Updated On07-22-2025 07:41:46 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	Yes
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
19'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 105.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 50.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 0.0
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments


Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	06-15-2025 06:00:41 MST		06-15-2025 06:00:41 MST		07-13-2025 06:00:00 MST	Danny Montoya	P	Assigned	

Signature

A handwritten signature in black ink, consisting of several loops and a horizontal stroke, positioned above a horizontal line.

Work Orders

#154682 - Weekly Pond Inspections



Created On Date06-08-2025 06:00:27 MST

Updated On07-14-2025 09:50:48 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
22'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
No	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 10.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	06-08-2025 06:00:27 MST		07-14-2025 09:50:42 MST	Danny Montoya	07-06-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink, consisting of several loops and a horizontal stroke, positioned above a horizontal line.

Work Orders

#152676 - Weekly Pond Inspections



Created On Date	Updated On
06-01-2025 06:00:42 MST	06-30-2025 12:50:10 MST

Site Information

Asset	Did you perform this inspection?
WLU 2309-24N WRF PAD	Yes
Inspected By (auto-populated if you select Yes)	Permit Number
Danny Montoya	3RF-29
Section	Township
24	23N
Range	County
09W	San Juan
State	Latitude
NM	36.205974
Longitude	Map Link
-107.741127	https://www.google.com/maps/search/?api=1&query=36.205974,-107.741127

General Information

Brief Description	Containment Currently Contains Fluids
Weekly Pond Inspections	Yes
Fencing is in Good condition and Functional	Gates are Closed and locked
Yes	No
Facility sign is visible and in good condition	Signs of Surface Water Runon?
Yes	No

Inspection Info for Recycling Containment

Pond Level	Containment has a minimum of three feet of freeboard
19'	Yes
Containment water surface is free of visible signs of oil	Injection and withdrawal of water is done through a header
No	Yes
Oil absorbent booms are on-site and in good condition	Is there evidence of a leak in the liner above the waterline
Yes	No
Site is free of evidence of leaks, spills or releases	If leak detection contained liquid, was it removed?
Yes	Yes
If leak detection contained liquid, was HSE notified?	

Upper Leak Detection

Water Present in ULD? Yes	Total Depth of (ULD) (ft) 99.1
Depth to Water in (ULD) (ft)	Height of Water in (ULD)
Gallons of Water Removed ULD 2.0	

Lower Leak Detection

Water Present in (LLD)? No	Total Depth of (LLD) (ft) 95.8
Depth to Water in (LLD) (ft)	Height of Water in (LLD)
Gallons of Water Removed (LLD) 0.0	

Bird Mitigation System

Audio Bird Deterants are present and in working order Yes	Visual Bird Deterants are present and in working order Yes
Facility was inspected, and no evidence of bird mortality was found Yes	If evidence of bird mortality was found, HSE was notified N/A

Comments

Technician / Employee Comments

Image Field

Assignments

Site	Created On	Created By	Updated On	Updated By	From	Contact	Status	Assignment Status	Assigned By
def	06-01-2025 06:00:42 MST		06-30-2025 12:50:03 MST	Danny Montoya	06-29-2025 06:00:00 MST	Danny Montoya	P	Completed	

Signature

A handwritten signature in black ink. It features a large, looped capital letter 'L' or 'R' that extends upwards and to the left. Below this main loop, there are two smaller, separate strokes: a short, curved line on the left and a longer, more complex stroke on the right that forms a small loop and ends with a horizontal tail.

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Friday, October 10, 2025 2:39 PM
To: Heather Huntington
Subject: 3RF-29 - WLU 2309 24N RECYCLING FACILITY ID [fCS1828842180]
Attachments: C-147 3RF-29 - WLU 2309 24N RECYCLING FACILITY ID [fCS1828842180] 10.10.2025.pdf

3RF-29 - WLU 2309 24N RECYCLING FACILITY ID [fCS1828842180]

Good afternoon Ms. Huntington.

NMOCD has reviewed the registration/permit extension request for 3RF-29 - WLU 2309 24N RECYCLING FACILITY ID [fCS1828842180] received from [372286] ENDURING RESOURCES, LLC on 09/10/2025, Application ID **504901**. The registration/permit extension request is approved with the following conditions of approval:

- 3RF-29 - WLU 2309 24N RECYCLING FACILITY ID [fCS1828842180] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of October 14, 2025. The new registration/permit expiration date is October 14, 2026.
- [372286] ENDURING RESOURCES, LLC will continue to operate, maintain, and close the 3RF-29 - WLU 2309 24N RECYCLING FACILITY ID [fCS1828842180] in compliance with 19.15.34 NMAC, to include but not limited to the performance of weekly inspections regardless of fluid levels in the containment; recording of detailed inspection reports; removal of debris, foreign objects and oil from the containment; and monthly reporting of recycling and reuse of produced water, drilling fluids, and liquid oil field waste via from C-148.
- [372286] ENDURING RESOURCES, LLC will maintain a liquid level in the containment that is at least equal to the weight of the liner plus 20%. [372286] ENDURING RESOURCES, LLC may maintain a higher liquid level if they choose.
- If less than 20% of the total fluid capacity is utilized every consecutive six months, operation of the facility is considered ceased and notification of cessation of operations should be sent electronically to OCD Online. An extension to extend the cessation of operations, not to exceed six months, may be submitted using a C-147 form through the OCD Online system.
- However, if after this 6-month period, the containment was not utilized at a minimum of 20% fluid capacity, no additional extensions would be granted, and the operator would be directed to remove all fluids and proceed with the closure requirements.
- The recycling containment is bonded pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC. Water reused and recycled from 3RF-29 - WLU 2309 24N RECYCLING FACILITY ID [fCS1828842180] is limited to wells owned or operated by [372286] ENDURING RESOURCES, LLC.
- A minimum of 3-feet freeboard must be maintained in the recycling containment at all times.
- [372286] ENDURING RESOURCES, LLC will comply with 19.15.29 NMAC Releases in the event of any release of produced water or produced water or other oil field wastes at 3RF-3RF-29 - WLU 2309 24N RECYCLING FACILITY ID [fCS1828842180]. [372286] ENDURING RESOURCES, LLC will comply with all other OCD rules.
- [372286] ENDURING RESOURCES, LLC must perform weekly inspections of the containment and leak detection system.
- If [372286] ENDURING RESOURCES, LLC wishes to extend the registration/permit past October 14, 2026, a registration/permit extension request must be submitted to OCD. Extension requests are reviewed on a case-by-case basis and evaluated on their merit. Extensions are considered for a maximum length of one year. Additional requests must be submitted to OCD through the OCD Online on a Form C-147 (long form) as an Extension request and should include a formal extension request letter, a summary of the prior registration/permit period inspection reports, and the copies of the detailed inspection records for the prior permit period (2023-2024). The extension request should be submitted no later than September 14, 2026.

Please let me know if you have any further questions or concerns.

Victoria Venegas • Senior Environmental Scientist
EMNRD - Oil Conservation Division
506 W. Texas Ave. Artesia, NM 88210
575.909.0269 | Victoria.Venegas@emnrd.nm.gov

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 504901

CONDITIONS

Operator: ENDURING RESOURCES, LLC 6300 S Syracuse Way Centennial, CO 80111	OGRID: 372286
	Action Number: 504901
	Action Type: [C-147] Water Recycle Long (C-147L)

CONDITIONS

Created By	Condition	Condition Date
vvenegas	3RF-29 - WLU 2309 24N RECYCLING FACILITY ID [fCS1828842180] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of October 14, 2025. The new registration/permit expiration date is October 14, 2026. If [372286] ENDURING RESOURCES, LLC wishes to extend the registration/permit past October 14, 2026, a registration/permit extension request must be submitted to OCD no later than September 14, 2026.	10/10/2025