Page 1 of 32

Incident ID	nAPP2305351774
District RP	
Facility ID	
Application ID	

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following it	ems must be included in the closure report.
X A scaled site and sampling diagram as described in 19.15.29.1	1 NMAC
X Photographs of the remediated site prior to backfill or photos must be notified 2 days prior to liner inspection)	of the liner integrity if applicable (Note: appropriate OCD District office
X Laboratory analyses of final sampling (Note: appropriate ODC	District office must be notified 2 days prior to final sampling)
X Description of remediation activities	
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of should their operations have failed to adequately investigate and renhuman health or the environment. In addition, OCD acceptance of a compliance with any other federal, state, or local laws and/or regular restore, reclaim, and re-vegetate the impacted surface area to the coraccordance with 19.15.29.13 NMAC including notification to the Octaviance of the coraccordance with 19.15.29.13 NMAC including notification to the Octaviance of the coraccordance with 19.15.29.13 NMAC including notification to the Octaviance of the coraccordance with 19.15.29.13 NMAC including notification to the Octaviance of the coraccordance with 19.15.29.13 NMAC including notification to the Octaviance of the coraccordance with 19.15.29.13 NMAC including notification to the Octaviance of the coraccordance with 19.15.29.13 NMAC including notification to the Octaviance of the coraccordance with 19.15.29.13 NMAC including notification to the Octaviance of the coraccordance with 19.15.29.13 NMAC including notification to the Octaviance of the coraccordance with 19.15.29.13 NMAC including notification to the Octaviance of the coraccordance with 19.15.29.13 NMAC including notification to the Octaviance of the coraccordance with 19.15.29.13 NMAC including notification to the Octaviance of the coraccordance with 19.15.29.13 NMAC including notification to the Octaviance of the coraccordance with 19.15.29.13 NMAC including notification to the Octaviance of the coraccordance with 19.15.29.13 NMAC including notification to the Octaviance of the coraccordance with 19.15.29.13 NMAC including notification to the Octaviance of the coraccordance with 19.15.29.13 NMAC including notification to the Octaviance of the coraccordance with 19.15.29.13 NMAC including notification to the Octaviance of the coraccordance with 19.15.29.13 NMAC including notification to the octaviance of the coraccordance with 19.15.29.13 NMAC inc	nediate contamination that pose a threat to groundwater, surface water, a C-141 report does not relieve the operator of responsibility for tions. The responsible party acknowledges they must substantially neditions that existed prior to the release or their final land use in CD when reclamation and re-vegetation are complete.
Printed Name: Dale Woodall	Title: EHS Professional
Signature: Dala Woodall	Date:3/13/2023
email:dale.woodall@dvn.com	Telephone: 405-318-4697
OCD Only	
Received by: Robert Hamlet	Date: 7/20/2023
	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible or regulations.
Closure Approved by: Robert Hamlet	Date: <u>7/20/2023</u>
Printed Name: Robert Hamlet	Title: Environmental Specialist - Advanced

	Page 2 of 3	2
Incident ID	nAPP2305351774	
District RP		
Facility ID		
Application ID		

### Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	>50 (ft bgs)					
Did this release impact groundwater or surface water?	Yes X No					
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	Yes No					
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?						
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	Yes No					
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	Yes X No					
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	Yes No					
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?						
Are the lateral extents of the release within 300 feet of a wetland?						
Are the lateral extents of the release overlying a subsurface mine?						
Are the lateral extents of the release overlying an unstable area such as karst geology?						
Are the lateral extents of the release within a 100-year floodplain?	Yes No					
Did the release impact areas <b>not</b> on an exploration, development, production, or storage site?						
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of scontamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.						
Characterization Report Checklist: Each of the following items must be included in the report.						
<ul> <li>         ∑ Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.     </li> <li>         ∑ Field data         ∑ Data table of soil contaminant concentration data         ∑ Depth to water determination         ∑ Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release         ∑ Boring or excavation logs         ∑ Photographs including date and GIS information         ∑ Topographic/Aerial maps         ∑ Laboratory data including chain of custody     </li> </ul>						

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 3/13/2023 3:01:37 PM Form C-141 State of New Mexico Page 4 Oil Conservation Division

	Page 3 of .
Incident ID	nAPP2305351774
District RP	
Facility ID	
Application ID	

I hereby certify that the information given above is true and complete to the regulations all operators are required to report and/or file certain release not public health or the environment. The acceptance of a C-141 report by the Gailed to adequately investigate and remediate contamination that pose a threaddition, OCD acceptance of a C-141 report does not relieve the operator of and/or regulations.	ifications and perform corrective actions for releases which may endanger DCD does not relieve the operator of liability should their operations have eat to groundwater, surface water, human health or the environment. In
Printed Name: Dale Woodall	Title: EHS Professional
Signature: Dals Woodall	Date:3/13/2023
email:dale.woodall@dvn.com	Telephone:405-318-4697
OCD Only	
Received by:	Date:03/13/2023

Page 4 of 32

	- "8" " " " " " " " " " " " " " " " " "
Incident ID	nAPP2305351774
District RP	
Facility ID	
Application ID	

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the follows	ing items must be included in the closure report.
X A scaled site and sampling diagram as described in 19.15	.29.11 NMAC
X Photographs of the remediated site prior to backfill or ph must be notified 2 days prior to liner inspection)	notos of the liner integrity if applicable (Note: appropriate OCD District office
X Laboratory analyses of final sampling (Note: appropriate	ODC District office must be notified 2 days prior to final sampling)
Description of remediation activities	
and regulations all operators are required to report and/or file comay endanger public health or the environment. The acceptance should their operations have failed to adequately investigate an human health or the environment. In addition, OCD acceptance compliance with any other federal, state, or local laws and/or refrestore, reclaim, and re-vegetate the impacted surface area to the accordance with 19.15.29.13 NMAC including notification to the state of	·
Printed Name: Dale Woodall	Title: EHS Professional
Signature: Dala Woodall	Date:3/13/2023
email:dale.woodall@dvn.com	Telephone: 405-318-4697
OCD Only	
Received by: Jocelyn Harimon	Date:03/13/2023
	party of liability should their operations have failed to adequately investigate and face water, human health, or the environment nor does not relieve the responsible and/or regulations.
Closure Approved by:	Date:
Printed Name:	Title:



5614 N. Lovington Highway
Hobbs, NM 88240
575-964-7740

March 13, 2023

Bureau of Land Management 620 East Green Street Carlsbad, NM 88220

NMOCD District 2 811 S. First St Artesia, NM, 88210

**RE:** Liner Inspection and Closure Report

Fiji 17 CTB 1 API No. N/A

**GPS:** Latitude 32.307547 Longitude -103.796232 UL G, Section 17, Township 23S, Range 31E,

**Eddy County, NM** 

NMOCD Reference No. NAPP2305351774

Devon Energy Production Company (Devon) has contracted Pima Environmental Services, LLC (Pima) to perform a liner inspection and prepare this closure report for a produced water release that happened at the Fiji 17 CTB 1 (Fiji). An initial C-141 was submitted on March 7, 2023, and can be found in Appendix B. This incident was assigned Incident ID NAPP2305351774, by the New Mexico Oil Conservation Division (NMOCD).

#### **Site Information and Site Characterization**

The Fiji is located approximately twenty-seven (27) miles southeast of Carlsbad, NM. This spill site is in Unit G, Section 17, Township 23S, Range 31E, Latitude 32.307547 Longitude -103.796232, Eddy County, NM. A Location Map can be found in Figure 1.

Based upon New Mexico Office of the State Engineer well water data, depth to the nearest groundwater in this area is 125 feet below grade surface (BGS). According to the United States Geological Survey well water data, depth to the nearest groundwater in this area is 125 feet BGS. See Appendix A for referenced water surveys. The Fiji is in a low karst area (Figure 3). A Topographic Map can be found in Figure 2.

#### **Release Information**

**NAPP2305351774:** On February 21, 2023, a seal on a pump developed a leak. Approximately 140 barrels (bbls) of produced water was released from the pump. A vacuum truck was dispatched and recovered all 140 bbls of fluid from the lined SPCC containment ring. Once fluids were removed, the liner was visually inspected by Devon field staff for any pinholes or punctures, and none were found. Based on this inspection there is no evidence that the spilled fluids left containment.

A Site Map can be found in Figure 4.

#### Site Assessment and Liner Inspection

On March 2, 2023, after sending the 48-hour notification email, Pima Environmental conducted a liner inspection at this location. We concluded that this liner and containment maintained its integrity and was able to retain the fluids. The Liner Inspection Form and Photographic Documentation can be found in Appendix C.

#### **Closure Request**

After careful review, Pima requests that this incident, NAPP2305351774 be closed. Devon has complied with the applicable closure requirements.

Should you have any questions or need additional information, please feel free to contact Gio Gomez at 806-782-1151 or gio@pimaoil.com.

Respectfully,

Gic Gomez Gio Gomez

Project Manager

Pima Environmental Services, LLC

#### **Attachments**

#### Figures:

- 1- Location Map
- 2- Topographic Map
- 3- Karst Map
- 4- Site Map

#### Appendices:

Appendix A- Referenced Water Surveys

Appendix B- C-141 Form & 48 Hour Notification

Appendix C- Liner Inspection Form & Photographic Documentation




## Figures:

1-Location Map


2-Topographic Map


3-Karst Map

4-Site Map











### Appendix A

Water Surveys:

OSE

**USGS** 

Wetlands Map

Surface Water Map



# New Mexico Office of the State Engineer

# Water Column/Average Depth to Water

(A CLW##### in the POD suffix indicates the POD has been replaced & no longer serves a water right file.)

(R=POD has been replaced, O=orphaned, C=the file is

closed)

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest) (NAD83 UTM in meters) (In feet)

		POD													
		Sub-			Q										Vater
POD Number	Code		County						-	X	Y	DistanceDe		pthWater Co	olumn
C 02954 EXPL		CUB	ED	3	1	4	20	23S	31E	613114	3572906*	2250	905		
C 02492 POD2		C	ED	3	2	2	07	23S	31E	611767	3576996	2420	400	125	275
<u>C 02492</u>		CUB	ED	4	4	4	06	23S	31E	612056	3577320*	2518	135	85	50
<u>C 02865</u>		CUB	ED	4	4	4	06	23S	31E	612056	3577320*	2518	174		
<u>C 02774</u>		CUB	ED	3	1	3	04	23S	31E	613857	3577745*	2652	1660		
<u>C 02664</u>		CUB	ED	3	3	2	05	23S	31E	613049	3578138*	3004	4291	354	3937
C 03520 POD1		C	ED	3	1	1	07	23S	31E	610733	3576905	3135	500		
<u>C 03351</u>		C	ED	4	1	4	04	23S	31E	614917	3577861	3145	320	168	152
<u>C 03140</u>		CUB	ED	4	2	4	04	23S	31E	615266	3577758*	3252	684		
<u>C 02773</u>		CUB	ED	4	1	3	03	23S	31E	615668	3577762*	3510	880		
<u>C 02777</u>		CUB	ED	4	4	4	10	23S	31E	616974	3575662	3682	890		
C 03749 POD1		CUB	ED		2	2	15	23S	31E	616974	3575662	3682	865	639	226
<u>C 02776</u>		CUB	ED	2	1	1	05	23S	31E	612440	3578731*	3692	661		
C 03222 EXPLORE		CUB	ED	1	1	4	12	23S	30E	609833	3576349*	3695	365		
<u>C 02725</u>		CUB	ED	1	1	1	05	23S	31E	612240	3578731*	3746	532		
<u>C 02775</u>		CUB	ED	1	1	1	05	23S	31E	612240	3578731*	3746	529		
<u>C 03139</u>		CUB	ED	4	2	4	01	23S	30E	610424	3577764*	3909	425		

Average Depth to Water: 274 feet Minimum Depth: 85 feet 639 feet

Maximum Depth:

Record Count: 17

<u>UTMNAD83 Radius Search (in meters):</u>

**Easting (X):** 613327.38 **Northing (Y):** 3575146.27 **Radius:** 4000

\*UTM location was derived from PLSS - see Help

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

2/23/23 8:03 AM

WATER COLUMN/ AVERAGE DEPTH TO WATER



**USGS Home Contact USGS** Search USGS

### **National Water Information System: Web Interface**

**USGS** Water Resources

Data Category:		Geographic Area:		
Groundwater	<b>~</b>	United States	~	GO

#### Click to hideNews Bulletins

- Explore the NEW USGS National Water Dashboard interactive map to access realtime water data from over 13,500 stations nationwide.
- Full News

Groundwater levels for the Nation

Important: <u>Next Generation Monitoring Location Page</u>

### Search Results -- 1 sites found

site no list =

321809103481801

#### Minimum number of levels = 1

Save file of selected sites to local disk for future upload

### USGS 321809103481801 23S.31E.17.31141

Available data for this site | Groundwater: Field measurements GO Eddy County, New Mexico Hydrologic Unit Code 13060011

Latitude 32°18'11.3", Longitude 103°48'23.4" NAD83

Land-surface elevation 3,326.00 feet above NGVD29

The depth of the well is 354 feet below land surface.


This well is completed in the Other aguifers (N9999OTHER) national aguifer.

This well is completed in the Rustler Formation (312RSLR) local aquifer.

### **Output formats**

Table of data	
<u>Tab-separated data</u>	
Graph of data	
Reselect period	

#### USGS 321809103481801 235.31E.17.31141



Breaks in the plot represent a gap of at least one year between field measurements. <u>Download a presentation-quality graph</u>

Questions about sites/data?
Feedback on this web site
Automated retrievals
Help
Data Tips
Explanation of terms
Subscribe for system changes
News

Accessibility

FOIA

Privacy

Policies and Notices

U.S. Department of the Interior | U.S. Geological Survey

**Title: Groundwater for USA: Water Levels** 

URL: https://nwis.waterdata.usgs.gov/nwis/gwlevels?

Page Contact Information: <u>USGS Water Data Support Team</u>


Page Last Modified: 2023-02-23 10:01:49 EST

0.62 0.51 nadww01





# Wetlands Map



February 23, 2023

#### Wetlands

Estuarine and Marine Deepwater

Estuarine and Marine Wetland

Freshwater Emergent Wetland

Freshwater Forested/Shrub Wetland


Freshwater Pond



Other



This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.





## Appendix B

C-141 Form

48-Hour Notification

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2305351774
District RP	
Facility ID	
Application ID	_

## **Release Notification**

### **Responsible Party**

Responsible Party Devon Energy Production Company				OGRID <sub>61</sub>	137	
Contact Name Dale Woodall				Contact Te	Contact Telephone	
Contact emai	<sup>il</sup> Dale.Wo	odall@dvn.cor	n	Incident #	(assigned by OCL	0)
Contact mail	ing address	6488 Seven Ri	vers Hwy Artes	ia, NM 88210		
			Location	of Release So		
Latitude 32	.30754	7	(NAD 83 in dec	Longitude _ imal degrees to 5 decin	Longitude -103.796232 Segrees to 5 decimal places)	
Site Name Fij	i 17 CTB	1		Site Type (	Dil	
Date Release	Discovered	2/21/2023		API# (if app	licable)	
Unit Letter	Section	Township	Range	Coun	nty	7
G	17	23S	31E	Edo	lv	
			ll that apply and attach	Volume of I	justification for th	ne volumes provided below)
Crude Oil		Volume Release	` /		Volume Recovered (bbls)	
Produced	Water		ed (bbls) 140 BBL			overed (bbls) 140 BBLS
			tion of total dissolv water >10,000 mg/	\ /	Yes 1	No
Condensa	te	Volume Release	ed (bbls)		Volume Recovered (bbls)	
Natural Gas Volume Released (Mcf)				Volume Recovered (Mcf)		
Other (describe) Volume/Weight Released (provide units			units)	Volume/Wei	ght Recovered (provide units)	
Cause of Rele	ease Seal o	on pump deve	eloped leak.		I	

Received by OCD: 3/13/2023/35.01/37 PM State of New Mexico
Page 2 Oil Conservation Division

Page 20 of 32

Incident ID	nAPP2305351774
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?  Yes No  If YES, was immediate not a second content of the second content	If YES, for what reason(s) does the responsible Spill is over 25 BBLS.	om? When and by what means (phone, email, etc)?
•	/ Dale Woodall on 2/22/2023	om vinon and by vinan mount (promb, order, order)
	Initial Re	esponse
The responsible	party must undertake the following actions immediately	unless they could create a safety hazard that would result in injury
Released materials ha	s been secured to protect human health and	ikes, absorbent pads, or other containment devices.  I managed appropriately.
has begun, please attach	a narrative of actions to date. If remedial	emediation immediately after discovery of a release. If remediation efforts have been successfully completed or if the release occurred lease attach all information needed for closure evaluation.
regulations all operators are public health or the environment failed to adequately investign addition, OCD acceptance of and/or regulations.  Printed Name: Kendr	required to report and/or file certain release notifient. The acceptance of a C-141 report by the O ate and remediate contamination that pose a threat a C-141 report does not relieve the operator of a Ruiz	rest of my knowledge and understand that pursuant to OCD rules and fications and perform corrective actions for releases which may endanger CD does not relieve the operator of liability should their operations have at to groundwater, surface water, human health or the environment. In responsibility for compliance with any other federal, state, or local laws  Title: EHS Associate
Signature: Kendra	ı Ruiz	Date: 3/7/2023_
<sub>email:</sub> Kendra.Ru	iz@dvn.com	Telephone: <u>575-748-0167</u>
OCD Only		
Received by:J	ocelyn Harimon	Date:03/08/2023

Spills In Line	d Containment
Measurements	Of Standing Fluid
Length(Ft)	70
Width(Ft)	70
Depth(in.)	2.5
Total Capacity without tank displacements (bbls)	181.82
No. of 500 bbl Tanks In Standing Fluid	6
No. of Other Tanks In Standing Fluid	
OD Of Other Tanks In Standing Fluid(feet)	
Total Volume of standing fluid accounting for tank displacement.	139.83

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 194092

#### **CONDITIONS**

Operator:	OGRID:
DEVON ENERGY PRODUCTION COMPANY, LP	6137
333 West Sheridan Ave.	Action Number:
Oklahoma City, OK 73102	194092
	Action Type:
	[C-141] Release Corrective Action (C-141)

#### CONDITIONS

Created By		Condition Date
jharimon	None	3/8/2023

Incident ID nAPP2305351774

District RP
Facility ID

Application ID

### **Site Assessment/Characterization**

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	>50 (ft bgs)			
Did this release impact groundwater or surface water?				
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	Yes No			
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	Yes X No			
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes 🗓 No			
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	Yes X No			
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	Yes X No			
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	Yes X No			
Are the lateral extents of the release within 300 feet of a wetland?	Yes No			
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ☑ No			
Are the lateral extents of the release overlying an unstable area such as karst geology?				
Are the lateral extents of the release within a 100-year floodplain?				
Did the release impact areas <b>not</b> on an exploration, development, production, or storage site?				
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.				
Characterization Report Checklist: Each of the following items must be included in the report.				
<ul> <li>Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.</li> <li>Field data</li> <li>Data table of soil contaminant concentration data</li> <li>Depth to water determination</li> <li>Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release</li> <li>Boring or excavation logs</li> <li>Photographs including date and GIS information</li> <li>Topographic/Aerial maps</li> <li>Laboratory data including chain of custody</li> </ul>				
Laboratory data including chain of custody				

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 3/13/2023 3:01:37 PM Form C-141 State of New Mexico Page 4 Oil Conservation Division

Received by:

	Page 24 of 3
Incident ID	nAPP2305351774
District RP	

Facility ID
Application ID

Date: \_\_\_\_\_

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Dale Woodall

Title: EHS Professional

Date: 3/13/2023

email: dale.woodall@dvn.com

Telephone: 405-318-4697

Page 25 of 32

	- "8" - " ) -
Incident ID	nAPP2305351774
District RP	
Facility ID	
Application ID	

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following is	tems must be included in the closure report.
X A scaled site and sampling diagram as described in 19.15.29.1	11 NMAC
x Photographs of the remediated site prior to backfill or photos must be notified 2 days prior to liner inspection)	of the liner integrity if applicable (Note: appropriate OCD District office
■ Laboratory analyses of final sampling (Note: appropriate ODC	C District office must be notified 2 days prior to final sampling)
Description of remediation activities	
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of should their operations have failed to adequately investigate and rer human health or the environment. In addition, OCD acceptance of compliance with any other federal, state, or local laws and/or regular restore, reclaim, and re-vegetate the impacted surface area to the coaccordance with 19.15.29.13 NMAC including notification to the OP rinted Name:  Dale Woodall	ntions. The responsible party acknowledges they must substantially inditions that existed prior to the release or their final land use in
	-
OCD Only	
Received by:	Date:
	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible for regulations.
Closure Approved by:	Date:
Printed Name:	Title:



Gio PimaOil <gio@pimaoil.com>

### Fiji 17 CTB 1 Liner Inspection NAPP2305351774

1 message

Gio PimaOil <gio@pimaoil.com>

Tue, Feb 28, 2023 at 7:44 AM

To: ocdonline@state.nm.us, Tom Pima Oil <tom@pimaoil.com>

Good Morning,

Pima Environmental would like to notify you that we will be conducting a liner Inspection at the Fiji 17 CTB 1 for incident NAPP2305351774. Pima personnel are scheduled to be on site for this Inspection event at approximately 8:00 a.m. On Thursday, March 2, 2023. If you have any questions or concerns, please let me know. Thank you

Gio Gomez Project Manager cell-806-782-1151 Office- 575-964-7740 Pima Environmental Services, LLC.



## Appendix C

**Liner Inspection Form** 

Photographic Documentation



## **Liner Inspection Form**

Company Name:	Devon E	Energy_			
Site:	Fiji(				
Lat/Long:	<u>32.3074</u>	<u>0934, -</u>	103.7962152		
NMOCD Incident ID & Incident Date:	NAPP2305351774 2/21/2023				
2-Day Notification Sent:	via E	mail by	/ Gio Gomez_2/28/2023		
Inspection Date:	3/2/2	2023			
Liner Type:	Earthen w/liner		Earthen no liner	Polystar	
	Steel w/	poly lin	Steel w/spray epoxy	No Liner	
Other:					
Visualization	Yes	No	Comments		
Is there a tear in the liner?		X			
Are there holes in the liner?	2	X			
Is the liner retaining any fluids?		X			
Does the liner have integrity to contain a leak?	X				
Comments:					
Inspector Name: <u>Ne</u>	ed Roger	<u>s</u>	Inspector Signature: _ <i>Ned Roge</i>	<i>થ</i> ાઇ	



### SITE PHOTOGRAPHS DEVON ENERGY FIJI 17 CTB 1

#### **Liner Inspection**
















District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 196472

#### **CONDITIONS**

Operator:	OGRID:
DEVON ENERGY PRODUCTION COMPANY, LP	6137
333 West Sheridan Ave.	Action Number:
Oklahoma City, OK 73102	196472
	Action Type:
	[C-141] Release Corrective Action (C-141)

#### CONDITIONS

Crea	ated By	Condition	Condition Date
rha	amlet	We have received your closure report and final C-141 for Incident #NAPP2305351774 FIJI 17 CTB 1, thank you. This closure is approved.	7/20/2023