RIGHT MEOW 31 CTB 7

07/27/2024

OCD INCIDENT nAPP2421124014

Spills In Lined Containment			
Measurements	Of Standing Fluid		
Length (Ft)	68		
Width(Ft)	68		
Depth(in.)	1		
Total Capacity without			
tank displacements (bbls)	68.63		
No. of 500 bbl Tanks In			
Standing Fluid	6		
No. of Other Tanks In			
Standing Fluid	0		
OD Of Other Tanks In			
Standing Fluid(feet)			
	0		
Total Volume of			
standing fluid	51.84		
accounting for tank	31.04		
displacement.			



LINER INSPECTION CLOSURE REPORT

Incident ID NAPP2421124014

Right Meow 31 CTB 7

Facility ID fAPP2125751032

Prepared By: Pima Environmental Services, LLC

Prepared For: Devon Energy Production, LP

September 2, 2024
Pima Environmental Services, LLC
5614 N Lovington Hwy, Hobbs, NM 88240



September 2, 2024

NMOCD District 2 811 S. First St Artesia, NM, 88210

RE: Liner Inspection and Closure Report

Right Meow 31 CTB 7

Facility ID: fAPP2125751032

GPS: Latitude 32.265538 Longitude -103.710866 UL- B, Section 31, Township 23S, Range 32E

Lea County, NM

NMOCD Reference No. NAPP2421124014

Devon Energy Production Company (Devon) has contracted Pima Environmental Services, LLC (Pima) to perform a liner inspection and prepare this closure report for a produced water release that occurred at the Right Meow 31 CTB 7 (Right Meow). This incident was assigned Incident ID:NAPP2421124014, by the New Mexico Oil Conservation Division (NMOCD).

Site Information and Site Characterization

The Right Meow is located approximately thirty-four (34) miles southwest of Eunice, NM. This spill site is in Unit B, Section 31, Township 23S, Range 32E, Latitude 32.265538 Longitude -103.710866, Lea County, NM. A Location Map can be found in Figure 1.

Based upon New Mexico Office of the State Engineer (C-04712 POD 1) well water data, depth to the nearest groundwater in this area is 55 feet belowgrade surface (BGS). located approximately 0.32 miles from the Right Meow. According to the United States Geological Survey (USGS 321609103445901 23S.31E.26.34411) well water data, depth to the nearest groundwater in this area is 100 feet BGS. See Appendix A for referenced water surveys and water related maps. The Right Meow is in a low karst area (Figure 3). A Topographic Map can be found in Figure 2.

Release Information

NAPP2421124014: On July 27, 2024, A pump failure caused a release in the lined containment. Approximately 52 barrels (bbls) of produced water were released from the pump into the lined secondary containment. A vacuum truck was dispatched and recovered approximately 47 bbls of fluid from the lined SPCC containment ring. Once the standing fluids were removed, the liner was visually inspected by Devon field staff for any pinholes or punctures, and none were found. Based on this inspection, there is no evidence that the spilled fluids left the containment. The remaining 5 bbls were recovered during the cleanup of the containment.

A Site Map can be found in Figure 4.

Site Assessment and Liner Inspection

On August 27, 2024, Pima personnel mobilized equipment to the site to perform power washing of the liner and containment. A vacuum truck accompanied the crew to recover the power washing fluids. During this process, the remaining 5 bbls of fluid missed during the initial recovery effort were also recovered.

On August 30, 2024, after submitting the 48-hour notification application ID: 378456 to the OCD, Pima Environmental conducted a liner inspection at this location. Pima concluded that the liner and containment maintained their integrity and successfully retained the fluids. The liner inspection form and photographic documentation can be found in Appendix C.

Pima Environmental Services

Received Live Of Com 943/2024 4:14:01 PM

Hobbs NM 88/20

Hobbs, NM 88240 575-964-7740



Closure Request

After careful review, Pima requests that this incident ID: NAPP2421124014, be closed. Devon has complied with the applicable closure requirements.

Should you have any questions or need additional information, please feel free to contact: Devon Energy – Dale Woodall at 575-748-0167 or Dale.Woodall@dvn.com.

Pima Environmental – Gio Gomez at 806-782-1151 or Gio@pimaoil.com.

Respectfully,

Gio Gomez

Project Manager

Pima Environmental Services, LLC

Attachments

Figures:

- 1- Location Map
- 2- Topographic Map
- 3- Karst Map
- 4- Site Map

Appendices:

Appendix A- Referenced Water Surveys

Appendix B- Soil Survey & Soil Maps, Geologic Data, FEMA, Wetlands

Appendix C- 48 Hour Notification, Liner Inspection Form

Appendix D- Photographic Documentation




Figures:


Figure 1- Location Map


Figure 2- Topographic Map

Figure 3- Karst Map

Figure 4- Site Map











Appendix A

Water Surveys:

- OSE
- USGS
- Surface Water Map



WELL RECORD & LOG

OFFICE OF THE STATE ENGINEER

www.ose.state.nm.us

100	OSE POD NO. (V		PODI	WELL TAG ID NO.	OSE FILE NO	s). (- c	1712		
1	WELL OWNER	1	-	<u> </u>	PHONE (OPTI	PHONE (OPTIONAL)			
1		rard		Company	CITY		STATE	ZIP	
	WELL OWNER	BOK S		W	Rosc	sell	NM 8	3202	
	WELL LOCATION (FROM GPS) DESCRIPTION		TUDE 3	REES MINUTES SECON 32 15 46. 33 42 58 GREET ADDRESS AND COMMON LANDMA	N • ACCURACE O DATUM RE	Y REQUIRED: ONE TENT QUIRED: WGS 84 OWNSHJIP, RANGE) WHE			
	LIGENIES NO		NAME OF LICENSED I	ADII I ED		NAME OF WELL DRI	LLING COMPANY		
	1833		NAME OF LICENSED I	Malen		Visian	Resources	6	
+	DRILLING STA	RTED		DEPTH OF COMPLETED WELL (FT)	BORE HOLE DEPTH (FT)		T ENCOUNTERED (FT)		
	Mar 9.	2003	3 9 23	55	55	Dry			
	COMPLETED	VELL IS:	ARTESIAN *add Centralizer info belo	DRY HOLE SHALLOW (UNCO		WATER LEVEL MPLETED WELL	DATE STATIC	MEASUR 1	
1	DRILLING FLU	ID:	AIR	MUD ADDITIVES – SPEC	CIFY:			(
	DRILLING ME	THOD: [VI	ROTARY HAMM	ER CABLE TOOL OTHER - SPEC	CIFY:	CHECK INSTAL	HERE IF PITLESS ADAI LED	PTER IS	
2. Drilleing & Capital in Ordinal	DEPTH (f	rO	BORE HOLE DIAM (inches)	CASING MATERIAL AND/OR GRADE (include each casing string, and note sections of screen)	CASING CONNECTION TYPE	CASING INSIDE DIAM. (inches)	CASING WALL THICKNESS (inches)	SLO SIZ (inch	
5	0	45	6	7 Costs Sch 40	(add coupling diameter)	2"	Sh 40	-	
Tringe	45	55	6	2" pue schab	Tread	2"	5ch40	,02	
4. DRI						nse nit gee	4 7077 om (-7/2		
							10 V		
	DEPTH (feet bgl) BORE HOLE			LIST ANNULAR SEAL MATERIAL AND GRAVEL PACK SIZE- RANGE BY INTERVAL		AMOUNT MET		THOD OF CEMENT	
KIN	FROM	ТО	DIAM. (inches)	*(if using Centralizers for Artesian wells-	indicate the spacing below	e spacing below) (cubic feet)		VIEW I	
ANNULAK MATEKIAL				None Putter	d And	Plugge	d		
3. ANI									
OR	OSE INTERN	IAL USE			WR	-20 WELL RECORD		22/2022	
			. PODI	POD NO.	TRN	NO. 743	189		

	DEPTH (fe	eet bgl)	THEKNESS	COLOR AND TYPE OF MATERIAL ENCOUNTERED -	WATER	ESTIMATED YIELD FOR		
	FROM	то	THICKNESS (feet)	INCLUDE WATER-BEARING CAVITIES OR FRACTURE ZONES (attach supplemental sheets to fully describe all units)		WATER- BEARING ZONES (gpm		
	0	20	20	White Caliche	Y N			
	20	45	25	Brow fine Sand	Y N			
	45	55	10	Red Sondy alkhe	Y N			
					Y N			
					Y N			
					Y N			
					Y N			
					Y N			
					Y N			
					Y N			
					Y N			
					Y N			
					Y N			
The constant of the constant o					Y N			
-					Y N			
					Y N			
					Y N			
					Y N			
					Y N			
N					Y N			
					Y N			
	METHOD US	TOTAL ESTIMATED						
U	PUMP AIR LIFT BAILER OTHER - SPECIFY: WELL YIELD (gpm):							
	WELL TEST		LUDING DISCHARGE M R THE TESTING PERIO					
	MISCELLANEOUS INFORMATION:							
S. IEST, MG SOI EN ISION	OSE 011 APR 4 2023 PML; 23							
	PRINT NAME(S) OF DRILL RIG SUPERVISOR(S) THAT PROVIDED ONSITE SUPERVISION OF WELL CONSTRUCTION OTHER THAN LICENSEE:							
		SIGNED		IES THAT, TO THE BEST OF HIS OR HER KNOWLEDGE AND BELII ESCRIBED HOLE AND THAT HE OR SHE WILL FILE THIS WELL R DOAYS AFTER COMPLETION OF WELL DRILLING:				
	CORRECT R	ECORD C		Jason Maley	3/24/23			
	CORRECT R	ECORD OF	OLDER WITHIN 30		3/24/23 DATE			
or State of the	CORRECT R	ECORD OF ERMIT HO	OLDER WITHIN 30	Jason Maley R / PRINT SIGNEE NAME	3/24/23 DATE			

Mike A. Hamman, P.E. State Engineer



Roswell Office 1900 WEST SECOND STREET ROSWELL, NM 88201

STATE OF NEW MEXICO OFFICE OF THE STATE ENGINEER

Trn Nbr: 743189 File Nbr: C 04712

Well File Nbr: C 04712 POD1

Apr. 04, 2023

VERTEX RESOURCES P.O. BOX 936 ROSWELL, NM 88202

Greetings:

The above numbered permit was issued in your name on 02/21/2023.

The Well Record was received in this office on 04/04/2023, stating that it had been completed on 03/09/2023, and was a dry well. The well is to be plugged according to 19.27.4.30 NMAC.


Please note that another well can be drilled under this permit if the well is completed and the well log filed on or before 02/21/2024.

If you have any questions, please feel free to contact us.

Sincerely,

Maret Thompson (575)622-6521

drywell





USGS Home **Contact USGS** Search USGS

National Water Information System: Web Interface

USGS Water Resources

Data Category:		Geographic Area:		
Groundwater	~	United States	~	GO

Click to hideNews Bulletins

• Explore the NEW USGS National Water Dashboard interactive map to access real-time water data from over 13,500 stations nationwide.

Groundwater levels for the Nation

Important: Next Generation Monitoring Location Page

Search Results -- 1 sites found

site no list =

• 321609103445901

Minimum number of levels = 1

Save file of selected sites to local disk for future upload


USGS 321609103445901 23S.31E.26.34411

Available data for this site Groundwater: Field measurements GO Eddy County, New Mexico Hydrologic Unit Code 13060011 Latitude 32°16'11.9", Longitude 103°45'01.2" NAD83 Land-surface elevation 3,451.00 feet above NGVD29 The depth of the well is 365 feet below land surface. This well is completed in the Other aguifers (N9999OTHER) national aguifer. This well is completed in the Dewey Lake Redbeds (312DYLK) local aquifer.

Output formats

Table of data	
Tab-separated data	
Graph of data	
Reselect period	

USGS 321609103445901 235,31E,26,34411



Breaks in the plot represent a gap of at least one year between field measurements. <u>Download a presentation-quality graph</u>

Questions or Comments
Help
Data Tips
Explanation of terms
Subscribe for system changes

Accessibility

FOIA

Privacy

Policies and Notices

<u>U.S. Department of the Interior</u> | <u>U.S. Geological Survey</u> **Title: Groundwater for USA: Water Levels**


URL: https://nwis.waterdata.usgs.gov/nwis/gwlevels?


Page Contact Information: <u>USGS Water Data Support Team</u> Page Last Modified: 2024-08-27 15:48:34 EDT

0.64 0.48 nadww01



Received by OCD: 9/3/2024 4:14:01 PM







Appendix B

- Soil Survey & Soil Maps
- Geological Data
- FEMA Flood Map
- Wetlands Map

Lea County, New Mexico

PU—Pyote and Maljamar fine sands

Map Unit Setting

National map unit symbol: dmqq Elevation: 3,000 to 3,900 feet

Mean annual precipitation: 10 to 12 inches
Mean annual air temperature: 60 to 62 degrees F

Frost-free period: 190 to 205 days

Farmland classification: Not prime farmland

Map Unit Composition

Pyote and similar soils: 46 percent Maljamar and similar soils: 44 percent

Minor components: 10 percent

Estimates are based on observations, descriptions, and transects of

the mapunit.

Description of Pyote

Setting

Landform: Plains

Landform position (three-dimensional): Rise

Down-slope shape: Linear Across-slope shape: Linear

Parent material: Sandy eolian deposits derived from sedimentary

rock

Typical profile

A - 0 to 30 inches: fine sand

Bt - 30 to 60 inches: fine sandy loam

Properties and qualities

Slope: 0 to 3 percent

Depth to restrictive feature: More than 80 inches

Drainage class: Well drained Runoff class: Negligible

Capacity of the most limiting layer to transmit water (Ksat): High

(2.00 to 6.00 in/hr)

Depth to water table: More than 80 inches

Frequency of flooding: None Frequency of ponding: None

Calcium carbonate, maximum content: 5 percent

Gypsum, maximum content: 1 percent

Maximum salinity: Nonsaline to very slightly saline (0.0 to 2.0


mmhos/cm)

Sodium adsorption ratio, maximum: 2.0

Available water supply, 0 to 60 inches: Low (about 5.1 inches)

Interpretive groups

Land capability classification (irrigated): 6e



Land capability classification (nonirrigated): 7s

Hydrologic Soil Group: A

Ecological site: R070BD003NM - Loamy Sand

Hydric soil rating: No

Description of Maljamar

Setting

Landform: Plains

Landform position (three-dimensional): Rise

Down-slope shape: Linear Across-slope shape: Linear

Parent material: Sandy eolian deposits derived from sedimentary

rock

Typical profile

A - 0 to 24 inches: fine sand

Bt - 24 to 50 inches: sandy clay loam
Bkm - 50 to 60 inches: cemented material

Properties and qualities

Slope: 0 to 3 percent

Depth to restrictive feature: 40 to 60 inches to petrocalcic

Drainage class: Well drained Runoff class: Very low

Capacity of the most limiting layer to transmit water (Ksat): Very low

to moderately low (0.00 to 0.06 in/hr) Depth to water table: More than 80 inches

Frequency of flooding: None Frequency of ponding: None

Calcium carbonate, maximum content: 5 percent

Gypsum, maximum content: 1 percent

Maximum salinity: Nonsaline to very slightly saline (0.0 to 2.0

mmhos/cm)

Sodium adsorption ratio, maximum: 2.0

Available water supply, 0 to 60 inches: Low (about 5.6 inches)

Interpretive groups

Land capability classification (irrigated): 6e Land capability classification (nonirrigated): 7e

Hydrologic Soil Group: B

Ecological site: R070BD003NM - Loamy Sand

Hydric soil rating: No

Minor Components

Kermit

Percent of map unit: 10 percent

Ecological site: R070BC022NM - Sandhills

Hydric soil rating: No

Data Source Information

Soil Survey Area: Lea County, New Mexico Survey Area Data: Version 20, Sep 6, 2023

Conservation Service

Received by OCD: 9/3/2024 4:14:01 PM



Soil Map—Lea County, New Mexico

MAP LEGEND

Area of Interest (AOI)

Area of Interest (AOI)

Soils

Soil Map Unit Polygons



Soil Map Unit Lines



Soil Map Unit Points

Special Point Features

 \odot

Blowout

 \boxtimes

Borrow Pit

366

Clay Spot



Closed Depression

Gravel Pit

Gravelly Spot

Landfill



Lava Flow



Marsh or swamp



Miscellaneous Water



Perennial Water



Rock Outcrop



Saline Spot



Sandy Spot



Severely Eroded Spot



Sinkhole



Slide or Slip



Sodic Spot

Spoil Area Stony Spot



Very Stony Spot



Wet Spot Other



Special Line Features

Water Features

Streams and Canals

Transportation

Rails



Interstate Highways



US Routes



Major Roads

Local Roads

Background



Aerial Photography

MAP INFORMATION

The soil surveys that comprise your AOI were mapped at 1:20.000.

Warning: Soil Map may not be valid at this scale.

Enlargement of maps beyond the scale of mapping can cause misunderstanding of the detail of mapping and accuracy of soil line placement. The maps do not show the small areas of contrasting soils that could have been shown at a more detailed

Please rely on the bar scale on each map sheet for map measurements.

Source of Map: Natural Resources Conservation Service Web Soil Survey URL:

Coordinate System: Web Mercator (EPSG:3857)

Maps from the Web Soil Survey are based on the Web Mercator projection, which preserves direction and shape but distorts distance and area. A projection that preserves area, such as the Albers equal-area conic projection, should be used if more accurate calculations of distance or area are required.

This product is generated from the USDA-NRCS certified data as of the version date(s) listed below.

Soil Survey Area: Lea County, New Mexico Survey Area Data: Version 20, Sep 6, 2023

Soil map units are labeled (as space allows) for map scales 1:50,000 or larger.

Date(s) aerial images were photographed: Feb 7, 2020—May 12, 2020

The orthophoto or other base map on which the soil lines were compiled and digitized probably differs from the background imagery displayed on these maps. As a result, some minor shifting of map unit boundaries may be evident.

Map Unit Legend

Map Unit Symbol	Map Unit Name	Acres in AOI	Percent of AOI
PT	Pyote loamy fine sand	0.5	3.7%
PU	Pyote and Maljamar fine sands	12.4	96.3%
Totals for Area of Interest		12.9	100.0%

(https://www.usgs.gov/)

Mineral Resources (https://www.usgs.gov/energy-and-minerals/mineral-resources-program)

- / Online Spatial Data (/) / Geology (/geology/) / by state (/geology/state/)
- / New Mexico (/geology/state/state.php?state=NM)

Eolian and piedmont deposits

XML (/geology/state/xml/NMQep;0)

JSON (/geology/state/json/NMQep;0)

Shapefile (/geology/state/unit-shape.php?unit=NMQep;0)

Interlayered eolian sands and piedmont-slope deposits along the eastern flank of the Pecos River valley, primarily between Roswell and Carlsbad. Typically capped by thin eolian deposits.

State	New Mexico (/geology/state/state.php?state=NM)	
Name	Eolian and piedmont deposits	
Geologic age	Holocene to middle Pleistocene	
Lithologic constituents	Major Unconsolidated (Eolian) Interlayered eolian sands and piedmont-slope deposits	
References	New Mexico Bureau of Geology and Mineral Resources, 2003, Geologic Map of New Mexico, scale 1:500,000 (includes some new polygons, faults, and attributes not in NM001 - heads up digitizing by JHorton).	
NGMDB product	NGMDB product page for 22974 (https://ngmdb.usgs.gov/Prodesc/proddesc_22974.htm)	

Received by OCD: 9/3/2024 4:14:01 PM

Counties

Chaves (/geology/state/fips-unit.php?code=f35005) - DeBaca (/geology/state/fips-unit.php?code=f35011) - Eddy (/geology/state/fips-unit.php?code=f35015) - Lea (/geology/state/fips-unit.php?code=f35025) - Roosevelt (/geology/state/fips-unit.php?code=f35041)

DOI Privacy Policy (https://www.doi.gov/privacy) | Legal (https://www.usgs.gov/laws/policies_notices.html) | Accessibility (https://www2.usgs.gov/laws/accessibility.html) | Site Map (https://www.usgs.gov/sitemap.html) | Contact USGS (https://answers.usgs.gov/)

U.S. Department of the Interior (https://www.doi.gov/) | DOI Inspector General (https://www.doi.gov/) | White House (https://www.whitehouse.gov/) |

E-gov (https://www.whitehouse.gov/omb/management/egov/) | No Fear Act (https://www.doi.gov/pmb/eeo/no-fear-act) | FOIA (https://www2.usgs.gov/foia)



2,000

250

500

1,000

1,500



SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT

With BFE or Depth Zone AE, AO, AH, VE, AF SPECIAL FLOOD **HAZARD AREAS** Regulatory Floodway

> 0.2% Annual Chance Flood Hazard, Areas of 1% annual chance flood with average depth less than one foot or with drain areas of less than one square mile Zone **Future Conditions 1% Annual** Chance Flood Hazard Zone X Area with Reduced Flood Risk due to

NO SCREEN Area of Minimal Flood Hazard Zone X

OTHER AREAS OF FLOOD HAZARD Levee. See Notes. Zone X Area with Flood Risk due to Levee Zone

Without Base Flood Elevation (BFE)

Effective LOMRs OTHER AREAS Area of Undetermined Flood Hazard Zone D

- - - Channel, Culvert, or Storm Sewer STRUCTURES | 1111111 Levee, Dike, or Floodwall

> 20.2 Cross Sections with 1% Annual Chance 17.5 Water Surface Elevation **Coastal Transect** Base Flood Elevation Line (BFE) Limit of Study **Jurisdiction Boundary** - -- Coastal Transect Baseline

OTHER **Profile Baseline FEATURES** Hydrographic Feature

> Digital Data Available No Digital Data Available

MAP PANELS

Unmapped

an authoritative property location.

The pin displayed on the map is an approximate point selected by the user and does not represent

This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards

The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 8/27/2024 at 3:56 PM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.

U.S. Fish and Wildlife Service

National Wetlands Inventory

Wetlands Map



August 27, 2024

Wetlands

Estuarine and Marine Deepwater

Estuarine and Marine Wetland

Freshwater Emergent Wetland

Freshwater Forested/Shrub Wetland

Freshwater Pond



Riverine

Other

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.



Appendix C

- 48-Hour Notification
- Liner Inspection Form

lynsey@pimaoil.com

From: Woodall, Dale <Dale.Woodall@dvn.com>
Sent: Tuesday, August 27, 2024 2:41 PM
To: 'Gio PimaOil'; Lynsey Pima Oil

Subject: FW: [EXTERNAL] The Oil Conservation Division (OCD) has accepted the application,

Application ID: 378456

Dale Woodall

Environmental Professional
Hobbs, NM

Office: 575-748-1838 Mobile: 405-318-4697 <u>Dale.Woodall@dvn.com</u>

From: OCDOnline@state.nm.us < OCDOnline@state.nm.us >

Sent: Tuesday, August 27, 2024 2:39 PM **To:** Woodall, Dale < Dale. Woodall@dvn.com>

Subject: [EXTERNAL] The Oil Conservation Division (OCD) has accepted the application, Application ID: 378456

To whom it may concern (c/o Dale Woodall for DEVON ENERGY PRODUCTION COMPANY, LP),

The OCD has received the submitted *Notification for Liner Inspection for a Release* (C-141L), for incident ID (n#) nAPP2421124014.

The liner inspection is expected to take place:

When: 08/30/2024 @ 08:00

Where: B-31-23S-32E 348 FSL 439 FEL (32.265538,-103.710866)

Additional Information: Andrew Franco 806-200-0054

Additional Instructions: B-31-23S-32E, (32.265538,-103.710866 NAD83) From the intersection of NM 128 and Red Rd, travel north on Red Rd for 1.70 miles, turn west on Lease Rd for 1.17 miles, turn south on lease Rd for 0.50 of a mile, turn west on lease Rd for 0.57 of a mile, arriving to location.

An OCD representative may be available onsite at the date and time reported. In the absence or presence of an OCD representative, liner inspection pursuant to 19.15.29.11.A(5)(a) NMAC is required. Should there be a change in the scheduled date and time of the sampling event, then another notification should be resubmitted through OCD permitting as soon as possible.

• Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.

If you have any questions regarding this application, or don't know why you have received this email, please contact us.

New Mexico Energy, Minerals and Natural Resources Department

1220 South St. Francis Drive Santa Fe, NM 87505

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.



Liner Inspection Form

Company Name:	e: <u>Devon Energy</u>					
Site:	Right Meow 31 CTB 7					
Lat/Long:	32.265538, -103.710866					
NMOCD Incident ID & Incident Date:	NAPP2	<u>42112</u>	4014	7/27/2024	_	
2-Day Notification Sent: via Email by Dale Woodall on OCD portal 8/27/2024 application ID: 378456.						
Inspection Date:	8/30	/2024_			_	
Liner Type:	Earthen	w/line	er	Earthen no line	r	Polystar
	Steel w/	poly li	ner	Steel w/spray e	poxy	No Liner
Other:						
Visualization	Yes	No		Com	ments	
Is there a tear in the liner?		X				
Are there holes in the liner?	е	X				
Is the liner retaining any fluids?	X		Fluid from	power washing th	e Liner	
Does the liner have integrity to contain a leak?	X					
Comments: Inspector Name:Ar				or Signature: _ <i>A</i> n	ndrew Franco	



Appendix D

Photographic Documentation

Pima Environmental Services, LLC.

Page 37 of 47

PHOTOGRAPHIC DOCUMENTATION

SITE NAME: Right Meow 31 CTB 7

Initial Liner Photos:



Site information Sign.



Aerial photo of liner taken prior to power washing.



Aerial photo of liner taken prior to power washing, taken facing North.



Photo of liner taken prior to power washing, taken facing Northwest.





Photo of liner taken prior to power washing, taken facing Southwest.

PHOTOGRAPHIC DOCUMENTATION



SITE NAME: Right Meow 31 CTB 7

Liner Inspection:



Photo taken pursuant to power washing, taken facing Northeast.



Photo taken pursuant to power washing, taken facing North.



Photo taken pursuant to power washing, taken facing Northwest.




Photo taken pursuant to power washing, taken facing West.





Photo taken pursuant to power washing, taken facing Northwest.



Photo taken pursuant to power washing, taken facing Southeast.



Photo taken pursuant to power washing, taken facing East.



Photo taken pursuant to power washing, taken facing South.

Page 41 of 47

PHOTOGRAPHIC DOCUMENTATION

SITE NAME: Right Meow 31 CTB 7

Aerial Liner Photos:



Aerial photo of liner.



Aerial photo of liner.



Aerial photo of liner.



Aerial photo of liner.

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 380282

QUESTIONS

Operator:	OGRID:
DEVON ENERGY PRODUCTION COMPANY, LP	6137
333 West Sheridan Ave.	Action Number:
Oklahoma City, OK 73102	380282
	Action Type:
	[C-141] Remediation Closure Request C-141 (C-141-v-Closure)

QUESTIONS

Prerequisites			
Incident ID (n#)	nAPP2421124014		
Incident Name	NAPP2421124014 RIGHT MEOW 31 CTB 7 @ 0		
Incident Type	Produced Water Release		
Incident Status	Remediation Closure Report Received		
Incident Facility	[fAPP2125751032] RIGHT MEOW 31 CTB 7		

Location of Release Source					
Please answer all the questions in this group.					
Site Name	RIGHT MEOW 31 CTB 7				
Date Release Discovered	07/27/2024				
Surface Owner	Federal				

Incident Details					
Please answer all the questions in this group.					
Incident Type	Produced Water Release				
Did this release result in a fire or is the result of a fire	No				
Did this release result in any injuries	No				
Has this release reached or does it have a reasonable probability of reaching a watercourse	No				
Has this release endangered or does it have a reasonable probability of endangering public health	No				
Has this release substantially damaged or will it substantially damage property or the environment	No				
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No				

Nature and Volume of Release	
Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.	
Crude Oil Released (bbls) Details	Not answered.
Produced Water Released (bbls) Details	Cause: Equipment Failure Pump Produced Water Released: 52 BBL Recovered: 47 BBL Lost: 5 BBL.
Is the concentration of chloride in the produced water >10,000 mg/l	Yes
Condensate Released (bbls) Details	Not answered.
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Not answered.
Other Released Details	Not answered.
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	Pump failure caused a 52 bbl produced water release into lined containment. 47 bbls recovered. E-mail sent to the OCD on 7/27/2024

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

<u>District IV</u> 1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 380282

Phone:(505) 476-3470 Fax:(505) 476-3462	
QUEST	IONS (continued)
Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102	OGRID: 6137 Action Number: 380282 Action Type: [C-141] Remediation Closure Request C-141 (C-141-v-Closure)
QUESTIONS	
Nature and Volume of Release (continued)	
Is this a gas only submission (i.e. only significant Mcf values reported)	No, according to supplied volumes this does not appear to be a "gas only" report.
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	Yes
Reasons why this would be considered a submission for a notification of a major release	From paragraph A. "Major release" determine using: (1) an unauthorized release of a volume, excluding gases, of 25 barrels or more.
With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.	e. gas only) are to be submitted on the C-129 form.
Initial Response The responsible party must undertake the following actions immediately unless they could create a	safety hazard that would result in injury.
The source of the release has been stopped	True
The impacted area has been secured to protect human health and the environment	True
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	True
All free liquids and recoverable materials have been removed and managed appropriately	True
If all the actions described above have not been undertaken, explain why	Not answered.
	liation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative o ted or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of evaluation in the follow-up C-141 submission.
to report and/or file certain release notifications and perform corrective actions for rele the OCD does not relieve the operator of liability should their operations have failed to	knowledge and understand that pursuant to OCD rules and regulations all operators are required ases which may endanger public health or the environment. The acceptance of a C-141 report by adequately investigate and remediate contamination that pose a threat to groundwater, surface it does not relieve the operator of responsibility for compliance with any other federal, state, or
I hereby agree and sign off to the above statement	Name: Dale Woodall Title: EHS Professional Email: Dale.Woodall@dvn.com

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 3

Action 380282

QUESTIONS (continued)

Operator:	OGRID:
DEVON ENERGY PRODUCTION COMPANY, LP	6137
333 West Sheridan Ave.	Action Number:
Oklahoma City, OK 73102	380282
	Action Type:
	[C-141] Remediation Closure Request C-141 (C-141-v-Closure)

QUESTIONS

Site Characterization	
Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the release discovery date.	
What is the shallowest depth to groundwater beneath the area affected by the release in feet below ground surface (ft bgs)	Between 51 and 75 (ft.)
What method was used to determine the depth to ground water	NM OSE iWaters Database Search
Did this release impact groundwater or surface water	No
What is the minimum distance, between the closest lateral extents of the release ar	nd the following surface areas:
A continuously flowing watercourse or any other significant watercourse	Greater than 5 (mi.)
Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)	Greater than 5 (mi.)
An occupied permanent residence, school, hospital, institution, or church	Greater than 5 (mi.)
A spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes	Greater than 5 (mi.)
Any other fresh water well or spring	Greater than 5 (mi.)
Incorporated municipal boundaries or a defined municipal fresh water well field	Greater than 5 (mi.)
A wetland	Greater than 5 (mi.)
A subsurface mine	Greater than 5 (mi.)
An (non-karst) unstable area	Greater than 5 (mi.)
Categorize the risk of this well / site being in a karst geology	Low
A 100-year floodplain	Greater than 5 (mi.)
Did the release impact areas not on an exploration, development, production, or storage site	No

district office no later than 90 days after the release discovery date. h the release have been determined, pursuant to 19.15.29.11 NMAC and 19.15.29.13 NMAC.		
h the release have been determined, pursuant to 19.15.29.11 NMAC and 19.15.29.13 NMAC.		
h the release have been determined, pursuant to 19.15.29.11 NMAC and 19.15.29.13 NMAC.		
Per Subsection B of 19.15.29.11 NMAC unless the site characterization report includes completed efforts at remediation, the report must include a proposed remediation plan in accordance with 19.15.29.12 NMAC, which includes the anticipated timelines for beginning and completing the remediation.		
024		
024		
024		
These estimated dates and measurements are recognized to be the best guess or calculation at the time of submission and may (be) change(d) over time as more remediation efforts are completed.		
20		

significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.

Released to Imaging: 9/18/2024 10:50:04 AM

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 **District II**

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 **District III**

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462 State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 4

Action 380282

QUESTIONS (continued)

Operator:	OGRID:
DEVON ENERGY PRODUCTION COMPANY, LP	6137
333 West Sheridan Ave.	Action Number:
Oklahoma City, OK 73102	380282
	Action Type:
	[C-141] Remediation Closure Request C-141 (C-141-v-Closure)

QUESTIONS

Remediation Plan (continued)	
Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.	
This remediation will (or is expected to) utilize the following processes to remediate / reduce contaminants:	
(Select all answers below that apply.)	
Is (or was) there affected material present needing to be removed	Yes
Is (or was) there a power wash of the lined containment area (to be) performed	Yes
OTHER (Non-listed remedial process)	No
Per Subsection B of 19 15 29 11 NMAC unless the site characterization report includes completed efforts at remediation, the report must include a proposed remediation plan in accordance with 19 15 29 12 NMAC	

Per Subsection B of 19.15.29.11 NMAC unless the site characterization report includes completed efforts at remediation, the report must include a proposed remediation plan in accordance with 19.15.29.12 NMAC which includes the anticipated timelines for beginning and completing the remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Name: Dale Woodall
Title: EHS Professional
Email: Dale.Woodall@dvn.com
Date: 09/03/2024

The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 **District II**

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 **District III**

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 6

Action 380282

QUESTIONS (continued)

Operator:	OGRID:
DEVON ENERGY PRODUCTION COMPANY, LP	6137
333 West Sheridan Ave.	Action Number:
Oklahoma City, OK 73102	380282
	Action Type:
	[C-141] Remediation Closure Request C-141 (C-141-v-Closure)

QUESTIONS

Liner Inspection Information	
Last liner inspection notification (C-141L) recorded	378456
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	08/30/2024
Was all the impacted materials removed from the liner	Yes
What was the liner inspection surface area in square feet	4855

Remediation Closure Request	
Only answer the questions in this group if seeking remediation closure for this release because all remediation steps have been completed.	
Requesting a remediation closure approval with this submission	Yes
Have the lateral and vertical extents of contamination been fully delineated	Yes
Was this release entirely contained within a lined containment area	Yes
What was the total surface area (in square feet) remediated	0
What was the total volume (cubic yards) remediated	0
Summarize any additional remediation activities not included by answers (above)	see report

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (in .pdf format) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

I hereby agree and sign off to the above statement

Name: Dale Woodall Title: EHS Professional Email: Dale.Woodall@dvn.com

Date: 09/03/2024

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 380282

CONDITIONS

Operator:	OGRID:
DEVON ENERGY PRODUCTION COMPANY, LP	6137
333 West Sheridan Ave.	Action Number:
Oklahoma City, OK 73102	380282
	Action Type:
	[C-141] Remediation Closure Request C-141 (C-141-v-Closure)

CONDITIONS

Created By		Condition Date
scwells	None	9/18/2024