Received by OCD: 1/11/2021 2:56:43 PM

•

Form 3160-5 (June 2015)		UNITED STATES Operator Copy EPARTMENT OF THE INTERIOR IREAU OF LAND MANAGEMENT			Сору		FORM APPROVED OMB No. 1004-0137					
	BUR	EAU OF LAND MANAGE	J OF LAND MANAGEMENT					Expires: January 31, 2018				
SUNDRY NOTICES AND REPORTS ON WELLS								5. Lease Serial No.				
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.							NM-78214 6. If Indian, Allottee or Tribe Name					
			<u> </u>					, Anollee of				
SU	7. If Unit or	7. If Unit or CA/Agreement, Name and/or No.										
1. Type of Well X Oil Well	Ga	s Well Other					8. Well Na	me and No),			
. Name of Operator							Anemo	Anemone ANE Federal 6				
EOG Resources,	Inc.	-						9. API Well No.				
3a. Address			3b. Phone	e No. <i>(include al</i>	rea cod	le)	30-015	30-015-33043				
104 S. 4th Str., 7				575-748-1	471		10. Field and Pool or Exploratory Area					
. Location of Well (Fo	otage, Sec.,T.,R.,M	, OR Survey Description)					Wildcat	Wildcat; Bone Spring				
							11. County	or Parish,	State			
		tion 9-T22S-R24E (I							New Mexico	. <u> </u>		
12. CHECI	K THE APPRO	OPRIATE BOX(ES) 1	TO IND	ICATE NAT	URE	OF NOT	TICE, REPOR	TORO	THER DATA			
TYPE OF SUE	BMISSION			T	YPE	OF ACTI	ON					
		Acidize		Deepen		Produ	retion (Start/Resume	<u>а</u> Г	Water Shut-Off			
X Notice of It	ntent	Alter Casing			ring		mation		Well Integrity			
				f ·								
Subsequent	Report	Casing Repair		New Constructio	n	Recon	nplete	L	Other			
		Change Plans	X	Plug and Abando	ท	Temp	orarily Abandon		· <u> </u>			
Final Aband	lonment Notice	Convert to Injection		Plug Back		Water	Disposal					
 MIRU all safety (2. Spot a 34 sx Cla Set a CIBP at 67 Spot a 25 sx Cla 	equipment as r ss "H" cement '43' with 7 sx C ss "C" cement ss "C" cement ss "C" cement ss "C" cement and weld on d	g and abandon this w needed. NU BOP. POG plug from 7333'-7514 Class "H" cement on to plug from 4259'-4408 plug from 2682'-2831 plug from 1735'-1884 plug from 110' up to s ry hole marker. Clean	OH with ' to cove op to 67(' to cove ' to cove surface.	production e er top of Wolf 08' to cover 3 er top of 2nd er top of 1st E er surface cas Backfill as ne	fcamp Ind Bo Bone Bone Sone S sing s seded	one Spring Spring. Spring. Shoe. WOO	perforations.	SQ	z cmt su			
4. I hereby certify that the	e foregoing is true	and correct. Name (Printed	d/Typed)				CONDITI	DNS-C)F APPROV A	ŧ₽!		
Tina Huerta				Title Regulatory Specialist					÷			
Тіи												
	a Huerta	2/1/2021 THIS SPACE I				y 4, 202						
pproved by						ANA			1 1 01			
anditions - fla	mexte	- Umo-	<u> </u>		itle ,	S/ E_7	<u> </u>	Date	1-8-21			
ertity that the applicant	holds legal or equi	Approval of this notice doe table title to those rights in	the subject	ctiease C	Office	110						
nch would entitle the ap		operations thereon. S.C. Section 1212, make it a	crime for	any nercon ker	inches	<u>LIU</u>	makete and					
		or representations as to any					make to any depa	aument or a	igency of the United S	ates		
structions on page 2)							·····	<u> </u>	<u></u>			



	lE Fede				TWN-RNG: DOTAGES:	1232' FNL & 19	-225-24E 80' FWL		API: GL: KB:	4195			
1 1			11	CASING	ETAIL						-		
	- 1		1 1		HOLE SIZE	SIZE	WGHT	GRADE	tap	Sottom.	Sx Cert	Croffoc	1 700
	·		1 1		26	20	10907 .	Conductor	0	40	33.04	C.MPIOC	TOC
			· · · ·	8	14 3/4	9.5/8	36	155 STAC	0				
						7				1.810	1630		-
1	- 1 1			E	834	· · ·	26	J-55 & L-80	0	8.715	1225	720	CBL
	.]]		1	· · · · -									
		·				L					L		
5ih Plug: Sur, Ceg. Shan													
	в. 7			FORMAT	ON TOPS								
						FORMATION	TOP			Fromation	TOP		
						Bone Spring	1935						
						tal Bone Spring	2757					Î	
						2nd Bony Spring	4334			1		(·	1
			1 :		1	3rd Bone Spring	7123				i —	·····	-
					1	Welftamp	7424		· ···				-
			1		1	Upper Pann	8055			I	<u> </u>	†	+
1			1 ·		1		6439			t			+
Abh Alum des Rome daul													
41h Plug: 1st Bone Springs Top	· •		1							L	I	I	.J
	1		1						_				
			1	Perforatio	on Detail					· · · · · · · · · · · · · · · · · · ·			
				— —	l	Formation	Top	Bottom		Treatment			
			· ·			Caryon	8080	8250		And & Rock Sait			
						3rd Bone Spring	6793	7395		Acd			· · ·
	,												
													1
					1								
			· ·		1				<u> </u>				-
	1										<u> </u>		
					i								-
Ord Plue: 2nd Bone Springs To	• •		· · ·										
					· · · · · · · · · · · · · · · · · · ·								
						ليحي				I			
			i	Plugs	1)						· · · · · ·	1
	· 1				5X	Class	Tep	Bottern	4	Notes	Tag		
	- 1			1	14	н)	7333	7514	181	Top of Wolfcamp	8		
	i i			2	7	н	6708	6743	35	3rd Bone Spring Perts	N		
	5 - C			1	25	c	4259	4404		Top of 2nd Bona Sprag	N		
				4	25	ç	2642	2931		Top of 1st Bone Spring	N		
				. 5	25	c	1735	1864		Surface Casing Shoe	- " .		<u> </u>
				6	25	c	0	110			¥		1
						- ·		9417	110	Surface Plug	-		1
	I		l .							· · · · ·			<u> </u>
									• • •				+
				H	<u> </u>						<u> </u>		<u> </u>
			Į	<u> </u>	1					· · · · · ·	<u> </u>		I
L L	ų p				<u> </u>								
2nd Plug: Open 1rd BS Perts			L .	<u> </u>			!						1
Id Bone Springs Perfs: 6793'.	1395° - 305	1											
	1												1
	· 1		J										
	-	· · · ·		ADDITION.	AL DETAIL								
at Plug: Wolfcamp Top						T	··	<u> </u>				·	<u> </u>
				0122/2011	CRP @ post								<u> </u>
		· · · · ·											1
		_			CBP @ 7993			· · · · · · · · · · · · · · · · · · ·					
	· E	_		9/23/2014	CHP (0 7931	40 ka Class H cml							
					· · · · · · · · · · · · · · · · · · ·					<u> </u>			1
	- E	_		<u> </u>	·								
018P w/ 30 sks cmt @ 4036"													
199 w/ 30 sks cmt @ 0030"		(
1897 w/ 20 wiss cmt @ 8020; [Caliyon Perts; 8080/4250;		ĺ											
1		1			<u> </u>			-					
1	3	1			Pret	and by: KJP	i						
anyon Perts; 8080'-8250'		1 MD			Pres	ared by: KJP		12/22/202					

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

District I 1625 N. French Dr., Hobbs, NM 88240

District II

District IV

Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

District III 1000 Rio Brazos Rd., Aztec, NM 87410 CONDITIONS

Action 14432

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS OF APPROVAL

Operator:				OGRID:	Action Number:	Action Type:
EOG RESOURCES INC	P.O. Box 2267	Midland, TX79702		7377	14432	C-103F
OCD Reviewer			Condi	tion		
gcordero			None			