
Remuda Basin State #004 - Current and Proposed WBD's



Constitution Copy Ho Appitophlate District: 24 AM	State of New Mexico	Form C-103	
Office District I – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.	
<u>District II</u> – (575) 748-1283	OIL CONSERVATION DIVISION	30-015-28420	
811 S. First St., Artesia, NM 88210		5. Indicate Type of Lease	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE X FEE	
District IV – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM			
87505	AND DEDODED ON WELL C		
	AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICATIO	TO DRILL OR TO DEEPEN OR PLUG BACK TO A N FOR PERMIT" (FORM C-101) FOR SUCH	Remuda Basin State	
PROPOSALS.)	TORTERINI (FORME 101) TORBEET	0. 777 11.37	
1. Type of Well: Oil Well 🗵 Gas Well 🗌 Other		8. Well Number 004	
2. Name of Operator		9. OGRID Number	
XTO Energy, In	C.	005380	
3. Address of Operator		10. Pool name or Wildcat	
6401 Holiday Hill Road, Bldg 5 Mic	lland Texas 79707	Forty Niner Ridge Bone Spring, West	
4. Well Location	maria, roxao roror	Transferrings Bana Spring, West	
Unit Letter N : 66	0 feet from the South line and	1980 feet from the West line	
			
Section 19	Township 23S Range 30E	NMPM County Eddy	
11.	Elevation (Show whether DR, RKB, RT, GR, etc.	.)	
12. Check Appro	opriate Box to Indicate Nature of Notice,	Report or Other Data	
NOTICE OF INTEN		SEQUENT REPORT OF:	
	JG AND ABANDON $\ \square$ REMEDIAL WOF	_	
TEMPORARILY ABANDON 🛛 CH	ANGE PLANS 🔲 COMMENCE DR	ILLING OPNS. P AND A	
PULL OR ALTER CASING MU	LTIPLE COMPL	IT JOB	
DOWNHOLE COMMINGLE			
CLOSED-LOOP SYSTEM			
OTHER:	☐ OTHER:		
13. Describe proposed or completed	operations. (Clearly state all pertinent details, ar	d give pertinent dates, including estimated date	
of starting any proposed work).	SEE RULE 19.15.7.14 NMAC. For Multiple Co	mpletions: Attach wellbore diagram of	
of starting any proposed work).		empletions: Attach wellbore diagram of	
of starting any proposed work). Sproposed completion or recompletion	etion.		
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re			
of starting any proposed work). Sproposed completion or recompletion	etion.		
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully reprocedure:	etion.		
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods.	etion.		
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'.	etion.		
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL	etion.		
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours	etion.		
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully reprocedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours 5. Tag TOC @ 6885'.	etion.		
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours	etion.		
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours 5. Tag TOC @ 6885'.	etion.		
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours 5. Tag TOC @ 6885'.	etion.		
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours 5. Tag TOC @ 6885'.	etion.		
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours 5. Tag TOC @ 6885'. 6. Run good MIT	etion. quests to temporarily abandon the above re		
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours 5. Tag TOC @ 6885'.	etion.		
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours 5. Tag TOC @ 6885'. 6. Run good MIT	etion. quests to temporarily abandon the above re		
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours 5. Tag TOC @ 6885'. 6. Run good MIT	etion. quests to temporarily abandon the above re		
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours 5. Tag TOC @ 6885'. 6. Run good MIT Spud Date:	Rig Release Date:	Ferenced well for 5-Years with the below	
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours 5. Tag TOC @ 6885'. 6. Run good MIT Spud Date:	etion. quests to temporarily abandon the above re	Ferenced well for 5-Years with the below	
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours 5. Tag TOC @ 6885'. 6. Run good MIT Spud Date:	Rig Release Date:	Ferenced well for 5-Years with the below	
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours 5. Tag TOC @ 6885'. 6. Run good MIT Spud Date:	Rig Release Date:	Ferenced well for 5-Years with the below	
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours 5. Tag TOC @ 6885'. 6. Run good MIT Spud Date:	Rig Release Date: ris true and complete to the best of my knowledged aduct TITLE Regulatory Coordinate	ge and belief. DATE 01/22/2021	
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours 5. Tag TOC @ 6885'. 6. Run good MIT Spud Date:	Rig Release Date: ris true and complete to the best of my knowledged aduct TITLE Regulatory Coordinate	ge and belief.	
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours 5. Tag TOC @ 6885'. 6. Run good MIT Spud Date: I hereby certify that the information above SIGNATURE Stephanie Rabe	Rig Release Date: ris true and complete to the best of my knowledged aduct TITLE Regulatory Coordinate	ge and belief. DATE 01/22/2021	
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours 5. Tag TOC @ 6885'. 6. Run good MIT Spud Date: I hereby certify that the information above SIGNATURE Stephanie Rabadu Type or print name Stephanie Rabadu For State Use Only	Rig Release Date: e is true and complete to the best of my knowledge address: TITLE Regulatory Coordinate stephanie.rabadue E-mail address:	ge and belief. DATE 01/22/2021 DATE 432-620-6714	
of starting any proposed work). proposed completion or recomple XTO Energy, Inc. respectfully re procedure: 1. POOH w/tbg & rods. 2. Set CIBP @ 6920'. 3. Cap w/35' Cmt via WL 4. WOC 4 Hours 5. Tag TOC @ 6885'. 6. Run good MIT Spud Date: I hereby certify that the information above SIGNATURE Stephanie Rabade Type or print name Stephanie Rabade	Rig Release Date: ris true and complete to the best of my knowledged aduct TITLE Regulatory Coordinate	ge and belief. DATE 01/22/2021 DATE 432-620-6714	

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 15457

CONDITIONS OF APPROVAL

Operator:	OGRID:	Action Number:	Action Type:
XTO ENERGY, INC 6401 Holiday Hill Road	5380	15457	C-103X
Building #5 Midland, TX79707			

OCD Reviewer	Condition
jagarcia	Notify District Personal 24 hours prior to prefroming MIT.