Submit 1 Copy To Appro Office <u>District I</u> – (575) 393-61 1625 N. French Dr., Hob	61 E	State of N nergy, Minerals a		Form C-103 Revised July 18, 2013 WELL API NO.			
District II – (575) 748-17 811 S. First St., Artesia, District III – (505) 334-6 1000 Rio Brazos Rd., Az District IV – (505) 476-2 1220 S. St. Francis Dr., 5	283 NM 88210 178 ttec, NM 87410 1460	OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505			30-025-29067 5. Indicate Type of Lease STATE X FEE 6. State Oil & Gas Lease No.		
S (DO NOT USE THIS FO	UNDRY NOTICES ADDRESS FOR PROPOSALS TO SIR. USE "APPLICATION OF THE WORLD TO THE WO	DRILL OR TO DEEP FOR PERMIT" (FORM	EN OR PLU		7. Lease Name or U State Lan 8. Well Number	nit Agreement Name	
2. Name of Operato	or o	orporation			9. OGRID Number		
3. Address of Oper	ator		2.11	2710	10. Pool name or W	ildcat	
4. Well Location	10x2769, Ho	bas, NM 8	8241-	[164	Anderson Kanch	Cisco Caryon; North	
Unit Letter Section	(73 feet from the	le S Rar	1ge 37E		he <u>West</u> line County lxa	
	11. E	levation (Show whe	ether DR, . 274 2				
	12. Check Approp				Report or Other Da	ata	
PERFORM REMED TEMPORARILY AB. PULL OR ALTER C. DOWNHOLE COMN CLOSED-LOOP SY OTHER: 13. Describe pro of starting at proposed co	ANDON CHANASING MULT MINGLE STEM Dosed or completed op ny proposed work). SE mpletion or recompletion	E AND ABANDON NGE PLANS FIPLE COMPL PERATIONS. (Clearly: EE RULE 19.15.7.1 On. Test and	14 NMAC.	OTHER: Por Multiple Control Co	give pertinent dates, inpletions: Attach well	AND A including estimated date bore diagram of	
P&S 50 sx Class & @7500 Abo WY. 0.	C. 4 his las son	he reported o	depth. D	(XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	XXX SPEWI 505X	s. Class H. WOC 4 hs Taggreport	
	1 4 SPF (0 4500) 4 SPF (0 422)					last store	
P&S 60 sx Class C @2700 7 Rivers/ Yates	8 4819 C 420'	ganger & circ-	150 SX	ans. WUCAN	whace (picture).		
P&S 50 sx Class C1400 top of salt	upty evorking tomk.	Hard contents of	1 1/2 ste	ct fant to Sun	dance Ednice.	1	
(2D WSU Cut W	f well head/a	inchors. 1	install regula	from Dry hole mo	rker.	
Fí	NAL LLEAN LLP W	intin 30 days	of blus.	ging down hi	ie.		
Spud Date: 4" dia	meter 4' tall Above Ground	Marker Rig Re	elease Date	\• I	CHED CONDITIONS APPROVAL		
I hereby certify that the	ne information above is	true and complete	to the bes	t of my knowledge	and belief.		
signature	to the ful	TITLE	Be	rdent	DATE	2/23/2021	
Type or print name	M-y Merchan	E-mai	il address:	mymerch@	enrocoil Garly	E: (575) 492-1236	
APPROVED BY: Conditions of Approv Released to Imaging:	Newy Ford al (if any): J 2/25/2021 9:53:52 Al	TITLE	Compli	ance Officer A	DATE	2/23/2021 IE: (575) 492-1236	

Pert/syz 420 CHO. TOBUY.

Penrocoil Corp

State Land 76 # 4

E. Sec. I. TIVS, R32E

Lea Counts, AM 30-025-29067

133/8, 48 415 W 4005x Clanic

85/8, 24/32, @ 4202 W 20005x

Purst 54 54 4500, 505h

Purst 812 1000. 505h

Per 8 10 462-10,476 2 13PF/24 holes

5/2".15.5/17 @10700

CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

- **1.** A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- **2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- **5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.
- **6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- **8.** Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- **10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- **13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- **14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- **16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- **18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, woe 4 hours and tag, this plug will be SO' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, woe and tagged. These plugs will be set SO' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III
1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 18564

CONDITIONS OF APPROVAL

Operator:			OGRID:	Action Number:	Action Type:
PENROC OIL CORP	P.O. Box 2769	Hobbs, NM88241-2769	17213	18564	C-103F

OCD Reviewer	Condition	
kfortner	See attached Conditions of Approval Note Changes to Proposed Procedure	