

Received by OCD: 2/22/2027 1:14:52			Form C-Rag 1 of 7	
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natu	ral Resources	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OVI GOVIGEDAVI TOO		WELL API NO. 30-25-28905	
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE STATE	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87	/505	6. State Oil & Gas Lease No.	
87505			96101	
SUNDRY NOTI	ICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLIC	SALS TO DRILL OR TO DEEPEN OR PLU CATION FOR PERMIT" (FORM C-101) FO	OR SUCH	T. 11 A 43 CG	
PROPOSALS.)			Kochia AAM State	
	Gas Well  Other SWD		8. Well Number 1 SWD	
2. Name of Operator SUNDOWN ENERGY LP			9. OGRID Number	
3. Address of Operator			232611 10. Pool name or Wildcat	
16400 DALLAS PARKWAY, STE	E. 100 DALLAS, TX 75248		Devonian	
4. Well Location				
Unit Letter <u>O</u> :	990 feet from the SOUTH	line and	2310 feet from the EAST line	
Section 35	Township 15S Rang	_	NMPM LEA County	
	11. Elevation (Show whether DR,			
MINISTER, WILL TO SEVE	3855' GR			
10 01 1		22.7	_	
12. Check A	Appropriate Box to Indicate Na	ature of Notice,	Report or Other Data	
NOTICE OF IN	TENTION TO	SUB	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🖂	REMEDIAL WOR		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	<u> </u>	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB	
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM				
OTHER:		OTHER: Did not	convert to ini	
13. Describe proposed or compl	leted operations. (Clearly state all p	ertinent details, an	d give pertinent dates, including estimated date	
of starting any proposed wo	ork). SEE RULE 19.15.7.14 NMAC	C. For Multiple Con	mpletions: Attach wellbore diagram of	
proposed completion or reco	ompletion.		4(b) Spot 25 sx Class H 10956 woc & tag	
1) Set CIBP @ 13,600'.			4 (c) Spot 25 Sx Class H 9720 woc & tag	
	oot 25 sxs balanced cement plug 13,	.200' to 13.600'. w	4 (d) Spot 25 sx Class H 8400 woc & ta oc&tag 4 (e) Spot 25 sx Class C 6516 woc & ta	
	isplace hole w/ 9.5 PPG mud. Press	•	4 (e) opot 20 3x 01a33 0 0010 woc a ta	
-	t 30 sxs balanced cement plug 1123	•	<u> </u>	
	t and pull 5 1/2" casing from 5500'. S			
	ving cement plugs if 5 ½" casing not			
	es at 4970' with 40 sxs cement plug 4000' with 40 sxs cement plug from			
	3150' with 40 sxs cement plug from			
	t at 1700' with 40 sxs cement plug 1			
11) Perf and squeeze surface at	t 450' with 100 sxs cement from 0 to	o 450'.		
Spud Date: 4" diameter 4' tall Above Ground Mar	ker Rig Release Da	te:   SEE ATTACH	HED S OF APPROVAL	
Above Ground Mar	Kei			
I hereby certify that the information a	above is true and complete to the be	st of my knowledg	e and belief.	
	D			
SIGNATURE Delinda	Aug C TIPE PIAL	Production Analys	t DATE 1/25/2021	
Type or print name Belinda Brad		ley@sundownener		
For State Use Only		The state of the s	100010	
10000000 THE WALL !	L ^	malian Offi	A 4/00/04	
APPROVED BY: Conditions of Approval (if any).	FULLE CO	mpliance Officer A	A DATE 4/22/21	

## WELL DATA SHEET PROPOSED



# WELL DATA SHEET PROPOSED FIELD: WILDCA



## CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

### Company representative will be on location during plugging procedures.

- **1.** A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- **2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- **5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.
- **6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- **8.** Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- **10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- **13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- **14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- **16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- **18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, woe 4 hours and tag, this plug will be SO' below the bottom and 50' above the top of the Formation.

**21.** If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, woe and tagged. These plugs will be set SO' below formation bottom to 50' above formation top inside the casing.

### DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

#### SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III
1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

COMMENTS

Action 18500

#### **COMMENTS**

Operator:			OGRID:	Action Number:	Action Type:
SUNDO	WN ENERGY LP	16400 Dallas Pkwy	232611	18500	C-103F
Suite 100	Dallas, TX75248				

Created By	Comment	Comment Date
plmartinez	DATA ENTRY PM	04/28/2021

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 18500

#### **CONDITIONS OF APPROVAL**

Operator:			OGRID:	Action Number:	Action Type:
SUNDOV	VN ENERGY LP	16400 Dallas Pkwy	232611	18500	C-103F
Suite 100	Dallas, TX75248				

OCD Reviewer	Condition
kfortner	See attached conditions of approval Note Changes to procedure