ceined by Opp P. Appropriate 1861.4	:19 AM St	ate of New Mex	tico		Form C-103	of 10	
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		WELL API NO.	Revised July 18, 2013	İ		
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OIL CON	OIL CONSERVATION DIVISION		30-025-2089			
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178		South St. France		5. Indicate Type STATE	of Lease ✓ FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Sa	anta Fe, NM 875	505	6. State Oil & G			
1220 S. St. Francis Dr., Santa Fe, NM 87505				17178			
SUNDRY NO (DO NOT USE THIS FORM FOR PROP	TICES AND REPO		C DACK TO A		or Unit Agreement Name		
DIFFERENT RESERVOIR. USE "APPI				NEW ME	XICO E STATE		
PROPOSALS.) 1. Type of Well: Oil Well				8. Well Number	001		
2. Name of Operator OXY USA INC.				9. OGRID Num 16696	ber		
3. Address of Operator	IOTON TV	77040		10. Pool name o			
P.O. BOX 4294 HOL	JSTON, TX	77210		MESCALER	RO; SAN ANDRES		
	: 990 feet fro	om the NORTH	line and 33	0 feet fro	om the WEST line		
Section 26			ge 32E	NMPM	County LEA		
	11. Elevation (S	Show whether DR, I	RKB, RT, GR, etc.)			
						I	
12. Check	Appropriate Bo	x to Indicate Na	ture of Notice,	Report or Other	· Data		
NOTICE OF I	NTENTION TO) .	SUB	SEQUENT RE	PORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABA	ANDON 🗹	REMEDIAL WOR	к 🗆	ALTERING CASING		
TEMPORARILY ABANDON			COMMENCE DRI		P AND A		
PULL OR ALTER CASING DOWNHOLE COMMINGLE		VIPL	CASING/CEMEN	1 106			
CLOSED-LOOP SYSTEM			OTUED.				
OTHER: 13. Describe proposed or com	npleted operations.		OTHER: ertinent details, and	d give pertinent dat	tes, including estimated date		
of starting any proposed v	work). SEE RULE						
	•						
SEE ATTACHED PROPOSED PROCEDURE							
LPC Area Below ground marker send pics before backfilling hole							
					TACHED CONDITIONS PROVAL	ı	
Spud Date:		Rig Release Date	e:				
I hereby certify that the informatio	n above is true and	complete to the bes	at of my knowledg	e and belief		-	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.							
SIGNATURE Stephen	anacek	TITLE_REGU	ILATORY EN	IGINEER D	ATE 3/22/21		
Type or print name STEPHEN	JANACEK	F_mail addrass	STEPHEN JANAC	CEK@OXY.COM DI	HONE: 713-493-1986		
For State Use Only	. 3,, 10 = 11	E-man address:		PI	TONE. 1.10 1000		
APPROVED BY:	Fortner	_ _{TITLE} _Compli	ance Officer A	DA	ATE 5/25/21		

Notice of Intent to PA

NEW MEXICO E STATE #001

30-025-20894

OXY USA INC.

PROCEDURE

10# MLF between plugs. Utilize above ground steel tanks.

SET CIBP @ 4024'. DUMP BAIL 5 SX CL C CMT. TAG TO VERIFY AND PRESSURE TEST.

SPOT 50 SX CL C CMT 3474'-2950'.

SPOT 25 SX CL C CMT 2260'-1987'.

SPOT 25 SX CL C CMT 1618'-1345'.

PERF @ 500'. CIRC 175 SX CL C CMT TO SURFACE. VERIFY CMT TO SURFACE.

FORMATION TOPS

INDICATE FORMATION TOPS IN CONFORMANCE WITH

Southeastern New Mexico T. Anhy __ T. Salt _ T. Strawn ___ B. Salt _ 2210 T. Yates.... ___ T. Miss ___ T. Men-3000 T. Siturien T. Queen ___ T. Montoya __ T. San Andres 3424 ____ T. Simpson ___ T. Glorieta _____ T. McKee ___ T. Paddock T. Ellenburger T. Dake T. Blinebry _____ T. Gr. Wash _____ T. Morr T. Granite ___ T. Drinkard _____ T. Delaware Send _____ T. Entr T. Abo _____ T. Bone Springs ____ _ T. Wing T. Welfcamp________T. lilnesand Foro 4066 T. Chin T. Peno. _____ T. ____ T Cisco (Bough C) _____ T. __


FORMATION RECORD (Attach additional

Current Wellbore

NEW MEXICO E STATE #001

30-025-20894-0000

Lea




String 1 OD 8.625 in TD 1550 ft TOC 0 ft

Proposed Wellbore

NEW MEXICO E STATE #001

30-025-20894-0000

Lea



String 1 OD 8.625 in TD 1550 ft TOC 0 ft

CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

- **1.** A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- **2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- **5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.
- **6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- **8.** Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- **10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- **13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- **14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- **16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- **18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, woe 4 hours and tag, this plug will be SO' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, woe and tagged. These plugs will be set SO' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

Notice of Intent to PA

NEW MEXICO E STATE #001

30-025-20894

OXY USA INC.

PROCEDURE

10# MLF between plugs. Utilize above ground steel tanks.

SET CIBP @ 4024'. DUMP BAIL 5 SX CL C CMT. TAG TO VERIFY AND PRESSURE TEST.

SPOT 50 SX CL C CMT 3474'-2950'.

SPOT 25 SX CL C CMT 2260'-1987'.

SPOT 25 SX CL C CMT 1618'-1345'.

PERF @ 500'. CIRC 175 SX CL C CMT TO SURFACE. VERIFY CMT TO SURFACE.

FORMATION TOPS

INDICATE FORMATION TOPS IN CONFORMANCE WITH

Southeastern New Mexico T. Anhy __ T. Salt _ T. Strawn ___ B. Salt _ 2210 T. Yates.... ___ T. Miss ___ T. Men-3000 T. Silurian T. Queen ___ T. Montoya __ T. San Andres 3424 ____ T. Simpson ___ T. Glorieta _____ T. McKee ___ T. Paddock T. Ellenburger T. Dake T. Blinebry _____ T. Gr. Wash _____ T. Morr T. Granite ___ T. Drinkard _____ T. Delaware Send _____ T. Entr T. Abo _____ T. Bone Springs ____ _ T. Wing T. Welfcamp________T. lilnesand Foro 4066 T. Chin T. Penn. _____ T. ____ T Cisco (Bough C) _____ T. __


FORMATION RECORD (Attach additional

Current Wellbore

NEW MEXICO E STATE #001

30-025-20894-0000

Lea




String 1 OD 8.625 in TD 1550 ft TOC 0 ft

Proposed Wellbore

NEW MEXICO E STATE #001

30-025-20894-0000

Lea



String 1 OD 8.625 in TD 1550 ft TOC 0 ft

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 21533

CONDITIONS

Operator:	OGRID:	
OXY USA INC	16696	
P.O. Box 4294	Action Number:	
Houston, TX 772104294	21533	
	Action Type:	
	[C-103] NOI Plug & Abandon (C-103F)	

CONDITIONS

Created By	Condition	Condition Date
kfortner	See attached conditions of approval	5/25/2021