Form 3160-3 FORM APPROVED OMB No. 1004-0137 (June 2015) Expires: January 31, 2018 **UNITED STATES** DEPARTMENT OF THE INTERIOR 5. Lease Serial No. NMNM128362 **BUREAU OF LAND MANAGEMENT** APPLICATION FOR PERMIT TO DRILL OR REENTER 6. If Indian, Allotee or Tribe Name 7. If Unit or CA Agreement, Name and No. **✓** DRILL REENTER 1a. Type of work: Oil Well 1b. Type of Well: Gas Well Other 8. Lease Name and Well No. 1c. Type of Completion: Hydraulic Fracturing Single Zone ✓ Multiple Zone DR AWKWARD 17-8 FEDERAL COM [329931] 9. API Well No. 2. Name of Operator 30-025-48947 [16696] **OXY USA INCORPORATED** 3a. Address 3b. Phone No. (include area code) 10. Field and Pool, or Exploratory [97366] BILBREY BASIN, BONE SPRING/BILBRE P.O. BOX 4294, HOUSTON, TX 77210 (432) 685-5717 4. Location of Well (Report location clearly and in accordance with any State requirements.*) 11. Sec., T. R. M. or Blk. and Survey or Area SEC 17/T22S/R32E/NMP At surface SWSW / 530 FSL / 1145 FWL / LAT 32.3857933 / LONG -103.7016322 At proposed prod. zone NENW / 20 FNL / 2200 FWL / LAT 32.4133248 / LONG -103.698251 14. Distance in miles and direction from nearest town or post office* 12. County or Parish 13. State I FA NM 24 miles 15. Distance from proposed* 16. No of acres in lease 17. Spacing Unit dedicated to this well 20 feet location to nearest property or lease line, ft. 640.0 (Also to nearest drig. unit line, if any) 18. Distance from proposed location* 19. Proposed Depth 20. BLM/BIA Bond No. in file to nearest well, drilling, completed, 35 feet 10650 feet / 21630 feet FED: ESB000226 applied for, on this lease, ft. 21. Elevations (Show whether DF, KDB, RT, GL, etc.) 22. Approximate date work will start* 23. Estimated duration 3690 feet 12/01/2020 45 days 24. Attachments The following, completed in accordance with the requirements of Onshore Oil and Gas Order No. 1, and the Hydraulic Fracturing rule per 43 CFR 3162.3-3 (as applicable) 1. Well plat certified by a registered surveyor. 4. Bond to cover the operations unless covered by an existing bond on file (see Item 20 above). 2. A Drilling Plan. 3. A Surface Use Plan (if the location is on National Forest System Lands, the 5. Operator certification. SUPO must be filed with the appropriate Forest Service Office). 6. Such other site specific information and/or plans as may be requested by the Name (Printed/Typed) Date 25. Signature LESLIE REEVES / Ph: (713) 366-5716 11/06/2019 (Electronic Submission) Title Advisor Regulatory Approved by (Signature) Date Name (Printed/Typed) (Electronic Submission) Cody Layton / Ph: (575) 234-5959 01/21/2021 Title Office Assistant Field Manager Lands & Minerals Carlsbad Field Office Application approval does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Conditions of approval, if any, are attached.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

GCP Rec 04/26/2021

SL

(Continued on page 2)

Released to Imaging: 6/1/2021 2:37:09 PM





*(Instructions on page 2)

Oxy USA Inc. - Dr Awkward 17 8 Federal Com 23H

1. Geologic Formations

TVD of target	10650'	Pilot Hole Depth	N/A
MD at TD:	21629'	Deepest Expected fresh water:	891'

Delaware Basin

Formation	TVD - RKB	Expected Fluids
Rustler	891	
Salado	1,194	Salt
Castile	2,800	Salt
Lamar/Delaware	4,777	Oil/Gas/Brine
Bell Canyon	4,850	Oil/Gas/Brine
Cherry Canyon	5,693	Oil/Gas/Brine
Brushy Canyon	6,891	Losses
Bone Spring	8,622	Oil/Gas
1st Bone Spring	9,719	Oil/Gas
2nd Bone Spring	10,376	Oil/Gas

^{*}H2S, water flows, loss of circulation, abnormal pressures, etc.

2. Casing Program

									Buoyant	Buoyant
Hala Sina (in)	Casing Int	terval	Csg. Size	Weight	Condo	Comm	SF	SF Burst	Body SF	Joint SF
Hole Size (in)	From (ft)	To (ft)	(in)	(lbs)	Grade	Conn.	Collapse	SF Burst	Tension	Tension
17.5	0	941	13.375	54.5	J-55	BTC	1.125	1.2	1.4	1.4
12.25	0	5743	9.625	40	J-55	BTC	1.125	1.2	1.4	1.4
8.5	0	21629	5.5	20	P-110	DQX	1.125	1.2	1.4	1.4
		-					SF Value	s will meet	or Exceed	

All casing strings will be tested in accordance with Onshore Oil and Gas Order #2 III.B.1.h

Annular Clearance Variance Request

As per the agreement reached in the Oxy/BLM meeting on Feb 22, 2018, Oxy requests permission to allow deviation from the 0.422" annular clearance requirement from Onshore Order #2 under the following conditions:

- 1. Annular clearance to meet or exceed 0.422" between intermediate casing ID and production casing coupling only on the first 500' overlap between both casings.
- 2. Annular clearance less than 0.422" is acceptable for the curve and lateral portions of the production open hole section.

	Y or N
Is casing new? If used, attach certification as required in Onshore Order #1	Y
Does casing meet API specifications? If no, attach casing specification sheet.	Y
Is premium or uncommon casing planned? If yes attach casing specification sheet.	Y

^{*}Oxy requests the option to set casing shallower yet still below the salts if losses or hole conditions require this. Cement volumes may be adjusted if casing is set shallower and a DV tool may be run in case hole conditions merit pumping a second stage cement job to comply with permitted top of cement. If cement circulated to surface during first stage, we will drop a cancelation cone and not pump the second stage.

^{*}Oxy requests the option to run production casing with DQX, SF TORQ, and/or DQW TORQ connections to accommodate hole conditions or drilling operations.

Oxy USA Inc. - Dr Awkward 17 8 Federal Com 23H

ONY CONTINUE DI NIVINITA II _ O I CACITAI COM 2511	
Does the above casing design meet or exceed BLM's minimum standards? If not provide justification (loading assumptions, casing design criteria).	Y
Will the intermediate pipe be kept at a minimum 1/3 fluid filled to avoid approaching the collapse pressure rating of the casing?	Y
Is well located within Capitan Reef?	N
If yes, does production casing cement tie back a minimum of 50' above the Reef?	
Is well within the designated 4 string boundary.	
7 111 11 007 1 1 7 111 70	
Is well located in SOPA but not in R-111-P?	N
If yes, are the first 2 strings cemented to surface and 3 rd string cement tied back	
500' into previous casing?	
Is well located in R-111-P and SOPA?	N
If yes, are the first three strings cemented to surface?	11
Is 2 nd string set 100' to 600' below the base of salt?	
Is well located in high Cave/Karst?	N
·	11
If yes, are there two strings cemented to surface?	
(For 2 string wells) If yes, is there a contingency casing if lost circulation occurs?	
Is well located in critical Cave/Karst?	N
If yes, are there three strings cemented to surface?	
<u> </u>	

3. Cementing Program

Casing String	# Sks	Wt. (lb/gal)	Yld (ft3/sack)	H20 (gal/sk)	500# Comp. Strength (hours)	Slurry Description
Surface (Lead)	N/A	N/A	N/A	N/A	N/A	N/A
Surface (Tail)	994	14.8	1.33	6.365	5:26	Class C Cement, Accelerator
Intermediate (Lead)	1366	12.9	1.73	8.784	15:26	Pozzolan Cement, Retarder
Intermediate (Tail)	155	14.8	1.33	6.368	7:11	Class C Cement, Accelerator
Production (Lead)	575	11.9	2.24	12.327	14:46	Class H Cement, Retarder, Dispersant, Salt
Production (Tail)	2238	13.2	1.38	6.686	3:49	Class H Cement, Retarder, Dispersant, Salt

Casing String	Top (ft)	Bottom (ft)	% Excess
Surface (Lead)	N/A	N/A	N/A
Surface (Tail)	0	941	100%
Intermediate (Lead)	0	5243	50%
Intermediate (Tail)	5243	5743	20%
Production (Lead)	5243	9948	20%
Production (Tail)	9948	21629	15%

Oxy requests a variance to cement the 9.625" and/or 7.625" intermediate casing strings offline in accordance to the approved variance, EC Tran 461365.

The summarized operational sequence will be as follows:

- 1. Run casing as per normal operations. While running casing, conduct negative pressure test and confirm integrity of the float equipment (float collar and shoe).
- 2. Land casing.
- 3. Fill pipe with kill weight fluid, and confirm well is static.
 - a. If well is not static notify BLM and kill well.
 - b. Once well is static notify BLM with intent to proceed with nipple down and offline cementing.

Oxy USA Inc. - Dr Awkward 17_8 Federal Com 23H

- 4. Set and pressure test annular packoff.
- 5. After confirmation of both annular barriers and internal barriers, nipple down BOP and install cap flange. If any barrier fails to test, the BOP stack will not be nippled down until after the cement job is completed.
- 6. Skid rig to next well on pad.
- 7. Confirm well is static before removing cap flange.
- 8. If well is not static notify BLM and kill well prior to cementing or nippling up for further remediation.
- 9. Install offline cement tool.
- 10. Rig up cement equipment.
 - a. Notify BLM prior to cement job.
- 11. Perform cement job.
- 12. Confirm well is static and floats are holding after cement job.
- 13. Remove cement equipment, offline cement tools and install night cap with pressure gauge for monitoring.

4. Pressure Control Equipment

saire Control Equip	mene					
BOP installed and tested before drilling which hole?	Size?	Min. Required WP	Туре		✓	Tested to:
		3M	Annula	Annular		70% of working pressure
12.25" Hole	13-5/8"		Blind R	am	✓	
12.23 Hole		234	Pipe Ram			250 psi / 3000 psi
		3M	Double Ram		✓	
			Other*			
	13-5/8"	5M	Annula	ar	✓	70% of working pressure
8.5" Hole			Blind R	am	✓	
		5M	Pipe Ra	Pipe Ram		250 mai / 5000 mai
		JIVI	Double F	Ram	✓	250 psi / 5000 psi
			Other*			

^{*}Specify if additional ram is utilized.

Oxy will utilize a 5M annular with a 10M BOPE stack. The BOP/BOPE will be tested by an independent service company to 250 psi low and the high pressure indicated above per Onshore Order 2 requirements. The System may be upgraded to a higher pressure but still tested to the working pressure listed in the table above. If the system is upgraded all the components installed will be functional and tested.

Pipe rams will be operationally checked each 24 hour period. Blind rams will be operationally checked on each trip out of the hole. These checks will be noted on the daily tour sheets. Other accessories to the BOP equipment will include a Kelly cock and floor safety valve (inside BOP) and choke lines and choke manifold. See attached schematics.

Formation integrity test will be performed per Onshore Order #2.			
On Ex	ploratory wells or on that portion of any well approved for a 5M BOPE system or		
greater, a pressure integrity test of each casing shoe shall be performed. Will be tested in			
accordance with Onshore Oil and Gas Order #2 III.B.1.i.			
A variance is requested for the use of a flexible choke line from the BOP to Choke			
Manifold. See attached for specs and hydrostatic test chart.			
Y	Are anchors required by manufacturer?		

Oxy USA Inc. - Dr Awkward 17 8 Federal Com 23H

A multibowl or a unionized multibowl wellhead system will be employed. The wellhead and connection to the BOPE will meet all API 6A requirements. The BOP will be tested per Onshore Order #2 after installation on the surface casing which will cover testing requirements for a maximum of 30 days. If any seal subject to test pressure is broken the system must be tested. We will test the flange connection of the wellhead with a test port that is directly in the flange. We are proposing that we will run the wellhead through the rotary prior to cementing surface casing as discussed with the BLM on October 8, 2015.

See attached schematics.

BOP Break Testing Request

Oxy requests permission to adjust the BOP break testing requirements as per the agreement reached in the OXY/BLM meeting on September 5, 2019. A separate sundry will be sent prior to spud that reflects the pad based break testing plan.

BOP break test under the following conditions:

- After a full BOP test is conducted
- When skidding to drill an intermediate section where ICP is set into the third Bone Spring or shallower.
- When skidding to drill a production section that does not penetrate into the third Bone Spring or deeper. If the kill line is broken prior to skid, two tests will be performed.
 - 1) Wellhead flange, co-flex hose, kill line connections and upper pipe rams
 - 2) Wellhead flange, HCR valve, check valve, upper pipe rams

If the kill line is not broken prior to skid, only one test will be performed.

1) Wellhead flange, co-flex hose, check valve, upper pipe rams

5. Mud Program

De	pth	Tymo	Weight	Vigagaity	Water Loss
From (ft)	To (ft)	Туре	(ppg)	Viscosity	water Loss
0	941	Water-Based Mud	8.6-8.8	40-60	N/C
941	5743	Saturated Brine- Mud	9.8-10.0	35-45	N/C
5743	21629	Saturated Brine- Based or Oil-Based Mud	8.0-9.6	38-50	N/C

Sufficient mud materials to maintain mud properties and meet minimum lost circulation and weight increase requirements will be kept on location at all times. The following is a general list of products: Barite, Bentonite, Gypsum, Lime, Soda Ash, Caustic Soda, Nut Plug, Cedar Fiber, Cotton Seed Hulls, Drilling Paper, Salt Water Clay, CACL2. Oxy will use a closed mud system.

What will be used to monitor the loss or gain of fluid? | PVT/MD Totco/Visual Monitoring

6. Logging and Testing Procedures

Logg	Logging, Coring and Testing.					
Yes	Will run GR from TD to surface (horizontal well – vertical portion of hole). Stated logs					
	run will be in the Completion Report and submitted to the BLM.					
No	Logs are planned based on well control or offset log information.					
No	Drill stem test? If yes, explain					

Oxy USA Inc. - Dr Awkward 17 8 Federal Com 23H

No	Coring? If ye	s, explain
		, 1

Addi	tional logs planned	Interval
No	Resistivity	
No	Density	
No	CBL	
Yes	Mud log	ICP - TD
No	PEX	

7. Drilling Conditions

Condition	Specify what type and where?						
BH Pressure at deepest TVD	5317 psi						
Abnormal Temperature	No						
BH Temperature at deepest TVD	166°F						

Pump high viscosity sweeps as needed for hole cleaning. The mud system will be monitored visually/manually as well as with an electronic PVT. The necessary mud products for additional weight and fluid loss control will be on location at all times. Appropriately weighted mud will be used to isolate potential gas, oil, and water zones until such time as casing can be cemented into place for zonal isolation.

Hydrogen Sulfide (H2S) monitors will be installed prior to drilling out the surface shoe. If H2S is detected in concentrations greater than 100 ppm, the operator will comply with the provisions of Onshore Oil and Gas Order #6. If Hydrogen Sulfide is encountered, measured values and formations will be provided to the BLM.

N H2S is present

varu	des and formations will be provided to the BEW.						
N	H2S is present						
Y	H2S Plan attached						

8. Other facets of operation	Yes/No
Will the well be drilled with a walking/skidding operation? If yes, describe.	Yes
• We plan to drill the six well pad in batch by section: all surface sections,	
intermediate sections and production sections. The wellhead will be secured	
with a night cap whenever the rig is not over the well.	
Will more than one drilling rig be used for drilling operations? If yes, describe.	Yes
Oxy requests the option to contract a Surface Rig to drill, set surface casing,	
and cement for this well. If the timing between rigs is such that Oxy would	
not be able to preset surface, the Primary Rig will MIRU and drill the well in	
its entirety per the APD. Please see the attached document for information	
on the spudder rig.	

Total estimated cuttings volume: 2095 bbls.

9. Company Personnel

Name	<u>Title</u>	Office Phone	Mobile Phone
Kurt Swafford	Drilling Engineer	713-497-2558	281-685-8405
William Turner	Drilling Engineer Supervisor	713-350-4951	661-817-4586
Simon Benavides	Drilling Superintendent	713-522-8652	281-684-6897
John Willis	Drilling Manager	713-366-5556	713-259-1417



Released to Imaging. 6/1/2021 2:37:09

Project: PRD NM DIRECTIONAL PLANS (NAD 1983)

Site: Dr Awkward 17_8 Federal Com Well: Dr Awkward 17_8 Federal Com 23H

Wellbore: WB00

Design: Permitting Plan

PROJECT DETAILS: NM DIRECTIONAL PLANS (NAD 1983)


Geodetic System: US State Plane 1983

Datum: North American Datum 1983

Ellipsoid: GRS 1980

Zone: New Mexico Eastern Zone

System Datum: Mean Sea Level



OXY

PRD NM DIRECTIONAL PLANS (NAD 1983)
Dr Awkward 17_8 Federal Com
Dr Awkward 17_8 Federal Com 23H

WB00

Plan: Permitting Plan

Standard Planning Report

20 September, 2019

Planning Report

Database: HOPSPP

Company: **ENGINEERING DESIGNS**

Project: PRD NM DIRECTIONAL PLANS (NAD 1983)

Site: Dr Awkward 17_8 Federal Com Well: Dr Awkward 17_8 Federal Com 23H

Wellbore: WB00 Design: Permitting Plan Local Co-ordinate Reference:

TVD Reference: MD Reference: North Reference:

Survey Calculation Method:

Well Dr Awkward 17_8 Federal Com 23H

RKB=26.5' @ 3716.20ft RKB=26.5' @ 3716.20ft

Minimum Curvature

Project PRD NM DIRECTIONAL PLANS (NAD 1983)

Map System: US State Plane 1983

North American Datum 1983 Geo Datum: Map Zone: New Mexico Eastern Zone

System Datum: Mean Sea Level

Using geodetic scale factor

Site Dr Awkward 17_8 Federal Com

Northing: 504,334.74 usft Site Position: Latitude: 32° 23' 5.444478 N From: Мар Easting: 739,795.94 usft Longitude: 103° 41' 25.533941 W **Position Uncertainty:** 50.00 ft Slot Radius: **Grid Convergence:** 0.34 13.200 in

Well Dr Awkward 17 8 Federal Com 23H

Well Position +N/-S 324.16 ft Northing: 504,658.88 usft Latitude: 32° 23' 8.855965 N +E/-W -3,461.46 ft Easting: 736,334.65 usft Longitude: 103° 42' 5.875816 W

Position Uncertainty 1.00 ft Wellhead Elevation: 0.00 ft **Ground Level:** 3,689.70 ft

Wellbore WB00 Declination **Field Strength** Magnetics **Model Name** Sample Date Dip Angle (°) (°) (nT) HDGM FILE 9/20/2019 6.72 60.12 48,042.10000000

Permitting Plan Design **Audit Notes:** Version: Phase: **PROTOTYPE** Tie On Depth: 0.00 **Vertical Section:** Depth From (TVD) +N/-S +E/-W Direction (ft) (ft) (ft) (°) 0.00 0.00 0.00 5.61

Plan Survey Tool Program Date 9/20/2019

Depth From Depth To

(ft) (ft) Survey (Wellbore) **Tool Name** Remarks

0.00 21,629.94 Permitting Plan (WB00) B001Mb_MWD+HRGM

OWSG MWD + HRGM

Plan Sections	Plan Sections												
Measured Depth (ft)	Inclination (°)	Azimuth (°)	Vertical Depth (ft)	+N/-S (ft)	+E/-W (ft)	Dogleg Rate (°/100ft)	Build Rate (°/100ft)	Turn Rate (°/100ft)	TFO (°)	Target			
0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00				
3,557.00	0.00	0.00	3,557.00	0.00	0.00	0.00	0.00	0.00	0.00				
4,356.85	16.00	137.99	4,346.50	-82.42	74.25	2.00	2.00	0.00	137.99				
8,955.00	16.00	137.99	8,766.59	-1,023.92	922.40	0.00	0.00	0.00	0.00				
10,448.02	16.00	359.60	10,235.17	-969.78	1,061.82	2.00	0.00	-9.27	-158.43				
11,188.02	90.00	359.60	10,650.20	-419.03	1,057.93	10.00	10.00	0.00	0.00	FTP (Dr Awkward			
21,629.94	90.00	359.60	10,650.20	10,022.63	984.30	0.00	0.00	0.00	0.00	PBHL (Dr Awkward			

Planning Report

Database: Company: Project: HOPSPP

ENGINEERING DESIGNS

PRD NM DIRECTIONAL PLANS (NAD 1983)

Site: Dr Awkward 17_8 Federal Com
Well: Dr Awkward 17_8 Federal Com 23H

Wellbore: WB00

Design: Permitting Plan

Local Co-ordinate Reference:

TVD Reference: MD Reference: North Reference:

Survey Calculation Method:

Well Dr Awkward 17_8 Federal Com 23H

RKB=26.5' @ 3716.20ft

RKB=26.5' @ 3716.20ft

Design:	Permitting Pla	ai i									
Planned Survey											
Measured Depth (ft)	Inclination (°)	Azimuth (°)	Vertical Depth (ft)	+N/-S (ft)	+E/-W (ft)	Vertical Section (ft)	Dogleg Rate (°/100ft)	Build Rate (°/100ft)	Turn Rate (°/100ft)		
0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00		
100.00	0.00	0.00	100.00	0.00	0.00	0.00	0.00	0.00	0.00		
200.00	0.00	0.00	200.00	0.00	0.00	0.00	0.00	0.00	0.00		
300.00	0.00	0.00	300.00	0.00	0.00	0.00	0.00	0.00	0.00		
400.00	0.00	0.00	400.00	0.00	0.00	0.00	0.00	0.00	0.00		
500.00	0.00	0.00	500.00	0.00	0.00	0.00	0.00	0.00	0.00		
600.00	0.00	0.00	600.00	0.00	0.00	0.00	0.00	0.00	0.00		
700.00	0.00	0.00	700.00	0.00	0.00	0.00	0.00	0.00	0.00		
800.00	0.00	0.00	800.00	0.00	0.00	0.00	0.00	0.00	0.00		
900.00	0.00	0.00	900.00	0.00	0.00	0.00	0.00	0.00	0.00		
1,000.00	0.00	0.00	1,000.00	0.00	0.00	0.00	0.00	0.00	0.00		
1,100.00	0.00	0.00	1,100.00	0.00	0.00	0.00	0.00	0.00	0.00		
1,200.00	0.00	0.00	1,200.00	0.00	0.00	0.00	0.00	0.00	0.00		
1,300.00	0.00	0.00	1,300.00	0.00	0.00	0.00	0.00	0.00	0.00		
1,400.00	0.00	0.00	1,400.00	0.00	0.00	0.00	0.00	0.00	0.00		
1,500.00	0.00	0.00	1,500.00	0.00	0.00	0.00	0.00	0.00	0.00		
1,600.00	0.00	0.00	1,600.00	0.00	0.00	0.00	0.00	0.00	0.00		
1,700.00	0.00	0.00	1,700.00	0.00	0.00	0.00	0.00	0.00	0.00		
1,800.00	0.00	0.00	1,800.00	0.00	0.00	0.00	0.00	0.00	0.00		
1,900.00	0.00	0.00	1,900.00	0.00	0.00	0.00	0.00	0.00	0.00		
2,000.00	0.00	0.00	2,000.00	0.00	0.00	0.00	0.00	0.00	0.00		
2,100.00	0.00	0.00	2,100.00	0.00	0.00	0.00	0.00	0.00	0.00		
2,200.00	0.00	0.00	2,200.00	0.00	0.00	0.00	0.00	0.00	0.00		
2,300.00	0.00	0.00	2,300.00	0.00	0.00	0.00	0.00	0.00	0.00		
2,400.00	0.00	0.00	2,400.00	0.00	0.00	0.00	0.00	0.00	0.00		
2,500.00	0.00	0.00	2,500.00	0.00	0.00	0.00	0.00	0.00	0.00		
2,600.00	0.00	0.00	2,600.00	0.00	0.00	0.00	0.00	0.00	0.00		
2,700.00	0.00	0.00	2,700.00	0.00	0.00	0.00	0.00	0.00	0.00		
2,800.00	0.00	0.00	2,800.00	0.00	0.00	0.00	0.00	0.00	0.00		
2,900.00	0.00	0.00	2,900.00	0.00	0.00	0.00	0.00	0.00	0.00		
3,000.00	0.00	0.00	3,000.00	0.00	0.00	0.00	0.00	0.00	0.00		
3,100.00	0.00	0.00	3,100.00	0.00	0.00	0.00	0.00	0.00	0.00		
3,200.00	0.00	0.00	3,200.00	0.00	0.00	0.00	0.00	0.00	0.00		
3,300.00	0.00	0.00	3,300.00	0.00	0.00	0.00	0.00	0.00	0.00		
3,400.00	0.00	0.00	3,400.00	0.00	0.00	0.00	0.00	0.00	0.00		
3,500.00	0.00	0.00	3,500.00	0.00	0.00	0.00	0.00	0.00	0.00		
3,557.00	0.00	0.00	3,557.00	0.00	0.00	0.00	0.00	0.00	0.00		
3,600.00	0.86	137.99	3,600.00	-0.24	0.22	-0.22	2.00	2.00	0.00		
3,700.00	2.86	137.99	3,699.94	-2.65	2.39	-2.41	2.00	2.00	0.00		
3,800.00	4.86	137.99	3,799.71	-7.65	6.89	-6.94	2.00	2.00	0.00		
3,900.00	6.86	137.99	3,899.18	-15.24	13.73	-13.82	2.00	2.00	0.00		
4,000.00	8.86	137.99	3,998.24	-25.40	22.88	-23.04	2.00	2.00	0.00		
4,100.00	10.86	137.99	4,096.75	-38.12	34.34	-34.58	2.00	2.00	0.00		
4,200.00	12.86	137.99	4,194.61	-53.39	48.10	-48.43	2.00	2.00	0.00		
4,300.00	14.86	137.99	4,291.70	-71.19	64.13	-64.58	2.00	2.00	0.00		
4,356.85	16.00	137.99	4,346.50	-82.42	74.25	-74.77	2.00	2.00	0.00		
4,400.00	16.00	137.99	4,387.98	-91.26	82.21	-82.79	0.00	0.00	0.00		
4,500.00	16.00	137.99	4,484.11	-111.73	100.66	-101.36	0.00	0.00	0.00		
4,600.00	16.00	137.99	4,580.23	-132.21	119.10	-119.94	0.00	0.00	0.00		
4,700.00	16.00	137.99	4,676.36	-152.68	137.55	-138.51	0.00	0.00	0.00		
4,800.00	16.00	137.99	4,772.49	-173.16	155.99	-157.08	0.00	0.00	0.00		
4,900.00	16.00	137.99	4,868.62	-193.64	174.44	-175.66	0.00	0.00	0.00		
5,000.00	16.00	137.99	4,964.74	-214.11	192.88	-194.23	0.00	0.00	0.00		
5,100.00	16.00	137.99	5,060.87	-234.59	211.33	-212.81	0.00	0.00	0.00		

Planning Report

Database: Company: HOPSPP

ENGINEERING DESIGNS

Project: PRD NM DIRECTIONAL PLANS (NAD 1983)
Site: PRD NM DIRECTIONAL PLANS (NAD 1983)
Dr Awkward 17_8 Federal Com

Site: Dr Awkward 17_8 Federal Com
Well: Dr Awkward 17_8 Federal Com 23H

Wellbore: WB00

Design: Permitting Plan

Local Co-ordinate Reference:

TVD Reference:
MD Reference:
North Reference:

Survey Calculation Method:

Well Dr Awkward 17_8 Federal Com 23H

RKB=26.5' @ 3716.20ft RKB=26.5' @ 3716.20ft

Grid

Design:	Permitting Plan										
Planned Survey											
Measured Depth (ft)	Inclination (°)	Azimuth (°)	Vertical Depth (ft)	+N/-S (ft)	+E/-W (ft)	Vertical Section (ft)	Dogleg Rate (°/100ft)	Build Rate (°/100ft)	Turn Rate (°/100ft)		
5,200.00	16.00	137.99	5,157.00	-255.06	229.77	-231.38	0.00	0.00	0.00		
5,300.00	16.00	137.99	5,253.13	-275.54	248.22	-249.96	0.00	0.00	0.00		
5,400.00	16.00	137.99	5,349.25	-296.01	266.66	-268.53	0.00	0.00	0.00		
5,500.00	16.00	137.99	5,445.38	-316.49	285.11	-287.11	0.00	0.00	0.00		
5,600.00	16.00	137.99	5,541.51	-336.96	303.56	-305.68	0.00	0.00	0.00		
5,700.00	16.00	137.99	5,637.64	-357.44	322.00	-324.26	0.00	0.00	0.00		
5,800.00	16.00	137.99	5,733.76	-377.92	340.45	-342.83	0.00	0.00	0.00		
5,900.00	16.00	137.99	5,829.89	-398.39	358.89	-361.41	0.00	0.00	0.00		
6,000.00	16.00	137.99	5,926.02	-418.87	377.34	-379.98	0.00	0.00	0.00		
6,100.00	16.00	137.99	6,022.15	-439.34	395.78	-398.56	0.00	0.00	0.00		
6,200.00	16.00	137.99	6,118.27	-459.82	414.23	-417.13	0.00	0.00	0.00		
6,300.00	16.00	137.99	6,214.40	-480.29	432.67	-435.71	0.00	0.00	0.00		
6,400.00	16.00	137.99	6,310.53	-500.77	451.12	-454.28	0.00	0.00	0.00		
6,500.00	16.00	137.99	6,406.66	-521.24	469.56	-472.85	0.00	0.00	0.00		
6,600.00	16.00	137.99	6,502.79	-541.72	488.01	-491.43	0.00	0.00	0.00		
6,700.00	16.00	137.99	6,598.91	-562.20	506.46	-510.00	0.00	0.00	0.00		
6.800.00	16.00	137.99	6,695.04	-582.67	524.90	-528.58	0.00	0.00	0.00		
6,900.00	16.00	137.99	6,791.17	-603.15	543.35	-547.15	0.00	0.00	0.00		
7.000.00	16.00	137.99	6,887.30	623.62	561.79	-565.73	0.00	0.00	0.00		
7,100.00	16.00	137.99	6,983.42	-644.10	580.24	-584.30	0.00	0.00	0.00		
7,200.00	16.00	137.99	7,079.55	-664.57	598.68	-602.88	0.00	0.00	0.00		
7,300.00	16.00	137.99	7,175.68	-685.05	617.13	-621.45	0.00	0.00	0.00		
7,400.00	16.00	137.99	7,173.00	-705.52	635.57	-640.03	0.00	0.00	0.00		
7,500.00	16.00	137.99	7,367.93	-726.00	654.02	-658.60	0.00	0.00	0.00		
7,600.00	16.00	137,99	7,464.06	-746.47	672.46	-677.18	0.00	0.00	0.00		
7,700.00	16.00	137.99	7,560.19	-766.95	690.91	-695.75	0.00	0.00	0.00		
7,800.00	16.00	137.99	7,656.32	-787.43	709.36	-714.33	0.00	0.00	0.00		
7,900.00	16.00	137.99	7,752.44	-807.90	727.80	-732.90	0.00	0.00	0.00		
8,000.00	16.00	137.99	7,848.57	-828.38	746.25	-751.47	0.00	0.00	0.00		
8,100.00	16.00	137.99	7,944.70	-848.85	764.69	-770.05	0.00	0.00	0.00		
8,200.00	16.00	137.99	8,040.83	-869.33	783.14	-788.62	0.00	0.00	0.00		
8,300.00	16.00	137.99	8,136.95	-889.80	801.58	-807.20	0.00	0.00	0.00		
8,400.00	16.00	137.99	8,233.08	-910.28	820.03	-825.77	0.00	0.00	0.00		
8,500.00	16.00	137.99	8,329.21	-930.75	838.47	-844.35	0.00	0.00	0.00		
8,600.00	16.00	137.99	8,425.34	-951.23	856.92	-862.92	0.00	0.00	0.00		
8,700.00	16.00	137.99	8,521.47	-971.71	875.36	-881.50	0.00	0.00	0.00		
8,800.00	16.00	137.99	8,617.59	-992.18	893.81	-900.07	0.00	0.00	0.00		
8,900.00	16.00	137.99	8,713.72	-1,012.66	912.26	-918.65	0.00	0.00	0.00		
8,955.00	16.00	137.99	8,766.59	-1,023.92	922.40	-928.86	0.00	0.00	0.00		
9,000.00	15.16	136.72	8,809.94	-1,032.81	930.59	-936.91	2.00	-1.85	-2.81		
9,100.00	13.34	133.36	8,906.86	-1,050.26	947.94	-952.58	2.00	-1.82	-3.36		
9,200.00	11.58	128.98	9,004.50	-1,064.49	964.13	-965.16	2.00	-1.76	-4.38		
9,300.00	9.90	123.10	9,102.75	-1,075.50	979.14	-974.65	2.00	-1.68	-5.88		
9,400.00	8.37	114.98	9,201.48	-1,083.27	992.94	-981.04	2.00	-1.53	-8.12		
9,500.00	7.07	103.60	9,300.58	-1,087.79	1,005.52	-984.31	2.00	-1.30	-11.38		
9,600.00	6.16	88.06	9,399.92	-1,089.06	1,016.86	-984.46	2.00	-0.91	-15.53		
9,700.00	5.81	69.08	9,499.38	-1,087.07	1,026.95	-981.49	2.00	-0.34	-18.99		
9,800.00	6.14	50.03	9,598.85	-1,081.82	1,035.78	-975.41	2.00	0.32	-19.05		
9,900.00	7.04	34.37	9,698.20	-1,073.33	1,043.34	-966.22	2.00	0.90	-15.66		
10,000.00	8.33	22.88	9,797.30	-1,061.60	1,049.61	-953.93	2.00	1.29	-11.49		
10,100.00	9.86	14.68	9,896.05	-1,046.65	1,054.60	-938.56	2.00	1.53	-8.20		
10,200.00	11.53	8.75	9,994.31	-1,028.49	1,058.29	-920.13	2.00	1.67	-5.93		
10,300.00	13.29	4.33	10,091.97	-1,007.15	1,060.67	-898.66	2.00	1.76	-4.41		
10,400.00	15.11	0.95	10,188 . 91	-982.65	1,061.76	-874.18	2.00	1.82	-3.38		

Planning Report

Database: Company:

Well:

HOPSPP

ENGINEERING DESIGNS

Project: Site: PRD NM DIRECTIONAL PLANS (NAD 1983)

Dr Awkward 17_8 Federal Com
Dr Awkward 17_8 Federal Com 23H

Wellbore: WB00

Design: Permitting Plan

Local Co-ordinate Reference:

TVD Reference: MD Reference: North Reference:

Survey Calculation Method:

Well Dr Awkward 17_8 Federal Com 23H

RKB=26.5' @ 3716.20ft RKB=26.5' @ 3716.20ft

Grid

esign:	Permitting Plan										
anned Survey											
Measured Depth (ft)	Inclination (°)	Azimuth (°)	Vertical Depth (ft)	+N/-S (ft)	+E/-W (ft)	Vertical Section (ft)	Dogleg Rate (°/100ft)	Build Rate (°/100ft)	Turn Rate (°/100ft)		
10,448 . 02 10,500 . 00	16.00 21.20	359.60 359.60	10,235.17 10,284.42	-969.78 -953.21	1,061.82 1,061.70	-861.36 -844.87	2.00 10.00	1.85 10.00	-2.82 0.00		
-			•								
10,600.00 10,700.00	31.20 41.20	359.60 359.60	10,374.04 10,454.63	-909.11 -850.13	1,061.39 1,060.97	-801.02 -742.37	10.00 10.00	10.00 10.00	0.00 0.00		
10,800.00	51.20	359.60	10,523.76	778.05	1,060.46	-670.68	10.00	10.00	0.00		
10,900.00	61.20	359.60	10,579.32	-695.06	1,059.88	-588.14	10.00	10.00	0.00		
11,000.00	71.20	359.60	10,619.63	-603.69	1,059.23	-497.27	10.00	10.00	0.00		
11,100.00	81.20	359.60	10,643.45	-506.70	1,058.55	-400.81	10.00	10.00	0.00		
11,188.02	90.00	359.60	10,650.20	-419.03	1,057.93	-313.62	10.00	10.00	0.00		
11,200.00	90.00	359.60	10,650.20	-407.05	1,057.85	-301.71	0.00	0.00	0.00		
11,300.00	90.00	359.60	10,650.20	-307.05	1,057.14	-202.26	0.00	0.00	0.00		
11,400.00	90.00	359.60	10,650 . 20	-207.05	1,056.44	-102.81	0.00	0.00	0.00		
11,500.00	90.00	359.60	10,650.20	-107.05	1,055.73	-3.36	0.00	0.00	0.00		
11,600.00	90.00	359.60	10,650.20	-7.06	1,055.03	96.09	0.00	0.00	0.00		
11,700.00	90.00	359.60	10,650.20	92.94	1,054.32	195.54	0.00	0.00	0.00		
11,800.00	90.00	359.60	10,650.20	192.94	1,053.62	294.99	0.00	0.00	0.00		
11,900.00	90.00	359.60	10,650.20	292.94	1,052.91	394.44	0.00	0.00	0.00		
12,000.00	90.00	359.60	10,650.20	392.93	1,052.21	493.89	0.00	0.00	0.00		
12,100.00	90.00	359.60	10,650.20	492.93	1,051.50	593.34	0.00	0.00	0.00		
12,200.00	90.00	359.60	10,650.20	592.93	1,050.80	692.79	0.00	0.00	0.00		
12,300.00 12,400.00	90.00 90.00	359.60 359.60	10,650.20 10,650.20	692.93 792.92	1,050 . 09 1,049 . 39	792.24 891.69	0.00 0.00	0.00 0.00	0.00 0.00		
12,500.00	90.00	359.60	10,650.20	892.92	1,048.68	991.14	0.00	0.00	0.00		
12,600.00	90.00	359.60	10,650.20	992.92	1,047.98	1,090.59	0.00	0.00	0.00		
12,700.00	90.00	359.60	10,650.20	1,092.92	1,047.27	1,190.04	0.00	0.00	0.00		
12,800.00	90.00	359.60	10,650.20	1,192.91	1,046.56	1,289.49	0.00	0.00	0.00		
12,900.00	90.00	359.60	10,650 . 20	1,292.91	1,045.86	1,388.94	0.00	0.00	0.00		
13,000.00	90.00	359.60	10,650 . 20	1,392.91	1,045.15	1,488.39	0.00	0.00	0.00		
13,100.00	90.00	359.60	10,650.20	1,492.91	1,044.45	1,587.84	0.00	0.00	0.00		
13,200.00	90.00	359.60	10,650.20	1,592.90	1,043.74	1,687.29	0.00	0.00	0.00		
13,300.00	90.00	359.60	10,650.20	1,692.90	1,043.04	1,786.74	0.00	0.00	0.00		
13,400.00	90.00	359.60	10,650 . 20	1,792.90	1,042.33	1,886.19	0.00	0.00	0.00		
13,500.00	90.00	359.60	10,650.20	1,892.90	1,041.63	1,985.64	0.00	0.00	0.00		
13,600.00	90.00	359.60	10,650.20	1,992.89	1,040.92	2,085.09	0.00	0.00	0.00		
13,700.00	90.00	359.60	10,650.20	2,092.89	1,040.22	2,184.54	0.00	0.00	0.00		
13,800.00	90.00	359.60	10,650.20	2,192.89	1,039.51	2,283.99	0.00	0.00	0.00		
13,900.00	90.00	359.60	10,650.20	2,292.89	1,038.81	2,383.44	0.00	0.00	0.00		
14,000.00	90.00	359.60	10,650.20	2,392.88	1,038.10	2,482.89	0.00	0.00	0.00		
14,100.00	90.00	359.60	10,650.20	2,492.88	1,037.40	2,582.34	0.00	0.00	0.00		
14,200.00	90.00	359.60	10,650.20	2,592.88	1,036.69	2,681.79	0.00	0.00	0.00		
14,300.00 14,400.00	90.00 90.00	359.60 359.60	10,650.20 10,650.20	2,692.88 2,792.87	1,035.99 1,035.28	2,781.24 2,880.69	0.00 0.00	0.00 0.00	0.00 0.00		
14,500.00	90.00	359.60	10,650.20	2,892.87	1,033.28	2,980.14	0.00	0.00	0.00		
14,600.00	90.00	359.60	10,650.20	2,892.87 2.992.87	1,034.56	2,960.14 3,079.59	0.00	0.00	0.00		
14,700.00	90.00	359.60	10,650.20	3,092.87	1,033.67	3,179.04	0.00	0.00	0.00		
14,800.00	90.00	359.60	10,650,20	3,192.86	1,032.46	3,278.49	0.00	0.00	0.00		
14,900.00	90.00	359.60	10,650.20	3,292.86	1,031.76	3,377.94	0.00	0.00	0.00		
15,000.00	90.00	359.60	10,650.20	3,392.86	1,031.05	3,477.39	0.00	0.00	0.00		
15,100.00	90.00	359.60	10,650.20	3,492.86	1,030.35	3,576.84	0.00	0.00	0.00		
15,200.00	90.00	359.60	10,650.20	3,592.85	1,029.64	3,676.29	0.00	0.00	0.00		
15,300.00	90.00	359.60	10,650.20	3,692.85	1,028.94	3,775.74	0.00	0.00	0.00		
15,400.00	90.00	359.60	10,650 . 20	3,792.85	1,028.23	3,875.19	0.00	0.00	0.00		
15,500.00	90.00	359.60	10,650.20	3,892.85	1,027.53	3,974.64	0.00	0.00	0.00		
15,600.00	90.00	359.60	10,650.20	3,992.84	1,026.82	4,074.09	0.00	0.00	0.00		

Planning Report

Database: Company: HOPSPP

ENGINEERING DESIGNS

Project: PRD NM DIRECTIONAL PLANS (NAD 1983)
Site: PRD NM DIRECTIONAL PLANS (NAD 1983)
Dr Awkward 17_8 Federal Com

Site: Dr Awkward 17_8 Federal Com
Well: Dr Awkward 17_8 Federal Com 23H

Wellbore: WB00

Design: Permitting Plan

Local Co-ordinate Reference:

TVD Reference: MD Reference: North Reference:

Survey Calculation Method:

Well Dr Awkward 17_8 Federal Com 23H

RKB=26.5' @ 3716.20ft

RKB=26.5' @ 3716.20ft

Planned Survey									
Measured	Inclination (°)	Azimuth (°)	Vertical Depth (ft)	+N/-S (ft)	+E/-W (ft)	Vertical Section (ft)	Dogleg Rate (°/100ft)	Build Rate (°/100ft)	Turn Rate (°/100 ft)
45 700 00			10.050.00			4 470 54	0.00	0.00	0.00
15,700.00	90.00	359.60	10,650.20	4,092.84	1,026.11	4,173.54	0.00	0.00	0.00
15,800.00 15,900.00	90.00 90.00	359.60 359.60	10,650.20 10,650.20	4,192.84 4,292.84	1,025.41 1,024.70	4,272 . 99 4,372 . 44	0.00 0.00	0.00 0.00	0.00 0.00
15,900.00	90.00	339.00	10,030.20	4,292.04	1,024.70	4,372.44	0.00	0.00	0.00
16,000.00	90.00	359.60	10,650.20	4,392.83	1,024.00	4,471.89	0.00	0.00	0.00
16,100.00	90.00	359.60	10,650.20	4,492.83	1,023.29	4,571.34	0.00	0.00	0.00
16,200.00	90.00	359.60	10,650.20	4,592.83	1,022.59	4,670.79	0.00	0.00	0.00
16,300.00	90.00	359.60	10,650.20	4,692.83	1,021.88	4,770.24	0.00	0.00	0.00
16,400.00	90.00	359.60	10,650.20	4,792.82	1,021.18	4,869.69	0.00	0.00	0.00
16,500.00	90.00	359.60	10,650.20	4,892.82	1,020.47	4,969.13	0.00	0.00	0.00
16,600.00	90.00	359.60	10,650.20	4,992.82	1,019.77	5,068.58	0.00	0.00	0.00
16,700.00	90.00	359.60	10,650.20	5,092.82	1,019.06	5,168.03	0.00	0.00	0.00
16,800.00	90.00	359.60	10,650.20	5,192.81	1,018.36	5,267.48	0.00	0.00	0.00
16,900.00	90.00	359.60	10,650.20	5,292.81	1,017.65	5,366.93	0.00	0.00	0.00
17,000.00	90.00	359.60	10,650.20	5,392.81	1,016.95	5,466.38	0.00	0.00	0.00
17,100.00	90.00	359.60	10,650.20	5,492.81	1,016.24	5,565.83	0.00	0.00	0.00
17,200.00	90.00	359.60	10,650.20	5,592.80	1,015.54	5,665 . 28	0.00	0.00	0.00
17,300.00	90.00	359.60	10,650.20	5,692.80	1,014.83	5,764.73	0.00	0.00	0.00
17,400.00	90.00	359.60	10,650.20	5,792.80	1,014.13	5,864.18	0.00	0.00	0.00
17,500.00	90.00	359.60	10,650.20	5,892.80	1,013.42	5,963.63	0.00	0.00	0.00
17,600.00	90.00	359.60	10,650.20	5,992.79	1,012.72	6,063.08	0.00	0.00	0.00
17,700.00	90.00	359.60	10,650.20	6,092.79	1,012.01	6,162.53	0.00	0.00	0.00
17,800.00	90.00	359.60	10,650.20	6,192.79	1,011.31	6,261.98	0.00	0.00	0.00
17,900.00	90.00	359.60	10,650.20	6,292.79	1,010.60	6,361.43	0.00	0.00	0.00
18,000.00	90.00	359.60	10,650.20	6,392.78	1,009.90	6,460.88	0.00	0.00	0.00
18,100.00	90.00	359.60	10,650.20	6,492.78	1,009.19	6,560.33	0.00	0.00	0.00
18,200.00	90.00	359.60	10,650.20	6,592.78	1,008.49	6,659.78	0.00	0.00	0.00
18,300.00	90.00	359.60	10,650.20	6,692.78	1,007.78	6,759.23	0.00	0.00	0.00
18,400.00	90.00	359.60	10,650.20	6,792.77	1,007.08	6,858.68	0.00	0.00	0.00
18,500.00	90.00	359.60	10,650.20	6,892.77	1,006.37	6,958.13	0.00	0.00	0.00
18,600.00	90.00	359.60	10,650.20	6,992.77	1,005.66	7,057.58	0.00	0.00	0.00
18,700.00	90.00	359.60	10,650.20	7,092.77	1,004.96	7,157.03	0.00	0.00	0.00
18,800.00	90.00	359.60	10,650.20	7,192.76	1,004.25	7,256.48	0.00	0.00	0.00
18,900.00	90.00	359.60	10,650.20	7,292.76	1,003.55	7,355.93	0.00	0.00	0.00
19,000.00	90.00	359.60	10,650.20	7,392.76	1,002.84	7,455.38	0.00	0.00	0.00
19,100.00	90.00	359.60	10,650.20	7,492.76	1,002.14	7,554.83	0.00	0.00	0.00
19,200.00	90.00	359.60	10,650.20	7,592.76	1,001.43	7,654.28	0.00	0.00	0.00
19,300.00	90.00	359.60	10,650.20	7,692.75	1,000.73	7,753.73	0.00	0.00	0.00
19,400.00	90.00	359.60	10,650.20	7,792.75	1,000.02	7,853.18	0.00	0.00	0.00
19,500.00	90.00	359.60	10,650.20	7,892.75	999.32	7,952.63	0.00	0.00	0.00
19,600.00	90.00	359.60	10,650.20	7,992.75	998.61	8,052.08	0.00	0.00	0.00
19,700.00	90.00	359.60	10,650.20	8,092.74	997.91	8,151.53	0.00	0.00	0.00
19,800.00	90.00	359.60	10,650.20	8,192.74	997.20	8,250.98	0.00	0.00	0.00
19,900.00	90.00	359.60	10,650.20	8,292.74	996.50	8,350.43	0.00	0.00	0.00
20,000.00	90.00	359.60	10,650.20	8,392.74	995.79	8,449.88	0.00	0.00	0.00
20,100.00	90.00	359.60	10,650.20	8,492.73	995.09	8,549.33	0.00	0.00	0.00
20,200.00	90.00	359.60	10,650.20	8,592.73	994.38	8,648.78	0.00	0.00	0.00
20,300.00	90.00	359.60 350.60	10,650.20	8,692.73	993.68	8,748.23	0.00	0.00	0.00
20,400.00	90.00	359.60	10,650.20	8,792.73	992.97	8,847.68	0.00	0.00	0.00
20,500.00	90.00	359.60	10,650.20	8,892.72	992.27	8,947.13	0.00	0.00	0.00
20,600.00	90.00	359.60	10,650.20	8,992.72	991.56	9,046.58	0.00	0.00	0.00
20,700.00	90.00	359.60	10,650.20	9,092.72	990.86	9,146.03	0.00	0.00	0.00
20,800.00	90.00	359.60	10,650.20	9,192.72	990.15	9,245.48	0.00	0.00	0.00
20,900.00	90.00	359.60	10,650.20	9,292.71	989.45	9,344.93	0.00	0.00	0.00
21,000.00	90.00	359.60	10,650.20	9,392.71	988.74	9,444.38	0.00	0.00	0.00

Planning Report

Database: HOPSPP

Company: ENGINEERING DESIGNS

Project: PRD NM DIRECTIONAL PLANS (NAD 1983)
Site: PRD NM DIRECTIONAL PLANS (NAD 1983)
Dr Awkward 17_8 Federal Com

Site: Dr Awkward 17_8 Federal Com
Well: Dr Awkward 17_8 Federal Com 23H

Wellbore: WB00

Design: Permitting Plan

Local Co-ordinate Reference:

TVD Reference: MD Reference: North Reference:

Survey Calculation Method:

Well Dr Awkward 17_8 Federal Com 23H

RKB=26.5' @ 3716.20ft RKB=26.5' @ 3716.20ft

Grid

Planned Survey									
Measured Depth (ft)	Inclination (°)	Azimuth (°)	Vertical Depth (ft)	+N/-S (ft)	+E/-W (ft)	Vertical Section (ft)	Dogleg Rate (°/100ft)	Build Rate (°/100ft)	Turn Rate (°/100ft)
21,100.00	90.00	359.60	10,650.20	9,492.71	988.04	9,543.83	0.00	0.00	0.00
21,200.00	90.00	359.60	10,650.20	9,592.71	987.33	9,643.28	0.00	0.00	0.00
21,300.00	90.00	359.60	10,650.20	9,692.70	986.63	9,742.73	0.00	0.00	0.00
21,400.00	90.00	359.60	10,650.20	9,792.70	985.92	9,842.18	0.00	0.00	0.00
21,500.00	90.00	359.60	10,650.20	9,892.70	985.21	9,941.63	0.00	0.00	0.00
21,600.00	90.00	359.60	10,650.20	9,992.70	984.51	10,041.08	0.00	0.00	0.00
21,629,94	90.00	359.60	10,650,20	10.022.63	984.30	10.070.85	0.00	0.00	0.00

Design Targets									
Target Name - hit/miss target - Shape	Dip Angle (°)	Dip Dir. (°)	TVD (ft)	+N/-S (ft)	+E/-W (ft)	Northing (usft)	Easting (usft)	Latitude	Longitude
PBHL (Dr Awkward - plan hits target cer - Point	0.00 nter	0.00	10,650.20	10,022.63	984.30	514,681.02	737,318.90	32° 24' 47.969180 N	103° 41' 53.703584
FTP (Dr Awkward - plan hits target cer - Point	0.00 nter	0.00	10,650.20	-419.03	1,057.93	504,239.87	737,392.53	32° 23' 4.647790 N	103° 41' 53.568117

Plan Annota	tions				
	Measured	Vertical	Local Coordinates		
	Depth (ft)	Depth (ft)	+N/-S (ft)	+E/-W (ft)	Comment
			` ,	` '	
I	3,557.00	3,557.00	0.00	0.00	Build 2.00°/100'
	4,356.85 8,955.00	4,346.50 8.766.59	-82.42 -1.023.92	74.25 922.40	Hold 16.00° Tangent Turn 2.00°/100'
	10.448.02	10.235.17	-1,023.92 -969.78	1.061.82	KOP. Build 10.00°/100'
	11.188.02	10,650.20	-419.03	1.057.93	Landing Point
	21,629.94	10,650.20	10,022.63	984.30	TD at 21629.94' MD

PECOS DISTRICT SURFACE USE CONDITIONS OF APPROVAL

Table Error! No text of specified style in document..1. Legal Land Descriptions and Surface Hole Locations of the Proposed Oil Wells

Proposed Well Name	Surface Hole Location	Legal Location*	Surface Ownership
Dr. Awkward 17-8 Federal Com 1H	345 FSL and 1,615 FWL		
Dr. Awkward 17-8 Federal Com 2H	345 FSL and 1,651 FWL		
Dr. Awkward 17-8 Federal Com 3H	270 FSL and 1,060 FWL	1	
Dr. Awkward 17-8 Federal Com 4H	270 FSL and 1,025 FEL	1	
Dr. Awkward 17-8 Federal Com 11H	525 FSL and 1,615 FWL		
Dr. Awkward 17-8 Federal Com 12H	525 FSL and 1,650 FWL		
Dr. Awkward 17-8 Federal Com 13H	525 FSL and 1,685 FWL	1	
Dr. Awkward 17-8 Federal Com 14H	450 FSL and 1,060 FEL	1	
Dr. Awkward 17-8 Federal Com 15H	450 FSL and 1,025 FEL	1	
Dr. Awkward 17-8 Federal Com 16H	450 FSL and 990 FEL	1	
Dr. Awkward 17-8 Federal Com 21H	530 FSL and 1,075 FWL	1	
Dr. Awkward 17-8 Federal Com 22H	530 FSL and 1,110 FWL	1	
Dr. Awkward 17-8 Federal Com 23H	530 FSL and 1,145 FWL	1	BLM
Dr. Awkward 17-8 Federal Com 24H	455 FSL and 1,600 FEL	Section 17, Township	
Dr. Awkward 17-8 Federal Com 25H	455 FSL and 1,565 FEL	- 22 South, Range 32 East	BLM
Dr. Awkward 17-8 Federal Com 26H	455 FSL and 1,530 FEL		
Dr. Awkward 17-8 Federal Com 31H	350 FSL and 1,075 FWL	0 FSL and 1,075 FWL	
Dr. Awkward 17-8 Federal Com 32H	350 FSL and 1,140 FWL		
Dr. Awkward 17-8 Federal Com 33H	350 FSL and 1,175 FWL	_	
Dr. Awkward 17-8 Federal Com 34H	275 FSL and 1,570 FEL		
Dr. Awkward 17-8 Federal Com 35H	275 FSL and 1,500 FEL	1	
Dr. Awkward 17-8 Federal Com 41H	345 FSL and 1,890 FWL	1	
Dr. Awkward 17-8 Federal Com 42H	345 FSL and 1,925 FWL	1	
Dr. Awkward 17-8 Federal Com 43H	270 FSL and 785 FEL		
Dr. Awkward 17-8 Federal Com 44H	270 FSL and 750 FEL		
Dr. Awkward 17-8 Federal Com 71H	525 FSL and 1,925 FWL]	
Dr. Awkward 17-8 Federal Com 72H	525 FSL and 1,960 FWL]	
Dr. Awkward 17-8 Federal Com 73H	450 FSL and 750 FEL		

PECOS DISTRICT DRILLING CONDITIONS OF APPROVAL

OPERATOR'S NAME: OXY USA INCORPORATED

LEASE NO.: NMNM128362

LOCATION: Section 17, T.22S S., R.32 E., NMP

COUNTY: LEA County, New Mexico

WELL NAME & NO.: DR AWKWARD 17-8 FEDERAL COM / 21H
SURFACE HOLE FOOTAGE: 530'/S & 1075'/W
BOTTOM HOLE FOOTAGE 20'/N & 440'/W

WELL NAME & NO.: DR AWKWARD 17-8 FEDERAL COM / 22H
SURFACE HOLE FOOTAGE: 530'/S & 1110'/W
BOTTOM HOLE FOOTAGE 20'/N & 1260'/W

WELL NAME & NO.: DR. AWKWARD 17-8 FEDERAL COM / 23H
SURFACE HOLE FOOTAGE: 275'/S & 1535'/E
BOTTOM HOLE FOOTAGE 20'/N & 1000'/E

WELL NAME & NO.: DR. AWKWARD 17-8 FEDERAL COM 24H SURFACE HOLE FOOTAGE: 325'/S & 1022'/W

BOTTOM HOLE FOOTAGE: 32578 & 10227W BOTTOM HOLE FOOTAGE 20'/N & 2178'/W

WELL NAME & NO.: DR. AWKWARD 17-8 FEDERAL COM 25H
SURFACE HOLE FOOTAGE: 455'/S & 1565'/E
BOTTOM HOLE FOOTAGE 20'/N & 1260'/E

WELL NAME & NO.: DR. AWKWARD 17-8 FEDERAL COM 26H
SURFACE HOLE FOOTAGE: 455'/S & 1530'/E
BOTTOM HOLE FOOTAGE 20'/N & 330'/E

COA

H2S	© Yes	No	
Potash	○ None	Secretary	C R-111-P
Cave/Karst Potential	• Low	○ Medium	் High
Cave/Karst Potential	Critical		
Variance	© None	Flex Hose	Other
Wellhead	© Conventional	[©] Multibowl	• Both
Other	☐4 String Area	Capitan Reef	WIPP
Other	Fluid Filled	Cement Squeeze	Pilot Hole
Special Requirements	Water Disposal	▼ COM	Unit

A. HYDROGEN SULFIDE

Hydrogen Sulfide (H2S) monitors shall be installed prior to drilling out the surface shoe. If H2S is detected in concentrations greater than 100 ppm, the Hydrogen Sulfide area shall meet Onshore Order 6 requirements, which includes equipment and personnel/public protection items. If Hydrogen Sulfide is encountered, provide measured values and formations to the BLM.

B. CASING

Casing Design:

- 1. The 13-3/8 inch surface casing shall be set at approximately 941 feet (a minimum of 25 feet (Lea County) into the Rustler Anhydrite and above the salt) and cemented to the surface.
 - a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run to verify the top of the cement. Temperature survey will be run a minimum of six hours after pumping cement and ideally between 8-10 hours after completing the cement job.
 - b. Wait on cement (WOC) time for a primary cement job will be a minimum of **24 hours in the Potash Area** or 500 pounds compressive strength, whichever is greater. (This is to include the lead cement)
 - c. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
 - d. If cement falls back, remedial cementing will be done prior to drilling out that string.

Intermediate casing must be kept fluid filled to meet BLM minimum collapse requirement.

2. The 9-5/8 inch surface casing shall be set at approximately 4700 feet. The minimum required fill of cement behind the 9-5/8 inch intermediate casing is:

Option 1 (Single Stage):

• Cement to surface. If cement does not circulate see B.1.a, c-d above. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to cave/karst or potash.

Option 2:

Operator has proposed a DV tool, the depth may be adjusted as long as the cement is changed proportionally. The DV tool may be cancelled if cement circulates to surface on the first stage.

- a. First stage to DV tool: Cement to circulate. If cement does not circulate off the DV tool, contact the appropriate BLM office before proceeding with second stage cement job.
- b. Second stage above DV tool:
 - Cement to surface. If cement does not circulate, contact the appropriate BLM office.
 - Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to cave/karst or potash.
- ❖ In <u>Secretary Potash Areas</u> if cement does not circulate to surface on the first two casing strings, the cement on the 3rd casing string must come to surface.
- 3. The minimum required fill of cement behind the 5-1/2 inch production casing is:

Option 1 (Single Stage):

• Cement should tie-back at least **500 feet** into previous casing string. Operator shall provide method of verification.

Option 2:

Operator has proposed a DV tool, the depth may be adjusted as long as the cement is changed proportionally. The DV tool may be cancelled if cement circulates to surface on the first stage.

- a. First stage to DV tool: Cement to circulate. If cement does not circulate off the DV tool, contact the appropriate BLM office before proceeding with second stage cement job.
- b. Second stage above DV tool:
 - Cement should tie-back at least **500 feet** into previous casing string. Operator shall provide method of verification.

C. PRESSURE CONTROL

1. Variance approved to use flex line from BOP to choke manifold. Manufacturer's specification to be readily available. No external damage to flex line. Flex line to be installed as straight as possible (no hard bends).'

2.

Option 1:

- a. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be **3000 (3M)** psi.
- b. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the intermediate casing shoe shall be **5000 (5M)** psi.

Option 2:

- 1. Operator has proposed a multi-bowl wellhead assembly. This assembly will only be tested when installed on the surface casing. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be **5000 (5M)** psi.
 - a. Wellhead shall be installed by manufacturer's representatives, submit documentation with subsequent sundry.
 - b. If the welding is performed by a third party, the manufacturer's representative shall monitor the temperature to verify that it does not exceed the maximum temperature of the seal.
 - c. Manufacturer representative shall install the test plug for the initial BOP test.
 - d. If the cement does not circulate and one inch operations would have been possible with a standard wellhead, the well head shall be cut off, cementing operations performed and another wellhead installed.
 - e. Whenever any seal subject to test pressure is broken, all the tests in OOGO2.III.A.2.i must be followed.

D. SPECIAL REQUIREMENT (S)

Communitization Agreement

- The operator will submit a Communitization Agreement to the Santa Fe Office, 301 Dinosaur Trail Santa Fe, New Mexico 87508, at least 90 days before the anticipated date of first production from a well subject to a spacing order issued by the New Mexico Oil Conservation Division. The Communitization Agreement will include the signatures of all working interest owners in all Federal and Indian leases subject to the Communitization Agreement (i.e., operating rights owners and lessees of record), or certification that the operator has obtained the written signatures of all such owners and will make those signatures available to the BLM immediately upon request.
- If the operator does not comply with this condition of approval, the BLM may take enforcement actions that include, but are not limited to, those specified in 43 CFR 3163.1.

• In addition, the well sign shall include the surface and bottom hole lease numbers. When the Communitization Agreement number is known, it shall also be on the sign.

Offline Cementing

• Contact the BLM prior to the commencement of any offline cementing procedure.

GENERAL REQUIREMENTS

The BLM is to be notified in advance for a representative to witness:

- a. Spudding well (minimum of 24 hours)
- b. Setting and/or Cementing of all casing strings (minimum of 4 hours)
- c. BOPE tests (minimum of 4 hours)
 - ☑ Eddy CountyCall the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (575) 361-2822
 - Lea County
 Call the Hobbs Field Station, 414 West Taylor, Hobbs NM 88240, (575)
 393-3612
- 1. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.
 - a. In the event the operator has proposed to drill multiple wells utilizing a skid/walking rig. Operator shall secure the wellbore on the current well, after installing and testing the wellhead, by installing a blind flange of like pressure rating to the wellhead and a pressure gauge that can be monitored while drilling is performed on the other well(s).
 - b. When the operator proposes to set surface casing with Spudder Rig
 - Notify the BLM when moving in and removing the Spudder Rig.
 - Notify the BLM when moving in the 2nd Rig. Rig to be moved in within 90 days of notification that Spudder Rig has left the location.
 - BOP/BOPE test to be conducted per Onshore Oil and Gas Order No. 2 as soon as 2nd Rig is rigged up on well.
- 2. Floor controls are required for 3M or Greater systems. These controls will be on the rig floor, unobstructed, readily accessible to the driller and will be operational at all times during drilling and/or completion activities. Rig floor is defined as the area immediately around the rotary table; the area immediately above the substructure on which the draw works are located, this does not include the dog house or stairway area.
- 3. The record of the drilling rate along with the GR/N well log run from TD to surface (horizontal well vertical portion of hole) shall be submitted to the BLM office as well as all other logs run on the borehole 30 days from completion. If available, a digital copy of the logs is to be submitted in addition to the paper copies. The Rustler top and top and bottom of Salt are to be recorded on the Completion Report.

Page 6 of 10

A. CASING

- 1. Changes to the approved APD casing program need prior approval if the items substituted are of lesser grade or different casing size or are Non-API. The Operator can exchange the components of the proposal with that of superior strength (i.e. changing from J-55 to N-80, or from 36# to 40#). Changes to the approved cement program need prior approval if the altered cement plan has less volume or strength or if the changes are substantial (i.e. Multistage tool, ECP, etc.). The initial wellhead installed on the well will remain on the well with spools used as needed.
- 2. Wait on cement (WOC) for Potash Areas: After cementing but before commencing any tests, the casing string shall stand cemented under pressure until both of the following conditions have been met: 1) cement reaches a minimum compressive strength of 500 psi for all cement blends, 2) until cement has been in place at least 24 hours. WOC time will be recorded in the driller's log. The casing intergrity test can be done (prior to the cement setting up) immediately after bumping the plug.
- 3. Wait on cement (WOC) for Water Basin: After cementing but before commencing any tests, the casing string shall stand cemented under pressure until both of the following conditions have been met: 1) cement reaches a minimum compressive strength of 500 psi at the shoe, 2) until cement has been in place at least 8 hours. WOC time will be recorded in the driller's log. See individual casing strings for details regarding lead cement slurry requirements. The casing intergrity test can be done (prior to the cement setting up) immediately after bumping the plug.
- 4. Provide compressive strengths including hours to reach required 500 pounds compressive strength prior to cementing each casing string. Have well specific cement details onsite prior to pumping the cement for each casing string.
- 5. No pea gravel permitted for remedial or fall back remedial without prior authorization from the BLM engineer.
- 6. On that portion of any well approved for a 5M BOPE system or greater, a pressure integrity test of each casing shoe shall be performed. Formation at the shoe shall be tested to a minimum of the mud weight equivalent anticipated to control the formation pressure to the next casing depth or at total depth of the well. This test shall be performed before drilling more than 20 feet of new hole.
- 7. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.
- 8. Whenever a casing string is cemented in the R-111-P potash area, the NMOCD requirements shall be followed.

B. PRESSURE CONTROL

- 1. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 2. If a variance is approved for a flexible hose to be installed from the BOP to the choke manifold, the following requirements apply: The flex line must meet the requirements of API 16C. Check condition of flexible line from BOP to choke manifold, replace if exterior is damaged or if line fails test. Line to be as straight as possible with no hard bends and is to be anchored according to Manufacturer's requirements. The flexible hose can be exchanged with a hose of equal size and equal or greater pressure rating. Anchor requirements, specification sheet and hydrostatic pressure test certification matching the hose in service, to be onsite for review. These documents shall be posted in the company man's trailer and on the rig floor.
- 3. 5M or higher system requires an HCR valve, remote kill line and annular to match. The remote kill line is to be installed prior to testing the system and tested to stack pressure.
- 4. If the operator has proposed a multi-bowl wellhead assembly in the APD. The following requirements must be met:
 - a. Wellhead shall be installed by manufacturer's representatives, submit documentation with subsequent sundry.
 - b. If the welding is performed by a third party, the manufacturer's representative shall monitor the temperature to verify that it does not exceed the maximum temperature of the seal.
 - c. Manufacturer representative shall install the test plug for the initial BOP test.
 - d. Whenever any seal subject to test pressure is broken, all the tests in OOGO2.III.A.2.i must be followed.
 - e. If the cement does not circulate and one inch operations would have been possible with a standard wellhead, the well head shall be cut off, cementing operations performed and another wellhead installed.
- 5. The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
 - a. In a water basin, for all casing strings utilizing slips, these are to be set as soon as the crew and rig are ready and any fallback cement remediation has been done. The casing cut-off and BOP installation can be initiated four hours after installing the slips, which will be approximately six hours after bumping the plug. For those casing strings not using slips, the minimum wait time before cut-off is eight hours after bumping the plug. BOP/BOPE testing can begin after cut-off or once cement reaches 500 psi compressive strength (including

- lead when specified), whichever is greater. However, if the float does not hold, cut-off cannot be initiated until cement reaches 500 psi compressive strength (including lead when specified).
- b. In potash areas, for all casing strings utilizing slips, these are to be set as soon as the crew and rig are ready and any fallback cement remediation has been done. For all casing strings, casing cut-off and BOP installation can be initiated at twelve hours after bumping the plug. However, **no tests** shall commence until the cement has had a minimum of 24 hours setup time, except the casing pressure test can be initiated immediately after bumping the plug (only applies to single stage cement jobs).
- c. The tests shall be done by an independent service company utilizing a test plug not a cup or J-packer. The operator also has the option of utilizing an independent tester to test without a plug (i.e. against the casing) pursuant to Onshore Order 2 with the pressure not to exceed 70% of the burst rating for the casing. Any test against the casing must meet the WOC time for water basin (8 hours) or potash (24 hours) or 500 pounds compressive strength, whichever is greater, prior to initiating the test (see casing segment as lead cement may be critical item).
- d. The test shall be run on a 5000 psi chart for a 2-3M BOP/BOP, on a 10000 psi chart for a 5M BOP/BOPE and on a 15000 psi chart for a 10M BOP/BOPE. If a linear chart is used, it shall be a one hour chart. A circular chart shall have a maximum 2 hour clock. If a twelve hour or twenty-four hour chart is used, tester shall make a notation that it is run with a two hour clock.
- e. The results of the test shall be reported to the appropriate BLM office.
- f. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
- g. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug. This test shall be performed prior to the test at full stack pressure.
- h. BOP/BOPE must be tested by an independent service company within 500 feet of the top of the Wolfcamp formation if the time between the setting of the intermediate casing and reaching this depth exceeds 20 days. This test does not exclude the test prior to drilling out the casing shoe as per Onshore Order No. 2.

C. DRILLING MUD

Mud system monitoring equipment, with derrick floor indicators and visual and audio alarms, shall be operating before drilling into the Wolfcamp formation, and shall be used until production casing is run and cemented.

D. WASTE MATERIAL AND FLUIDS

All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of drilling operations and completion operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area.

Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.

NMK12082020




Permian Drilling Hydrogen Sulfide Drilling Operations Plan Dr Awkward 17_8 Fed Com 23H

Open drill site. No homes or buildings are near the proposed location.

1. Escape

Personnel shall escape upwind of wellbore in the event of an emergency gas release. Escape can take place through the lease road on the Southeast side of the location. Personnel need to move to a safe distance and block the entrance to location. If the primary route is not an option due to the wind direction, then a secondary egress route should be taken.





Permian Drilling Hydrogen Sulfide Drilling Operations Plan New Mexico

Scope

This contingency plan establishes guidelines for the public, all company employees, and contract employees who's work activities may involve exposure to hydrogen sulfide (H2S) gas.

While drilling this well, it is possible to encounter H2S bearing formations. At all times, the first barrier to control H2S emissions will be the drilling fluid, which will have a density high enough to control influx.

Objective

- 1. Provide an immediate and predetermined response plan to any condition when H2S is detected. All H2S detections in excess of 10 parts per million (ppm) concentration are considered an Emergency.
- 2. Prevent any and all accidents, and prevent the uncontrolled release of hydrogen sulfide into the atmosphere.
- 3. Provide proper evacuation procedures to cope with emergencies.
- 4. Provide immediate and adequate medical attention should an injury occur.

Discussion

Implementation: This plan with all details is to be fully implemented

before drilling to commence.

Emergency response

Procedure:

This section outlines the conditions and denotes steps

to be taken in the event of an emergency.

Emergency equipment

Procedure:

This section outlines the safety and emergency

equipment that will be required for the drilling of this

well.

Training provisions: This section outlines the training provisions that must

be adhered to prior to drilling.

Drilling emergency call lists: Included are the telephone numbers of all persons to

be contacted should an emergency exist.

Briefing: This section deals with the briefing of all people

involved in the drilling operation.

Public safety: Public safety personnel will be made aware of any

potential evacuation and any additional support

needed.

Check lists: Status check lists and procedural check lists have been

included to insure adherence to the plan.

General information: A general information section has been included to

supply support information.

Hydrogen Sulfide Training

All personnel, whether regularly assigned, contracted, or employed on an unscheduled basis, will receive training from a qualified instructor in the following areas prior to commencing drilling operations on the well:

- 1. The hazards and characteristics of H2S.
- 2. Proper use and maintenance of personal protective equipment and life support systems.
- 3. H2S detection.
- 4. Proper use of H2S detectors, alarms, warning systems, briefing areas, evacuation procedures and prevailing winds.
- 5. Proper techniques for first aid and rescue procedures.
- 6. Physical effects of hydrogen sulfide on the human body.
- 7. Toxicity of hydrogen sulfide and sulfur dioxide.
- 8. Use of SCBA and supplied air equipment.
- 9. First aid and artificial respiration.
- 10. Emergency rescue.

In addition, supervisory personnel will be trained in the following areas:

- 1. The effects of H2S on metal components. If high tensile strength tubular is to be used, personnel will be trained in their special maintenance requirements.
- 2. Corrective action and shut-in procedures when drilling a well, blowout prevention and well control procedures.
- 3. The contents and requirements of the H2S Drilling Operations Plan.

H2S training refresher must have been taken within one year prior to drilling the well. Specifics on the well to be drilled will be discussed during the pre-spud meeting. H2S and well control (choke) drills will be performed while drilling the well, at least on a weekly basis. This plan shall be available in the well site. All personnel will be required to carry the documentation proving that the H2S training has been taken.

Service company and visiting personnel

- A. Each service company that will be on this well will be notified if the zone contains H2S.
- B. Each service company must provide for the training and equipment of their employees before they arrive at the well site.
- C. Each service company will be expected to attend a well site briefing

Emergency Equipment Requirements

1. Well control equipment

The well shall have hydraulic BOP equipment for the anticipated pressures. Equipment is to be tested on installation and follow Oxy Well Control standard, as well as BLM Onshore Order #2.

Special control equipment:

- A. Hydraulic BOP equipment with remote control on ground. Remotely operated choke.
- B. Rotating head
- C. Gas buster equipment shall be installed before drilling out of surface pipe.

2. <u>Protective equipment for personnel</u>

- A. Four (4) 30-minute positive pressure air packs (2 at each briefing area) on location.
- B. Adequate fire extinguishers shall be located at strategic locations.
- C. Radio / cell telephone communication will be available at the rig.
 - Rig floor and trailers.
 - Vehicle.

3. Hydrogen sulfide sensors and alarms

- A. H2S sensor with alarms will be located on the rig floor, at the bell nipple, and at the flow line. These monitors will be set to alarm at 10 ppm with strobe light, and audible alarm.
- B. Hand operated detectors with tubes.
- C. H2S monitor tester (to be provided by contract Safety Company.)
- D. There shall be one combustible gas detector on location at all times.

4. <u>Visual Warning Systems</u>

A. One sign located at each location entrance with the following language:

Caution – potential poison gas Hydrogen sulfide No admittance without authorization

Wind sock – wind streamers:

- A. One 36" (in length) wind sock located at protection center, at height visible from rig floor.
- B. One 36" (in length) wind sock located at height visible from pit areas.

Condition flags

A. One each condition flag to be displayed to denote conditions.

```
green – normal conditions
yellow – potential danger
red – danger, H2S present
```

B. Condition flag shall be posted at each location sign entrance.

5. <u>Mud Program</u>

The mud program is designed to minimize the risk of having H2S and other formation fluids at surface. Proper mud weight and safe drilling practices will be applied. H2S scavengers will be used to minimize the hazards while drilling. Below is a summary of the drilling program.

Mud inspection devices:

Garrett gas train or hatch tester for inspection of sulfide concentration in mud system.

6. <u>Metallurgy</u>

- A. Drill string, casing, tubing, wellhead, blowout preventers, drilling spools or adapters, kill lines, choke manifold, lines and valves shall be suitable for the H2S service.
- B. All the elastomers, packing, seals and ring gaskets shall be suitable for H2S service.

7. Well Testing

No drill stem test will be performed on this well.

8. Evacuation plan

Evacuation routes should be established prior to well spud for each well and discussed with all rig personnel.

9. <u>Designated area</u>

- A. Parking and visitor area: all vehicles are to be parked at a predetermined safe distance from the wellhead.
- B. There will be a designated smoking area.
- C. Two briefing areas on either side of the location at the maximum allowable distance from the well bore so they offset prevailing winds perpendicularly, or at a 45-degree angle if wind direction tends to shift in the area.

Emergency procedures

- A. In the event of any evidence of H2S level above 10 ppm, take the following steps:
 - 1. The Driller will pick up off bottom, shut down the pumps, slow down the pipe rotation.
 - 2. Secure and don escape breathing equipment, report to the upwind designated safe briefing / muster area.
 - 3. All personnel on location will be accounted for and emergency search should begin for any missing, the Buddy System will be implemented.
 - 4. Order non-essential personnel to leave the well site, order all essential personnel out of the danger zone and upwind to the nearest designated safe briefing / muster area.
 - 5. Entrance to the location will be secured to a higher level than our usual "Meet and Greet" requirement, and the proper condition flag will be displayed at the entrance to the location.
 - 6. Take steps to determine if the H2S level can be corrected or suppressed and, if so, proceed as required.

B. If uncontrollable conditions occur:

1. Take steps to protect and/or remove any public in the down-wind area from the rig – partial evacuation and isolation. Notify necessary public safety personnel and appropriate regulatory entities (i.e. BLM) of the situation.

- 2. Remove all personnel to the nearest upwind designated safe briefing / muster area or off location.
- 3. Notify public safety personnel of safe briefing / muster area.
- 4. An assigned crew member will blockade the entrance to the location. No unauthorized personnel will be allowed entry to the location.
- 5. Proceed with best plan (at the time) to regain control of the well. Maintain tight security and safety procedures.

C. Responsibility:

- 1. Designated personnel.
 - a. Shall be responsible for the total implementation of this plan.
 - b. Shall be in complete command during any emergency.
 - c. Shall designate a back-up.

4 11		
A 11	narconna	٠
Δ III	personne	L.

- 1. On alarm, don escape unit and report to the nearest upwind designated safe briefing / muster area upw
- 2. Check status of personnel (buddy system).
- 3. Secure breathing equipment.
- 4. Await orders from supervisor.

Drill site manager:

- 1. Don escape unit if necessary and report to nearest upwind designated safe briefing / muster area.
- 2. Coordinate preparations of individuals to return to point of release with tool pusher and driller (using the buddy system).
- 3. Determine H2S concentrations.
- 4. Assess situation and take control measures.

Tool pusher:

- 1. Don escape unit Report to up nearest upwind designated safe briefing / muster area.
- 2. Coordinate preparation of individuals to return to point of release with tool pusher drill site manager (using the buddy system).
- 3. Determine H2S concentration.
- 4. Assess situation and take control measures.

Driller:

1. Don escape unit, shut down pumps, continue

- rotating DP.
- 2. Check monitor for point of release.
- 3. Report to nearest upwind designated safe briefing / muster area.
- 4. Check status of personnel (in an attempt to rescue, use the buddy system).
- 5. Assigns least essential person to notify Drill Site Manager and tool pusher by quickest means in case of their absence.
- 6. Assumes the responsibilities of the Drill Site Manager and tool pusher until they arrive should they be absent.

Derrick man Floor man #1 Floor man #2 1. Will remain in briefing / muster area until instructed by supervisor.

Mud engineer:

- 1. Report to nearest upwind designated safe briefing / muster area.
- 2. When instructed, begin check of mud for ph and H2S level. (Garett gas train.)

Safety personnel:

1. Mask up and check status of all personnel and secure operations as instructed by drill site manager.

Taking a kick

When taking a kick during an H2S emergency, all personnel will follow standard Well control procedures after reporting to briefing area and masking up.

Open-hole logging

All unnecessary personnel off floor. Drill Site Manager and safety personnel should monitor condition, advise status and determine need for use of air equipment.

Running casing or plugging

Following the same "tripping" procedure as above. Drill Site Manager and safety personnel should determine if all personnel have access to protective equipment.

Ignition procedures

The decision to ignite the well is the responsibility of the operator (Oxy Drilling Management). The decision should be made only as a last resort and in a situation where it is clear that:

- 1. Human life and property are endangered.
- 2. There is no hope controlling the blowout under the prevailing conditions at the well.

Instructions for igniting the well

- 1. Two people are required for the actual igniting operation. They must wear self-contained breathing units and have a safety rope attached. One man (tool pusher or safety engineer) will check the atmosphere for explosive gases with the gas monitor. The other man is responsible for igniting the well.
- 2. Primary method to ignite: 25 mm flare gun with range of approximately 500 feet.
- 3. Ignite upwind and do not approach any closer than is warranted.
- 4. Select the ignition site best for protection, and which offers an easy escape route.
- 5. Before firing, check for presence of combustible gas.
- 6. After lighting, continue emergency action and procedure as before.
- 7. All unassigned personnel will remain in briefing area until instructed by supervisor or directed by the Drill Site Manager.

Remember: After well is ignited, burning hydrogen sulfide will convert to sulfur dioxide, which is also highly toxic. **Do not assume the area is safe after the well is ignited.**

Status check list

Note: All items on this list must be completed before drilling to production casing point.

- 1. H2S sign at location entrance.
- 2. Two (2) wind socks located as required.
- 3. Four (4) 30-minute positive pressure air packs (2 at each Briefing area) on location for all rig personnel and mud loggers.
- 4. Air packs inspected and ready for use.
- 5. Cascade system and hose line hook-up as needed.
- 6. Cascade system for refilling air bottles as needed.
- 7. Condition flag on location and ready for use.
- 8. H2S detection system hooked up and tested.
- 9. H2S alarm system hooked up and tested.
- 10. Hand operated H2S detector with tubes on location.
- 11. 1 100' length of nylon rope on location.
- 12. All rig crew and supervisors trained as required.
- 13. All outside service contractors advised of potential H2S hazard on well.
- 14. No smoking sign posted and a designated smoking area identified.
- 15. Calibration of all H2S equipment shall be noted on the IADC report.

Checked by:	Date:	

Procedural check list during H2S events

Perform each tour:

- 1. Check fire extinguishers to see that they have the proper charge.
- 2. Check breathing equipment to ensure that it in proper working order.
- 3. Make sure all the H2S detection system is operative.

Perform each week:

- 1. Check each piece of breathing equipment to make sure that demand or forced air regulator is working. This requires that the bottle be opened and the mask assembly be put on tight enough so that when you inhale, you receive air or feel air flow.
- 2. BOP skills (well control drills).
- 3. Check supply pressure on BOP accumulator stand by source.
- 4. Check breathing equipment mask assembly to see that straps are loosened and turned back, ready to put on.
- 5. Check pressure on breathing equipment air bottles to make sure they are charged to full volume. (Air quality checked for proper air grade "D" before bringing to location)
- 6. Confirm pressure on all supply air bottles.
- 7. Perform breathing equipment drills with on-site personnel.
- 8. Check the following supplies for availability.
 - A. Emergency telephone list.
 - B. Hand operated H2S detectors and tubes.

General evacuation plan

- 1. When the company approved supervisor (Drill Site Manager, consultant, rig pusher, or driller) determines the H2S gas cannot be limited to the well location and the public will be involved, he will activate the evacuation plan.
- 2. Drill Site Manager or designee will notify local government agency that a hazardous condition exists and evacuation needs to be implemented.
- 3. Company or contractor safety personnel that have been trained in the use of H2S detection equipment and self-contained breathing equipment will monitor H2S concentrations, wind directions, and area of exposure. They will delineate the outer perimeter of the hazardous gas area. Extension to the evacuation area will be determined from information gathered.
- 4. Law enforcement personnel (state police, police dept., fire dept., and sheriff's dept.) Will be called to aid in setting up and maintaining road blocks. Also, they will aid in evacuation of the public if necessary.
- 5. After the discharge of gas has been controlled, company safety personnel will determine when the area is safe for re-entry.

<u>Important:</u> Law enforcement personnel will not be asked to come into a contaminated area. Their assistance will be limited to uncontaminated areas. Constant radio contact will be maintained with them.

Emergency actions

Well blowout – if emergency

- 1. Evacuate all personnel to "Safe Briefing / Muster Areas" or off location if needed.
- 2. If sour gas evacuate rig personnel.
- 3. If sour gas evacuate public within 3000 ft radius of exposure.
- 4. Don SCBA and shut well in if possible using the buddy system.
- 5. Notify Drilling Superintendent and call 911 for emergency help (fire dept and ambulance) if needed.
- 6. Implement the Blowout Contingency Plan, and Drilling Emergency Action Plan.
- 6. Give first aid as needed.

Person down location/facility

- 1. If immediately possible, contact 911. Give location and wait for confirmation.
- 2. Don SCBA and perform rescue operation using buddy system.

Toxic effects of hydrogen sulfide

Hydrogen sulfide is extremely toxic. The acceptable ceiling concentration for eight-hour exposure is 10 ppm, which is .001% by volume. Hydrogen sulfide is heavier than air (specific gravity – 1.192) and colorless. It forms an explosive mixture with air between 4.3 and 46.0 percent by volume. Hydrogen sulfide is almost as toxic as hydrogen cyanide and is between five and six times more toxic than carbon monoxide. Toxicity data for hydrogen sulfide and various other gases are compared in table i. Physical effects at various hydrogen sulfide exposure levels are shown in table ii.

Table i Toxicity of various gases

Common name	Chemical formula	Specific gravity (sc=1)	Threshold limit (1)	Hazardous limit (2)	Lethal concentration (3)
Hydrogen Cyanide	Hen	0.94	10 ppm	150 ppm/hr	300 ppm
Hydrogen Sulfide	H2S	1.18	10 ppm	250 ppm/hr	600 ppm
Sulfur Dioxide	So2	2.21	5 ppm	-	1000 ppm
Chlorine	C12	2.45	1 ppm	4 ppm/hr	1000 ppm
Carbon Monoxide	Co	0.97	50 ppm	400 ppm/hr	1000 ppm
Carbon Dioxide	Co2	1.52	5000 ppm	5%	10%
Methane	Ch4	0.55	90,000 ppm	Combustibl	e above 5% in air

- 1) threshold limit concentration at which it is believed that all workers may be repeatedly exposed day after day without adverse effects.
- 2) hazardous limit concentration that will cause death with short-term exposure.
- 3) lethal concentration concentration that will cause death with short-term exposure.

Toxic effects of hydrogen sulfide

Table ii Physical effects of hydrogen sulfide

		Concentration	Physical effects
Percent (%)	<u>Ppm</u>	Grains	
	_	100 std. Ft3*	
0.001	<10	00.65	Obvious and unpleasant odor.

0.002	10	01.30	Safe for 8 hours of exposure.
0.010	100	06.48	Kill smell in $3 - 15$ minutes. May sting eyes and throat.
0.020	200	12.96	Kills smell shortly; stings eyes and throat.
0.050	500	32.96	Dizziness; breathing ceases in a few minutes; needs prompt artificial respiration.
0.070	700	45.36	Unconscious quickly; death will result if not rescued promptly.
0.100	1000	64.30	Unconscious at once; followed by death within minutes.

^{*}at 15.00 psia and 60'f.

Use of self-contained breathing equipment (SCBA)

- 1. Written procedures shall be prepared covering safe use of SCBA's in dangerous atmosphere, which might be encountered in normal operations or in emergencies. Personnel shall be familiar with these procedures and the available SCBA.
- 2 SCBA's shall be inspected frequently at random to insure that they are properly used, cleaned, and maintained.
- 3. Anyone who may use the SCBA's shall be trained in how to insure proper facepiece to face seal. They shall wear SCBA's in normal air and then wear them in a
 test atmosphere. (note: such items as facial hair {beard or sideburns} and
 eyeglasses will not allow proper seal.) Anyone that may be reasonably expected
 to wear SCBA's should have these items removed before entering a toxic
 atmosphere. A special mask must be obtained for anyone who must wear
 eyeglasses or contact lenses.
- 4. Maintenance and care of SCBA's:
 - a. A program for maintenance and care of SCBA's shall include the following:
 - 1. Inspection for defects, including leak checks.
 - 2. Cleaning and disinfecting.
 - 3. Repair.
 - 4. Storage.
 - b. Inspection, self-contained breathing apparatus for emergency use shall be inspected monthly.
 - 1. Fully charged cylinders.
 - 2. Regulator and warning device operation.
 - 3. Condition of face piece and connections.
 - 4. Rubber parts shall be maintained to keep them pliable and prevent deterioration.
 - c. Routinely used SCBA's shall be collected, cleaned and disinfected as frequently as necessary to insure proper protection is provided.
- 5. Persons assigned tasks that requires use of self-contained breathing equipment shall be certified physically fit (medically cleared) for breathing equipment usage at least annually.
- 6. SCBA's should be worn when:
 - A. Any employee works near the top or on top of any tank unless test reveals less than 10 ppm of H2S.

- B. When breaking out any line where H2S can reasonably be expected.
- C. When sampling air in areas to determine if toxic concentrations of H2S exists.
- D. When working in areas where over 10 ppm H2S has been detected.
- E. At any time there is a doubt as to the H2S level in the area to be entered.

Rescue First aid for H2S poisoning

Do not panic!

Remain calm – think!

- 1. Don SCBA breathing equipment.
- 2. Remove victim(s) utilizing buddy system to fresh air as quickly as possible. (go up-wind from source or at right angle to the wind. Not down wind.)
- 3. Briefly apply chest pressure arm lift method of artificial respiration to clean the victim's lungs and to avoid inhaling any toxic gas directly from the victim's lungs.
- 4. Provide for prompt transportation to the hospital, and continue giving artificial respiration if needed.
- 5. Hospital(s) or medical facilities need to be informed, before-hand, of the possibility of H2S gas poisoning no matter how remote the possibility is.
- 6. Notify emergency room personnel that the victim(s) has been exposed to H2S gas.

Besides basic first aid, everyone on location should have a good working knowledge of artificial respiration.

Revised CM 6/27/2012


OXY Permian Crisis Team Hotline					
Person	Location	Office Phone	Cell/Mobile Phone	Home Phone	Pager Number
	1				_
Drilling & Completions Department					
Orilling & Completions Manager: John Willis	Houston	(713) 366-5556	(713) 259-1417		
Drilling Superintendent: Simon Benavides	Houston	(713) 215-7403	(832) 528-3547		
Completions Superintendent: Chris Winter	Houston	(713) 366-5212	(806) 239-8774		
Drilling Eng. Supervisor: Diego Tellez	Houston	(713) 350-4602	(713) 303-4932		
Orilling Eng. Supervisor: Randy Neel	Houston	(713) 215-7987	(713) 517-5544		
Completions Eng. Supervisor: Evan Hinkel	Houston	(713) 366-5436	(281) 236-6153		
Drilling & Completions HES Lead. Ryan Green	Houston	713-336-5753	281-520-5216		
Drilling & Completions HES Advisor:Kenny Williams	Carlsbad (432) 686-14	(432) 686-1434	(337) 208-0911		
Drilling & Completions HES Advisor:Kyle Holden	Carlsbad	(432) 686-1435	(661) 369-5328		
Drilling & Completions HES Advisor Sr:Dave Schmidt	Carlsbad		(559) 310-8572		
Drilling & Completions HES Advisor. :Seth Doyle	Carlsbad		(337) 499-0756		
HES / Enviromental & Regulatory Department	Location	Office	Cell Phone		
Jon Hamil-HES Manager	Houston	(713) 497-2494	(832) 537-9885		
Mark Birk-HES Manager	Houston	(713) 350-4615	(949) 413-3127		
Austin Tramell	Midland	(432) 699-4208	(575) 499-4919		
Rico Munoz	Midland	(432) 699-8366	(432) 803-4116		
Amber DuckWorth	Midland		(832) 966-1879		
Kelley Montgomery- Regulatory Manager	Houston	(713) 366-5716	(832) 454-8137		
Sandra Musallam -Regulatory Lead	Houston	+1 (713) 366-5106	+1 (713) 504-8577		
Bishop, Steve-DOT Pipeline Coordinator	Midland	432-685-5614			
Wilson, Dusty-Safety Advisor	Midland	432-685-5771	(432) 254-2336		
John W Dittrich Eniromental Advisor	Midland		(575) 390-2828		
William (Jack) Calhoun-Environmental Lead	Houston	+713 (350) 4906	(281) 917-8571		
Dahart Daman Dial Francisco Manage	Houston	(742) 200 F044	(832) 867-5336		
Robert Barrow-Risk Engineer Manager	Midland	(713) 366-5611	(632) 607-3330		
Sarah Holmes-HSE Cordinator		432-685-5758			
Administrative	Location	Office			
Sarah Holmes	Midland	432-685-5830	+ +		
Robertson, Debbie	Midland	432-685-5812	(400) 004 55 11		
_aci Hollaway	Midland	(432) 685-5716	(432) 631-6341		
Administrative	Location	Office			
Rosalinda Escajeda	Midland	432-685-5831			
Moreno, Leslie (contract)	Hobbs	575-397-8247	1		
Sehon, Angela (contractor)	Levelland	806-894-8347			
Vasquez, Claudia (contractor)	North Cowden	432-385-3120			
XstremeMD	Location	Office			
Medical Case Management	Orla, TX	(337) 205-9314			
Axiom Medical Consulting	Location	Office			
Medical Case Management		(877) 502-9466			
Regulatory Agencies					
Bureau of Land Management	Carlsbad, NM	(505) 887-6544			
Bureau of Land Management	Hobbs, NM	(505) 393-3612			
Bureau of Land Management	Roswell, NM	(505) 393-3612			
Bureau of Land Management	Santa Fe, NM	(505) 988-6030			

DOT Juisdictional Pipelines-Incident Reporting New		(505) 827-3549		
Mexico Public Regulaion Commission	Santa Fe, NM	(505) 490-2375		
DOT Juisdictional Pipelines-Incident Reporting Texas		(512) 462 6700		
Railroad Commission	Austin, TX	(512) 463-6788		
EPA Hot Line	Dallas, Texas	(214) 665-6444		
Federal OSHA, Area Office	Lubbock, Texas	(806) 472-7681		
National Response Center	Washington, D. C.	(800) 424-8802		
National Infrastructure Coordinator Center		(202) 282-9201		
New Mexico Air Quality Bureau	Santa Fe, NM	(505) 827-1494	After Hours (505) 370-	
New Mexico Oil Conservation Division	Artesia, NM	(505) 748-1283	7545	
New Mexico Oil Conservation Division	Hobbs, NM	(505) 393-6161		
New Mexico Oil Conservation Division	Santa Fe, NM	(505) 471-1068		
New Mexico OCD Environmental Bureau	Santa Fe, NM	(505) 476-3470		
New Mexico Environmental Department	Hobbs, NM	(505) 827-9329		
NM State Emergency Response Center	Santa Fe, NM	(505) 827-9222		
Railroad Commission of TX	District 1 San Antonio.	(210) 227-1313		
Railroad Commission of TX	District 7C San Angelo	(325) 657-7450		
Railroad Commission of TX	District 8, 8A Midland.	(432) 684-5581		
	1 1			
Texas Emergency Response Center TCEQ Air	Austin, TX	(512) 463-7727		
	Region 2 Lubbock, TX	(806) 796-3494		
TCEQ Water/Waste/Air	Region 3 Abilene, TX	(325) 698-9674		
TCEQ Water/Waste/Air	Region 7 Midland, TX	(432) 570-1359		
TCEQ Water/Waste/Air	Region 9 San Antonio,	(512) 734-7981		
TCEQ Water/Waste/Air	Region 8 San Angelo	(325) 655-9479		
Medical Facilities				
Abernathy Medical Clinic	Abernathy, TX	(806) 298-2524		
Alliance Hospital	Odessa, TX	(432) 550-1000		
Artesia General Hospital	Artesia, NM	(505) 748-3333		
Brownfield Regional Medical Center	Brownfield, TX	(806) 637-3551		
Cogdell Memorial Hospital	Snyder, TX	(325) 573-6374		
Covenant Hospital Levelland	Levelland, TX	(806) 894-4963		
Covenant Medical Center	Lubbock, TX	(806) 725-1011		
Covenant Medical Center Lakeside	Lubbock, TX	(806) 725-6000		
Covenant Family Health	Synder, TX	(325) 573-1300		
Crockett County Hospital	Ozona, TX	(325) 392-2671		
Guadalupe Medical Center	Carlsbad, NM	(505) 887-6633		
Lea Regional Hospital	Hobbs, NM	(505) 492-5000		
McCamey Hospital	McCamey, TX	(432) 652-8626		
Medical Arts Hospital	Lamesa, TX	(806) 872-2183		
Medical Center Hospital	Odessa, TX	(432) 640-4000		
Medi Center Hospital	San Angelo, TX	(325) 653-6741		
Memorial Hospital	Ft. Stockton	(432) 336-2241		
Memorial Hospital	Seminole, TX	(432) 758-5811		
Midland Memorial Hospital	Midland, TX	(432) 685-1111		
Nor-Lea General Hospital	Lovington, NM	(505) 396-6611		
Odessa Regional Hospital	Odessa, TX	(432) 334-8200		
Permian General Hospital	Andrews, TX	(432) 523-2200		
Reagan County Hospital	Big Lake, TX	(325) 884-2561		
Reeves County Hospital	Pecos, TX	(432) 447-3551		
Shannon Medical Center	San Angelo, TX	(325) 653-6741		
Union County General Hospital	Clayton, NM	(505) 374-2585		
University Medical Center	Lubbock, TX	(806) 725-8200		
Val Verde Regional Medical Center	Del Rio, TX	(830) 775-8566		
Ward Memorial Hospital	Monahans, TX	(432) 943-2511		
Yoakum County Hospital	Denver City, TX	(806) 592-5484		
1 oakam County 110spitai	Denver City, 1A	(000) 374-3404	l	

			1		1
Law Enforcement - Sheriff					
Andrews Cty Sheriff's Department	Andrews County(Andr	(432) 523-5545			
Crane Cty Sheriff's Department	Crane, County (Crane)	(432) 558-3571			
Crockett Cty Sheriff's Department	Crockett County (Ozon	(325) 392-2661			
Dawson Cty Sheriff's Department	Dawson County (Lame	(806) 872-7560			
Ector Cty Sheriff's Department	Ector County (Odessa)	(432) 335-3050			
Eddy Cty Sheriff's Department	Eddy County (Artesia)	(505) 746-2704			
Eddy Cty Sheriff's Department	Eddy County (Carlsbac	(505) 887-7551			
Gaines Cty Sheriff's Department	Gaines County (Semin	(432) 758-9871			
Hockley Cty Sheriff's Department	Hockley County(Levell	(806) 894-3126			
Kent Cty (Jayton City Sheriff's Dept.)	Kent County(Jayton)	(806) 237-3801			
Lea Cty Sheriff's Department	Lea County (Eunice)	(505) 384-2020			
Lea Cty Sheriff's Department	Lea County (Hobbs)	(505) 393-2515			
Lea Cty Sheriff's Department	Lea County (Lovington	(505) 396-3611			
Lubbock Cty Sheriff's Department	Lubbock Cty (Abernatl	(806) 296-2724			
Midland Cty Sheriffs Department	Midland County (Midla	(432) 688-1277			
Pecos Cty Sheriff's Department	Pecos County (Iraan)	(432) 639-2251			
Reeves Cty Sheriff's Department	Reeves County (Pecos)	(432) 445-4901			1
Scurry Cty Sheriff's Department	Scurry County (Snyder	(325) 573-3551			
Ferry Cty Sheriff's Department	Terry County (Brownfi	(806) 637-2212			
Union Cty Sheriff's Department	Union County (Clayton	(505) 374-2583			1
* *					
Upton Cty Sheriff's Department	Upton County (Rankin	(432) 693-2422			
Ward Cty Sheriff's Department	Ward County (Monaha	(432) 943-3254			
Yoakum City Sheriff's Department	Yoakum Co. (Denever	(806) 456-2377			
Law Enforcement - Police					
Abernathy City Police	Abernathy, TX	(806) 298-2545			
Andrews City Police	Andrews, TX	(432) 523-5675			
Artesia City Police	Artesia, NM	(505) 746-2704			
Brownfield City Police	Brownfield, TX	(806) 637-2544			
Carlsbad City Police	Carlsbad, NM	(505) 885-2111			
Clayton City Police	Clayton, NM	(505) 374-2504			
Denver City Police	Denver City, TX	(806) 592-3516			
Eunice City Police	Eunice, NM	(505) 394-2112			
Hobbs City Police	Hobbs, NM	393-2677			
al City Police	Jal, NM	(505) 395-2501			
Tayton City Police	Jayton, TX	(806) 237-3801			
Lamesa City Police	Lamesa, TX	(806) 872-2121			1
Levelland City Police	Levelland, TX	(806) 894-6164			1
Lovington City Police	Lovington, NM	(505) 396-2811			
Midland City Police	Midland, TX	(432) 685-7113			
	Monahans, TX				1
Monahans City Police		(432) 943-3254			1
Odessa City Police	Odessa, TX	(432) 335-3378			+
Seminole City Police	Seminole, TX	(432) 758-9871			1
Snyder City Police	Snyder, TX	(325) 573-2611			1
Sundown City Police	Sundown, TX	(806) 229-8241		-	
Law Enforcement - FBI					
FBI	Alburqueque, NM	(505) 224-2000			
FBI	Midland, TX	(432) 570-0255			
Law Enforcement - DPS					
NM State Police	Artesia, NM	(505) 746-2704			
NM State Police	Carlsbad, NM	(505) 885-3137			
				1	

			1	
NM State Police	Hobbs, NM	(505) 392-5588		
NM State Police	Clayton, NM	(505) 374-2473; 911		
TX Dept of Public Safety	Andrews, TX	(432) 524-1443		
TX Dept of Public Safety	Big Lake, TX	(325) 884-2301		
TX Dept of Public Safety	Brownfield, TX	(806) 637-2312		
TX Dept of Public Safety	Iraan, TX	(432) 639-3232		
TX Dept of Public Safety	Lamesa, TX	(806) 872-8675		
TX Dept of Public Safety	Levelland, TX	(806) 894-4385		
TX Dept of Public Safety	Lubbock, TX	(806) 747-4491		
TX Dept of Public Safety	Midland, TX	(432) 697-2211		
TX Dept of Public Safety	Monahans, TX	(432) 943-5857		
TX Dept of Public Safety	Odessa, TX	(432) 332-6100		
TX Dept of Public Safety	Ozona, TX	(325) 392-2621		
TX Dept of Public Safety	Pecos, TX	(432) 447-3533		
TX Dept of Public Safety	Seminole, TX	(432) 758-4041		
TX Dept of Public Safety	Snyder, TX	(325) 573-0113		
TX Dept of Public Safety	Terry County TX	(806) 637-8913		
TX Dept of Public Safety	Yoakum County TX	(806) 456-2377		
		, , , , , , , , , , , ,		
Firefighting & Rescue				
Abernathy	Abernathy, TX	(806) 298-2022		
Amistad/Rosebud	Amistad/Rosebud, NM			
Andrews	Andrews, TX	523-3111		
Artesia	Artesia, NM	(505) 746-5051		
Big Lake	Big Lake, TX	1 1		
Brownfield-Administrative & other calls		(325) 884-3650		
	Brownfield, TX	(816) 637-4547		
Brownfield emergency only	Brownfield, TX	-911		
Carlsbad	Carlsbad, NM	(505) 885-3125		
Clayton	Clayton, NM	(505) 374-2435		
Cotton Center	Cotton Center, TX	(806) 879-2157		
Crane	Crane, TX	(432) 558-2361		
Del Rio	Del Rio, TX	(830) 774-8650		
Denver City	Denver City, TX	(806) 592-3516		
Eldorado	Eldorado, TX	(325) 853-2691		
Eunice	Eunice, NM	(505) 394-2111		
Garden City	Garden City, TX	(432) 354-2404		
Goldsmith	Goldsmith, TX	(432) 827-3445		
Hale Center	Hale Center, TX	(806) 839-2411		
Halfway	Halfway, TX			
Hobbs	Hobbs, NM	(505) 397-9308		
Jal	Jal, NM	(505) 395-2221		
Jayton	Jayton, TX	(806) 237-3801		
Kermit	Kermit, TX	(432) 586-3468		
Lamesa	Lamesa, TX	(806) 872-4352		
Levelland	Levelland, TX	(806) 894-3154		
Lovington	Lovington, NM	(505) 396-2359		
Maljamar	Maljamar, NM	(505) 676-4100		
McCamey	McCamey, TX	(432) 652-8232		
Midland	Midland, TX	(432) 685-7346		
Monahans	Monahans, TX	(432) 943-4343		
Nara Visa	Nara Visa, NM	(505) 461-3300		
Notrees	Notress, TX	(432) 827-3445		
Odessa	Odessa, TX	(432) 335-4659		
Ozona	Ozona, TX	(325) 392-2626		
	IOZOHA, IA	(343) 374-4040	1	
		(432) 445 2421		
Pecos Petersburg	Pecos, TX Petersburg, TX	(432) 445-2421 (806) 667-3461		

Plains	Plains, TX	(806) 456-8067		
Plainview	Plainview, TX	(806) 296-1170		
Rankin	Rankin, TX	(432) 693-2252		
San Angelo	San Angelo, TX	(325) 657-4355		
Sanderson	Sanderson, TX	(432) 345-2525		
Seminole	Seminole, TX	758-9871		
Smyer	Smyer, TX	(806) 234-3861		
Snyder	Snyder, TX	(325) 573-6215		
Sundown	Sundown, TX	911		
Tucumcari	Tucumcari, NM	911		
West Odessa	Odessa, TX	(432) 381-3033		
Ambulance				
Abernathy Ambulance	Abernathy, TX	(806) 298-2241		
Amistad/Rosebud	Amistad/Rosebud, NM	(505) 633-9113		
Andrews Ambulance	Andrews, TX	(432) 523-5675		
Artesia Ambulance	Artesia, NM	(505) 746-2701		
Big Lake Ambulance	Big Lake, TX	(325) 884-2423		
Big Spring Ambulance	Big Spring, TX	(432) 264-2550		
Brownfield Ambulance	Brownfield, TX	(806) 637-2511		
Carlsbad Ambulance	Carlsbad, NM	(505) 885-2111; 911		
Clayton, NM	Clayton, NM	(505) 374-2501		
Denver City Ambulance	Denver City, TX	(806) 592-3516		
Eldorado Ambulance	Eldorado, TX	(325) 853-3456		
Eunice Ambulance	Eunice, NM	(505) 394-3258		
Goldsmith Ambulance	Goldsmith, TX	(432) 827-3445		
Hobbs, NM	Hobbs, NM	(505) 397-9308		
Jal, NM	Jal, NM	(505) 395-2501		
Jayton Ambulance	Jayton, TX	(806) 237-3801		
Lamesa Ambulance	Lamesa, TX	(806) 872-3464		
Levelland Ambulance	Levelland, TX	(806) 894-8855		
Lovington Ambulance	Lovington, NM	(505) 396-2811		
McCamey Hospital	McCamey, TX	(432) 652-8626		
Midland Ambulance	Midland, TX	(432) 685-7499		
Monahans Ambulance	Monahans, TX	3731		
Nara Visa, NM	Nara Visa, NM	(505) 461-3300		
Odessa Ambulance	Odessa, TX	(432) 335-3378		
Ozona Ambulance	Ozona, TX	(325) 392-2671		
Pecos Ambulance	Pecos, TX	(432) 445-4444		
Rankin Ambulance	Rankin, TX	(432) 693-2443		
San Angelo Ambulance	San Angelo, TX	(325) 657-4357		
Seminole Ambulance	Seminole, TX	758-9871		
Snyder Ambulance	Snyder, TX	(325) 573-1911		
Stanton Ambulance	Stanton, TX	(432) 756-2211		
Sundown Ambulance	Sundown, TX	911		
Tucumcari, NM	Tucumcari, NM	911		
Medical Air Ambulance Service				
AEROCARE - Methodist Hospital	Lubbock, TX	(800) 627-2376		
San Angelo Med-Vac Air Ambulance	San Angelo, TX	(800) 277-4354		
Southwest Air Ambulance Service	Stanford, TX	(800) 242-6199		
Southwest MediVac	Snyder, TX	(800) 242-6199		
Southwest MediVac	Hobbs, NM	(800) 242-6199		
Odessa Care Star	Odessa, TX	(888) 624-3571		
NWTH Medivac	Amarillo, TX	(800) 692-1331		



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone: (575) 748-1283 Fax: (575) 748-9720
District III
1000 Rio Brazos Road, Aztec, NM 87410
Phone: (505) 334-6178 Fax: (505) 334-6170
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505
Phone: (505) 476-3460 Fax: (505) 476-3462

State of New Mexico Energy, Minerals & Natural Resources Department OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-102 Revised August 1, 2011 Submit one copy to appropriate District Office

☐ AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT

	API Number		Pool Code	Pool Name	
30-025- 30-025-48947		97366 BILBREY BASIN; BONE SPRING, SOUT		I	
Property Code 329931		Prop	perty Name	Well Number	
			DR AWKWARD "17_	23H	
OGRID No.			Ope	rator Name	Elevation
16696 <i>OXY</i>		OXY U	ISA INC.	3689.7'	
			C	Location	


Surface Location

UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
М	17	22 SOUTH	32 EAST, N.M.P.M.		530'	SOUTH	1145'	WEST	LEA

Bottom Hole Location If Different From Surface

UL or lot no.	Section	Township	Range		Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County	
С	8	22 SOUTH	32 EAST, N.	М. Р. М.		20'	NORTH	2200'	WEST	LEA	
Dedicated	Acres	Joint or Infill	Consolidation Code	Order No.							
640											

No allowable will be assigned to this completion until all interests have been consolidated or a non-standard unit has been approved by the division.



Released to Imaging: 6/1/2021 2:37:09 PM⁵⁰

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy, Minerals and Natural Resources Department

Submit Original to Appropriate District Office

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

GAS CAPTURE PLAN

Date: 10/22/2019	
□ Original	Operator & OGRID No.: OXY USA INC 16696
☐ Amended - Reason for Amend	lment:
This Gas Capture Plan outlines a	ctions to be taken by the Operator to reduce well/production facility flaring/venting for
new completion (new drill, recom	plete to new zone, re-frac) activity.
Note: Form C-129 must be submitted of	and approved prior to exceeding 60 days allowed by Rule (Subsection A of 19.15.18.12 NMAC).

Well(s)/Production Facility - Name of facility

The well(s) that will be located at the production facility are shown in the table below.

Well Name	API	Well Location (ULSTR)	Footages	Expected MCF/D	Flared or Vented	Comments
Dr Awkward 17-8 Federal Com 21H	PENDING	M-17-22S-32E	530 FSL 1075 FWL	2375	0	
Dr Awkward 17-8 Federal Com 22H	PENDING	M-17-22S-32E	530 FSL 1110 FWL	2375	0	
Dr Awkward 17-8 Federal Com 23H 30	-025-48947	M-17-22S-32E	530 FSL 1145 FWL	2375	0	
Dr Awkward 17-8 Federal Com 24H	PENDING	O-17-22S-32E	455 FSL 1600 FEL	2375	0	
Dr Awkward 17-8 Federal Com 25H	PENDING	O-17-22S-32E	455 FSL 1565 FEL	2375	0	
Dr Awkward 17-8 Federal Com 26H	PENDING	O-17-22S-32E	455 FSL 1530 FEL	2375	0	
Dr Awkward 17-8 Federal Com 31H	PENDING	M-17-22S-32E	350 FSL 1075 FWL	3418	0	
Dr Awkward 17-8 Federal Com 32H	PENDING	M-17-22S-32E	350 FSL 1140 FWL	3418	0	
Dr Awkward 17-8 Federal Com 33H	PENDING	M-17-22S-32E	350 FSL 1175 FWL	3418	0	
Dr Awkward 17-8 Federal Com 34H	PENDING	O-17-22S-32E	275 FSL 1570 FEL	3418	0	
Dr Awkward 17-8 Federal Com 35H	PENDING	O-17-22S-32E	275 FSL 1500 FEL	3418	0	
Dr Awkward 17-8 Federal Com 311H	PENDING	M-17-22S-32E	350 FSL 1105 FWL	3418	0	
Dr Awkward 17-8 Federal Com 312H	PENDING	O-17-22S-32E	275 FSL 1600 FEL	3418	0	
Dr Awkward 17-8 Federal Com 313H	PENDING	M-17-22S-32E	275 FSL 1000 FEL	3418	0	

Gathering System and Pipeline Notification

Well(s) will be connected to a production facility after flowback operations are complete, where a gas transporter system is in place. The gas produced from production facility is dedicated to <u>DCP Midstream, LP ("DCP")</u> and will be connected to <u>DCP's</u> low/high pressure gathering system located in Lea County, New Mexico. <u>OXY USA INC. ("OXY")</u> provides (periodically) to <u>DCP</u> a drilling, completion and estimated first production date for wells that are scheduled to be drilled in the foreseeable future. In addition, <u>OXY</u> and <u>DCP</u> have periodic conference calls to discuss changes to drilling and completion schedules. Gas from these wells will be processed at <u>DCP's Zia Processing Plant located in Sec. 19, Twn. 19S, Rng. 32E, Lea County</u>, New Mexico. The actual flow of the gas will be based on compression operating parameters and gathering system pressures.

Flowback Strategy

After the fracture treatment/completion operations, well(s) will be produced to temporary production tanks and gas will be flared or vented. During flowback, the fluids and sand content will be monitored. When the produced fluids contain minimal sand, the wells will be turned to production facilities. Gas sales should start as soon as the wells start flowing through the production facilities, unless there are operational issues on <u>DCP's</u> system at that time. Based on current information, it is <u>OXY's</u> belief the system can take this gas upon completion of the well(s).

Safety requirements during cleanout operations from the use of underbalanced air cleanout systems may necessitate that sand and non-pipeline quality gas be vented and/or flared rather than sold on a temporary basis.

Alternatives to Reduce Flaring

Below are alternatives considered from a conceptual standpoint to reduce the amount of gas flared.

- Power Generation On lease
 - o Only a portion of gas is consumed operating the generator, remainder of gas will be flared
- Compressed Natural Gas On lease
 - o Gas flared would be minimal, but might be uneconomical to operate when gas volume declines
- NGL Removal On lease
 - o Plants are expensive, residue gas is still flared, and uneconomical to operate when gas volume declines

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 25663

CONDITIONS

Operator:	OGRID:			
OXY USA INC	16696			
P.O. Box 4294	Action Number:			
Houston, TX 772104294	25663			
	Action Type:			
	[C-101] BLM - Federal/Indian Land Lease (Form 3160-3)			

CONDITIONS

Created	Condition	Condition
Ву		Date
pkautz	Will require a File As Drilled C-102 and a Directional Survey with the C-104	
pkautz	Once the well is spud, to prevent ground water contamination through whole or partial conduits from the surface, the operator shall drill without interruption through the fresh water zone or	
	zones and shall immediately set in cement the water protection string	