ceined by Op Po Appropriate Districts:	State of New Mexico	Form $\mathcal{E}_{-103}^{age 103}$
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO. 30-025-45106
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOT	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ICATION FOR PERMIT" (FORM C-101) FOR SUCH	Commander
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	8. Well Number # 4H
 Type of Well: Oil Well Name of Operator 	Gas well Other	9. OGRID Number
Joint Resources Company		372938
3. Address of Operator 5416 Birchman Avenue, Fort W	orth, TX 76107	10. Pool name or Wildcat San Andres
4. Well Location		
Unit Letter M:	700 feet from the S line and 1	
Section 31	Township 17S Range 39E	NMPM County Lea
	11. Elevation (Show whether DR, RKB, RT, GR, 6	etc.)
12. Check	Appropriate Box to Indicate Nature of Notice	ce, Report or Other Data
NOTICE OF IN	NTENTION TO: SU	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL W	
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE	DRILLING OPNS. P AND A
TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐	CHANGE PLANS COMMENCE	DRILLING OPNS. P AND A
TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE	CHANGE PLANS COMMENCE CASING/CEM	DRILLING OPNS. P AND A
TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER:	CHANGE PLANS COMMENCE CASING/CEM	DRILLING OPNS. P AND A ENT JOB
TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp	CHANGE PLANS COMMENCE CASING/CEM DOTHER: pleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple	DRILLING OPNS. P AND A A ENT JOB A A And give pertinent dates, including estimated date
TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or composed or starting any proposed we proposed completion or recomposed completion or recomposed.	CHANGE PLANS COMMENCE CASING/CEM DOTHER: pleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple	DRILLING OPNS. P AND A ENT JOB and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or composed was proposed completion or recomposed completion or recomposed to the starting any proposed was proposed completion or recomposed completion or recomposed to the starting any proposed was proposed completion or recomposed completion or recomposed to the starting any proposed was proposed completion or recomposed to the starting any proposed was proposed completion or recomposed to the starting any proposed was proposed to the starting any proposed was proposed to the starting any proposed was proposed was proposed to the starting any proposed was propose	CHANGE PLANS MULTIPLE COMPL OTHER: pleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. Circ hole w/ MLF. Pressure test csg. Spot 25 sx cm 100'. WOC & Tag (B/Salt)	DRILLING OPNS. P AND A ENT JOB and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compost starting any proposed we proposed completion or recomposed completion or recomposed to the starting and proposed we proposed completion or recomposed to the starting and proposed we proposed completion or recomposed to the starting and proposed we proposed completion or recomposed to the starting and proposed we proposed completion or recomposed to the starting and proposed with the starting and proposed we proposed to the starting and proposed with the starting and proposed we proposed we proposed we proposed to the starting and proposed we proposed with the starting and proposed we proposed we proposed with the starting and proposed we proposed we proposed we proposed with the starting and proposed we proposed with the starting and proposed we proposed we proposed we proposed with the starting and proposed we proposed we proposed we proposed with the starting and the startin	CHANGE PLANS MULTIPLE COMPL OTHER: pleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. Girc hole w/ MLF. Pressure test csg. Spot 25 sx cm 100°. WOC & Tag (B/Salt) -2060°. WOC & Tag (T/Salt & 9 5/8 Shoe)	DRILLING OPNS. P AND A ENT JOB and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compost starting any proposed we proposed completion or recomposed completion or recomposed to the starting and proposed we proposed completion or recomposed completion or recomposed to the starting and proposed we proposed completion or recomposed to the starting and proposed we proposed completion or recomposed completion or recomposed to the starting and the starti	CHANGE PLANS MULTIPLE COMPL OTHER: pleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. Girc hole w/ MLF. Pressure test csg. Spot 25 sx cm 100°. WOC & Tag (B/Salt) -2060°. WOC & Tag (T/Salt & 9 5/8 Shoe)	DRILLING OPNS. P AND A ENT JOB and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compost starting any proposed we proposed completion or recomposed completion or recomposed to the starting and proposed we proposed completion or recomposed completion or recomposed to the starting and proposed we proposed completion or recomposed to the starting and proposed we proposed completion or recomposed to the starting and proposed we proposed to the starting and proposed we proposed we proposed to the starting and proposed we proposed we proposed we proposed we will be starting and proposed we proposed we proposed we proposed we proposed we will be starting and proposed we proposed we will be starting and proposed we will be sta	CHANGE PLANS MULTIPLE COMPL OTHER: Colleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. Circ hole w/ MLF. Pressure test csg. Spot 25 sx cm 100°. WOC & Tag (B/Salt) -2060°. WOC & Tag (T/Salt & 9 5/8 Shoe) surface. Cent at surface, weld ob Dry Hole Marker.	DRILLING OPNS. P AND A ENT JOB and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compost starting any proposed we proposed completion or recomposed completion or recomposed to the starting and proposed we proposed completion or recomposed completion or recomposed to the starting and proposed we proposed completion or recomposed to the starting and proposed we proposed completion or recomposed to the starting and proposed we proposed to the starting and proposed we proposed we proposed to the starting and proposed we proposed we proposed we proposed we will be starting and proposed we proposed we proposed we proposed we proposed we will be starting and proposed we proposed we will be starting and proposed we will be sta	CHANGE PLANS MULTIPLE COMPL OTHER: Deleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. Girc hole w/ MLF. Pressure test csg. Spot 25 sx cm 100°. WOC & Tag (B/Salt) -2060°. WOC & Tag (T/Salt & 9 5/8 Shoe) surface. Emt at surface, weld ob Dry Hole Marker.	DRILLING OPNS. P AND A not perform the performance of the performance
TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or composed with proposed completion or recomposed completion or recomposed completion or recomposed with proposed completion or recomposed completion or reco	CHANGE PLANS MULTIPLE COMPL OTHER: colleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. Circ hole w/ MLF. Pressure test csg. Spot 25 sx cm 100°. WOC & Tag (B/Salt) -2060°. WOC & Tag (T/Salt & 9 5/8 Shoe) surface. cmt at surface, weld ob Dry Hole Marker.	DRILLING OPNS. P AND A ENT JOB and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or composed with proposed completion or recomplete to the proposed completion or recomposed complete to the proposed complete on the	CHANGE PLANS MULTIPLE COMPL OTHER: Deleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. Girc hole w/ MLF. Pressure test csg. Spot 25 sx cm 100°. WOC & Tag (B/Salt) -2060°. WOC & Tag (T/Salt & 9 5/8 Shoe) surface. Emt at surface, weld ob Dry Hole Marker.	DRILLING OPNS. P AND A name of
PULL OR ALTER CASING PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or composed starting any proposed we proposed completion or recomposed completion or recomposed to the starting and proposed we proposed completion or recomposed to the starting and proposed we proposed completion or recomposed to the starting and proposed we proposed completion or recomposed to the starting and proposed we proposed to the starting and proposed we proposed we proposed we proposed to the starting and proposed we	CHANGE PLANS MULTIPLE COMPL OTHER: colleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. Circ hole w/ MLF. Pressure test csg. Spot 25 sx cm 100°. WOC & Tag (B/Salt) -2060°. WOC & Tag (T/Salt & 9 5/8 Shoe) surface. cmt at surface, weld ob Dry Hole Marker.	DRILLING OPNS. P AND A A ENT JOB A A A A AND A A AND A A AND A A AND A A
TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compost starting any proposed we proposed completion or recomposed completion or recomposed to the starting and proposed we proposed completion or recomposed completion or recomposed to the starting and proposed we proposed completion or recomposed completion or recomposed to the starting and proposed we proposed completion or recomposed completion or recom	CHANGE PLANS MULTIPLE COMPL OTHER: Deleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. Girc hole w/ MLF. Pressure test csg. Spot 25 sx cm 100°. WOC & Tag (B/Salt) -2060°. WOC & Tag (T/Salt & 9 5/8 Shoe) surface. Emt at surface, weld ob Dry Hole Marker. Rig Release Date:	DRILLING OPNS. P AND A SENT JOB PAND A SENT JOB STATE AND A SENT JOB SENT JOB SENT JOB PAND A SENT JOB SENT JOB PAND A SENT JOB S
TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compost starting any proposed we proposed completion or recomposed completion or recomposed completion or recomposed to the starting and proposed we proposed completion or recomposed	CHANGE PLANS MULTIPLE COMPL OTHER: pleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. Girc hole w/ MLF. Pressure test csg. Spot 25 sx cm 100'. WOC & Tag (B/Salt) -2060'. WOC & Tag (T/Salt & 9 5/8 Shoe) surface. cmt at surface, weld ob Dry Hole Marker. Rig Release Date: Rig Release Date:	DRILLING OPNS. P AND A A SINT JOB AND A SINT JOB AN


Page 2 of 15

nt Resources Company		Proposed	
Abby BCM			
Commander	Well No.	#4H	
Carter	_ API #:	30-025-45106	
Lea	Location:	Sec 31, T17S, R39E	
NM	_	700 FSL & 1310 FWL	
9/6/2018	_ GL:	3635	
	Abby BCM Commander Carter Lea NM	Abby BCM Commander Well No. API #: Lea Location:	

Description	O.D.	Grade	Weight	Depth	Hole	Cmt Sx	TOC
Surface Csg	9 5/8	J55	40#	2,141	12 1/4	950	0
Prod Csg	5 1/2	L80	20#	11,148	8 3/4	3,250	0

8 3/4

Hole Size:



CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E) Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - 1) Glorieta
 - J) Yates.
 - K) Cherry Canyon Eddy County
 - L) Potash---(In the R-111-P Area (Page 3 & 4), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

R-111-P Area

T 18S - R 30E

Sec 10 Unit P. Sec 11 Unit M,N. Sec 13 Unit L,M,N. Sec 14 Unit C -P. Sec 15 Unit A G,H,I,J,K,N,O,P. Sec 22 Unit All except for M. Sec 23, Sec 24 Unit C,D,E,L, Sec 26 Unit A-G, Sec 27 Unit A,B,C

T 19S - R 29E

Sec 11 Unit P. Sec 12 Unit H-P. Sec 13. Sec 14 Unit A,B,F-P. Sec 15 Unit P. Sec 22 Unit A,B,C,F,G,H,I,J K,N,O,P. Sec 23. Sec 24. Sec 25 Unit D. Sec 26 Unit A-F. Sec 27 Unit A,B,C,F,G,H.

T 19S - R 30E

Sec 2 Unit K,L,M,N. Sec 3 Unit I,L,M,N,O,P. Sec 4 Unit C,D,E,F,G,I-P. Sec 5 Unit A,B,C,E-P. Sec 6 Unit I,O,P. Sec 7 – Sec 10. Sec 11 Unit D, G—P. Sec 12 Unit A,B,E-P. Sec 13 Unit A-O. Sec 14-Sec 18. Sec 19 Unit A-L, P. Sec 20 – Sec 23. Sec 24 Unit C,D,E,F,L,M,N. Sec 25 Unit D. Sec 26 Unit A-G, I-P. Sec 27, Sec 28, Sec 29 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 32 Unit A,B,G,H,I,J,N,O,P. Sec 33. Sec 34. Sec 35. Sec 36 Unit D,E,F,I-P.

T 19S - R 31E

Sec 7 Unit C,D,E,F,L. Sec 18 Unit C,D,E,F,G,K,L. Sec 31 Unit M. Sec 34 Unit P. Sec 35 Unit M,N,O. Sec 36 Unit O,P.

T 20S - R 29E

Sec 1 Unit H,I,P. Sec 13 Unit E,L,M,N. Sec 14 Unit B-P. Sec 15 Unit A,H,I,J,N,O,P. Sec 22 Unit A,B,C,F,G,H,I,J,O,P. Sec 23. Sec 24 Unit C,D,E,F,G,J-P. Sec 25 Unit A-O. Sec 26. Sec 27 Unit A,B,G,H,I,J,O,P. Sec 34 Unit A,B,G,H. Sec 35 Unit A-H. Sec 36 Unit B-G.

T 20S - R 30E

Sec 1 – Sec 4. Sec 5 Unit A,B,C,E-P. Sec 6 Unit E,G-P. Sec 7 Unit A-H,I,J,O,P. Sec 8 – 17. Sec 18 Unit A,B,G,H,I,J,O,P. Sec 19 Unit A,B,G,H,I,J,O,P. Sec 30 Unit A-L,N,O,P. Sec 31 Unit A,B,G,H,I,P. Sec 32 – Sec 36.

T 20S - R 31E

Sec 1 Unit A,B,C,E-P. Sec 2. Sec 3 Unit A,B,G,H,I,J,O,P. Sec 6 Unit D,E,F,J-P. Sec 7. Sec 8 Unit E-P. Sec 9 Unit E,F,J-P. Sec 10 Unit A,B,G-P. Sec 11 – Sec 36.

T 21S - R 29E

Sec 1 – Sec 3. Sec 4 Unit L1 – L16,I,J,K,O,P. Sec 5 Unit L1. Sec 10 Unit A,B,H,P. Sec 11 – Sec 14. Sec 15 Unit A,H,I. Sec 23 Unit A,B. Sec 24 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 25 Unit A,O,P. Sec 35 Unit G,H,I,J,K,N,O,P. Sec 36 A,B,C,F – P.

T 21S - R 30E

Sec 1 – Sec 36

T 21S - R 31E

Sec 1 – Sec 36

T 22S - R 28E

Sec 36 Unit A,H,I,P.

T 22S - R 29E

Sec 1. Sec2. Sec 3 Unit I,J,N,O,P. Sec 9 Unit G – P. Sec 10 – Sec 16. Sec 19 Unit H,I,J. Sec 20 – Sec 28. Sec 29 Unit A,B,C,D,G,H,I,J,O,P. Sec 30 Unit A. Section 31 Unit C – P. Sec 32 – Sec 36

T 22S - R 30E

Sec 1 – Sec 36

T 22S - R 31E

Sec 1 – Sec 11. Sec 12 Unit B,C,D,E,F,L. Sec 13 Unit E,F,K,L,M,N. Sec 14 – Sec 23. Sec 24 Unit C,D,E,F,K,L,M,N. Sec 25 Unit A,B,C,D. Sec 26 Unit A,BC,D,G,H. Sec 27 – Sec 34.

T 23S - R 28E

Sec 1 Unit A

T 23S - R 29E

Sec 1 – Sec 5. Sec 6 Unit A – I, N,O,P. Sec 7 Unit A,B,C,G,H,I,P. Sec 8 Unit A – L, N,O,P. Sec 9 – Sec 16. Sec 17 Unit A,B,G,H,I,P. Sec 21 – Sec 23. Sec 24 Unit A – N. Sec 25 Unit D,E,L. Sec 26. Sec 27. Sec 28 Unit A – J, N,O,P. Sec 33 Unit A,B,C. Sec 34 Unit A,B,C,D,F,G,H. Sec 35. Sec 36 Unit B,C,D,E,F,G,K,L.

T 23S - R 30E

Sec 1 – Sec 18. Sec 19 Unit A – I,N,O,P. Sec 20, Sec 21. Sec 22 Unit A – N, P. Sec 23, Sec 24, Sec 25. Sec 26 Unit A,B,F-P. Sec 27 Unit C,D,E,I,N,O,P. Sec 28 Unit A – H, K,L,M,N. Sec 29 Unit A – J, O,P. Sec 30 Unit A,B. Sec 32 A,B. Sec 33 Unit C,D,H,I,O,P. Sec 34, Sec 35, Sec 36.

T 23S - R 31E

Sec 2 Unit D,E,J,O. Sec 3 – Sec 7. Sec 8 Unit A – G, K – N. Sec 9 Unit A,B,C,D. Sec 10 Unit D,P. Sec 11 Unit G,H,I,J,M,N,O,P. Sec 12 Unit E,L,K,M,N. Sec 13 Unit C,D,E,F,G,J,K,L,M,N,O. Sec 14. Sec 15 Unit A,B,E – P. Sec 16 Unit I, K – P. Sec 17 Unit B,C,D,E, I – P. Sec 18 – Sec 23. Sec 24 Unit B – G, K,L,M,N. Sec 25 Unit B – G, J,K,L. Sec 26 – Sec 34. Sec 35 Unit C,D,E.

T 24S – R 29E

Sec 2 Unit A, B, C, D. Sec 3 Unit A

T 24S - R 30E

Sec 1 Unit A – H, J – N. Sec 2, Sec 3. Sec 4 Unit A,B,F – K, M,N,O,P. Sec 9 Unit A – L. Sec 10 Unit A – L, O,P. Sec 11. Sec 12 Unit D,E,L. Sec 14 Unit B – G. Sec 15 Unit A,B,G,H.

T 24S - R 31E

Sec 3 Unit B – G, J – O. Sec 4. Sec 5 Unit A – L, P. Sec 6 Unit A – L. Sec 9 Unit A – J, O,P. Sec 10 Unit B – G, K – N. Sec 35 Unit E – P. Sec 36 Unit E,K,L,M,N.


T 25S - R 31E

Sec 1 Unit C,D,E,F. Sec 2 Unit A – H.

Office	State of New Mexic	0	Form $\mathcal{E}_{-103}^{age 30}$
District I – (575) 393-6161	Energy, Minerals and Natural		Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
District II – (575) 748-1283	OIL CONSERVATION DI	VISION	30-025-45106
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St. Francis		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 8750		STATE FEE 6. State Oil & Gas Lease No.
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Sulta 1 0, 1111 0730.		o. State on & Gas Lease No.
SUNDRY NO	TICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PLUG B	ACK TO A	7. Lease Name or Unit Agreement Name Commander
`	LICATION FOR PERMIT" (FORM C-101) FOR S		8. Well Number #4H
PROPOSALS.)	Can Wall Other		8. Well Number #4n
 Type of Well: Oil Well Name of Operator 	Gas Well Other		9. OGRID Number
Joint Resources Company			372938
3. Address of Operator			10. Pool name or Wildcat
5416 Birchman Avenue, Fort V	Worth, TX 76107		San Andres
4. Well Location			
Unit Letter M:			
Section 31	Township 17S Rang		NMPM County Lea
	11. Elevation (Show whether DR, RK	B, RT, GR, etc	c.)
	3635		
10 (1 1	A	CNI	D (01 D)
12. Check	Appropriate Box to Indicate Natu	re of Notice	e, Report or Other Data
NOTICE OF	INTENTION TO:	SUI	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK [EMEDIAL WO	
TEMPORARILY ABANDON [☐ CHANGE PLANS ☐ CO	DMMENCE DE	RILLING OPNS. ☐ P AND A ☐
PULL OR ALTER CASING [☐ MULTIPLE COMPL ☐ CA	ASING/CEME	NT JOB
DOWNHOLE COMMINGLE [
CLOSED LOOD SVSTEM	¬		
-			_
OTHER:	O	ΓHER:	
OTHER: 13. Describe proposed or cor	npleted operations. (Clearly state all pertiwork). SEE RULE 19.15.7.14 NMAC. F	nent details, a	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or cor of starting any proposed proposed completion or r	mpleted operations. (Clearly state all perti work). SEE RULE 19.15.7.14 NMAC. Frecompletion.	nent details, a or Multiple Co	ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or corn of starting any proposed proposed completion or 1 1. Set 5 ½ CIBP @ 4700'.	npleted operations. (Clearly state all pertiwork). SEE RULE 19.15.7.14 NMAC. Frecompletion. Circ hole w/ MLF. Pressure test csg. Sp	nent details, a or Multiple Co	ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or corn of starting any proposed proposed completion or 1 1. Set 5 ½ CIBP @ 4700'. 2. Spot 25 sx cmt @ 3300-	npleted operations. (Clearly state all pertiwork). SEE RULE 19.15.7.14 NMAC. Feecompletion. Circ hole w/ MLF. Pressure test csg. Sp 3100'. WOC & Tag (B/Salt)	nent details, a or Multiple Co	ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or corn of starting any proposed proposed completion or 1 1. Set 5 ½ CIBP @ 4700'. 2. Spot 25 sx cmt @ 3300-3. Perf & Sqz 50 sx @ 226	npleted operations. (Clearly state all pertiwork). SEE RULE 19.15.7.14 NMAC. Frecompletion. Circ hole w/ MLF. Pressure test csg. Sp 3100'. WOC & Tag (B/Salt) 0-2060'. WOC & Tag (T/Salt & 9 5/8 Sl	nent details, a or Multiple Co	ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or cor of starting any proposed proposed completion or 1 1. Set 5 ½ CIBP @ 4700'. 2. Spot 25 sx cmt @ 3300- 3. Perf & Sqz 50 sx @ 226 4. Spot 25 sx cmt @ 200' t	npleted operations. (Clearly state all perti work). SEE RULE 19.15.7.14 NMAC. Frecompletion. Circ hole w/ MLF. Pressure test csg. Sp 3100'. WOC & Tag (B/Salt) 0-2060'. WOC & Tag (T/Salt & 9 5/8 Sloo surface.	nent details, a or Multiple Co ot 25 sx cmt (ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or cor of starting any proposed proposed completion or 1 1. Set 5 ½ CIBP @ 4700'. 2. Spot 25 sx cmt @ 3300- 3. Perf & Sqz 50 sx @ 226 4. Spot 25 sx cmt @ 200' t	npleted operations. (Clearly state all pertiwork). SEE RULE 19.15.7.14 NMAC. Frecompletion. Circ hole w/ MLF. Pressure test csg. Sp 3100'. WOC & Tag (B/Salt) 0-2060'. WOC & Tag (T/Salt & 9 5/8 Sl	nent details, a or Multiple Co ot 25 sx cmt (ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or cor of starting any proposed proposed completion or 1 1. Set 5 ½ CIBP @ 4700'. 2. Spot 25 sx cmt @ 3300- 3. Perf & Sqz 50 sx @ 226 4. Spot 25 sx cmt @ 200' t	npleted operations. (Clearly state all perti work). SEE RULE 19.15.7.14 NMAC. Frecompletion. Circ hole w/ MLF. Pressure test csg. Sp 3100'. WOC & Tag (B/Salt) 0-2060'. WOC & Tag (T/Salt & 9 5/8 Sloo surface.	nent details, a or Multiple Co ot 25 sx cmt (ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or cor of starting any proposed proposed completion or 1 1. Set 5 ½ CIBP @ 4700'. 2. Spot 25 sx cmt @ 3300- 3. Perf & Sqz 50 sx @ 226 4. Spot 25 sx cmt @ 200' t	npleted operations. (Clearly state all perti work). SEE RULE 19.15.7.14 NMAC. Frecompletion. Circ hole w/ MLF. Pressure test csg. Sp 3100'. WOC & Tag (B/Salt) 0-2060'. WOC & Tag (T/Salt & 9 5/8 Sloo surface.	nent details, a or Multiple Co ot 25 sx cmt (ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or cornof starting any proposed proposed completion or 1 1. Set 5 ½ CIBP @ 4700'. 2. Spot 25 sx cmt @ 3300- 3. Perf & Sqz 50 sx @ 226 4. Spot 25 sx cmt @ 200' t	npleted operations. (Clearly state all perti work). SEE RULE 19.15.7.14 NMAC. Frecompletion. Circ hole w/ MLF. Pressure test csg. Sp 3100'. WOC & Tag (B/Salt) 0-2060'. WOC & Tag (T/Salt & 9 5/8 Sloo surface.	nent details, a or Multiple Co ot 25 sx cmt (ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or cor of starting any proposed proposed completion or 1 1. Set 5 ½ CIBP @ 4700'. 2. Spot 25 sx cmt @ 3300- 3. Perf & Sqz 50 sx @ 226 4. Spot 25 sx cmt @ 200' t 5. Cut off wellhead, verify	npleted operations. (Clearly state all perti work). SEE RULE 19.15.7.14 NMAC. Frecompletion. Circ hole w/ MLF. Pressure test csg. Sp 3100'. WOC & Tag (B/Salt) 0-2060'. WOC & Tag (T/Salt & 9 5/8 Slo surface. cmt at surface, weld ob Dry Hole Mark	nent details, a or Multiple Co	ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or cor of starting any proposed proposed completion or 1 1. Set 5 ½ CIBP @ 4700'. 2. Spot 25 sx cmt @ 3300- 3. Perf & Sqz 50 sx @ 226 4. Spot 25 sx cmt @ 200' t 5. Cut off wellhead, verify	npleted operations. (Clearly state all perti work). SEE RULE 19.15.7.14 NMAC. Frecompletion. Circ hole w/ MLF. Pressure test csg. Sp 3100'. WOC & Tag (B/Salt) 0-2060'. WOC & Tag (T/Salt & 9 5/8 Sloo surface.	nent details, a or Multiple Co	ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or cor of starting any proposed proposed completion or 1 1. Set 5 ½ CIBP @ 4700'. 2. Spot 25 sx cmt @ 3300- 3. Perf & Sqz 50 sx @ 226 4. Spot 25 sx cmt @ 200' t 5. Cut off wellhead, verify	npleted operations. (Clearly state all perti work). SEE RULE 19.15.7.14 NMAC. Frecompletion. Circ hole w/ MLF. Pressure test csg. Sp 3100'. WOC & Tag (B/Salt) 0-2060'. WOC & Tag (T/Salt & 9 5/8 Slo surface. cmt at surface, weld ob Dry Hole Mark	nent details, a or Multiple Co	ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or cor of starting any proposed proposed completion or 1 1. Set 5 ½ CIBP @ 4700'. 2. Spot 25 sx cmt @ 3300- 3. Perf & Sqz 50 sx @ 226 4. Spot 25 sx cmt @ 200' t 5. Cut off wellhead, verify	npleted operations. (Clearly state all perti work). SEE RULE 19.15.7.14 NMAC. Frecompletion. Circ hole w/ MLF. Pressure test csg. Sp 3100'. WOC & Tag (B/Salt) 0-2060'. WOC & Tag (T/Salt & 9 5/8 Slo surface. cmt at surface, weld ob Dry Hole Mark	nent details, a or Multiple Co	ompletions: Attach wellbore diagram of @ 4700-4500'.
OTHER: 13. Describe proposed or cor of starting any proposed proposed completion or 1 1. Set 5 ½ CIBP @ 4700'. 2. Spot 25 sx cmt @ 3300-3. Perf & Sqz 50 sx @ 226 4. Spot 25 sx cmt @ 200' t 5. Cut off wellhead, verify	npleted operations. (Clearly state all perti work). SEE RULE 19.15.7.14 NMAC. Frecompletion. Circ hole w/ MLF. Pressure test csg. Sp 3100'. WOC & Tag (B/Salt) 0-2060'. WOC & Tag (T/Salt & 9 5/8 Slo surface. cmt at surface, weld ob Dry Hole Mark	nent details, a or Multiple Co	ompletions: Attach wellbore diagram of @ 4700-4500'.
OTHER: 13. Describe proposed or cor of starting any proposed proposed completion or 1 1. Set 5 ½ CIBP @ 4700'. 2. Spot 25 sx cmt @ 3300-3. Perf & Sqz 50 sx @ 226 4. Spot 25 sx cmt @ 200' t 5. Cut off wellhead, verify spud Date:	npleted operations. (Clearly state all perti work). SEE RULE 19.15.7.14 NMAC. Frecompletion. Circ hole w/ MLF. Pressure test csg. Sp 3100'. WOC & Tag (B/Salt) 0-2060'. WOC & Tag (T/Salt & 9 5/8 Sloo surface. cmt at surface, weld ob Dry Hole Mark Rig Release Date:	nent details, a or Multiple Co	ompletions: Attach wellbore diagram of @ 4700-4500'. ge and belief.
OTHER: 13. Describe proposed or cor of starting any proposed proposed completion or 1 1. Set 5 ½ CIBP @ 4700'. 2. Spot 25 sx cmt @ 3300-3. Perf & Sqz 50 sx @ 226 4. Spot 25 sx cmt @ 200' t 5. Cut off wellhead, verify Spud Date: hereby certify that the information of the starting star	mpleted operations. (Clearly state all pertitions). SEE RULE 19.15.7.14 NMAC. For ecompletion. Circ hole w/ MLF. Pressure test csg. Sp 3100'. WOC & Tag (B/Salt) 0-2060'. WOC & Tag (T/Salt & 9 5/8 Sloo surface. Tent at surface, weld ob Dry Hole Mark Rig Release Date: TITLE TITLE	nent details, a or Multiple Co	ompletions: Attach wellbore diagram of @ 4700-4500'. lge and belief. DATE
OTHER: 13. Describe proposed or cor of starting any proposed proposed completion or 1 1. Set 5 ½ CIBP @ 4700'. 2. Spot 25 sx cmt @ 3300- 3. Perf & Sqz 50 sx @ 226 4. Spot 25 sx cmt @ 200' t 5. Cut off wellhead, verify pud Date: hereby certify that the information IGNATURE Type or print name	mpleted operations. (Clearly state all pertitions). SEE RULE 19.15.7.14 NMAC. For ecompletion. Circ hole w/ MLF. Pressure test csg. Sp 3100'. WOC & Tag (B/Salt) 0-2060'. WOC & Tag (T/Salt & 9 5/8 Sloo surface. Tent at surface, weld ob Dry Hole Mark Rig Release Date: TITLE TITLE	nent details, a or Multiple Co	ompletions: Attach wellbore diagram of @ 4700-4500'. ge and belief.
OTHER: 13. Describe proposed or cor of starting any proposed proposed completion or 1 1. Set 5 ½ CIBP @ 4700'. 2. Spot 25 sx cmt @ 3300- 3. Perf & Sqz 50 sx @ 226 4. Spot 25 sx cmt @ 200' t 5. Cut off wellhead, verify Spud Date: hereby certify that the information of the starting of the starti	mpleted operations. (Clearly state all pertitions). SEE RULE 19.15.7.14 NMAC. For ecompletion. Circ hole w/ MLF. Pressure test csg. Sp 3100'. WOC & Tag (B/Salt) 0-2060'. WOC & Tag (T/Salt & 9 5/8 Sloo surface. Tent at surface, weld ob Dry Hole Mark Rig Release Date: TITLE TITLE	nent details, a or Multiple Co	ompletions: Attach wellbore diagram of @ 4700-4500'. description
OTHER: 13. Describe proposed or cor of starting any proposed proposed completion or 1 1. Set 5 ½ CIBP @ 4700'. 2. Spot 25 sx cmt @ 3300- 3. Perf & Sqz 50 sx @ 226 4. Spot 25 sx cmt @ 200' t 5. Cut off wellhead, verify Spud Date: Signature Type or print name For State Use Only	mpleted operations. (Clearly state all pertimork). SEE RULE 19.15.7.14 NMAC. Freecompletion. Circ hole w/ MLF. Pressure test csg. Sp 3100'. WOC & Tag (B/Salt) 0-2060'. WOC & Tag (T/Salt & 9 5/8 Sho surface. Tentral at surface, weld ob Dry Hole Mark Rig Release Date: TITLE E-mail address:	nent details, a or Multiple Co	ompletions: Attach wellbore diagram of @ 4700-4500'. description

Received by OCD: 4/23/2023 10:26:14 AM

Page 8 of 15




Received by OCD: 4/23/2023 10:26:14 AM


w/2 Poz H (yield 14.2). Comments

Formation Top Summary Formation Name

	Top(TVD ft)
T. Anhy	2,095
T. Salt	2,210
B. Salt	3,247
Yates	3,373
7 Rivers	3,697
Queen	4,205
Grayburg	4,476
T. San Andres	5.214

Last Updated: 10/12/2018 02:19 PM





Received by OCD: 4/23/2023 10:26:14 AM


Page 10 of 15

Joint Resource	es Company		Proposed	
Author:	Abby BCM			
Well Name	Commander	Well No.	#4H	
Field/Pool	Carter	_ API #:	30-025-45106	
County	Lea	Location:	Sec 31, T17S, R39E	
State	NM	_	700 FSL & 1310 FWL	
Spud Date	9/6/2018	GL:	3635	

Description	O.D.	Grade	Weight	Depth	Hole	Cmt Sx	TOC
Surface Csg	9 5/8	J55	40#	2,141	12 1/4	950	0
Prod Csg	5 1/2	L80	20#	11,148	8 3/4	3,250	0


8 3/4

Hole Size:



Received by OCD: 4/23/2023 10:26:14 AM

Page 11 of 15




Received by OCD: 4/23/2023 10:26:14 AM


w/2 Poz H (yield 14.2). Comments

Formation Top Summary Formation Name

	Top(TVD ft)
T. Anhy	2,095
T. Salt	2,210
B. Salt	3,247
Yates	3,373
7 Rivers	3,697
Queen	4,205
Grayburg	4,476
T. San Andres	5.214

Last Updated: 10/12/2018 02:19 PM






Received by OCD: 4/23/2023 10:26:14 AM

Page 13 of 15

nt Resources Company		Proposed	
Abby BCM			
Commander	Well No.	#4H	
Carter	_ API #:	30-025-45106	
Lea	Location:	Sec 31, T17S, R39E	
NM	_	700 FSL & 1310 FWL	
9/6/2018	_ GL:	3635	
	Abby BCM Commander Carter Lea NM	Abby BCM Commander Well No. API #: Lea Location:	

Description	O.D.	Grade	Weight	Depth	Hole	Cmt Sx	TOC
Surface Csg	9 5/8	J55	40#	2,141	12 1/4	950	0
Prod Csg	5 1/2	L80	20#	11,148	8 3/4	3,250	0



4 1/2" L80 Liner @ 11,148

Hole Size: 8 3/4

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 209893

COMMENTS

Operator:	OGRID:
JOINT RESOURCES COMPANY	372938
5416 Birchman Avenue	Action Number:
Fort Worth, TX 761075111	209893
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

COMMENTS

Created B	Comment	Comment Date
plmartin	DATA ENTRY PM	5/1/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 209893

CONDITIONS

Operator:	OGRID:
JOINT RESOURCES COMPANY	372938
5416 Birchman Avenue	Action Number:
Fort Worth, TX 761075111	209893
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
kfortner	See attached COA	5/1/2023