

<b>Well Name:</b> SAN JUAN 30-6 UNIT SWD	<b>Well Location:</b> T30N / R7W / SEC 23 / NWNW / 36.80446 / -107.54646	<b>County or Parish/State:</b> RIO ARRIBA / NM
<b>Well Number:</b> 2	<b>Type of Well:</b> INJECTION - ENHANCED RECOVERY	<b>Allottee or Tribe Name:</b>
<b>Lease Number:</b> NMSF079382	<b>Unit or CA Name:</b>	<b>Unit or CA Number:</b>
<b>US Well Number:</b> 3003924518	<b>Well Status:</b> Water Disposal Well	<b>Operator:</b> HILCORP ENERGY COMPANY

### Subsequent Report

**Sundry ID:** 2753679

**Type of Submission:** Subsequent Report

**Type of Action:** Workover Operations

**Date Sundry Submitted:** 09/27/2023

**Time Sundry Submitted:** 12:28

**Date Operation Actually Began:** 09/27/2023

**Actual Procedure:** 9/27/23: Hilcorp Energy pumped 550 gallons of 2% KCL water with Biocide/scale/corrosion inhibitor down tubing. Beginning SITP 515, SICP 0. Total pump time 38 minutes. Tubing pressure increased to 581 psi & csg pressure remained at 0 psi during pumping operations. SI well upon completion. 5 min SITP 549 psi, SICP 0. John Durham, NMOCD was present for injection test.



Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 269681

**CONDITIONS**

Operator:  HILCORP ENERGY COMPANY 1111 Travis Street Houston, TX 77002	OGRID: 372171
	Action Number: 269681
	Action Type: [C-103] Sub. Workover (C-103R)

**CONDITIONS**

Created By	Condition	Condition Date
andrew.fordyce	Accepted for record.	1/30/2026