Submit 3 Copies To Appropriate District	State of New M	lexico		Form C-1	
Office District I	Energy, Minerals and Nat	ural Resources		Revised March 25, 19	999
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		1
District II OH CONSEDVATION DIVISION		30-053-20014			
811 South First, Artesia, 1914 86210		5. Indicate Type	of Lease		
District III 1220 South St. Francis Dr.		,	X FEE 🗆		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		6. State Oil & C			
1220 S. St. Francis Dr., Santa Fe, NM			o. State On & C	ias lease no.	ì
87505					
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name	or Unit Agreement	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			Name:		1
DIFFERENT RESERVOIR. USE "APPLICA	ATION FOR PERMIT" (FORM C-101) F	OR SUCH	Dulce Draw State	2	
PROPOSALS.)					!
1. Type of Well:	777		İ		
Oil Well Gas Well X	X Other		A 777 11 3 7		
2. Name of Operator			8. Well No. 1		
Primero Operating, Inc.					
3. Address of Operator			8. Pool name or Wildcat		
PO Box 1433, Roswell, NM 88202	-1433		Wildcat, Atoka		
4. Well Location					Ì
					1
Unit Letter E :	1980 feet from the North	line and 66	60 feet from	m the Westli	ine
Section 2	Township 4S	Range 9E	NMPM	Socorro County	
	10. Elevation (Show whether				
	4036.8	, , , , , , , , , , , , , , , , , , , ,			
11 Chook A	propriate Box to Indicate N	Intura of Matina 1	Panart or Other	Doto	
NOTICE OF IN			SEQUENT <u>R</u> EI		_
PERFORM REMEDIAL WORK	PLUG AND ABANDON L	REMEDIAL WOR	K 🗀	ALTERING CASING	i L
	CHANGE PLANS	COMMENCE DRI	LLING OPNS. []	PLUG AND	X
TEMPORARILY ABANDON					
		040000 7507 4		ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE	CASING TEST A	ND 🗆	ABANDONVENT	
	MULTIPLE COMPLETION	CASING TEST AI	ND 🗆	ABANDONNEN	
PULL OR ALTER CASING		CEMENT JOB		ABANDONWENT	
PULL OR ALTER CASING OTHER:	COMPLETION	OTHER: Complete	tion Operations		
OTHER: 12. Describe proposed or complete	COMPLETION d operations. (Clearly state all p	OTHER: Comple	tion Operations give pertinent dates.	including estimated d	
OTHER: 12. Describe proposed or complete of starting any proposed work).	COMPLETION	OTHER: Comple	tion Operations give pertinent dates.	including estimated d	
OTHER: 12. Describe proposed or complete	COMPLETION d operations. (Clearly state all p	OTHER: Comple	tion Operations give pertinent dates.	including estimated d	
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation.	COMPLETION d operations. (Clearly state all p	OTHER: Comple	tion Operations give pertinent dates.	including estimated d	
OTHER: 12. Describe proposed or complete of starting any proposed work).	COMPLETION d operations. (Clearly state all p	OTHER: Comple	tion Operations give pertinent dates.	including estimated d	
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows:	COMPLETION d operations. (Clearly state all p SEE RULE 1103. For Multiple	OTHER: Comple	tion Operations give pertinent dates.	including estimated d	
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255	COMPLETION d operations. (Clearly state all p SEE RULE 1103. For Multiple	OTHER: Completertinent details, and go Completions: Attack	tion Operations give pertinent dates.	including estimated d	
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', F	COMPLETION d operations. (Clearly state all p SEE RULE 1103. For Multiple 50°	OTHER: Completertinent details, and go Completions: Attack	tion Operations give pertinent dates.	including estimated d	
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', FPlug #2 40 sx class C - 2000' to 1	COMPLETION d operations. (Clearly state all p SEE RULE 1103. For Multiple 50' RIH w/ tubing and tagged plug at 900'	OTHER: Completertinent details, and go Completions: Attack	tion Operations give pertinent dates.	including estimated d	
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', F	COMPLETION d operations. (Clearly state all p SEE RULE 1103. For Multiple 50' RIH w/ tubing and tagged plug at 900'	OTHER: Completertinent details, and go Completions: Attack	tion Operations give pertinent dates.	including estimated d	
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', FPlug #2 40 sx class C - 2000' to 1	COMPLETION d operations. (Clearly state all p SEE RULE 1103. For Multiple 50' RIH w/ tubing and tagged plug at 900'	OTHER: Completertinent details, and go Completions: Attack	tion Operations give pertinent dates.	including estimated d	
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', Flug #2 40 sx class C - 2000' to 1 Plug #3 90 sx class C - 1333' to 1	COMPLETION d operations. (Clearly state all p SEE RULE 1103. For Multiple 50' RIH w/ tubing and tagged plug at 900'	CEMENT JOB OTHER: Completertinent details, and go completions: Attack	tion Operations give pertinent dates, th wellbore diagram	including estimated d	
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', Plug #2 40 sx class C - 2000' to 1 Plug #3 90 sx class C - 1333' to 1 Plug #4 10 sx class C at surface.	d operations. (Clearly state all p SEE RULE 1103. For Multiple 50' RIH w/ tubing and tagged plug at 900' 233'	CEMENT JOB OTHER: Completertinent details, and go completions: Attack	tion Operations give pertinent dates, th wellbore diagram	including estimated d	
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', Flug #2 40 sx class C - 2000' to 1 Plug #3 90 sx class C - 1333' to 1	d operations. (Clearly state all p SEE RULE 1103. For Multiple 50' RIH w/ tubing and tagged plug at 900' 233'	CEMENT JOB OTHER: Completertinent details, and go completions: Attack	tion Operations give pertinent dates, th wellbore diagram	including estimated d	
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', Plug #2 40 sx class C - 2000' to 1 Plug #3 90 sx class C - 1333' to 1 Plug #4 10 sx class C at surface.	d operations. (Clearly state all p SEE RULE 1103. For Multiple 50' RIH w/ tubing and tagged plug at 900' 233'	CEMENT JOB OTHER: Completertinent details, and go completions: Attack	tion Operations give pertinent dates, th wellbore diagram	including estimated d	
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', Plug #2 40 sx class C - 2000' to 1 Plug #3 90 sx class C - 1333' to 1 Plug #4 10 sx class C at surface.	d operations. (Clearly state all p SEE RULE 1103. For Multiple 50' RIH w/ tubing and tagged plug at 900' 233'	CEMENT JOB OTHER: Completertinent details, and go completions: Attack	tion Operations give pertinent dates, th wellbore diagram	including estimated d	
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', Plug #2 40 sx class C - 2000' to 1 Plug #3 90 sx class C - 1333' to 1 Plug #4 10 sx class C at surface.	d operations. (Clearly state all p SEE RULE 1103. For Multiple 50' RIH w/ tubing and tagged plug at 900' 233'	CEMENT JOB OTHER: Completertinent details, and go completions: Attack	tion Operations give pertinent dates.	including estimated d	
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', F Plug #2 40 sx class C - 2000' to 1 Plug #3 90 sx class C - 1333' to 1 Plug #4 10 sx class C at surface. Welded on dry hole marker and clean	d operations. (Clearly state all p SEE RULE 1103. For Multiple 50° RIH w/ tubing and tagged plug at 900° 233°	CEMENT JOB OTHER: Complete ertinent details, and ge completions: Attack	tion Operations give pertinent dates, the wellbore diagram	including estimated d	
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', Plug #2 40 sx class C - 2000' to 1 Plug #3 90 sx class C - 1333' to 1 Plug #4 10 sx class C at surface.	d operations. (Clearly state all p SEE RULE 1103. For Multiple 50° RIH w/ tubing and tagged plug at 900° 233°	CEMENT JOB OTHER: Complete ertinent details, and ge completions: Attack	tion Operations give pertinent dates, the wellbore diagram	including estimated d	
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', Plug #2 40 sx class C - 2000' to 19 Plug #3 90 sx class C - 1333' to 19 Plug #4 10 sx class C at surface. Welded on dry hole marker and clear	d operations. (Clearly state all p SEE RULE 1103. For Multiple 50° RIH w/ tubing and tagged plug at 900° 233° aned and leveled location.	CEMENT JOB OTHER: Completertinent details, and get Completions: Attack	tion Operations give pertinent dates, the wellbore diagram	including estimated d	on
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', F Plug #2 40 sx class C - 2000' to 1 Plug #3 90 sx class C - 1333' to 1 Plug #4 10 sx class C at surface. Welded on dry hole marker and clean	d operations. (Clearly state all p SEE RULE 1103. For Multiple 50° RIH w/ tubing and tagged plug at 900° 233° aned and leveled location.	CEMENT JOB OTHER: Complete ertinent details, and ge completions: Attack	tion Operations give pertinent dates, the wellbore diagram	including estimated d	on
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', Plug #2 40 sx class C - 2000' to 1 Plug #3 90 sx class C - 1333' to 1 Plug #4 10 sx class C at surface. Welded on dry hole marker and clear	d operations. (Clearly state all p SEE RULE 1103. For Multiple 60° RIH w/ tubing and tagged plug at 900° 233° aned and leveled location.	CEMENT JOB OTHER: Completertinent details, and get Completions: Attack	sive pertinent dates, the wellbore diagram	including estimated do not proposed completing the pro	l
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', Flug #2 40 sx class C - 2000' to 1 Plug #3 90 sx class C - 1333' to 1 Plug #4 10 sx class C at surface. Welded on dry hole marker and clear I hereby certify that the information SIGNATURE Type or print name Phelps White	d operations. (Clearly state all p SEE RULE 1103. For Multiple 60° RIH w/ tubing and tagged plug at 900° 233° aned and leveled location.	CEMENT JOB OTHER: Completertinent details, and get Completions: Attack	sive pertinent dates, the wellbore diagram	including estimated d	l
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', Plug #2 40 sx class C - 2000' to 1 Plug #3 90 sx class C - 1333' to 1 Plug #4 10 sx class C at surface. Welded on dry hole marker and clear	d operations. (Clearly state all p SEE RULE 1103. For Multiple 60° RIH w/ tubing and tagged plug at 900° 233° aned and leveled location.	CEMENT JOB OTHER: Completertinent details, and get Completions: Attack	sive pertinent dates, the wellbore diagram	including estimated do not proposed completing the pro	l
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', Flug #2 40 sx class C - 2000' to 1 Plug #3 90 sx class C - 1333' to 1 Plug #4 10 sx class C at surface. Welded on dry hole marker and clear the complete of the	d operations. (Clearly state all p SEE RULE 1103. For Multiple of the second of the se	CEMENT JOB OTHER: Complete ertinent details, and go completions: Attack 2590' Luce best of my knowled ertinent details, and go completions: Attack President	sive pertinent dates, the wellbore diagram	DATE11/29/0	l
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', Flug #2 40 sx class C - 2000' to 1 Plug #3 90 sx class C - 1333' to 1 Plug #4 10 sx class C at surface. Welded on dry hole marker and clear I hereby certify that the information SIGNATURE Type or print name Phelps White	d operations. (Clearly state all p SEE RULE 1103. For Multiple of the second of the se	CEMENT JOB OTHER: Completertinent details, and get Completions: Attack	sive pertinent dates, the wellbore diagram	DATE11/29/0	
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. Plugged well as follows: Plug #1 60 sx class C 2700' to 255 Peforate 4 squeeze holes at 1283', Flug #2 40 sx class C - 2000' to 1 Plug #3 90 sx class C - 1333' to 1 Plug #4 10 sx class C at surface. Welded on dry hole marker and clear the complete of the	d operations. (Clearly state all p SEE RULE 1103. For Multiple of the second of the se	CEMENT JOB OTHER: Complete ertinent details, and go completions: Attack 2590' Luce best of my knowled ertinent details, and go completions: Attack President	sive pertinent dates, the wellbore diagram	DATE11/29/0	