
ENGINE TO THE

NEW MEXICO OIL CONSERVATION DIVISION

- Engineering Bureau -1220 South St. Francis Drive, Santa Fe, NM 87505



ADMINISTRATIVE APPLICATION CHECKLIST

			NDATORY FOR ALL ADMINISTRATIVE WHICH REQUIRE PROCESS			S AND REGULATIONS
Applic	[DHC	n-Stand -Down PC-Poo [dard Location] [NSP-Non-Sta hole Commingling] [CTB-Le	ease Commingling Lease Storage] [PMX-Pressure II] [IPI-Injection	g] [PLC-Pool/Lease Cor [OLM-Off-Lease Measure Maintenance Expansion] Pressure Increase]	mmingling] ement]
[1]		OF API [A]	PLICATION - Check Those V Location - Spacing Unit - Sin NSL NSP	ultaneous Dedica	_	
		Check ([B]	One Only for [B] or [C] Commingling - Storage - Mea X DHC	asurement	OLS OLM	
	i	[C]	Injection - Disposal - Pressure			
	[[D]	Other: Specify			
[2]		CATIC	ON REQUIRED TO: - Check Working, Royalty or Ove	-	. 1	
	[[B]	Offset Operators, Leaseh	olders or Surface	Owner	
	!	[C]	Application is One Which	ch Requires Publis	shed Legal Notice	
	l	[D]	Notification and/or Conc U.S. Bureau of Land Management - Co	urrent Approval b	y BLM or SLO ds, State Land Office	
	[[E]	For all of the above, Prod	of of Notification	or Publication is Attached	, and/or,
	. ([F]	☐ Waivers are Attached			
[3]			TURATE AND COMPLETE FION INDICATED ABOVE		N REQUIRED TO PRO	CESS THE TYPE
[4] approv applica	al is accu i	rate an	ION: I hereby certify that the d complete to the best of my k uired information and notificate	nowledge. I also	understand that no action	for administrative will be taken on this
		Note:	Statement must be completed by an	<i>'</i>		•
	Corley Type Name)	Signature	<u>sr</u> <u>Sr</u>	. Regulatory Analyst Title corleyml@bp.com e-mail Address	Date

Form C-107A Revised May 15,

2000

District II

811 South First Street, Artesia, NM 88210

District III 1000 Rio Brazos Road, Aztec, NM 87410

Pools District IV

2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

2040 South Pacheco

Santa Fe, New Mexico 87505

APPLICATION FOR DOWNHOLE COMMINGLING

APPLICATION TYPE X Single Well Establish Pre-Approved

EXISTING WELLBORE

X Yes No

BP America Production	Company P. O. Box 3092	2 Houston, TX 77253						
Operator I S		Idress Section 35 T29N, R08W	San Juan					
Jones LS Lease		-Section-Township-Range	County					
OGRID No. <u>000778</u> Property Code <u>000762</u> API No. <u>30-045-22833</u> Lease Type: <u>X</u> Federal State Fee								
DATA ELEMENT	UPPER ZONE	INTERMEDIATE ZONE	LOWERZONE					
Pool Name	Blanco Pictured Cliffs	Otero Chacra	Blanco Mesaverde					
Pool Code	72359 🗸	82320 196540	72319					
Top & Bottom of Pay Section (Perforated or Open-Hole Interval)	2574' – 2692'	To Be Determined	4098' – 5202'					
Method of Production (Flowing or Artificial Lift)	Artificial Lift	Flowing	Artificial Lift					
Bottomhole Pressure	475	430	480					
Oil Gravity or Gas BTU (Degree API or Gas BTU)	950	1230	950					
Producing, Shut-In or New Zone	Producing	New Zone	Producing					
Date and Oil/Gas/Water Rates of Last Production.	Date: Rates:	Date: Rates:	Date: Rates:					
Fixed Allocation Percentage	Oil Gas %	Oil Gas %	Oil Gas % %					
	ADDITION	NAL DATA						
	ing royalty interests identical in all cor overriding royalty interest owners bee		Yes_X No Yes No					
Are all produced fluids from all com	mingled zones compatible with each o	other?	Yes_X_ No					
Will commingling decrease the value	e of production?							
			Yes NoX					
	vith, state or federal lands, has either the Management been notified in writing		Yes No					
NMOCD Reference Case No. applic	able to this well:							
Production curve for each zone for zones with no production his Data to support allocation method Notification list of working, royal	ningled showing its spacing unit and action at least one year. (If not available, story, estimated production rates and sold or formula. alty and overriding royalty interests for documents required to support com-	attach explanation.) supporting data. r uncommon interest cases.						
	PRE-APPRO	VED POOLS						
If application	is to establish Pre-Approved Pools th	ne following additional information wil	1 he required:					

Pre-Approved Pools, the following additional information will be required:

__DATE___<u>04/01/2005</u>

List of other orders approving downhole commingling within the proposed Pre-Approved Pools

List of all operators within the proposed Pre-Approved Pools Proof that all operators within the proposed Pre-Approved Pools were provided notice of this application.

Bottomhole pressure data.

I hereby certify that	t the in	forma	itign abov	e is true a	nd complete	e to the best of my knowledge and	d belief.
			///		•		
SIGNATURE	(arl	1/	MILIL		TITLE	e to the best of my knowledge and Sr. Regulatory Analyst	DAT
J. J. W. J. W. J. W. J. W. J. W.		r - 6		1	_ · · · · <i></i> -	Strategulatory Amaryst	DA

TYPE OR PRINT NAME V Corley TELEPHONE NO. (281) 366-4491 District I

1625 N. French Dr., Hobbs, NM 88240

State of New Mexico
Energy, Minerals & Natural Resources Department

Form C-102 Revised August 15, 2000

District II

811 South First, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410 District IV

District IV 2040 South Pacheco, Santa Fe, NM 87505

OIL CONSERVATION DIVISION

2040 South Pacheco Santa Fe, NM 87505 Submit to Appropriate District Office

State Lease - 4 Copies

Fee Lease - 3 Copies

AMENDED REPORT


WELL LOCATION AND ACREAGE DEDICATION PLAT

'API Number 30-045-22833	* Pool Code 82329	³ Pool Name Otero Chacra
⁴ Property Code 000762	⁵ Property Name Jones LS	⁶ Well Number
⁷ OGRID No. 000778	8 Operator Name BP America Production Company	' Elevation 5980' GR

Surface Location

UL or lot no. J	Section 35	Township 29N	Range 08W	Lot Idn	Feet from 1450	North/South South	Feet from 1740	East/West East	County San Juan
Bottom Hole Location If Different From Surface									
UL or lot no.	Section	Township	Range	Lot Idn	Feet from	North/South	Feet	East/West	County
12 Dedicated Acres		¹³ Joint o	r Infill	<u></u> -	¹⁴ Consolidation C	Code		15	Order No.

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



Allocation Method Jones LS 1A

BP America Production Company request permission to complete the subject well into the Otero Chacra and tricommingle production downhole with the existing Blanco South Pictured Cliffs and Blanco Mesaverde Pools as per the attached procedure.

The interest owners are identical between these three Pools, therefore, no additional notification is required prior to downhole commingling approval.

Production is proposed to be allocated based on a fixed percentage. Each zone will be tested to determine the percentage of the whole to be allocated to each zone. A test will be performed on the Mesaverde prior to initiating the recompletion into the Chacra. Upon completion into the Chacra a combined test will be performed on both the Chacra and the Pictured Cliffs then the Pictured Cliffs will be isolated from the Chacra and the Chacra will be tested to determine the volume to be attributed to the Pictured Cliffs.

Commingling Production Downhole in the subject well from the proposed pools with not reduce the value of the total remaining production.

Application has also been submitted to BLM on Form 3160-5, Federal Lease No. SF - 03549.

Pre Approved Pools:

Blanco-Mesaverde (72319) & Blanco-Pictured Cliffs (72359) Pools

Blanco-Mesaverde (72319) & Otero-Chacra (82329) Pools

Blanco-Pictured Cliffs (72359) & Otero-Chacra (82329) Pools


Jones LS 1 A Procedure to Complete into the Chacra & DHC with Mesaverde & Pictured Cliffs March 9, 2005

- 1. Perform pre-rig site inspection. Check for: size of location, Gas Taps, other wells, other operators, running equipment, wetlands, wash (dikes req.), H2S, barriers needed for equipment, Landowner issues, location of pits (buried lines in pits), Raptor nesting, critical location, check anchors. Check ID wellhead, if earth pit is required have One Call made 48 hours prior to digging.
- 2. Perform second site visit after lines are marked to ensure all lines clear marked pit locations. Planning and Scheduling to ready location for rig.
- 3. RU slickline unit or wireline unit. Pressure test lubricator and equipment. RIH and set **two** barriers (CIBP, tbg collar stop w/plug, or plug set in nipple) for isolation in tubing strings.
- 4. Check and record tubing, casing, and bradenhead pressures. Ensure production casing has double casing valves installed. Double valve all casing strings.
- 5. MIRU workover rig. LO/TO all necessary equipment including but not limited to: meter run, Automation, Separators and water lines.
- 6. Blow down well. Kill with 2% KCL water ONLY if necessary.
- 7. Check all casing strings to ensure no pressure exist on any annulus. The operations of removal of wellhead and installation of BOP's will be performed under a dispensation for one (1) barrier on the backside.
- 8. Nipple down Wellhead. NU BOPs and diversion spool with 3" outlets and 3" pipe to the blow tank. Pressure test BOPs to 200 psi above BHP. Monitor flowing casing pressure with gauge (with casing flowing to blow tank) throughout workover.
- 9. Install stripping rubber.
- 10. TOH and LD 1-1/4" production tubing currently set at 2712'. Using approved "Under Balance Well Control Tripping Procedure".
- 11. TOH w/ packer and 2-3/8" production tubing currently set at 5137'. Using approved "Under Balance Well Control Tripping Procedure".
- 12. TIH w/ scraper for 4-1/2". Check the distance between the top of the blind rams and the length of the bottom hole assembly that is being run. If the BHA is too long then the well has to be top killed and monitored prior to opening bind rams. RIH to PBTD at 5,206'. POOH.
- 13. Set bridge plug at 4,000'. Fill casing to PC w/ 2%KCl.
- 14. RU E-line equipment. Pressure test lubricator and equipment. Log well w/ CBL from PBTD to TOL. If TOC is below Chacra, contact engineer to discuss need for remedial cement squeeze.

- 15. TIH w/ workstring and blow well dry.
- 16. Prepare for explosive operations. Follow Schlumberger Explosive SOP including radio silence, suspension of welding operations, and isolation of electrical devices from the work area. Perform Pre-job Safety Meeting to review JSA and procedures.
- 17. RIH with 3-1/8" casing guns w/lubricator. Perforate Chacra formation w/ 4 SPF.
- 18. RIH w/ packer and 3-1/2" by 2-7/8" frac string. Set packer at 2,800'.
- 19. Install and monitor production casing and treating pressure during entire job in frac van via pressure transducers on production casing and treating line. Spearhead 500 gal 15% HCL, establish injection rate, and proceed with fracture stimulation according to Schlumberger schedule. Maintain surface pressures, less than 5,000 psi during frac job. Flush frac with foam. Fill out GWSI scorecard.
- 20. Flowback frac immediately. Flow well through choke manifold on 1/4", 1/2" and 3/4" chokes increasing drawdown until well dies or stabilizes. This is to aid in reducing sand flowback. Recommend 8 hours of flow for each choke size.
- 21. Rig up air package/unit, pressure test all lines (Testing procedure to be supplied from air company), TIH with tubing and bit for 4-1/2" casing. Cleanout fill to top of BP set at 4,000'. Perform well test on Chacra for regulatory and document well test in DIMS.
- 22. Cleanout fill and BP set at 4,000'. Cleanout to PBTD at 5,206'. Blow well dry.
- 23. Rabbit tubing and RIH with 2-3/8" production tubing (with muleshoe, F-nipple with plug, 4 ft pup, X-nipple with plug).
- 24. Land 2-3/8" production tubing at +/-5,150'. Lock down hanger.
- 25. Pressure test tubing to 500 psi with air unit, make sure tubing spool valves are open. Care should be taken during pressure testing of the tubing due to potential problem caused if tubing parts close to surface or above the hanger. Check all casing string for pressure. The operations of removal of wellhead and installation of BOP's will be performed under a dispensation for one (1) barrier on the backside.
- 26. ND BOP's. NU Wellhead. During Master valve placement ensure the top of hanger has spacer nipple in place to bottom of bonnet flange so plunger equipment will not hang up through tree. Pressure test Wellhead.
- 27. RU WL unit. Run gauge ring for 2-3/8" tubing. Pull plugs and set tubing stop for plunger. Communicate plunger equipment status to IC room personnel.
- 28. RD slickline unit.
- 29. Test well for air. Return well to production and downhole tri-mingle PC, Chacra and Mesaverde.

Jones LS 1 A

Sec 35, T29N, R8W API # 30-045-22833



updated: 3/9/05 CFR