### Bratcher, Mike, EMNRD

From:

Bob Allen [ballen@sesi-nm.com] Wednesday, April 11, 2012 3:35 PM

Sent: To:

Bratcher, Mike, EMNRD

Cc:

Green, Bill; nora.vazquez@hollyenergy.com; lori.coupland@hollyenergy.com; Susana

Rodriguez

Subject: Attachments: St Marys Federal Delineation Workplan St Marys' Delineation Workplan.docx

Mike...

I have attached the Delineation Workplan for the St Marys Federal spill reported by Holly Energy Partners on December 13, 2011 via C-141. Please review the proposal and forward your approval at your earliest convenience. Thank you.

Bob Allen CSP, CHMM Cell # 575.390.7063 Office # 575.397.0510 Fax # 575.393.4388

#### Isaiah 40:31

They that wait upon the Lord shall renew their strength; they shall mount up with wings as eagles; they shall run, and not be weary; and they shall walk, and not faint.

## Holly Energy Partners

## St. Mary's Federal Section 28 of Township 19 South, Range 29 East, Eddy County, New Mexico

## **Delineation Workplan**

April 5, 2012



### Prepared for:

Holly Energy Partners P.O. Box 1260 Artesia, New Mexico 88211

By:

Safety & Environmental Solutions, Inc. 703 East Clinton Street Hobbs, New Mexico 88240 (575) 397-0510

## TABLE OF CONTENTS

	COMPANY CONTACTS	i
I.	BACKGROUND	1
III.	SURFACE AND GROUND WATER	1
V.	CHARACTERIZATION	1
٧.	WORK PERFORMED	2
VI.	ACTION PLAN	2
VII.	FIGURES & APPENDICES  igure 1 – Vicinity Map  igure 2 – Site Plan  ippendix A – Site Photographs  ippendix B – C-141	2
F	igure 1 – Vicinity Map ·	3
۲	igure 2 – Site Plan	4
Α	ppendix A – Site Photographs	5
Δ.	nnondry H C 1/1	6

#### I. Company Contacts

Representative	Company	Telephone	E-mail
Nora Vazquez	Holly Energy Partners	575-746-5475	Nora.Vazquez@hollyenergy.com
Bill Green	Holly Energy Partners	575-748-8968	bill.green@hollyenergy.com
Bob Allen	SESI	575-397-0510	ballen@sesi-nm.com

#### II. Background

Safety and Environmental Solutions, Inc. (SESI) was engaged by Holly Energy Partners (HEP) to perform site assessment of a release area at the St. Mary's Federal located in Section 28 of Township 19 South, Range 29 East, Eddy County, New Mexico.

The New Mexico Oil Conservation Division (OCD) C-141 was filed on December 13, 2011. A contractor working for another company was excavating in the area and hit the 4" steel pipeline with a trackhoe. (HEP did not receive notification of planned excavation per the one-call ticket #2011491401). Clean-up crews were dispatched and free product was removed. Approximately 120 barrels of crude oil was released with approximately 110 barrels recovered.

The site is located on Bureau of Land Management (BLM) land.

#### III. Surface and Ground Water

The nearest groundwater record listed with the New Mexico Office of State Engineers (NMOSE) is in Section 34 Range 29 East and Township 19 South, which is located 0.82 miles southeast of the site. The depth to groundwater was reported at 60 feet in April 1989.

#### IV. Characterization

The target cleanup levels are determined using the "Guidelines for Remediation of Leaks, Spills and Releases" (NMOCD, August 13, 1993). Application of the OCD's soil ranking criteria indicates the Recommended Remediation Action Levels (RRALs) are 10 parts per million (ppm) Benzene, 50 ppm combined BTEX constituents, and 1,000 ppm Total Petroleum Hydrocarbons (TPH), as presented in the following determination:

Depth to Ground Water:	····. · · · · · · · · · · · · · · · · ·	Marie All	
(Vertical distance from contaminants to	Less than 50 feet	20 points	
seasonal high water elevation of	50 feet to 99 feet	10 points	X
groundwater)	>100 feet	0 points	
Wellhead Protection Area:			
(Less than 200 feet from a private domestic	Yes	20 points	
water source; or less than 1000 feet from all	No	0 points	Х
other water sources)			
Distance to Surface Water:			
(Horizontal distance to perennial lakes,	Less than 200 feet	20 points	
ponds, rivers, streams, creeks, irrigation	200 feet to 1000 feet	10 points	
canals and ditches)	>1000 feet	0 points	X
NOONE WAY AND ARREST	RANKING SCORE (T	OTAL POINTS)	₹10

#### V. Work Performed

On April 3, 2012, SESI arrived on location and met with Mr Oscar Moreno and Mr. Kris Jones, Holly Frontier representatives. Mr. Moreno informed SESI that the contractor had hit a Holly 4" steel line while installing a ditch and there was about 2 ft of oil at the bottom of the excavation (ditch). A vacuum truck was onsite and removed all fluid from inside the cut right of way. Mr. Jones stated that Holly fixed the steel line that was damaged. The impacted area was 3-4 feet in depth and >100 barrels of oil was recovered. Devon excavated the area and placed the contaminated soil on a liner, then backfilled the ditch. The poly line within the ditch is a 6" line.

Mr. Jeff Stubblefield, with Holly Frontier, was contacted regarding the release. Mr. Stubblefield stated that there were no initial photographs taken and no sampling was performed.

SESI observed small area of surface staining to the north and west of the right of way with odor. The site was mapped with a Trimble Geo Explorer and photographed. (See Figure 1 and Appendix A)

#### VI. Action Plan

Delineation of the site is necessary. SESI proposes to use a backhoe to vertically and horizontally delineate the spill area below the ditch line because the soil will be too hard for the use of a hand auger. Vertical and horizontal extent will be considered delineated when the TPH concentration in the soil is 1,000 ppm or less.

The ditch in which the release occurred was approximately 60 feet in length and 3 to 4 feet in width and depth. Three (3) test trenches will be installed perpendicular to the ditch line at regular intervals. Samples will be retrieved from native soil at the bottom of the ditch at 3 feet intervals in each of the test trenches. Samples will be split for field PID analysis. The PID results will be recorded in the field notebook and used for later correlation with the laboratory results. Lab-sSamples will be properly packaged, labeled, preserved and transported under chain of custody to Cardinal Laboratories in Hobbs, New Mexico for analysis for Benzene, Toluene, Ethylbenzene and total Xylenes (BTEX) and TPH by GRO/DRO methodology (Modified 8015).


A One Call has been initiated for the site and no responses from any companies operating in the area have been received. SESI will contact Devon directly before any excavation in performed. SESI would like to have a representative from Devon onsite during the delineation activities. A record of all correspondence will be kept and included in the report of delineation activities.


Upon completion of the delineation, the delineation excavations will be backfilled. An estimate of the amount of contaminated soil will be determined and an appropriate work plan will be prepared. The work plan will address onsite remediate technologies that will insure closure under NMOCD and BLM Guidelines.

### VII. Figures & Appendices

Figure 1 – Vicinity Map Figure 2 – Site Plan Appendix A – Site Photographs Appendix B - C-141


# Figure 1 Vicinity Map






# Figure 2 Site Plan

.




Formatted: Font: (Default) Arial, 11 pt, Font color: Red




Formatted: Font: (Default) Arial, 11 pt, Font color: Red

Appendix A Site Photographs Site Photographs April 3, 2012


Surface staining north of spill area



Spill area facing east




Spill area facing west



Spoils pile facing east



Spoils pile facing west



Visible staining west of spill area

# Appendix B C-141

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aziec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

#### State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

			Rei	ease Notific	catioi	n and Co	orrective A	ction				
						OPERA?	ГOR	(	Initia	ıl Report	Final Repor	
Name of Company Holly Energy Partners						Contact Jeff Stubblefield						
Address 1602 W Main Street Artesia, NM 88210						Telephone No 972-322-5782						
Facility Name St Mary's Federal						Facility Type Gathering Line						
Surface Ow	Surface Owner BLM Mineral Owner								Lease N	lo		
LOCATION OF RELEASE												
Unit Letter	Section 28	Township T19S	Range 29E	Feet from the	North	/South Line	Feet from the	East/W	est Line	Coun Edd		
			Latit	ude N 32.627			gitude W 104.	07345				
Type of Rele	926	Crude Oil		NAI	UKE	OF RELI	Release ~120 bb	16	Volume D	ecovered 110 b	hle	
Source of Re		Citide Oil					our of Occurrence			Hour of Discovery		
4" steel pipel				v		12/13/2011				1 2 45 pm		
Was Immedia	ate Notice C		Yes [	No Not Re	equired	If YES, To Randy Dad	Whom? le 575-626-1372					
By Whom?							our 12/13/2011			ıcemail		
Was a Water	course Reac		Yes 🏻	No		If YES. Volume Impacting the Watercourse						
If a Watercou	ise was Im	pacted Descri	be Fully *									
N/A						•						
Describe Cau	se of Proble	em and Remed	Iral Action	Taken *								
B&H Construction was excavating in the area and hit the 4' steel pipeline with a trackhoe. (HEP did not receive notification of planned excavation per the one-call ticket #2011491401.) Clean-up crews have been dispatched and free product has been removed. Sleeves have been applied to the pipe where damage occurred. Contaminated soil will be removed and our environmental contractor will finalize a clean-up plan.												
All released p	Describe Area Affected and Cleanup Action Taken * All released product flowed into the drich adjacent to the road excavated beginning 12/14/2011.  The tree product has been recovered via vacuum truck. The contaminated soil will be excavated beginning 12/14/2011.											
regulations at public health should their o	l operators a or the envir- perations ha ment In ac	are required to onment. The ave failed to a ddition, NMO	report an acceptance dequately CD accept	d/or file certain re e of a C-141 repo investigate and re	clease no it by the emediate	oufications an NMOCD ma contamination	d perform correct irked as "Final Re on that pose a thre the operator of in	ive action poit" doc at to giou esponsibi	ns for releases not relied ind water, lity for co	iant to NMOCD reases which may ereve the operator of surface water, humphance with any	ndanger Trability man health	
	) 4						OIL CONS	ERVA	TION I	DIVISION		
Signature: Love Coupland					Approved by District Supervisor							
Printed Name Lori Coupland												
Title Mgr Rep	Title Mgr Regulatory Compliance A						Approval Date		Expiration Date			
E-mail Address lori coupland@hollyenergy.com						Conditions of Approval Attached			Attached			
Date 12/13/2011 Phone 575.748 4076												

Date 12/13/2011 Phone 575.748 40
Attach Additional Sheets If Necessary