<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

iJMW1324739268

State of New Mexico Energy Minerals and Natural Resources SEP 0 3 2013

RECEIVED

Form C-141 Revised August 8, 2011

Oil Conservation Division NMOCD ARTES Propriete District Office in 1220 S. of St. F. S. P. 1220 South St. Francis Dr.

Santa Fe, NM 87505

Release Notification and Corrective Action											
nJMW 1324738438						OPERATOR ☑ Initial Report ☐ Final Report				rt	
Name of Company DCP Midstream, LP 36785					Contact Dan Landenberger						
Address 10 Desta Drive, Suite 400 W, Midland, TX.,79705						& E-mail: 432.6				ı	
					Facility Typ	ger@dcpmidstre e Pipeline	eam.con	n		-	
Surface Ow	ner BLM			Mineral C)wner				API No		٦
 				<u> </u>		LOEDE	EAGE		1	·	_
Unit Letter					ON OF RELEASE orth/South Line Feet from the East/West Line County					٦	
Omi Letter	23	23S	31E	rect from the	Norui	South Line	Last		vest Line	Eddy	
•				Latitude N32	2.28969	6 Longitud	e W103.74347				
				NAT	TIRE	OF RELI	EASE				_
Type of Rele	ase Gas an	d Crude oil		IVAL	ORE		Release 250 Ms	cf	Volume R	Recovered	٦
						and 10-15 bbls					1
Source of Re	lease Pineli	ne (Line Nan	ne: 20-200	<u> </u>		Date and Hour of Occurrence			Date and Hour of Discovery		
	<u>.</u>	`		,		9/2/2013 20:30					
Was Immedia	ate Notice (1.,			If YES, To Whom?					
			Yes	No Not Re	quired	Mike Brat					╛
By Whom? I Was a Water						Date and Hour 9/3/2013 7:50 If YES, Volume Impacting the Watercourse.					\dashv
was a water	course read		Yes 🛚	No		N/A					
If a Watercou	ırse was İm	nacted Descr	ibe Fully *	N/A		<u> </u>				· · · · · · · · · · · · · · · · · · ·	\dashv
		pacica, Desci	ioo i unij.								
											ŀ
Describe Cau	se of Probl	em and Reme	dial Action	Taken.* Leak	in pipe	line caused d	lischarge of gas a	and cru	de oil. Vi	isible free liquids mixed with	┨
surrounding	soil to min	imize runoff	from wea	ther (rain).						•	4
		and Cleanup A			surface	contaminati	on and placed or	n nlasti	r. Remedis	ation will follow when line is	
repaired and			~,	1101110704			o aa p.a.cca o.	praser	. Atomoun		
										suant to NMOCD rules and	┪
										eases which may endanger leve the operator of liability	
should their o	perations h	ave failed to a	adequately	investigate and re	emediate	contaminati	on that pose a thre	eat to gr	round water	, surface water, human health	l
or the enviror federal, state,	ment. In a	ddition, NMC	OCD accept	tance of a C-141	report do	es not reliev	e the operator of	responsi	ibility for co	ompliance with any other	
rederal, state,	or local lav	vs and/or regu	nations.				OIL CON	SERV	ATION	DIVISION	┥
Dav. Jan	Sinkliner						OIL COIV	<u>JLIC V</u>	7111011	DIVISIOIV	١
Man. V						٨ ــــــ الـــــ	Fi	:.			١
Signature:						Approved by	Environmental S _l	pecians	l:		
Printed Name	: Dan Lan	denberger					·	hamis	By M	14 Demuce	
			•	-							1
Title: Sr. Env	/ironmenta	l Specialist	•		1	Approval Da	EP 0 4 201	\$	Expiration	Date:	_
E-mail Addre	ss: drlande	enberger@dc	pmidstrea	m.com	(Conditions of	Approval:			Attached 🗖	
Data: 00/02/	2012	DI.		10 4005	D.	modiation	ner OCD Rule &	Guide	lines, &	Attached	
Date: 09/03/2			one:432-62		— like	annroval b	v BLM. <u>SUBMIT</u>	REIVIE	DIATION _	200 1000	
4.JWI	N132	4738	5212		-	PROP	OSAL NO LATER	IHAN:	_	2RP-1893	フ
· Tu	1120	11720				<u>)ctok</u>	ses 4,2	<u> </u>	•		

Bratcher, Mike, EMNRD

From:

Landenberger, Dan R < DRLandenberger@dcpmidstream.com>

Sent:

Tuesday, September 03, 2013 7:56 PM

To:

Bratcher, Mike, EMNRD

Cc:

Randy Pair (rpair@blm.gov); Maggard, Roger L

Subject:

RE: Line leak 20-200

Attachments:

C-141Line20-200.pdf

Mike, please see attached a C-141 initial report regarding a DCP line leak that was reported today. Thanks

Dan Landenberger **Senior Environmental Specialist Permian Region**

DCP Midstream, LP 10 Desta Drive, Suite 400 West Midland, TX 79705 Ofc: 432-620-4085

Cell: 432-557-4824

e-mail: drlandenberger@dcpmidstream.com

Bratcher, Mike, EMNRD

From:

Landenberger, Dan R < DRLandenberger@dcpmidstream.com>

Sent:

Tuesday, September 03, 2013 6:50 AM

To:

Bratcher, Mike, EMNRD

Cc:

Randy Pair (rpair@blm.gov)

Subject:

Line leak

Attachments:

20-200 Leak Report 09-02-13 leak 1.docx; Initial Incident Report 20-200 line 9-2-13.doc

Mike, DCP had a line leak yesterday (See attached reports). I just found out about this morning. I will follow up with C-141 report as soon as I get put there and get more info. Thanks

Dan Landenberger Senior Environmental Specialist Permian Region

DCP Midstream, LP 10 Desta Drive, Suite 400 West Midland, TX 79705 Ofc: 432-620-4085

Cell: 432-520-4085

e-mail: drlandenberger@dcpmidstream.com



PODS Leak Entry Form						
Type Leak: Blowing	Mino	r Seeping	(Circle or Highl	ight one)		
LÉ	AK INFO	RMATION				
PODS Line Name 20-200 Line Size: 6.25" steel			Subsystem Booster	n: Gathering Sand Dunes		
Leak Stationing:	B	N32.289696 Ft e: W103.74347 Ft				
Finder Information						
Discovery Date & Time: 09-02-13 @ 2030HRS Reported By: DCP Operator(Keith Beckham)						
One Call Ticket		LINE SHUT IN	YES (X)	NO ()		

Directions- North on Red road from Hwy 128 to Plains Thomason Station then first road West $\frac{1}{4}$ mile red ribbon on left side of road

BLOWDOWN/VENT LOSS

Meter #	Daily Mcf	PSIG Start			
Devon #131- 55-051					
Devon 131-55- 037					
Devon 131-55- 36					
Oxy 131-55-038					

.



INITIAL INCIDENT REPORT

Region	West
Asset	South East New Mexico
Work Group	Field operations
Date of Report	9/2/2013
Date of Incident	9/2/2013
Time of Incident	2030
Work Group Supervisor	Maggard
Person(s) Involved	Field operators
Incident Type	Product Spill
Incident Category	Unknown
What Happened	20-200 line leaked
Additional Comments	Heavy crude oil released from line onto ground

Note: This form is to be completed by the supervisor within 24-Hours of any incident and distributed as necessary depending on the Incident Type and Category.