

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

OCT 10 2013

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NJMW1328952516

OPERATOR

☒ Initial Report

☐ Final Report

Name of Company: Oxy Permian LTD (192463) 16696

Contact: Chris Jones

Address: 1502 W. Commerce, Carlsbad, NM 88220

Telephone No.: 575-628-4121

Facility Name: NMN IB Indian Station 117

Facility Type: Satellite Station

Surface Owner: Federal

Mineral Owner

API#: Lease #:

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County: Eddy
	17	21S	23E		North			

Latitude N 32.473430 Longitude W -104.5233

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 73 bbls	Volume Recovered: 20 bbls
Source of Release: 6" Water Line	Date and Hour of Occurrence: 9/9/2013	Date and Hour of Discovery: 9/9/2013
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD/Mike Bratcher & BLM/Jim Amos	
By Whom: Chris Jones	Date and Hour: 9/10/2013 10:14 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A 6-inch steel flow line was found to be leaking due to corrosion causing a release of 73 barrels of produced water. A vac truck was immediately called to the location and recovered 20 barrels. The flow line was isolated, drained of all fluids, replaced and returned to service. Talon/LPE was contacted to complete the site assessment to determine appropriate clean up actions.

Describe Area Affected and Cleanup Action Taken.* Oxy conducted some initial remediation. The impacted area was inside the berm of the facility. 3 barrels flowed outside the facility measuring approximately 6' x 8'. Once laboratory results are available Talon will submit a detailed work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination from a spill to ground water, surface water, human or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of liability for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Chris Jones

Title: HES Specialist

E-mail Address: Christopher_Jones@oxy.com

Date: 9/10/2013

Phone: 575-628-4121

* Attach Additional Sheets If Necessary

FJMW1328952317

ijmw1328953117

Signed By

Approved:

OCT 16 2013

Remediation per OCD Rule & Guidelines, &
like approval by BLM. SUBMIT REMEDIATION

PROPOSAL NO LATER THAN:

November 16, 2013

2RP-
1993

Bratcher, Mike, EMNRD

From: Christopher_Jones@oxy.com
Sent: Tuesday, September 10, 2013 10:14 AM
To: jamos@blm.gov; Bratcher, Mike, EMNRD
Cc: Tiffney_Burkham@oxy.com; dadkins@talonlpe.com
Subject: 117 Station

This is to inform you that Oxy had a leak at the 117 Station on 9-9-11. The leak totaled 73 bbls, recovered 20, all but about 3 bbls stayed on location. Talon will be going out today to do some sampling. A C141 will follow with a plan to be approved as well.

6 INCH STEEL PRODUCED WATER LINE FROM STATION 117 TO EIB FACILITY LEAK IS WITHIN THE 117 STATION FACILITY
ESTIMATED DAILY PRODUCTION LOSS IS N/A NORMAL OPERATING PRESSURE IS 50 PSI VOLUME OF LEAK IS 73 BBLS
WATER (70 BBLS WITHIN THE FACILITY 3 BBLS OUTSIDE FACILITY) 20 BBLS RECOVERED LEAK IS RECORDABLE SURFACE
AREA IS 6x8 FT DID LEAK LEAVE LOCATION: YES FURTHER REMEDIATION IS REQUIRED NO H2S NON SENSITIVE AREA NO
PUBLIC EXPOSURE NO LANDMARK LEAK IS BELOW GROUND SURFACE OWNER/SURFACE LEASEE OXY REGULATORY
LEASE # UNKNOWN SECT 17 T21S R23E EDDY COUNTY NEW MEXICO

Chris Jones
HES Specialist
Permian Primary Production
Carlsbad, NM
Cell 575-499-3337
Off 575-628-4121

"We do not inherit the earth from
our ancestors; we borrow it from
our children." Chief Seattle

2:35 pm
10/2/13 - Called Chris - Requesting C-141 initial or information. *SM*

10:23 AM
10/10/13 - Called Chris - F/u on Reving C-141 initial.
He said he would contact
Talon to F/u. *SM*