


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*NTM* 1402142800 OPERATOR  Initial Report  Final Report

Name of Company	Oxy Permian Ltd. 192463	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Righthand Canyon 35-7 SWD Battery	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	API No. 30-015-34529 (nearest well)

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	35	21S	24E					Eddy County, NM

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	800 bbls	Volume Recovered	720 bbls
Source of Release	Bad service card on PLC caused power loss to pumps so tanks spilled over	Date and Hour of Occurrence	01/01/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD, James Amos-BLM		
By Whom?	Jennifer Gilkey, BBC International	Date and Hour	01/02/2014 @ 1:58 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* A bad service card on the PLC caused a power loss to the pumps causing the tanks to spill 800 bbls of produced water onto the ground. 720 bbls of produced water were recovered via vacuum truck and the service card was replaced.					
Describe Area Affected and Cleanup Action Taken.* The affected area is approximately 60' x 100' on location. Remediation will be completed in accordance with a plan approved by NMOCD and the BLM.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature:		<b>OIL CONSERVATION DIVISION</b>			
Printed Name: Christopher Jones		Approved by District Supervisor: Signed By			
Title: HES Specialist		Approval Date: JAN 21 2014		Expiration Date:	
E-mail Address: Christopher.Jones@oxy.com		Conditions of Approval:			Attached <input type="checkbox"/>
Date: 1/9/14	Phone: (575) 628-4121	Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN: February 21, 2014</b>			

\* Attach Additional Sheets If Necessary

2RP-2152

**Bratcher, Mike, EMNRD**

---

**From:** Kathy Purvis <kathy@bbcinternational.com>  
**Sent:** Thursday, January 09, 2014 9:24 AM  
**To:** Bratcher, Mike, EMNRD; jamos@blm.gov  
**Cc:** christopher\_jones@oxy.com; cbrunson@bbcinternational.com;  
kswinney@bbcinternational.com; jgilkey@bbcinternational.com  
**Subject:** Initial C-141, Righthand Canyon 35-7 SWD Battery  
**Attachments:** Initial C-141, Righthand Canyon 35-7 SWD Btry.pdf

**Follow Up Flag:** Follow up  
**Flag Status:** Completed

Attached is the initial C-141 for a leak that occurred at the Righthand Canyon 35-7 SWD Battery on 01/01/2014 in Eddy County, NM. Receipt notification via email is greatly appreciated.

*Kathy Purvis*  
BBC International, Inc.  
1324 W. Marland  
Hobbs, NM 88240  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
Email: [kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)

**Bratcher, Mike, EMNRD**

---

**From:** Jennifer Gilkey <jgilkey@bbcinternational.com>  
**Sent:** Thursday, January 02, 2014 1:58 PM  
**To:** James Amos; Bratcher, Mike, EMNRD  
**Cc:** Christopher\_Jones@oxy.com; Cliff Brunson ; Ken Swinney; Kathy Purvis  
**Subject:** Leak Notification - Righthand Canyon 35-7 SWD

On behalf of Oxy, this is to inform you Oxy Permian Primary NM North had a release at the Righthand Canyon 35-7 SWD on January 1, 2014. Oxy released 800 bbls of produced water, 720 bbls were recovered using a vacuum truck. Spill did not leave the location. The leak was due to a bad service card which caused a power loss to the pumps and caused the tanks to spill over. The leak is located in UL K, Sec 35, T21S, R24E in Eddy County. API number 30-015-34259. Initial C141 to follow. BBC will delineate at a later date. Driving directions: Carlsbad – go north on Hwy 285 to CR 137, go 10 miles, cross over low water crossing, take 1<sup>st</sup> left go on caliche road, go 4 miles to top of hill, take 1<sup>st</sup> right to facility.

Have a great day!

.....  
*Jennifer Gilkey*  
*Administrative Manager*  
BBC International, Inc.  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
E-mail: [jgilkey@bbcinternational.com](mailto:jgilkey@bbcinternational.com)  
1324 W. Marland Blvd.  
Hobbs, NM 88240  
.....

