

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBES.OCD

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

JUL 11 2014

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

OPERATOR

RECEIVED

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production	Contact Tracy Kidd	
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575.513.0628	
Facility Name Bell Lake 19 State 1H	Facility Type Oil well	
Surface Owner State	Mineral Owner State	API No. 30-025-41024

LOCATION OF RELEASE

Unit Letter M	Section 19	Township 24S	Range 33E	Feet from the 200	North/South Line FSL	Feet from the 700	East/West Line FWL	County Lea
------------------	---------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	---------------

Latitude: 32.1964625 N

Longitude: 103.6175640W

NATURE OF RELEASE

Type of Release Spill produced water	Volume of Release 12BBLS	Volume Recovered 5BBLS
Source of Release vacuum truck sight glass	Date and Hour of Occurrence July 2, 2014 11:30 AM	Date and Hour of Discovery July 2, 2014 11:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Thomas Oberding; OCD & Jim Amos BLM	
By Whom? Lynn Smith, Assistant Production Foreman	Date and Hour July 2, 2014 11:45 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

After Basic water truck driver loaded her truck with water the sight glass broke due to weatherization and fatigue. She immediately closed two valves at the sight glass to minimize the amount of fluid spilled. The fluid was blown out of the truck and back into the water tank. A total of 5 barrels of produced water were spilled and Basic recovered 5 barrels with a vacuum truck on the same day.

Describe Area Affected and Cleanup Action Taken.*

The spill occurred near the water tank on location at the load line affecting approximately 15' x 20'. Basic services removed the affected soil on July 9, 2014 and replaced it with fresh soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sandra Farley</i>	OIL CONSERVATION DIVISION	
Printed Name: Sandra Farley	Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 7-14-14	Expiration Date: 9-7-14
E-mail Address: Sandy.Farley@dvn.com	Conditions of Approval: <i>Site Samples 1 year</i>	Attached <input type="checkbox"/>
Date: July 9, 2014 Phone: 575.746.5587	<i>Determine & remediate area 9.5 pm</i>	<i>7-14-3169</i>

* Attach Additional Sheets If Necessary

per NMOCD guides. Submit final C-141 by 9-17-14

*OSD 6137
ATO 14 19-531901
p 10 17 19-532073*

JUL 14 2014