MDistrict I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

SEP 0 2 2014

Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

SEF 0 5 2014

Release Notification and Corrective Action

	OPERATOR	☐ Initial Report ☐ Final Report
Name of Company Chevron USA Inc.	Contact David A. Pagano	
Address 15 Smith Rd., Midland, TX, 79705	Telephone No. wk: 575-396-	-4414X275 cell: 505-787-9816
Facility Name: West Lovington Unit No. 72	Facility Type: Production Well	
Surface Owner NA Mineral Owner	State of New Mexico	API No. 3002530964
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County		
Unit Letter Section Township Range Feet from the North	n/South Line Feet from the East W	t/West Line County Lea
Latitude = 32.863975° Longitude = -103.363827°		
NAMUDE OF DELEACE		
Type of Release Spill to Land Volume of Release 0.55 bbl oil Volume Recovered 0mcf		
Type of Release Spirito Land	& 10.0 bbl produced water	volume Recovered offici
Source of Release West Suction Tank	Date and Hour of Occurrence	Date and Hour of Discovery
	11/13/13 2:00PM	11/13/13 2:00PM
Was Immediate Notice Given?	If YES, To Whom? Geoffrey Leking	
By Whom? James Trujillo	Date and Hour 11/14/13 10:30AM	
Was a Watercourse Reached?	If YES, Volume Impacting the W	
☐ Yes ☒ No		
If a Watercourse was Impacted, Describe Fully.*		
N/A		
Describe Cause of Problem and Remedial Action Taken.*		
Well was shot in Co. 24 hours have in the stand of While the could not shot in well reached higher hottom halo pressure than stuffing how rating and the		
Well was shut in for 24 hour chemical treatment. While the well was shut in, well reached higher bottom hole pressure than stuffing box rating and the BOP rams did not hold leading to a stuffing box leak.		
Describe Area Affected and Cleanup Action Taken.*		
Spill area was approx. 108' by 18' area rectangular are to the West of the well head and a 24. Vacuum Truck called out to vacuum up standing fluids and		
backhoe excavated top layer of soil approx. 12-18". Vacuum Truck Recovered 9.5 bbls of fluid. Next step is to take samples to determine effectiveness of		
local remediation and possibly turn remediation over to the Chevron Environmental Management Company.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and		
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability		
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health		
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other		
federal, state, or local laws and/or regulations. OH. CONSEDIVATION DIVISION		
Signature: David Pagano	OIL CONSERVATION DIVISION	
Signature: David Jayano		
Printed Name: David A. Pagano	Approved by Environmental Specialist:	
·		
Title: Health & Environmental Specialist	Approval Date: 9-2-14	Expiration Date: 1/-2-/4
E-mail Address: dpgn@chevron.com	Conditions of Approval:	A 441 1 -
		Attached 🗆
Date: 11/23/13 Phone: 505-787-9816 * Attach Additional Sheets If Necessary	Site Suplar regard Dobe smedate area as por	Nmoco (Rf-3298
Autach Aughlohai Sheets II Necessary	grado, grant fine (-)	MTO 1424 541814
	11-2-14	P701414 541197
		<i>p</i> (** , ** , ** , ** , ** , ** , ** , **