

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

OCT 08 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NABI428133861

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. <i>2100737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: North Indian Flats 26 Federal #1	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-27556	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	26	21S	28E	2150	North	1980	East	Eddy

Latitude N 32.452537 Longitude W 104.054648

NATURE OF RELEASE

Type of Release: Crude oil and Produced water	Volume of Release: 2 bbls crude oil and 8 bbls produced water	Volume Recovered: 1 bbl crude oil and 4 bbls produced water
Source of Release: Flange gasket on water transfer pump.	Date and Hour of Occurrence: 9/24/14 time unknown	Date and Hour of Discovery: 9/24/14 at approximately 2:20 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher, H. Patterson and Jim Amos	
By Whom? Tony Savoie	Date and Hour: 9/24/14 at 2:46 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A flange gasket failed on the water transfer pump. The flange gasket was replaced.

Describe Area Affected and Cleanup Action Taken.* The spill affected approximately 450 sq. ft. of earthen containment berm around the water storage tank. The spill area will be remediated following the NMOCD and BLM guidelines for spills and releases.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <i>10/8/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval: Attached <input type="checkbox"/>	
Date: <i>10/7/14</i> Phone: 432-556-8730	Remediation per O.C.D. Rules & Guidelines	
SUBMIT REMEDIATION PROPOSAL NO		
LATER THAN: <i>11/8/14</i>		

* Attach Additional Sheets If Necessary

2RP-2523

Patterson, Heather, EMNRD

From: Savoie, Tony A. <TASavoie@BassPet.Com>
Sent: Wednesday, September 24, 2014 2:46 PM
To: Jim Amos (James_Amos@blm.gov); Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: Spill North Indian Flats 26 Federal #1
Attachments: 20140924_140438.jpg; text_0002.txt

Truck is in route to recover fluid from the dirt containment.
Doesn't look like anything got outside the berm.
Will get a volume estimate and submit a C-141
Thanks
Tony

From: 4325568730@mms.att.net [mailto:4325568730@mms.att.net]
Sent: Wednesday, September 24, 2014 2:41 PM
To: Savoie, Tony A.
Subject:

2RP-2523

FIELD SPILL REPORT

Distribution List: CJ Barry, TA Savoie, RL Gawlik, JR Smitherman, SF Johnson, FD Schoch, G Fletcher, J Fuqua, A Ruth, A Thompson, S Walters, B Blevins

DATE: September 24, 2014

LOCATION OF SPILL SITE: North Indian Flats 26 #1 Btry (API-20-015-27556) UL C-26-21S-28E

GPS COORDINATES (Lat & Long): 32.452537 -104.054648

ESTIMATED VOLUMES (Oil & Water Separately):

*If BBLs Recovered are not available at time of Initial Report: Send in Followup report when numbers are known

Volume spilled:		BBLs Spilled	*BBLs Recovered	Net Spilled			BBLs Spilled	*BBLs Recovered	Net Spilled
On ground /or earth berm -	Oil:	2.1	1.5	0.6	Water:		7.4	3.5	3.9
Contained in impervious liner -	Oil:			0	Water:				0
	Total:	2.1	1.5	0.6	Water:		7.4	3.5	3.9




DESCRIPTION (What happened?):

Flange gasket on water transfer pump failed

SPILL RESPONSE (How was the spill cleaned up?):

Vac truck called to location. Loction will need to be remediated

PICTURE ATTACHMENT:



9-25-14 EHS

A. Ruth


V.A 26 Federal #1

Occurred 9-24-14 Flange gasket on water transfer pump failed.

Source GPS - 32.45256° N
104.25462° W

123 truck recovered 1.5 bbls oil, 3.5 bbls PW

earthen berm at NE corner of pad



Oil	PW	
$20' \times 5' \times 2' \times 1'' = 0.14$	$20' \times 5' \times 2' \times \frac{5}{8}'' = 0.74$	100 Sq. Ft.
$25' \times 10' \times 1'' = 0.19$	$25' \times 10' \times 5'' = 0.93$	250 Sq. Ft.
$10' \times 10' \times 4'' = 0.30$	$10' \times 10' \times 2.5' = 2.23$	100 Sq. Ft.
Hbls: 0.63	bbls 3.9	450 Tot