

OCT 22 2014

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC.  
**RECEIVED**

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Linn Operating Inc.	Contact Brian Wall
Address 2130 W Bender Blvd Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name Caprock Maljamar Unit #38	Facility Type Injection

Surface Owner State	Mineral Owner	API No. 30-025-01485
---------------------	---------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	19	17S	33E	660	North	2047	West	Lea

Latitude 32.8254613924331 Longitude -103.704645184513

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 120 bbls	Volume Recovered 70 bbls
Source of Release High Pressure Hose	Date and Hour of Occurrence 10/20/2014	Date and Hour of Discovery 10/20/2014 8am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson -BLM Tomas Oberding- NM OCD	
By Whom? Brian Wall	Date and Hour 10/22/2014 0800	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* Electricians called me and mentioned seeing a leak on the ground. Went to location and saw water being ejected into the air and spraying location with water. We shut in inj well and stopped the flow of water. Leak was caused by a blown hose that connects to the inj well and the well head. Called Benco Svcs to vacuum up water. DFSI to come and fix hoses and replace fittings. Injection well was not taking water prior to incident.

Describe Area Affected and Cleanup Action Taken.\* approximately 300 X 20 ran off location south east stayed mostly on lease road. Directions to site: Turn south on 126 from maljamar for approx. 1 mile. Turn east on Mescalero RD and continue east for approx 5 miles until you hit lease rd W3. turn left and continue 1 mile. Turn right and continue for about 200 yds. Turn right to location

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Brian Wall	Approved by Environmental Specialist:	
Title: Construction Foreman II	Approval Date: 10-22-14	Expiration Date: 12-20-14
E-mail Address: bwall@linnenergy.com	Conditions of Approval: <i>Site Sample upon Release. Enclosure as per NMOCD guidelines. Submit form C-141 by 12-22-14</i>	Attached <input type="checkbox"/> <b>IRP-3390</b>
Date: 10/22/2014 Phone: 806-367-0645		

\* Attach Additional Sheets If Necessary

Og rid: 269324  
N701929594827  
P701929595801

OCT 27 2014