

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Chevron USA Inc.	Contact Edem Sededji
Address: 15 Smith Rd., Midland, TX, 79705	Telephone No. 432-234-4437
Facility Name CVU 274	Facility Type: Oil Well/Injection Well

Surface Owner N/A	Mineral Owner	API No. 30-025-40466
-------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	31	17S	35-E	2033	NORTH	1187	WEST	LEA

Latitude 32.7932 Longitude -103.5016

NATURE OF RELEASE

Type of Release Spill to land	Volume of Release 83.06 bbls	Volume Recovered 70 bbls
Source of Release Half an inch orifice on strainer	Date and Hour of Occurrence 10/15/2014 08:00 AM	Date and Hour of Discovery 10/15/2014 08:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Dr. Tomas Oberding	
By Whom? Edem Sededji	Date and Hour 10/15/2014 09:08 MT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NMOCSD

OCT 31 2014

Describe Cause of Problem and Remedial Action Taken.*

RECEIVED

The spill was due to thread on strainer that stripped. Immediate remedial action was taken using a vacuum truck to clean up the spill. 70 bbls of fluid were recovered.

Describe Area Affected and Cleanup Action Taken.*

The area affected was around Central Vacuum Unit Satellite 4. A vacuum truck was called out and recovered 70 bbls of fluid. The next step is for backhoe to excavate top layer of soil approximate 12" deep and soil samples will be taken to the laboratory to determine TPH, Benzene and Chlorides contaminants levels. In case any of the contaminants levels are still high, the spill location will be turned over to Chevron management Company (EMC) for further remediation.


I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

NOV 04 2014

OIL CONSERVATION DIVISION

10/30/2014

Approved by Environmental Specialist:



X Edem Sededji

Edem Sededji
Health and Environmental Specialist

Signature: Signed by: Edem Sededji

Printed Name: Edem Sededji

Title: HE Specialist

Approval Date: 10-31-14

Expiration Date: _____

E-mail Address: etpo@chevron.com

Conditions of Approval:

Attached

Date: 10/30/2014

Phone: 432-234-4437

IRP-3403

* Attach Additional Sheets If Necessary

1701430726307
P701430726595
Ogrid 4323

HOBBS OCD

OCT 31 2014

RECEIVED