

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*PAB1435830421*  
*PAB1436541962*

**OPERATOR**  Initial Report  Final Report

Name of Company OXY USA WTP LP	Contact CAMPBELL, RODNEY
Address 329 Marathon Rd, Lakewood	Telephone No. (575) 628-4167
Facility Name INDIAN BASIN GAS PLANT	Facility Type GAS PROCESSING FACILITY

Surface Owner	Mineral Owner INDIAN BASIN	Lease No.
---------------	----------------------------	-----------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	23	21-S	23-E					Eddy

Latitude 32.58444 Longitude 104.56666  
Latitude 32°27'52.502" Longitude 104°34'28.004"

**NATURE OF RELEASE**

Type of Release Gas	Volume of Release 1505 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 6/7/2014 11:10:00 AM	Date and Hour of Discovery 6/7/2014 11:10:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MIKE BRATCHER	
By Whom? RODNEY CAMPBELL	Date and Hour 06/09/2014 9:30 A.M. LEFT VOICEMAIL	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

**NM OIL CONSERVATION**

If a Watercourse was Impacted, Describe Fully.* N/A	ARTESIA DISTRICT JUL 16 2014
--	---------------------------------

**RECEIVED**

Describe Cause of Problem and Remedial Action Taken.\*  
Cause:  
OXY INDIAN BASIN GAS PLANT FLARED RESIDUE SALES GAS FOR 50 MINUTES DUE TO KINDER MORGAN'S TOTAL SULFUR SENSOR FAILING CAUSING THE FLARE VALVE TO OPEN.  
Remedial Action Taken:  
OPERATIONS DIDN'T SHOW ANY ALARMS OR INDICATIONS OF WHY RESIDUE SALES GAS WAS FLARING. OPERATIONS CALLED THE OPERATOR OF KINDER MORGAN'S RESIDUE GAS LINE TO SEE IF HE COULD COME CHECK HIS SENSORS AND VALVES. KINDER MORGAN REP FOUND TOTAL SULFUR SENSOR HAD FAILED, HE BLOCKED IN FLARE VALVE AND WORKED ON SENSOR.

Describe Area Affected and Cleanup Action Taken.\*  
N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rodney Campbell</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: RODNEY CAMPBELL	Approved by District Supervisor: <i>Mike Bratcher</i>	
Title: <i>HES Specialist</i>	Approval Date: <i>12/31/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: RODNEY_CAMPBELL@OXY.COM	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date: <i>7-14-14</i> Phone: 575-628-4167		

\* Attach Additional Sheets If Necessary

*PAB1436542831*

*2RP-2702*