State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT Form C-141 Revised August 8, 2011 JAN 06 2015 Submit I Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

NABIEN	1200		Rele	ease Notific	cation	and Co	orrective A	ction					
NAB1501328737						OPERA	ГOR	🛛 Initi	al Report		Final Repor		
Name of Company: BOPCO, L.P. 240737						Contact: Tony Savoie							
						Telephone No. 575-887-7329 Facility Type: Exploration and Production							
Facility Nar	ne: PLU-C	VX-JV-PC	#006H (a	ika PC 33 Fed#	IH) I	Facility Typ	be: Exploration a	and Pro	duction				
Surface Ow	ner: Federa	Federal API No. 30-015-36636											
				LOC	ATION	N OF REI	LEASE						
Unit Letter P	Section 33	Township 24S	Range 30E	Feet from the 350	North/ Sout	South Line th	Feet from the 350	East/V Eas	West Line t	County Eddy			
	I		L	Latitude <u>N 32</u>	.168137	_Longitud	e <u>W 103.87842</u>	24					
				NAT	TURE	OF REL	EASE	-					
Type of Rele						Volume of Release: 40 bbls. Volume Recovered: 20 bbls.							
Source of Re	lease: 1" va	lve on the lact	t unit/truc	k load line header	ſ					Hour of Discovery:			
Was Immediate Notice Given?						1/3/15 time unknown 1/3/15 at 12:21 p.m. If YES, To Whom? NMOCD emergency #104 and the BLM							
By Whom? T	ony Savoie	· · · · · · · · · · · · · · · · · · ·				Date and Hour: 1/3/15 at 3:24 p.m.							
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.						
If a Watercou	irse was Imi	nacted. Descri	ibe Fully.'				······					<u></u>	
A 1" valve co Describe Are The spill imp congealed to around the sp recovered, th The spill area I hereby certi	a Affected a acted appro the point th iill area. The e remainder a will be clear fy that the i	and Cleanup A ximately 10,8 e vacuum truc e next day a v of the oil soa aned up in acc nformation gi	truck load Action Tak 90 sq.ft. c ck could n acuum tru ked into t cordance t ven above	line header broke ten.* of caliche tank bar ot pick up the flu ck and a crew co- he ground. The sp o the NMOCD ar t is true and comp	ttery pad id. The g ntinued v pill area v pd BLM	. A vacuum t ground was fr working on fl was left as is remediation he best of my	ruck was dispatch ozen and covered uid recovery, a to pending final rem guidelines. knowledge and u	with ice tal of 40 nediation	e and snow) bbls of mo n. nd that pur:	A tempora elted snow a suant to NM	ry fenc and oil y	e was built was ules and	
public health should their c or the enviror	or the envir operations homent. In a	onment. The ave failed to a	acceptand adequately OCD accep	ce of a C-141 report investigate and i	ort by the remediate	e NMOCD m e contaminati	nd perform correct parked as "Final R ion that pose a thr ye the operator of	eport" d eat to gr responsi	loes not rel round wate ibility for c	ieve the ope r, surface w compliance	erator of ater, hu with any	f liability man health	
Signature: Low Zourie Printed Name: Tony Savoie						OIL CONSERVATION DIVISION Signed By Mile Democrace Approved by Environmental Specialist:							
	-	it and Remedi	ation Spe	cialist		Approval Date: 1/13/15 Expiration Date:				Date: N/	NIA		
E-mail Addre							Conditions of Approval: Mediation per O.C.D. Rules & Guidelines						
Date: 1/6/15			F	Phone: 432-556-8	730 SUE	<u>BMIT REM</u>	EDIATION PR	1162 G 10000	Sal No	IES			
Attach Addit	ional Shee	ts If Necess	ary		LAT	ER THAN	:	5_	_		2RF	2.2727	

FIELD SPILL REPORT

Distribution List: CJ Barry, TA Savoie, RL Gawlik, JR Smitherman, SF Johnson, FD Schoch, G Fletcher, J Fuqua, A Ruth, A Thompson, B Blevins, K Bright

DATE: January 3, 2015

LOCATION OF SPILL SITE: PLU-CVX-JV-PC #006H API 30-015-36636 UL P, Sec 33, Twns. 24S, R 30E

"aka" Pierce Canyon 33 Federal #1H

GPS COORDINATES (Lat & Long): N 32. 168137° W 103.878424°

ESTIMATED VOLUMES (Oil & Water Separately):

*If BBLs Recovered are not available at time of Initial Report: Send in Follow-up report when numbers are known

Volume spilled:	BBIs Spilled	*BBls Recovered	Net Spilled		BBIs Spilled	*BBls Recovered	Net Spilled	
On ground /or earth berm -	40	20	20	Water:	0		0	
Contained in impervious liner - Oil:				0	Water:			0
Total:	Oil:	40	20	20	Water:	0	0	0


DESCRIPTION (What happened?):

A 1" valve on the truck load line and lact unit suction header failed. EHS was notified at 3 p.m. and the agencies were notified at 3:24 p.m. 1/3/15

SPILL RESPONSE (How was the spill cleaned up?):

The vacuum truck was unable to pick up oil on 1/3/15 due to frozen conditions. Returned on 1/4/15 with a crew and was able to squeegee and recover most of the free standing fluid. EH&S reviewed the site at 9 a.m. It was reported that about 45 bbls total fluid was recovered, a little over half was rain-water . Photographed and determined oil loss in soil. (Photos 1/4/14 at 9:06 am)

PICTURE ATTACHMENT:





PLÚ-CVX JV-PC #006H




ALC: NO

201) 3:00:pm











Goog