

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

MAR 17 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

Amended

NAB1507829746

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company	Devon Energy Production Company	Contact	Production Foreman; Joah Weidemann
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-513-1528
Facility Name	Ross Ranch 10 Federal 1 SWD	Facility Type	Salt Water Disposal

Surface Owner	Federal	Mineral Owner	Federal	API No	30-015-29605
---------------	---------	---------------	---------	--------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	10	26S	31E	1980	North	660	East	Eddy

Latitude: 32.059235486

Longitude: -103.75905787

NATURE OF RELEASE

Type of Release	produced water spill	Volume of Release	45 BBLS	Volume Recovered	45 BBLS
Source of Release	hole in the 2" equalizing line on the back of the produced water tanks	Date and Hour of Occurrence	March 11, 2015 8:30 AM	Date and Hour of Discovery	March 11, 2015 8:30 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher; OCD & Jeff Robertson; BLM		
By Whom?	Assistant Production Foreman; David Washington	Date and Hour	March 12, 2015 8:30 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		
If a Watercourse was Impacted, Describe Fully.*	N/A				
Describe Cause of Problem and Remedial Action Taken.*	Corrosion caused a hole in the 3" equalizing line on the back of the produced water tanks. The leak was stopped by disconnecting and plugging the leaking line. The corroded line has been replaced.				
Describe Area Affected and Cleanup Action Taken.*	45 BBLS of produced water was released into the lined containment around the water storage tanks. Containment was not breached. All of the 45 BBLS released was recovered by vacuum truck and returned to the storage tanks. No further action is required.				

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Sandy Farley</u>	OIL CONSERVATION DIVISION	
Printed Name: Sandra Farley	Signed By <u>Mike Bratcher</u>	
Title: <u>Field Admin Support</u>	Approved by Environmental Specialist:	
E-mail Address: <u>sandy.farley@dm.com</u>	Approval Date: <u>3/19/15</u>	Expiration Date: <u>N/A</u>
Date: <u>3/16/15</u> Phone: <u>575.746.5587</u>	Conditions of Approval: <u>FINAL</u>	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-2894

Bratcher, Mike, EMNRD

From: Farley, Sandy <Sandy.Farley@dm.com>
Sent: Tuesday, March 17, 2015 3:58 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Jeff Robertson (jlr@blm.gov); Sol Hughes (shughes@blm.gov); Jim Amos (jamos@blm.gov)
Subject: RE: Ross Ranch 10 Fed 1 SWD 45BBLS PW Spill 3.11.15
Attachments: Ross Ranch 10 Fed 1 SWD 45BBLS PW Spill 3.11.15 Initial and Final C-141.doc

Good afternoon,

Attached is an amended copy of the Initial and Final C-141 I submitted yesterday regarding the 45 BBLS produced water spill that occurred at the Ross Ranch 10 Fed 1 SWD on March 11, 2015. The original document stated that corrosion caused a leak in the 2" equalizing line; this is incorrect as it is a 3" equalizing line.

Amended copy attached.

Apologies for the inconvenience.

Have a wonderful day

Sandra Farley

Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, New Mexico 88211
575 746 5587



From: Farley, Sandy
Sent: Monday, March 16, 2015 3:50 PM
To: Mike Bratcher (mike.bratcher@state.nm.us)- OCD Eddy County; 'Patterson, Heather, EMNRD'
Cc: Jeff Robertson (jlr@blm.gov); Sol Hughes (shughes@blm.gov); Jim Amos (jamos@blm.gov)
Subject: Ross Ranch 10 Fed 1 SWD 45BBLS PW Spill 3.11.15

Good afternoon,

Attached is the Initial and Final C-141, pictures and GIS Image for the 45 BBLS produced water release that occurred at the Ross Ranch 10 Fed 1 SWD on March 11, 2015. The pink dot on the GIS Image marks the approximate origin of the release.

Have a wonderful day

Sandra Farley

Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, New Mexico 88211
575 746 5587



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.