

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1522941534

Name of Company		Contact	OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Oxy Permian Ltd.		CJ Summers			
Address 6 Desta Drive, Midland, TX 79705		Telephone No. (432) 685-5824			
Facility Name Coyote 21 #2		Facility Type Well			
Surface Owner McDonald/Bradley		Mineral Owner		API No. 30-015-29864	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	21	24S	29E					Eddy County, NM

Latitude N 32.19845° Longitude W 103.99052°

NATURE OF RELEASE

Type of Release Oil and produced water	Volume of Release 5 bbls oil, 30 bbls produced water	Volume Recovered 30 bbls
Source of Release Over pressure on the stuffing box caused the packing to blow out of the well head	Date and Hour of Occurrence 07/23/2015	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Heather Patterson-NMOCD	
By Whom? Jennifer Gilkey @ BBC International Inc.	Date and Hour 07/24/2015 @ 5:07 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Over pressure on the stuffing box caused the packing to blow out on the well head and spill 5 bbls of oil and 30 bbls of produced water onto the ground. A vacuum truck recovered 30 bbls of fluids and the packing was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 85' x 70' on location. Remediation will be completed according to a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: CJ Summers		Approved by Environmental Specialist:	
Title: HES Lead		Approval Date: 8/17/15	Expiration Date: N/A
E-mail Address: chancey_summers@oxy.com		Conditions of Approval:	
Date: 8-13-15 Phone: (432) 685-5824		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 9/18/15

2RP-3203

Patterson, Heather, EMNRD

From: Amanda Trujillo <ATrujillo@concho.com>
Sent: Friday, August 14, 2015 5:16 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; James Amos; stucker@blm.gov
Subject: (Notification/C-141 Initial-Final) Blue Thunder 5 Federal #4 (30-015-38477)
Attachments: 7-22-2015 Blue Thunder 5 Federal #4 (TB) Initial-Final.pdf

Mr. Bratcher,

COG Operating LLC is reporting a release on the Blue Thunder 5 Federal #4 (30-015-38477)
Unit P Section 5 Township 19S Range 31E
The release occurred at 10:00 am 7/22/2015
Released: 17 bbls PW
Recovered: 13 bbls PW

This release was caused by corrosion of a 4" line and T. Vacuum trucks were dispatched to recover all standing fluid and repairs were made to the facility. This release remained within the lined berm, fluids were able to be recovered and the facility was cleaned then put back into production. Attached is a C-141 Initial-Final for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

2407 Pecos Ave.
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.