

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Occidental Permian Limited Partnership	Contact Steven M. Bishop
Address 1017 West Stanolind Road, Hobbs, N.M. 88240	Telephone No. (505) 397-8251
Facility Name Turner Tract 2 Central T/B	Facility Type Production

Surface Owner Oxy Permian	Mineral Owner Oxy Permian	Lease No.
---------------------------	---------------------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
'D'	10	19-S	38-E					LEA

Latitude 32°40'47.05" Longitude 103°08'33.64"

38'

NATURE OF RELEASE

Type of Release Produced water and oil	Volume of Release <2 bbls	Volume Recovered 1.5 bbls
Source of Release Heater Treater	Date and Hour of Occurrence 01/13/2006 08:30 AM	Date and Hour of Discovery 01/13/2006 08:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Patricia Caperton	
By Whom? Steven M. Bishop	Date and Hour 01/13/2006 08:50 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Hole came in fire tube of heater treater allowing oil and water to seep into bermed area around heater treater. Pilot light in the heater treater caught oil on fire and lit the oil in the bermed area. Hobbs Fire Department responded to area when smoke was seen. Wells were shut off, circulating pump shut down, and fire was extinguished.

Describe Area Affected and Cleanup Action Taken.*

All liquid spilled was contained in the small bermed area around the heater treater. A vacuum truck was called and all spilled fluid remaining was vacuumed up out of berm. Also emptied heater treater with truck and transferred fluid to tanks. Heater will be removed and repaired or replaced with like vessel. Area will be remediated to NMOCD spill guidelines when heater is removed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Steven M. Bishop		Approved by District Supervisor:	
Title: HES Technician		Approval Date:	Expiration Date:
E-mail Address: Steven_Bishop@oxy.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 01/16/2006	Phone: (505) 397-8251		

* Attach Additional Sheets If Necessary

Oxy 157984
Facility - FPAC0606547150

incident - nPAC0606547286
application - pPAC0606547656