District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

# State of New Mexico Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011
hmit I Conv to appropriate District Office in

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

TAD 152	8 W3 <u>O</u> 2	30	Kele	ease Notific	ation	and Co	orrective A	ction					
NAB15286331221						OPERA?	ГOR		Initia	d Report		Final Report	
							nael Lanc	٠٤.					
						Telephone No. 469-744-6/82							
							Facility Type: Tank Battery						
Surface Owner: Private Mineral Owner:							API No.						
Surface Owner. Filvate Mineral Owner:							AFI NO.						
				LOCA	TION	OF RE	LEASE						
Unit Letter Section Township Range Feet from the North/						South Line	Feet from the	East/W	East/West Line County Eddy				
Latitude <u>32.31587</u> Longitude <u>-104.04916</u>													
NATURE OF RELEASE													
Type of Release: Crude							Volume of Release: 65bbls Volume Recovered: 63.5						
Source of Release: Tank overflow							I I				our of Discovery:		
W							10/9/15 @ 8:30am 10/9/15 @ 8:30am						
Was Immediate Notice Given?  ☑ Yes ☐ No ☐ Not Required							If YES, To Whom? Heather Patterson & Mike Bratcher NMOCD District II						
							Date and Hour:						
By Whom? Sheldon Hitchcock-Talon/LPE							100/16 10 05						
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse, WIVI OIL CONSERVATION						
☐ Yes ☒ No							ARTESIA DISTRICT						
If a Watercourse was Impacted, Describe Fully.*							OCT <b>0 9 2015</b>						
				RE	CEIV	ED							
Describe Cause of Problem and Remedial Action Taken.*  Human error caused a tank battery to overflow while a truck was unloading into the tanks. Vacuum trucks were immediately dispatched to the location to recover the released fluid. All of the fluid was contained within a lined and bermed facility.													
Describe Area Affected and Cleanup Action Taken.*  The affected area was inside of a lined and bermed tank battery. Vacuum trucks were utilized to recover 63.5bbls of crude from the battery. Soil sampling will not be possible within the facility due to the liner. The gravel in the battery will be removed, hauled to an NMOCD approved solid waste disposal facility and replaced. Once the remediation activities are complete, a final C-141 will be submitted to NMOCD for review.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
							OIL CONSERVATION DIVISION						
Signature: Florel							i1 //						
							Approved by Environmental Specialist: Hublin						
Title: Fuld Safety Rep.						Approval Date: 0/13/15 Expiration Date: NA							
E-mail Address: alance bridgergroup.com Conditions of Approval: Remediation per O.C.D. Rules & Guidelineshed													
Date: 10 9 15 Phone: 469-744-6182 SLIBMIT REMEDIATION PROPOSAL NO													
		ets If Necess				ATER TH		3115	<u> </u>	_ ^	RP.	3323	

# Patterson, Heather, EMNRD

From: Sheldon Hitchcock <slhitchcock@talonlpe.com>

**Sent:** Friday, October 09, 2015 5:57 PM

To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD

Cc: Angel Lance; Otis Randle; Tony Strickland; David Adkins; Puranapanda, Venkat R

Subject: Bridger- Pecos River Station Oxy Unload Initial C-141

Attachments: c141.pdf

#### Heather.

Please see the attached initial C-141. As I stated in the notification, all off the fluid was contained within the lined battery. Approximately 65bbls of oil was lost, 63.5bbls were recovered. Obviously due to the liner it will not be possible or necessary to collect soil samples. We are planning on excavating the impacted gravel within the battery, disposing of the gravel at an NMOCD approved solid waste disposal facility and backfilling the battery. Once the remediation is complete I will follow up with a final C-141. Please let me know if you have any questions or concerns. Thank you.

## Respectfully,

### Sheldon L. Hitchcock

Project Manager Talon/LPE 408 West Texas Avenue Artesia, New Mexico 88210

Office: (575) 746-8768 Direct: (575) 616-4021 Cell: (575) 689-5198 Fax: (575) 746-8905

Email: slhitchcock@talonlpe.com

Web: www.talonlpe.com



Better Business Bureau Torch Award for Marketplace Ethics: 2010 Winner, 2009 Finalist

Staples Foundation for Learning Hall of Fame Recipient: 2010 ICIC and Business Week-Top 100: 2010, 2009, 2008, 2007, 2006

Inc. 500/5000: 2012, 2011, 2010, 2009, 2008, 2007

This email and any files transmitted with it are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the system manager. This message contains confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this e-mail. Please notify the sender immediately by e-mail if you have received this e-mail by mistake and delete this e-mail from your system. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited.