

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

FAB1435830421
NAB1530739013

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company OXY USA WTP LP	Contact CAMPBELL, RODNEY
Address 329 Marathon Rd, Lakewood	Telephone No. (575) 628-4167
Facility Name INDIAN BASIN GAS PLANT	Facility Type GAS PROCESSING FACILITY

Surface Owner	Mineral Owner INDIAN BASIN	Lease No.
---------------	----------------------------	-----------


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	23	21S	23E					Eddy

Latitude 32°27'52.502" Longitude 104°34'28.004"

NATURE OF RELEASE

Type of Release Gas	Volume of Release 78.69 MCF	Volume Recovered 0
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Acid Gas Flare	4/4/2014 9:15:00 AM	4/4/2014 9:15:00 AM
Was Immediate Notice Given?	If YES, To Whom?	
<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Cause: OXY INDAIN BASIN GAS PLANT FLARED ACID GAS FOR 85 MINUTES DUE TO LOAD SHED WHILE SWITCHING TO HIGH SPEED TO HANDLE ADDITIONAL GAS RATES. UNIT WOULDN'T RESTART IN HIGH OR LOW SPEED. Remedial Action Taken: OPERATIONS AND PLANT ELECTRICIAN WENT TO MCC TO TROUBLESHOOT LOCKOUT. THE SWITCH GEAR HAD THEM LOCKEDOUT. SWITCH GEAR WAS RESET AND UNIT STILL WOULDN'T START ON HIGH SPEED. UNIT WAS RESTARTED IN LOW SPEED PENDING FURTHER TROUBLESHOOTING ON HIGH SPEED.		
Describe Area Affected and Cleanup Action Taken.* N/A		



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>R. Campbell</u>		OIL CONSERVATION DIVISION	
Printed Name: RODNEY CAMPBELL		Signed By: <u>Mike [Signature]</u>	
Title: <u>HEI Specialist</u>		Approval Date: <u>11/3/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: RODNEY_CAMPBELL@OXY.COM		Conditions of Approval: <u>FINAL</u>	
Date: <u>7-21-2017</u> Phone: (575) 628-4167		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-3370

2RP-3370