<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

JAN 1 5 2016 Submit I Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action	
NAB1601931572	OPERATOR
Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU 139	Facility Type: Exploration and Production
Surface Owner: Federal Mineral Owner	er: Federal API No. 3001529847
LOCATION OF RELEASE	
Unit Letter Section Township Range Feet from the No 24 24S 30E 1980	rth/ <u>South Line</u> Feet from the East/West Line County Eddy
Latitude : 32.19998 Longitude : 103.83173	
NATURE OF RELEASE	
Type of Release: Crude Oil and Produced Water	Volume of Release: 118 barrels oil and 33 barrels PW Volume Recovered: 90 barrels oil and 5 barrels PW
Source of Release: Failed flowline	Date and Hour of Occurrence: Date and Hour of Discovery: 1-12-16 @ 11:00am 1-12-16 @ 12:08pm
Was Immediate Notice Given?	If YES, To Whom?
☐ Yes ☐ No ☐ Not Requir	ed Mike Bratcher, Heather Patterson, Jim Amos
By Whom? Bradley Blevins	Date and Hour: I-12-16 @ 2:45pm via email
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.
If a Watercourse was Impacted, Describe Fully.*	
The materiodise was impacted, Describe Fully.	
·	
Describe Cause of Problem and Remedial Action Taken.*	
The PLU 139 well was pickled and the flowline was flushed with fresh water, due to low lying areas of the flowline the fresh water settled and froze causing flowline to split. A check valve at the battery header also failed causing fluid to flow back down the flowline and was released out the failed	
flowline. Describe Area Affected and Cleanup Action Taken.*	
Vacuum trucks were called to the location and were able to recover 90 barrels of oil and 5 barrels of produced water. A response crew is scheduled to remove the saturated surface material and haul to an approved disposal.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and	
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability	
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health	
or the environment. In addition, NMOCD acceptance of a C-141 reported federal, state, or local laws and/or regulations.	rt does not relieve the operator of responsibility for compliance with any other
rederal, state, or rocal taws and/or regulations.	OIL CONSERVATION DIVISION
	1
Signature: Fradley Blevins	Annual de Fraireannantal Spacialists
Printed Name: Bradley Blevins	Approved by Environmental Specialist:
Title: Assistant Remediation Foreman	Approval Date: 1516 Expiration Date: NA
E-mail Address: bblevins@basspet.com	
•	Gonditions of Approval Gondition per O.C.D. Rules & Guide Integrated Substitute REMEDIATION PROPOSAL NO
Date: 1-15-16 Phone: 432-214-3704 * Attach Additional Sheets If Necessary	
Attach Additional Sheets If Necessary	2RP-3503

Patterson, Heather, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>

Sent: Friday, January 15, 2016 7:38 AM

To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Amos, James

Cc: Blevins, Bradley

Subject:Initial C-141 PLU 139.docAttachments:Initial C-141 PLU 139.doc

Αll,

Please find the attached initial C-141 for the release that occurred at the PLU 139. If you have any question please let me know. Thanks

Bratcher, Mike, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>

Sent: Wednesday, January 13, 2016 3:44 PM

To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Jim Amos

Cc: Blevins, Bradley
Subject: RE: PLU 139 Release

Good Afternoon,

As a follow up to the release that occurred at the PLU 139. The flowline failed due to a split in the line caused by freezing temperatures, the check valve at the battery header also failed causing fluid to back flow out the ruptured pipe. A vacuum truck was called to the location and was able to recover 90 barrels of oil and 5 barrels of PW. I plan on sending a response crew to the spill site to remove the initial saturated material from the surface. I will follow up with an initial C-141. If you have any questions please let me know. Thanks

-----Original Message-----From: Blevins, Bradley

Sent: Tuesday, January 12, 2016 2:45 PM

To: Mike Bratcher; heather.patterson@state.nm.us; Jim Amos

Cc: Blevins, Bradley Subject: PLU 139 Release

All.

Bopco EHS was notified of a release that occurred on the PLU 139 due to a Flowline failure. At this point the vacuum truck is still recovering fluid from the pasture area, the release will exceed 25 barrel volume (oil and PW released). I will follow up once I have more details and a final volume count. Thanks

Sent from my iPhone

Bratcher, Mike, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>

Sent: Tuesday, January 12, 2016 2:45 PM

To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Jim Amos

Cc: Blevins, Bradley
Subject: PLU 139 Release

All,

Bopco EHS was notified of a release that occurred on the PLU 139 due to a Flowline failure. At this point the vacuum truck is still recovering fluid from the pasture area, the release will exceed 25 barrel volume (oil and PW released). I will follow up once I have more details and a final volume count. Thanks

Sent from my iPhone