<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240

NM OIL CONSERVATION of New Mexico
ARTESIA DISPRECTMINERALS and Natural Resources

Form C-141 Revised August 8, 2011

District II 811 S. First St., Artesia, NM 88210 District III

APR 11 2006 Conservation Division 1220 South St. Francis Dr.

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505

PORECEIVED Santa Fe, NM 87505

			Kel	ease Notifica	atio	on and Co	orrective A	ction	1 .				
DABIL	110351	105/060		OPERATOR			☐ Initial Report ☐ Final Report						
Name of Co	ompany SN	'n Ě <u>NERGY</u>		3	Contact LISA HUNT								
Address 630			Telephone No. (432) 848-4833										
Facility Nat	ne Geroni	mo Battery			j	Facility Type Battery							
Surface Ow	ner BLM		wner	API No. 3001524927									
<del></del>			T =2			N OF RE				r			
Unit Letter	Unit Letter Section Township Range Feet from the No G 24 185 31E 2310 N								East/West Line County E Eddy				
G 24 18,5 31E 2510 N				IN		2310	-		Eddy				
				Latitu	de 32	2.734005 <b>Lo</b> r	rgitude				_	,	
				NATI	URE	OF REL				•		,	
Type of Rele	ase Produce	Volume of Release Volume Recovered											
Source of Re	lease Check	14.33 BBLS   13 BBLS     Date and Hour of Occurrence   Date and Hour of Discovery						<u> </u>					
		3/31/16 3/31/16 7:30					00,701						
Was Immedia	ate Notice (			7		If YES, To	Whom?				_		
			Yes _	No Not Rex	juired								
By Whom?		Date and Hour											
Was a Water	course Reac	If YES, Volume Impacting the Watercourse.											
If a Watercou	irse was Im	pacted, Descr	ibe.Fully.	*		_,							
i													
Describe Cau											_	<del> </del>	
While making his rounds, the lease operator discovered that the 1/4" plug on a check valve located on the discharge of the produced water transfer pump													
had failed and was causing a spray of produced water to be released into the bermed portion of the battery.													
j										$\overline{}$			
Describe Are	a Affected :	and Cleanup A	Action Tal	:*		(K)							
				uck driver picked t	ıp star	nding fluid and	l placed the fluid	into the	PW ta	he affected	soil ir	iside the	
battery will b	e blended w	ith fresh soil.											
Lhereby certi	tv that the i	ntormation of	ven above	is true and comple	ete to	the best of my	knowledge and n	nderstar	ad that mure	nant to NM	<u> </u>	rules and	
				id/or file certain rel									
				e of a C-141 report									
				investigate and reatance of a C-141 re									
federal, state,				italice of a C-141 fc	гропс	uoes not renev	e the operator or .	responsi	omy for co	impuance w	Tur au	y other	
		<u></u> 1					OIL CON	SERV	ATION	DIVISIO	N	<b>W</b>	
	<b>√</b> .	$\neg$ d.	. —		Į		0.2 0011	<u>JDIC (</u>	1,	<u> </u>	<u></u>		
Signature: (	Sua.	1 the	1 <u> </u>				C: 1 D.	" As	1/2 X				
Printed Name	eLisa Flunt				Ī	Approved by	Environiaendi B	pecialis	(14 N)K	minicipe_	Ξ		
							Minhi			- <b> A</b>			
Title:Regulate	ory Technic	ian				Approval Dat			Expiration I	, , , ,	L		
E-mail Addre	ss: Lhunt@	sm-energy.co	Conditions of	Approvic.D. F	Rules (	Guldeli	nes Attached						
Date: Phone: SI							SUBMIT REMEDIATION 12 1/2						
Auach Addit	ional Shee	ts If Necess	ary ,	Λ	ı	ATER THA	N:	<u> </u>	<del></del>	_	7DE	1.36A5	
ANK	prodic	15 15	not i	approved						4	<b>-</b> ヘ		
W &		7	/	//									