									NSERV	ATION	
								AUG	2 4 201	7	
IN S. First St., Artesia, NM 88210					State of New Mexico y Minerals and Natural Resources Oil Conservation Division 220 South St. Francis Dr.			RECEIVED Form C- Revised April 3, Submit 1 Copy to appropriate District Offic accordance with 19.15.29 NM			13,201
istrict IV 1220 Sou) St. Fran 9, NM 87:					
ABIS	5286	30830	⊃ Rele				orrective A	ctio	1		
AAB!	724	140145 Ikota Trucki	5 a	turion 27		OPERA Contact Dre	TOR			al Report 🛛 Fina	Repo
the second s		itic Ave. Co River Station	coa Beacl	i, FL 32931			No. 352-274-09 pe Tank Battery				
urface Ow				Mineral (d				API No). N/A	
				LOCA	TION	N OF RE	LEASE			·	
Unit Letter L	Letter Section Township Range 12 28S 23E		Range 23E	Feet from the	North/	South Line	Feet from the	East/	Vest Line	County Eddy	
			Latitude	32.31587	Lo	ngitude_ <u>-1</u>	04.04916	_ NAI	83	k	
				NAT	URE	OF REL		······ • • • • • • • • • • • • • • • •		10111	
ype of Rele Source of Re	lease Tank	Overflow		<u></u>		Volume of Release 9bbls Date and Hour of Occurrence 8/15/17 @ 8:00am		e		Recovered 9bbls Hour of Discovery 9 8:00am	
Was Immediate Notice Given?						IFYES. To Whosh					
By Whom? N/A						1 1.11					
ly Whom? I	N/A			NO KI NOTR	equired	M/A Threes					
		ched?] Yes 🛛	· · · · · · · · · · · · · · · · · · ·	equired	The		he Wate	rcourse.		
Was a Water If a Waterco N/A	course Rea urse was In	ched?] Yes 🔯 ribe Fully.] No	equired	Theres.		he Wate	rcourse.		
Was a Water If a Waterco N/A Describe Cau Human error	course Rea urse was In use of Prob	ched?] Yes 🔀 ribe Fully. ¹ edial Actio ow at the C	No •	iver stati	Der and f R VES, Sa N/A	the the stating t			ed into the lined containm	ent. A
Was a Water If a Waterco N/A Describe Cat Human error vacuum truc Describe Are All of the flu	course Rea urse was In use of Prob r resulted ir k was utiliz ea Affected uid was con	ched?	Yes X ribe Fully.' edial Actio ow at the C all of the f Action Tal the lined b	No Taken.* Centurion Pecos R luid from the batt ten.* attery. A vacuum	iver stati ery. truck wa	ion. Approxi	mately 9bbls of cr	ude oil ·	were release	e stained gravel ballast we	
Was a Water If a Watercoo N/A Describe Can Human error vacuum truc Describe Ara All of the flu removed and I hereby cert regulations a public healti should their or the enviro	course Rea urse was In use of Prob r resulted in k was utiliz ea Affected aid was con 1 disposed of tify that the all operators operations onment. In	ched? pacted, Description lem and Remed a tank overflow a tank overflow ted to recover and Cleanup tained within of. The liner w information g s are required ironment. The have failed to	Yes ribe Fully. ¹ edial Actio ow at the C all of the f Action Tal the lined b vas inspector given above to report al e acceptan adequately OCD accep	No Taken.* Centurion Pecos R luid from the batt ten.* attery. A vacuum cd and determined is true and comp nd/or file certain is ce of a C-141 repu- investigate and r	iver stati ery. truck was to be in lete to the release no ort by the emediate	ion. Approxi	mately 9bbls of cr recover the fluid i avel ballast was in knowledge and u nd perform correc tarked as "Final R ion that pose a thr re the operator of the	ude oil from the stalled i nderstar tive acti eport" d eat to gr responsi	battery. Th the battery d that purss ons for rele poes not relif oound water, bility for co	e stained gravel ballast way. uant to NMOCD rules and asses which may endanger eve the operator of liability , surface water, human hea ompliance with any other	S
Was a Water (f a Watercow N/A Describe Can Human error vacuum truc Describe Ara All of the flu removed and 1 hereby cert regulations a public healti should their or the enviro	course Rea urse was In use of Prob r resulted in k was utiliz ea Affected aid was con 1 disposed of tify that the all operators operations onment. In	ched? pacted, Description lem and Reme a tank overfle ed to recover and Cleanup tained within of. The liner w information g s are required ironment. The have failed to addition, NMG	Yes ribe Fully. ¹ edial Actio ow at the C all of the f Action Tal the lined b vas inspector given above to report al e acceptan adequately OCD accep	No Taken.* Centurion Pecos R luid from the batt ten.* attery. A vacuum cd and determined is true and comp nd/or file certain is ce of a C-141 repu- investigate and r	iver stati ery. truck was to be in lete to the release no ort by the emediate	ion. Approxi	mately 9bbls of cr recover the fluid i avel ballast was in knowledge and u nd perform correc tarked as "Final R ion that pose a thr re the operator of the	ude oil from the stalled i nderstar tive acti eport" d eat to gr responsi	battery. Th the battery d that purss ons for rele poes not relif oound water, bility for co	e stained gravel ballast way, y. uant to NMOCD rules and ases which may endanger eve the operator of liability	S
Was a Water f a Watercov V/A Describe Cat Human error vacuum truc Describe Arr All of the flu removed and I hereby cert regulations a public healti should their or the enviro federal, state	course Rea urse was In use of Prob r resulted ir k was utiliz ea Affected id was con i disposed of hify that the all operators h or the env operations onment. In e, or local h	ched? pacted, Descr lem and Remo a tank overflo red to recover and Cleanup tained within of. The liner w information g s are required ironment. The have failed to addition, NM aws and/or reg	Yes ribe Fully. ¹ edial Actio ow at the C all of the f Action Tal the lined b vas inspector given above to report al e acceptan adequately OCD accep	No Taken.* Centurion Pecos R luid from the batt ten.* attery. A vacuum cd and determined is true and comp nd/or file certain is ce of a C-141 repu- investigate and r	iver stati ery. truck wa to be in lete to the clease no ort by the emediate report de	ion. Approxi as utilized to tact. New gra- te best of my otifications a e NMOCD m e contaminations not relieved	mately 9bbls of cr recover the fluid i avel ballast was in knowledge and u nd perform correc tarked as "Final R ion that pose a thr re the operator of the	ude oil from the istalled i nderstar tive acti eport" d eat to gr responsi SERV	battery. The battery. The the batter ons for relections ound water, billity for control ATION	e stained gravel ballast way. uant to NMOCD rules and asses which may endanger eve the operator of liability , surface water, human hea ompliance with any other	S
Was a Water f a Watercov N/A Describe Can Human error vacuum truc Describe Arr All of the flu removed and I hereby cert regulations a public healt should their or the envire federal, state Signature:	course Rea urse was In use of Prob r resulted ir k was utiliz ea Affected id was con d disposed of hify that the all operators operations	ched? apacted, Description lem and Remed a tank overfle ed to recover and Cleanup tained within of. The liner w information g s are required ironment. The have failed to addition, NMM aws and/or reg	Yes ribe Fully. ¹ edial Actio ow at the C all of the f Action Tal the lined b vas inspector given above to report al e acceptan adequately OCD accep	No Taken.* Centurion Pecos R luid from the batt ten.* attery. A vacuum cd and determined is true and comp nd/or file certain is ce of a C-141 repu- investigate and r	iver statiery. truck wait to be in elease no. ort by the emediate report de	ion. Approxi as utilized to tact. New gra- te best of my otifications a e NMOCD m e contaminations not relieved	mately 9bbls of cr recover the fluid i avel ballast was in recover the pose a the recover the operator of recover OIL CON: recover the fluid i recover the second second second second recover the second second second second second second recover the second se	ude oil from the istalled inderstartive actieport" deat to grresponsi	battery. The battery. The the batter ons for relections ound water, billity for control ATION	te stained gravel ballast way. uant to NMOCD rules and asses which may endanger eve the operator of liability , surface water, human her ompliance with any other DIVISION	S
Was a Water N/A Describe Can Human error vacuum truc Describe Are All of the flur removed and I hereby cert regulations a public health should their or the enviro federal, state Signature: Printed Narr Title: Finan	course Rea urse was In use of Prob r resulted ir k was utiliz ea Affected aid was con i disposed of tify that the all operatorn h or the env operations poment. In e, or local h me: Drew M cial Control	ched? apacted, Description lem and Remed a tank overfle ed to recover and Cleanup tained within of. The liner w information g s are required ironment. The have failed to addition, NMM aws and/or reg	Yes ribe Fully. ¹ edial Actio ow at the C all of the f Action Tal the lined b vas inspector siven above to report al e acceptan adequately OCD accep gulations.	No Taken.* Centurion Pecos R luid from the batt ten.* attery. A vacuum cd and determined to file certain to ce of a C-141 reporting investigate and related to ance of a C-141	iver stati ery. truck was to be in lete to the release no ort by the emediate	ion. Approxi is utilized to tact. New gra- te best of my otifications a be NMOCD m contaminations not reliev Approved by	inately 9bbls of cr recover the fluid f avel ballast was in knowledge and u nd perform correc tarked as "Final R ion that pose a thr ce the operator of f OIL CON Environmental S te: 2221	ude oil from the istalled inderstartive actieport" deat to grresponsi	battery. The n the battery d that purst ons for rele ound water, bility for co ATION	te stained gravel ballast way. uant to NMOCD rules and asses which may endanger eve the operator of liability , surface water, human her ompliance with any other DIVISION	S

Bratcher, Mike, EMNRD

From:	Sheldon Hitchcock <slhitchcock@talonlpe.com></slhitchcock@talonlpe.com>
Sent:	Thursday, August 24, 2017 11:02 AM
То:	Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD
Cc:	drew.miros@nakotatrucking.com; Clayton_McDonald@oxy.com; David Adkins
Subject:	Nakota Trucking: Pecos River Station Oxy Unlad Inital/Final C-141
Attachments:	20170824104820563.pdf

Mike,

Nakota Trucking had a release at the Centurion Pecos River Station Oxy Unload. They lost approximately 9bbls of fluid. We recovered the fluid, excavated the stained gravel, inspected the liner, and installed new gravel. You may remember a year or so ago we rebuilt that battery and installed a brand new 40-mil liner. The structural integrity of the liner is still sound. I have attached an Initial/Final C-141. Let me know if you have any questions or concerns.

Respectfully,

Sheldon Hitchcock

Project Manager Office: 575.746.8768 Direct: 575.616.4021 Cell: 575.689.5198 Fax: 575.746.8905 Emergency: 866.742.0742 Web: <u>www.talonlpe.com</u>

