

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAY 17 2018

Form C-141
Revised April 3, 2017

Submit to the appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1814140713

OPERATOR

Initial Report Final Report

Name of Company <i>Devon Energy Production Company 12137</i>	Contact <i>Merle Lewis, Production Foreman</i>
Address <i>6488 Seven Rivers Hwy Artesia, NM 88210</i>	Telephone No. <i>575-748-3371</i>
Facility Name <i>Aldabra 26 Fed 8H (release occurred at the Aldabra 26 & 27 CTB)</i>	Facility Type <i>Oil</i>

Surface Owner <i>Federal</i>	Mineral Owner <i>Federal</i>	API No. <i>30-015-38624</i>
------------------------------	------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>P</i>	<i>27</i>	<i>23S</i>	<i>31E</i>					<i>Eddy</i>

Latitude *32.269824* Longitude *103.758459* NAD83

NATURE OF RELEASE

Type of Release <i>Produced Water</i>	Volume of Release <i>66bbbs</i>	Volume Recovered <i>66bbbs</i>
Source of Release <i>Water load line</i>	Date and Hour of Occurrence <i>May 6, 2018 @ 2:00 PM MST</i>	Date and Hour of Discovery <i>May 6, 2018 @ 2:00 PM MST</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>NMOCD-Mike Bratcher & Crystal Weaver BLM-Shelly Tucker</i>	
By Whom? <i>Mike Shoemaker</i>	Date and Hour <i>May 7, 2018 @ 3:17 PM MST</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <i>N/A</i>	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
The 3" water line became corroded and a hole formed causing water to spill into the lined SPCC containment ring. Closed valve & isolated load line to stop any further release.

Describe Area Affected and Cleanup Action Taken.*
Approximately 66bbbs produced water was released into lined containment. A vacuum truck was dispatched and recovered approximately 66bbbs of produced water. All fluid stayed inside the lined SPCC containment. Once fluids were removed the liner was visually inspected by Devon field staff for any pinholes or punctures and none were found. Based on this inspection there is no evidence that the spill fluids left containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>		OIL CONSERVATION DIVISION	
Printed Name: <i>Sheila Fisher</i>		Approved by Environmental Specialist <i>Signed By Mike Bratcher</i>	
Title: <i>Field Admin Support</i>		Approval Date: <i>5/17/18</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>Sheila.Fisher@dvn.com</i>		Conditions of Approval: <i>FINAL</i>	
Date: <i>5/9/18</i> Phone: <i>575.748.1829</i>		Attached <input type="checkbox"/> <i>APP 47110</i>	

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Fisher, Sheila <Sheila.Fisher@dvn.com>
Sent: Thursday, May 17, 2018 9:16 AM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Shelly Tucker (stucker@blm.gov)
Cc: Shoemaker, Mike; Fulks, Brett; Lewis, Merle; Coombes, Justin; West, Christopher
Subject: Aldabra 26 & 27 CTB_66bbbls pw release_5.6.18
Attachments: Aldabra 26 & 27 CTB_66bbbls pw_Initial & Final C-141_5.6.18.doc; Aldabra 26 & 27 CTB_66bbbls pw_GIS Image_5.6.18.pdf

Good Morning,

Attached please find the Initial & Final C-141 and GIS Image for the 66bbbl produced water release at the Aldabra 26 & 27 CTB on 5.6.18.

During initial notification provided by Mike Shoemaker the following information was provided:

1. Aldabra 26 & 27 CTB (The GPS Coordinates for this facility are as follows Lat: 32.269778, Long 103.758172) the nearest Devon well is the Aldabra 26 Fed 8H-API #30-015-38632.
 - a. The 3" water line became corroded and a hole formed causing water to spill into the lined SPCC containment ring. Approximately 66 bbls of produced water was released into the lined SPCC containment ring. Approximately 66 bbls of produced water was recovered.

Since this notification the following information has been corrected and is correctly provided in the C-141.

- Aldabra 26 Fed 8H-API #30-015-38624.
- GPS Coordinates for this facility are as follows Lat: 32.269778, Long 103.758172 the GPS coordinates for the point of origin are Lat: 32.269824, Long 103.758459

If you have any questions please feel free to contact us.

Thank you,

Sheila Fisher
Field Admin Support
Production
B-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any

Aldabra 26 & 27 CTB

66bbbls pw_5.6.18



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by: Sheila Fisher
Map is current as of: 10-May-2018



Miles
0 0.01 0.02 0.04 1:1,779



ASS - SITE - 3-1
NENE

Bratcher, Mike, EMNRD

From: Shoemaker, Mike <Mike.Shoemaker@dvn.com>
Sent: Monday, May 7, 2018 3:17 PM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Shelly Tucker (stucker@blm.gov)
Subject: Aldabra 26 & 27 CTB (Nearest Devon Well is the Aldabra 26 Fed 8H-API # 30-015-38632)

Good Afternoon,

Devon identified the following release at approximately 2:00 PM MST on 05/06/18.


1. Aldabra 26 & 27 CTB (The GPS Coordinates for this facility are as follows Lat: 32.269778, Long 103.758172) the nearest Devon well is the Aldabra 26 Fed 8H-API #30-015-38632.
 - a. The 3" water line became corroded and a hole formed causing water to spill into the lined SPCC containment ring. Approximately 66 bbls of produced water was released into the lined SPCC containment ring. Approximately 66 bbls of produced water was recovered.

A C-141 will be prepared and submitted with GPS coordinates of the area affected.

Thanks,

Mike Shoemaker
EHS Representative

Devon Energy Corporation
6488 Seven Rivers Highway
Artesia, New Mexico 88210
575-746-5566 Office
575-513-5035 Mobile



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.