

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1821343703

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production Company #6137	Contact Aaron Kidd; Foreman Technical Services
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-748-3371
Facility Name Burton Flat Deep Unit 44	Facility Type Salt Water Disposal

Surface Owner Federal	Mineral Owner Federal	API No.30-015-32274
-----------------------	-----------------------	---------------------

LOCATION OF RELEASE

Unit Letter F	Section 3	Township 21S	Range 27E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude_32.635483 N_ Longitude -104.071270 W_ NAD83

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 40.63 BBLS	Volume Recovered 30 BBLS
Source of Release Inlet Line	Date and Hour of Occurrence 7/17/2018 @ 9:15 AM MST	Date and Hour of Discovery 7/17/2018 @ 9:15 AM MST
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? ENMRD Mike Bratcher and Maria Pruett BLM Shelly Tucker	
By Whom? Brett Fulks; EHS Professional	Date and Hour OCD and BLM 7/18/2018 @ 3:51 PM MST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Lease operator discovered a flange on the inlet side of the H-pump had developed a leak. Pumps were shut off and the leak was isolated immediately.

Describe Area Affected and Cleanup Action Taken.*

Water released in containment; scheduled recovery of fluids with Vac truck. (PW: Spilled - 40.63 bbls., Rec. - 30 bbls., Lost - 10 bbls.)

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tamala J. Robison</i>		OIL CONSERVATION DIVISION	
Printed Name: Tamala J. Robison			
Title: Field Admin Support		Approved by Environmental Specialist: <i>Maria Pruett</i>	
E-mail Address: Tamala.Robison@dv.com		Approval Date: 8/01/2018	Expiration Date: n/a
Date: 7/25/2018	Phone: 575-748-3371	Conditions of Approval: See Attached	
		Attached <input type="checkbox"/> 2RP-4885	

* Attach Additional Sheets If Necessary

Operator/Responsible Party,

The OCD has received the form C-141 you provided on 07/31/18 regarding an unauthorized release. The information contained on that form has been entered into our incident database and remediation case number 2RP-4885 has been assigned. **Please refer to this case number in all future correspondence.**

It is the Division's obligation under both the Oil & Gas Act and Water Quality Act to provide for the protection of public health and the environment. Our regulations (19.15.29.11 NMAC) state the following,

The responsible person shall complete division-approved corrective action for releases that endanger public health or the environment. The responsible person shall address releases in accordance with a remediation plan submitted to and approved by the division or with an abatement plan submitted in accordance with 19.15.30 NMAC. [emphasis added]

Release characterization is the first phase of corrective action unless the release is ongoing or is of limited volume and all impacts can be immediately addressed. Proper and cost-effective remediation typically cannot occur without adequate characterization of the impacts of any release. Furthermore, the Division has the ability to impose reasonable conditions upon the efforts it oversees. **As such, the Division is requiring a workplan for the characterization of impacts associated with this release be submitted to the OCD District 2 office in Artesia on or before 08/17/18. If and when the release characterization workplan is approved, there will be an associated deadline for submittal of the resultant investigation report. Modest extensions of time to these deadlines may be granted, but only with acceptable justification.**

The goals of a characterization effort are: 1) determination of the lateral and vertical extents along with the magnitude of soil contamination. 2) determine if groundwater or surface waters have been impacted. 3) If groundwater or surface waters have been impacted, what are the extents and magnitude of that impact. 4) The characterization of any other adverse impacts that may have occurred (examples: impacts on vegetation, impacts on wildlife, air quality, loss of use of property, etc.). To meet these goals as quickly as possible, the following items must, at a minimum, be addressed in the release characterization workplan and subsequent reporting:

- Horizontal delineation of soil impacts in each of the four cardinal compass directions. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. This is not an exclusive list of potential contaminants. Analyzed parameters should be modified based on the nature of the released substance(s). Soil sampling must be both within the impacted area and beyond.

- Vertical delineation of soil impacts. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. As above, this is not an exclusive list of potential contaminants and can be modified. Vertical characterization samples should be taken at depth intervals no greater than five feet apart. Lithologic description of encountered soils must also be provided. At least ten vertical feet of soils with contaminant concentrations at or below these values must be demonstrated as existing above the water table.

- Nominal detection limits for field and laboratory analyses must be provided.

- Composite sampling is not generally allowed.

- Field screening and assessment techniques are acceptable (headspace, titration, EC [include algorithm for validation purposes], EM, etc.), but the sampling and assay procedures must be clearly defined. Copies of field notes are highly desirable. A statistically significant set of split samples must be submitted for confirmatory laboratory analysis, including the laterally farthest and vertically deepest sets of soil samples. Make sure there are at least two soil samples submitted

for laboratory analysis from each borehole or test pit (highest observed contamination and deepest depth investigated). Copies of the actual laboratory results must be provided including chain of custody documentation.

- Probable depth to shallowest protectable groundwater and lateral distance to nearest surface water. If there is an estimate of groundwater depth, the information used to arrive at that estimate must be provided. If there is a reasonable assumption that the depth to protectable water is 50 feet or less, the responsible party should anticipate the need for at least one groundwater monitoring well to be installed in the area of likely maximum contamination.

- If groundwater contamination is encountered, an additional investigation workplan may be required to determine the extents of that contamination. Groundwater and/or surface water samples, if any, must be analyzed by a competent laboratory for volatile organic hydrocarbons (typically Method 8260 full list), total dissolved solids, pH, major anions and cations including chloride and sulfate, dissolved iron, and dissolved manganese. The investigation workplan must provide the groundwater sampling method(s) and sample handling protocols. To the fullest extent possible, aqueous analyses must be undertaken using nominal method detection limits. As with the soil analyses, copies of the actual laboratory results must be provided including chain of custody documentation.

- Accurately scaled and well-drafted site maps must be provided providing the location of borings, test pits, monitoring wells, potentially impacted areas, and significant surface features including roads and site infrastructure that might limit either the release characterization or remedial efforts. Field sketches may be included in subsequent reporting, but should not be considered stand-alone documentation of the site's layout. Digital photographic documentation of the location and fieldwork is recommended, especially if unusual circumstances are encountered.

Nothing herein should be interpreted to preclude emergency response actions or to imply immediate remediation by removal cannot proceed as warranted. Nonetheless, characterization of impacts and confirmation of the effectiveness of remedial efforts must still be provided to the OCD before any release incident will be closed.

Jim Griswold

OCD Environmental Bureau Chief

1220 South St. Francis Drive

Santa Fe, New Mexico 87505

505-476-3465

jim.griswold@state.nm.us

Bustamante, Amalia, EMNRD

From: Pruett, Maria, EMNRD
Sent: Wednesday, August 1, 2018 7:23 AM
To: Bustamante, Amalia, EMNRD
Cc: Bratcher, Mike, EMNRD
Subject: FW: Burton Flat Deep Unit 44 SWD (API # 30-015-32274) Initial C-141
Attachments: Burton Flat Deep Unit 44 SWD_40.63bbls PW_7.17.2018_GIS Map.pdf; OCD Received Signed C-141 Burton Flat Deep Unit 44 SWD_40.63bbls PW_7.17.2018_.doc; revised C-141 directive of 11-4-16.pdf

Good Morning Amalia,

Please find attached the signed/dated C-141 and directive. Please note this also has a photo of site.

Best Regards,

Maria Pruett

Environmental Specialist
N.M. Oil Conservation Division
District 2
811 S. 1st Street
Artesia, NM 88210
Desk: 575 748-1283 X 101
Cell: 575 840-5963
Fax: 575748-9720

From: Fulks, Brett <Brett.Fulks@dvn.com>
Sent: Tuesday, July 31, 2018 9:02 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Pruett, Maria, EMNRD <Maria.Pruett@state.nm.us>; Tucker, Shelly <stucker@blm.gov>
Cc: Shoemaker, Mike <Mike.Shoemaker@dvn.com>; Kidd, Aaron <Aaron.Kidd@dvn.com>; Robison, Tamala <Tamala.Robison@dvn.com>; Jeter, Brandon <Brandon.Jeter@dvn.com>
Subject: Burton Flat Deep Unit 44 SWD (API # 30-015-32274) Initial C-141

Good evening,

Per the below initial notification, please find attached the initial C-141 for a release on 7/17/2018 at the Burton Flat Deep Unit 44 SWD. Please let me know if you have any questions regarding this release.

Thanks,

Brett Fulks
EHS Representative

Devon Energy Corporation

6488 Seven Rivers Highway
Artesia, New Mexico 88210
575 748 1844 Direct
432 301 3223 Mobile



From: Fulks, Brett

Sent: Wednesday, July 18, 2018 3:51 PM

To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Pruett, Maria, EMNRD <Maria.Pruett@state.nm.us>; Tucker, Shelly <stucker@blm.gov>

Cc: Shoemaker, Mike <Mike.Shoemaker@dvn.com>; Kidd, Aaron <Aaron.Kidd@dvn.com>; Fisher, Sheila <Sheila.Fisher@dvn.com>; DeLaRosa, Dana <Dana.DeLaRosa@dvn.com>

Subject: Burton Flat Deep Unit 44 SWD (API # 30-015-32274)

Good afternoon,

Devon had the following release occur at 9:15 AM MST on 07/17/18. The incident is described below.

1. Burton Flat Deep Unit 44 SWD (API # 30-015-32274)
 - a. A lease operator discovered a flange on the inlet side of an H-pump had developed a leak. The pumps were shut off and the leak was isolated immediately. The exact volume of the release was unknown until this morning when Devon received estimates from water haulers of what they recovered from inside the containment. Approximately 40.63 bbls of produced water were released with approximately 30 bbls recovered.

A C-141 will be prepared and submitted with GPS coordinates of the area affected.

Thanks,

Thanks,

Brett Fulks
EHS Representative

Devon Energy Corporation
6488 Seven Rivers Highway
Artesia, New Mexico 88210
575 748 1844 Direct
432 301 3223 Mobile



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s),

are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.