State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action													
						OPERA	ſOR	Σ	Initia	al Report		Final Report	
Name of Company Chevron						Contact Larry D. Ridenour							
Address H	CR 60 Box	423 Loving	88260	-	Telephone No. 505.396.4414								
Facility Nat	ne Vacuu	m Glorietta '	t #92]	Facility Type Injection well								
Surface Ow	mer State		Mineral C	Owner S	State Lease No. B-2146-07 DN OF RELEASE AFIT 30 025 022 120000 th/South Line Least form the Least West Line Country								
				IOC			FASEAPIT	730 025	うのみえい	20000			
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/We	est Line	County			
L	36	17-8	34-E	1426	South		199	West		Lea			
<u> </u>	1.00		.			Tomotend		1					
			ШA	atitude_N 32 4' NAT		OF REL	eW 103 30 5 E ASE	5.9					
Type of Rele	ase Produc	ed Water			Volume of Release 30 bbls Volume Recovered 20 bbls						· · · · · · · · · · · · · · · · · · ·		
Source of Re	lease inject	tion line			Date and Hour of Occurrence			Date and Hour of Discovery					
Was Immedi	ate Notice (Given?			8/15/06 8:30 AM 8/15/06 9:30 AM If YES, To Whom? Pater Caperton								
Yes No Not Required													
By Whom? Larry Ridenour						Date and Hour 8/15/06 11:45 AM							
Was a Water	course Read	ched?	l No		If YES, Volume Impacting the Watercourse.								
		pacted, Descr				11830 -72-							
		puerea, 2000	ice rung.						12 13 14 16 3		~ .		
2 Million 8													
Describe Cause of Problem and Remedial Action Taken.*													
Leak in fiberglass injection line. Well was shut in upon discovery. Vacuum truck picked up water on top of ground. Line will be repaired.													
									` .	<u>.</u>			
Describe Are	Describe Area Affreded and Classon Action Talan *												
	Describe Area Affected and Cleanup Action Taken.* Affected area is approximately 400' x 50 '. (Land was sloping so water ran before pooling up.) Rain water was also a factor. Soil will be tested to												
determine ac	tual extent o	of leak and wi	ll be reme	diated as necessar	ry.								
				e is true and comp nd/or file certain 1									
				ce of a C-141 rep									
				investigate and i									
		ws and/or regu		otance of a C-141	report do	bes not reliev	e the operator of	responsibi	ility for co	ompliance w	ith any	other	
						OIL CONSERVATION DIVISION							
Signature: Jan D Rich						Approved by District Supervisor:							
Printed Name: Larry D. Ridenour													
Title: Operations Representative					4	Approval Date: E			Expiration Date:				
E-mail Address: LRidenour@Chevron.com						Conditions of Approval:			Attached 🔲				
Date: 8/ Attach Addi	16/06 tional Shee	ets If Necess	one: 505.396.441	4									
Mei	lent -	n PAC	06a	4031166 4031292					0M	را در ا	/		
appli	cation	~-pPA	C0(qQ	4021292	ر				KP	¢ Ø/4	Ø		