

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RELEASE NOTIFICATION AND CORRECTIVE ACTION

OPERATOR

Initial Report Final Report

Name of Company: Duke Energy Field Services	Contact: Mark Owens
Address: 1625 West Marland, Hobbs, NM 88240	Telephone No.: (505) 397-5541
Facility Name: A-19-19-3-1	Facility Type: 6" steel pipeline
Surface Owner: State of New Mexico	Mineral Owner: State of New Mexico
Lease No.:	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	12	17 S	34 E					Lea

90~' Latitude: N 32° 43' 33.805" Longitude: W 103° 40' 28.619"

NATURE OF RELEASE

Type of Release: Natural Gas Pipeline Fluids	Volume of Release: ≈ 7 barrels	Volume Recovered: 0 barrels
Source of Release: 6" low-pressure steel pipeline operating at 15-20 lbs	Date and Hour of Occurrence: 29 June 2005	Date and Hour of Discovery: 29 June 2005
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson, NMOCD Hobbs District	
By Whom? Lynn Ward, DEFS Midland	Date and Hour 1041hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Not Applicable.	
If a Watercourse was Impacted, Describe Fully.* Not Applicable		

Describe Cause of Problem and Remedial Action Taken.*
6" steel line began leaking, probably due to internal corrosion. A line repair clamp was installed.

Describe Area Affected and Cleanup Action Taken.* The affected area consists of approximately 2,640 square feet of pasture land owned by the State of New Mexico and leased by Herschel Caviness. A line repair clamp was installed and the line put back into operation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Lynn Ward</i>	OIL CONSERVATION DIVISION	
Printed Name: Lynn Ward	Approved by District Supervisor:	
Title: Environmental Specialist	Approval Date:	Expiration Date:
E-mail Address: lward@Duke-Energy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	Phone:	

* Attach Additional Sheets If Necessary

Facility - APAC 0635350678
Incident - APAC 0635350755
Application - APAC 0635350846

RP# 1151