<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Form C-141 Revised October 10, 2003

					uita i	0, 1111 075						
*****			Rele	ease Notific	eatio	n and Co	orrective A	ction	1			
						OPER/	ATOR		x Initia	al Report	ĬΧ	Final Repor
Name of Cor	npany: Oc	cidental Perm	ian Limite	d Partnership	T	Contact: To	ny Summers				1	
				Telephone No: 505.397.8236 or 505.390.9228								
				Facility Type Production								
Surface Own	er Kelly l	Myers		Mineral C	Jumer	Oxy Lease No.						
Surface Own	ici iciiy i	WIYOIS										
	<u> </u>	m 1:				N OF RE		F-+0	West Line	C		
Unit Letter	Section 31	Township 23S	Range 37E	Feet from the 1398	south		Feet from the 1564	east	west Line	County Le	a	
(~)	100)		Latitude N 32°	15.55	2' Longitude	e W 103° 11.84	5'				
				NAT	URE	OF REL			.			
Type of Release							Release 210			Recovered 1		
Source of Rele	ease Whole	e in injection	trunk line			i i	Iour of Occurrence prox. 11:00am	e	Date and 1:10 pm	Hour of Dis	covery	[,] 3/10/07
Was Immediat	te Notice C	Given?		<u> </u>			Whom? Chris W	illiams				·
		x	Yes	No Not Rec	quired							
By Whom?						Date and Hour If YES, Volume Impacting the Watercourse.						
Was a Waterco	ourse Reac	ched?	Yes x	No		If YES, Vo	olume Impacting t	the Wate	ercourse.			
If a Watercour	rse was Im	nacted Descr	ibe Fully	*			-					
in a watercour	ise was mi	pactoa, Besor	1001 4119.									
Describe Caus	e of Proble	em and Reme	dial Actio	n Taken * On Sat	urday (3/10/07 oper	ator found leak in	injectio	n trunk line	for Myere	Langli	e Mattix nit
							illed. Truck picke					
210 that was le				•			F					
Describe Area	Affected a	and Cleanup A	Action Tal	ken.* The leak har	ppened	on the edge of	f a caliche/sandy	oad. Al	l produced	water stave	d in ro	ad and ran
down road and	d covered a	an area approx	kimately 2	00 yds x 20 yds x	3"to 6	" deep. Vacuu	ım truck picked uj	p all fre				
in to back-dra	ig road. Ac	cording to the	e NMSEO	, average depth to	water	is 120' giving	area a ranking of	0.				
I hereby certify	y that the i	nformation gi	iven above	is true and comp	lete to	the best of my	knowledge and u	ndersta	nd that purs	uant to NM	OCD 1	ules and
							nd perform correc					
							arked as "Final R ion that pose a thr					
or the environ	ment. In a	ddition. NMC	OCD accer	otance of a C-141	report	does not reliev	e the operator of	respons	ibility for co	, surrace wa	vith an	v other
federal, state, o					J		o me operator or	Ороль	1011109 101 0	ompilanoo ,	************	, ourer
							OIL CON	SERV	ATION	DIVISIO	<u>N</u>	
Signature:											_	
Signature.						4	District C		11.	11.1	_	•
Printed Name:	Tony Sur	nmers				Approved by	District Supervise	or: 	pus	Wel	lia	we
Title: HES Tec	chnician				Ī	Approxial Day	3/20/0	,	Euniveties	Dota: 2	120	104
THE TES TE	cimician			<u></u>		Approvar Da	ic. 5/20/0	/	Expiration .	Date: Of	4	-0
E-mail Addres	s: tony_su	mmers@oxy	.com_			Conditions of	District Supervise te: 3/20/0 Approval: Klebownu Kelly	uscu	seed	Attached		
Date:			Phone	: 505.397.8236		W Kand	owner Kell	y m	eyera,			

Facility - PAC0708024203

application - PACO708024338



March 16, 2007

New Mexico Oil Conservation Division District I 1625 N. French Drive Hobbs, New Mexico 88240

Attn: Environmental Engineering

RE: Remediation Plan

Warren McKee Unit SWD UL 'F', Sec. 7, T-20S, R-38E

At 10:30 AM on 03/12/07 tanks from Warren McKee SWD were found running over. Storm from night before had knocked down electricity and alarm communications at approximately 1:00 am. Approximately 350 barrels of produced water was spilled into diked area. Vacuum truck picked up 180 barrels of free standing fluid. Average chlorides for this particular produced water are \(\frac{78}{5}\),000 ppm. No fluid got into pasture. The NMSEO states average depth to water is 80' giving area a ranking of 10. Remediation of spill site will be as follows:

- 1. Piping will be excavated and repaired.
- 2. Affected area (road) will be tested for chloride content along with background samples.
- 3. NMOCD guidelines will be used to insure entire site is in compliance with guidelines.

If you have any questions, or if I can be of further assistance, please contact me at (505) 397-8251.

Tony Summers
HES Technician/Seminole RMT
Tony summers@oxy.com

(505) 397-8236

Attachments: Initial C-141 Hand drawn map of spill site and sample sites







IN; L'Ne leak 3/10/07 MLMU map of sample points Samples taken 3/15/07 75,00 N. Beickground Sompe 50 JG 5079 110765 Leak N 32° 15, 52 2' W 103° 11, 845'



PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR OXY-SEMINOLE RMT ATTN: TONY SUMMERS 1017 W. STANOLIND RD. HOBBS, NM 88240 FAX TO:

Receiving Date: 03/15/07 Reporting Date: 03/19/07 Project Owner: OXY

Project Name: MLMU INJ. LEAK

Project Location: MLMU

Analysis Date: 03/19/07 Sampling Date: 03/15/07

Sample Type: SOIL

Sample Condition: COOL & INTACT

Sample Received By: BC

Analyzed By: HM

		CI [—]	
LAB NO.	SAMPLE ID	(mg/Kg)	
H12342-1	NORTH BACKGROUND	< 16	
H12342-2	SOUTH BACKGROUND	< 16	
H12342-3	#1	176	
H12342-4	#2	3719	
H12342-5	#3	560	
	,		
Quality Cor	500		
True Value	True Value QC		
% Recovery	100		
Relative Pe	rcent Difference	4.1	

METHOD:	Standard	Method:	S	4500-Cl ⁻ B
	4			

NOTE: Analyses performed on 1:4 w:v aqueous extracts.

Chémist

Date