*District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

		onocorniiii				Contact Renneth N. Andersen					
Address 4001 Penbrook, Odessa, TX 79762						Telephone No. 505.676.2371.5569					
Facility Nam	e MCA	Unit Well #		F	Facility Type Oil and Gas						
Surface Own	ner BLM		Mineral O	wner F	er BLM				Lease No LC - 058697B		
LOCATION OF RELEASE											
Unit Letter	T 8					l l			1 -		
F	25	17S	32E	1980	North		1980	West		Lea Co., NM	
Latitude 32.80729N Longitude 103.72202W NATURE OF RELEASE PP # 3002 50068 0000											
Type of Relea	ise		,	Volum					Volume Recovered		
Produced V				11 bb	1 bbl (0 oil, 11 water)				0 oil, 0 water)		
Source of Rel				Date a	ate and Hour of Occurrence				Date and Hour of Discovery		
MCA # 139	injection	line 1" rise	g.	I .					0/22/04 2025h9s		
Was Immedia			8	If YES	YES, To Whom?					5,	
		es 🗌 No	Required		/				\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		
By Whom?	/ ,			Date a	te and Hour				1 0 4 6 6 1 6 1 6 1 6 1 6 1 6 1 6 1 6 1 6 1		
Was a Water	ourse Read	ched?							25 7.80	6	
Was a water	ourse recu	люи. П	No	11 12	100					77	
								\ <u>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</u>	8		
If a Watercou	rse was Im	pacted, Descr	•		100				79		
									1057		200/
Describe Cou	an of Dunchi	om and Doma	dial Actio	n Tolson *					Com - 277	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
Describe Cause of Problem and Remedial Action Taken.* The lock was caused by interpret coversion of the threads on the 1" visor causing the injection line to part. The III visor by wellhood.											
The leak was caused by internal corrosion of the threads on the 1" riser causing the injection line to part. The 1" riser & wellhead											
piping will be inspected and replaced as needed and will maintain well surveillance to prevent future leaks.											
Describe Area Affected and Cleanup Action Taken *											
Describe Area Affected and Cleanup Action Taken.* The area affected in - 70ff 100ff of day calieba wellbood and then 50ff 100ff of day conductors and 2ff 120ff of day calieba.											
The area affected is ~ 70ftX100ft of dry caliche wellhead pad, then 50ftX100ft of dry sandy pasture, and 3ftX180ft of dry caliche											
road. There were no cows present. See attachment for more details.											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and											
				nd/or file certain re							
public health	or the envi	conment. The	accentan	e of a C-141 repo	rt hy the	NMOCD m	arked as "Final R	enort" de	nes not reli	ieve the operato	r of liability
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health											
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other											
federal, state, or local laws and/or regulations.											
		100	2		OIL CONSERVATION DIVISION						
	K	AH)	(/2								
Signature:	enn	ex //	rouser								
Dulanta d Mana	. 1741.	N 4 J		A	Approved by District Supervisor:			The	Wille		
Printed Name	. Kennetn	IN Andersen						me a team			
Title: SHEa	R Snecialis	e t			۸ ا	Approval Dat	e 5/2/10	7	expiration :	Date: 6/2	1/07
111101 011234	- C D D C C C C C C C C C C C C C C C C				ripprovar bate.			Aparation .	Date.	/ /	
E-mail Addre	ss: ken.n.a	ndersen@co	ps.com		Conditions of Approval:			Attached			
Date: 10/26	/04]	05.676.2371.5569	l							
Attacl	Addition	al Sheets If	Necessar	v			·				1
200=2:122=11N											tan
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										+125(1	
\mathcal{M}	10 1/W	ent -		227	ο· ψ ₀				KT' 1500		
00-L. PACO7 435>404											-
Attach Additional Sheets If Necessary Mcidenk - n PAC0714330168 Application PAC07 4333 909											
Ů	1119	• -	T								



MCA Unit Well # 139 attachment.

There is no water source or surface water within 1,000 feet of the spill site and the site is not in a Wellhead Protection Area. Based on data from the ground water monitoring well located at the Frontier Field Services Maljamar Gas Plant, depth to ground water is approximately 90 feet. Due to the above data, the Ranking Criteria Score from the NMOCD "Guideline for Remediation of Leaks, Spills, and Releases" is 10ppm Benzene, 50ppm BTEX, and 100ppm TPH.

The site is an injection well caliche pad and sandy pasture with a slope to the south & west. The leak runs north to south for approximately 70 wide feet by 100 feet long of wellhead pad, then 50 wide by 100 feet long of sandy pasture. The leak also runs east to west for approximately 3 feet by 180 feet of caliche road.

Taking into consideration that the depth to groundwater is greater than 89 feet, that the subsurface soil lithology at the site consists of caliche and sandstone layers, and that only approximately 5 bbls of the 11 bbls impacted sandy pasture land, the rest being on the caliche pad and road; it is evident that the migration of the chlorides of this spill to groundwater is unlikely. The spill will be remediated in place by removing the top \sim 6 inches of contaminated sandy pasture soil and putting in clean soil with amendments added. The caliche wellhead pad and road will be back dragged with a back hoe.

 H_2S is a safety concern at the spill site.

The driving directions to the spill site are as follows: From Maljamar go south on CR 126 3.0 miles then turn east and go 2.4 miles on dirt road to MCA #139. (See enclosed map).

Therefore, ConocoPhillips is submitting this completed closure plan for NMOCD approval. Should there be any questions, please contact me at 505.390.4821. Thank You.

ConocoPhillips





