

NM1 - 3

MONITORING REPORTS


YEAR(S):

1988-1989

MAP

DIKES	ELEV. OF TOP	PIT	ELEV. OF FLUID LEVELS
A	3451	1	3447
CONSTRUCTED B	3451	2	3458
C	3461	3	3458
D	3439	4	3435
E	3439	5	3446
F	3461	6	3447
G	3450	7	3447
H	3450		
I	3450		

HOLE NO.	ELEV. TOP OF PERFS.	ELEV. BASE OF PERFS.
1 - 21	3451	3427
23 - 32	3461	3436
33 - 40	3462	3436
41 - 51	3440	3390
52 - 63	3442+	3415
64 - 76	3449 OR BELOW	3410 OR BELOW
77 - 87	3440	3410



- LEGEND
- TEST HOLE; ● TRIASSIC ENCOUNTERED
 - MONITOR HOLE
 - MONITOR HOLE, ABANDONED
 - △ PIT FLOOR; ▲ TRIASSIC ENCOUNTERED
 - + PIT RIM
 - △ INSTRUMENT STATION
 - ◎ CORE HOLE
 - △ GRAVEL EXPLORATION HOLE
 - DIKE/CORE TRENCH
 - PROPOSED PIPELINE

FIGURE-1

LEA COUNTY, NEW MEXICO
PARABO, INC.

TOP OF TRIASSIC

REV. 2/81
REV. 11/81
REV. 6/16/82
REV. 10/19/83
REV. 4/1/85
REV. 10/30/85

ED L. REED & ASSOCIATES, INC.
CONSULTING HYDROLOGISTS
MIDLAND-CORPUS CHRISTI, TEXAS

copy 2/2 (field copy)