

NM1 - 3

MONITORING REPORTS


YEAR(S):

1988-1989

MAP

DIKES		ELEV. OF TOP	PIT	ELEV. OF FLUID LEVELS
CONSTRUCTED	A	3451	1	3447
	B	3451	2	3458
	C	3461	3	3458
	D	3439	4	3435
	E	3439	5	3446
	F	3461	6	3447
	G	3450	7 (proposed)	3440
	H	3450		
(proposed) I		3443		

MONITOR HOLES			
HOLE NO.	ELEV. TOP OF PERFS.	ELEV. BASE OF PERFS.	
1-21	3451	3427	
23-32	3461	3436	
33-40	3462	3436	
41-51	3440	3390	
52-63	3442+	3415	
64-76	3449 OR BELOW	3410 OR BELOW	
77-87	3440	3410	



- LEGEND
- TEST HOLE; ● TRIASSIC ENCOUNTERED
 - MONITOR HOLE
 - MONITOR HOLE, ABANDONED
 - △ PIT FLOOR; ▲ TRIASSIC ENCOUNTERED
 - + PIT RIM
 - △ INSTRUMENT STATION
 - CORE HOLE
 - GRAVEL EXPLORATION HOLE
 - DIKE/CORE TRENCH
 - PROPOSED PIPELINE

LEA COUNTY, NEW MEXICO
PARABO, INC.
TOP OF TRIASSIC

REV. 2/81
REV. 11/81
REV. 6/16/82
REV. 10/19/83

ED L. REED & ASSOCIATES, INC.
CONSULTING HYDROLOGISTS
MIDLAND-CORPUS CHRISTI, TEXAS