District 1 1625 N French Dr., Hobbs, NM 88240 District 11 1301 W Grand Avenue, Artesia, NM 88210 District 111 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St. Francis Dr., Santa Fe, NM 87505

.

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action										
						OPERATOR (x Initial Report] Final Report				
							Contact: Tony Summers Telephone No: 505.397.8236 or 505.390.9228			
						Facility Type - Producing Well				
Surface Owner DK Boyd Mineral Owner							API LeaseNo. 30.025.22337			
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County Lea										
Unit Letter N	27	23S	37E	reet from the	North	South Line	Feet from the	East west Line	County Lea	
			La	titude	_ Longitud			WIFE		
NATURE OF RELEASE										
Type of Release Produced Water Source of Release Braden head leak						Volume of Release 100 bblsVolume Recovered 90 bblsDate and Hour of OccurrenceDate and Hour of Discovery 4-28-2008				
						4-28-2008 6am 8am				
Was Immediate Notice Given? x Yes No Not Required						If YES, To Whom? Chris Williams				
By Whom? Tony Summers						Date and Hour 4-28-2008 10am Left message				
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.				
1 II A WAIGICGUISE WAS IMPACIED, DESCRIPTION I MIY.										
5/22/08										
Describe Cause of Problem and Remedial Action Taken.* At approximately 8 am lease operator discreased with the second in some sinch nipple out of Braden head On the end of the nipple was a closed gate valve There was a spilt in nipple from exterior correston vacuum trucks were called and picked up free standing water. Backhoe was brought in ASAP and small 5'x 5' x 5' was dug to flow water into for containment. Another pit was dug next to it and Akome Pit liners were called and arrived a few hours later. Pit was lined and flow was then diverted to that pit with vacuum trucks continuing to haul.										
Describe Area Affected and Cleanup Action Taken.* Water ran across location, over old reserve pit area, into pasture, and down Carter Foundation road for approximately ¾ mile. BBC International has been called in for cleanup assist. According to BBC, average depth to ground water for this area is 75' giving it a ranking on 10.										
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations										
T. T.						OIL CONSERVATION DIVISION				
Signature: La Vanne Va						Approved by District Supervisor:				
Title: HES Technician						Approval Da	te. 5/22/0	8 Expiration	Date 8/22/08	
E-mail Address: tony_summers@oxy.com						Conditions of Approval:			Attached []	
Date: /	* Attach Additional Sheets If Necessary									
+ Allach Additional Sheets II Necessary + COHO 815 141473										

