

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company DCP Midstream, LP	Contact Johnnie Bradford
Address 10 Desta Drive, Ste. 400W, Midland, TX 79705	Telephone No. (432) 620-4166
Facility Name C-11 Pipeline	Facility Type low pressure natural gas gathering pipeline

Surface Owner FEDERAL	Mineral Owner	Lease No.
-----------------------	---------------	-----------

LOCATION OF RELEASE

API# 30.025.02341

Unit Letter A	Section 20	Township 19S	Range 34E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
---------------	------------	--------------	-----------	---------------	------------------	---------------	----------------	------------

Latitude N 32° 39.08" Longitude W 103° 34.41"

NATURE OF RELEASE

Type of Release natural gas	Volume of Release 1500 mcf	Volume Recovered 0 mcf
Source of Release pipeline rupture	Date and Hour of Occurrence 10/8/2008, 1:50 p.m.	Date and Hour of Discovery 10/8/2008, 1:58 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD Incident No. 1RP1972	
By Whom? OCD Incident No. 1RP1972	Date and Hour OCD Incident No. 1RP1972	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	



If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken \*  
A DCP Midstream, LP pipeline was stuck by Harpole Construction while working for El Paso Natural Gas. Work was progressing north for approximately 7.5 miles from southwest of Monument NM, across Hwy 62-180 to new power plant. A One-Call was completed and the line was marked.

FIRE RESULTED,  
DITCHER BURNED - TOTAL LOSS - NO INJURIES.

Describe Area Affected and Cleanup Action Taken.\*  
No liquids were released, so no cleanup was necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION 	
Printed Name: Johnnie Bradford	Approved by District ENVIRONMENTAL ENGINEER	
Title: Sr. Environmental Specialist	Approval Date: 10.22.08	Expiration Date: —
E-mail Address: jbradford@dcpmidstream.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/21/2008 Phone: (432) 620-4166	—	1RP# 1972

\* Attach Additional Sheets If Necessary

FGRL0834448547