


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

H KMW 1035634128

OPERATOR Initial Report Final Report

Name of Company – EnerVest Operating LLC <i>143199</i>	Contact – Elroy Ardoin
Address – 1001 Fannin Street, Suite 800, Houston, TX 77002	Telephone No. (713) 495 6534
Facility Name – Robinson Federal Tank Battery	Facility Type – Tank Battery for Robinson Federal #2

Surface Owner – BLM	Mineral Owner	API No. 3001524134
---------------------	---------------	--------------------

LOCATION OF RELEASE

Unit Letter	Section 35	Township 17S	Range 29E	Feet from the	South Line	Feet from the	East/West Line	County Eddy
-------------	---------------	-----------------	--------------	---------------	------------	---------------	----------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release - Oil	Volume of Release estimated 40bbbls	Volume Recovered 20bbbls
Source of Release – Hole in nipple in tank	Date and Hour of Occurrence ? 7/2/2010 – 10:00AM	Date and Hour of Discovery 7/2/2010 - 12:00PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos – BLM – Carlsbad office	
By Whom? Robert Griffin – EnerVest Production foreman	Date and Hour – 12:00PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A hole in nipple of holding tank attached to flow line was source of oil spill. The spill was contained within the tank battery dike area. An estimated 40bbbls was spilled and 20bbbls was recovered and pumped back into storage tank. The faulty nipple was replaced immediately. The spill area within the tank battery dike is 12yds X 25yds. This tank battery is for the Robinson Federal #2 API #3001524134. Remediation action taken was to pump 20bbbls of freestanding oil back into tank. No further remedial action has been taken yet. A sampling investigation will be conducted to delineate the extent of contamination. A sampling report will be submitted to OCD with a remediation plan to be implemented upon NMOCD approval.

Describe Area Affected and Cleanup Action Taken.*

This oil spill was completely contained within the bermed area of tank battery facility. No other area was impacted. The spill area within the tank battery dike is 12yds X 25yds. Recommended remediation is to conduct "dig & haul" operation with lab analysis. Contaminated soil will be removed to a locally approved disposal site and back filled with clay based impermeable soil. A closing report will then be submitted to OCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Elroy Ardoin</i>
Printed Name: Elroy Ardoin
Title: HS&E Coordinator
E-mail Address: eardoin@enervest.net
Date: 7/9/2010 Phone: (713) 495 6534

OIL CONSERVATION DIVISION	
Signed By <i>Mike Brannon</i>	
Approved by District Supervisor:	
Approval Date: <i>3/7/11</i>	Expiration Date:
Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: <i>4/7/11</i>	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2 RP-518

Bratcher, Mike, EMNRD

From: Andy Price [andyprice@grandecom.net]
Sent: Friday, July 09, 2010 10:21 AM
To: Bratcher, Mike, EMNRD
Cc: Elroy Ardoin
Subject: EnerVest Operating - c141 spill report - Robinson Fed. #2 Tank Battery
Attachments: c141 - EnerVest- Robinson Fed. Tank Battery spill rpt-7-9-2010.pdf

Mike,

This is the spill I discussed with you on the phone. This was reported immediately to BLM. I will keep you updated with each step of our remediation process and submit the appropriate documentation.

Thank you.

Andy Price
REM
432-352-6400
Baseline Solutions, LLC
511 W. Ohio St., Ste. 400
Midland, TX, 79701