# Water Compatibility in San Juan Basin



- The San Juan basin has productive siliciclastic reservoirs (Pictured Cliffs, Blanco Mesaverde, Basin Dakota, etc.) and a productive coalbed methane reservoir (Basin Fruitland Coal).
- These siliciclastic and coalbed methane reservoirs are commingled extensively throughout the basin in many different combinations with no observed damage from clay swelling due to differing formation waters.
- The Basin Fruitland Coal and Blanco Mesaverde/Basin Dakota samples (attached) both show fresh water with low TDS.

### Lambe Com #200 Water Sample



### This is a representative Fruitland Coal standalone water sample.



dzufelt@greenanalytical.com p: 970.247.4220 f: 970.247.4227 75 Suttle Street Durango, CO 81303

www.GreenAnalytical.com

Hilcorp Project: API - Oil Field "Complete Water"

382 Road 3100 Project Name / Number: Comingle Water Testing Reported:
Aztec NM, 87410 Project Manager: Kevin Fredrickson 11/05/19 14:13

Lambe Com 200

#### 1910302-01 (Produced Water)

Analyte	Result	RL	MDL	Units	Dilution	Analyzed	Method	Notes	Analyst
General Chemistry									
Alkalinity, Bicarbonate as CaCO3*	150	10.0		mg/L	10	10/30/19 10:30	2320 B		VJL
Alkalinity, Carbonate as CaCO3*	<10.0	10.0		mg/L	10	10/30/19 10:30	2320 B		VJL
Alkalinity, Hydroxide as CaCO3*	<10.0	10.0		mg/L	10	10/30/19 10:30	2320 B		VJL
Alkalinity, Total as CaCO3*	150	10.0	3.06	mg/L	10	10/30/19 10:30	2320 B		VJL
Chloride*	22.8	25.0	4.82	mg/L	25	10/30/19 21:05	EPA300.0		AES
Conductivity*	272	10.0		umho/cm @ 25.0°C	1	10/30/19 13:50	2510 B		FGH
pH*	7.04			pH Units	1	10/30/19 13:50	EPA150.1	H4	FGH
Resistivity	3680			ohm/cm	1	11/01/19 13:24	2510 B		FGH
Total Dissolved Solids*	700	100		mg/L	10	10/30/19 16:10	EPA160.1		VJL
Specific Gravity	0.9990	0.8000		No Unit	1	10/30/19 12:15	ASTM D1429-03		VJL
Sulfate*	<7.38	25.0	7.38	mg/L	25	10/30/19 21:05	EPA300.0		AES

### Lambe #3M Water Sample



## This is a representative Blanco Mesaverde/Basin Dakota water sample.



dzufelt@greenanalytical.com p: 970.247.4220 f: 970.247.4227 75 Suttle Street Durango, CO 81303

www.GreenAnalytical.com

Hilcorp Project: API - Oil Field "Complete Water"

382 Road 3100 Project Name / Number: Comingle Water Testing Reported:
Aztec NM, 87410 Project Manager: Kevin Fredrickson 11/05/19 14:13

Lambe 3M

#### 1910302-02 (Produced Water)

Analyte	Result	RL	MDL	Units	Dilution	Analyzed	Method	Notes	Analyst
General Chemistry									
Alkalinity, Bicarbonate as CaCO3*	60.0	10.0		mg/L	10	10/30/19 10:30	2320 B		VJL
Alkalinity, Carbonate as CaCO3*	<10.0	10.0		mg/L	10	10/30/19 10:30	2320 B		VJL
Alkalinity, Hydroxide as CaCO3*	<10.0	10.0		mg/L	10	10/30/19 10:30	2320 B		VJL
Alkalinity, Total as CaCO3*	60.0	10.0	3.06	mg/L	10	10/30/19 10:30	2320 B		VJL
Chloride*	2570	100	19.3	mg/L	100	10/30/19 21:23	EPA300.0		AES
Conductivity*	9300	10.0		umho/cm @	1	10/30/19 13:50	2510 B		FGH
				25.0°C					
pH*	5.70			pH Units	1	10/30/19 13:50	EPA150.1	H4	FGH
Resistivity	108			ohm/cm	1	11/01/19 13:24	2510 B		FGH
Total Dissolved Solids*	4550	100		mg/L	10	10/30/19 16:10	EPA160.1		VJL
Specific Gravity	0.9990	0.8000		No Unit	1	10/30/19 12:15	ASTM D1429-03		VJL
Sulfate*	<29.5	100	29.5	mg/L	100	10/30/19 21:23	EPA300.0		AES