AP-77 Pride Energy #14 - South Fork Lakes Unit

Sept 2004 - well spudded

Oct 2004 - well completed

Aug 2007 - Closure form C-144 submitted

Jan 2008 - Form C-141 submitted

Feb 2008 - Abatement Plan required

Sept 2008 - Stage 2 Abatement Plan submitted

chronology in Stage 2 Plan refers to pollution coming from a Humble Oil legacy pit from 1961 using 1964 aerial photo of site. apparently Pride Energy constructed their drilling pit for Well #14 at the same location as the 1961 pit. Claim that "evidence collected to date permits a conclusion that the documented impairment of groundwater (2500 mg/l Cl) is wholly or primarily due to seepage associated with the 1961 drilling pit."

Mar 1961 Humble Oil submits Notice of Intent to Drill unit #1 July 1961 well is completed July 1967 Humble submits plugging and abandonment form C-103

Pride Energy abatement plan is "pump and use"

depth to groundwater estimated with info from surrounding wells at 24 to 38 ft bgs later determined to be 23 ft bgs

"brine from the pit probably migrated through the vadose zone to groundwater via saturated flow during operation of the drilling pit or sometime during the drying process"

MW1 located at SE corner of former drilling pit footprint concentration in groundwater 3 ft below water table: 1100 mg/l Cl and 2200 mg/l TDS concentration in groundwater 17-20 ft below water table: 3100 mg/l Cl and 5400 mg/l TDS concentration after purging: 4700 mg/l Cl and 8100 mg/l TDS

estimate downgradient migration at 150 feet

the following data dated Jan 2008 soil concentrations at 8 ft: 1300 to 14,000 mg/kg soil concentrations at 12 ft: 1500 to 12,000 mg/kg soil concentrations at 16 ft: 900 to 9200 mg/kg highest concentrations in center of pit and SE corner

used trench burial system for closure

STAGE 2 WORKPLANS

STAGE 2 WORKPLANS

R. T. HICKS CONSULTANTS, LTD.

901 Rio Grande Blvd NW 🛦 Suite F-142 🛦 Albuquerque, NM 87104 🛦 505.266.5004 🛦 Fax: 505.266-0745

September 15, 2008

Mr. Wayne Price New Mexico Oil Conservation Division 1220 South St. Francis Drive Santa Fe, New Mexico 87505

RE: Pride Energy South Four Lakes #14 NMOCD #AP-077

Dear Wayne:

Please accept this Stage 2 Abatement Plan for the above-referenced site as fulfillment of Pride Energy's mandate to submit a Stage 2 Abatement Plan. We installed two borings down gradient of the former drilling pit. The magnitude and extent of brine impact is consistent with a release from the legacy pit drilled by Humble Oil in 1961. The extent of chloride impairment of ground water (i.e. concentrations in excess of 250 mg/L) appears restricted to the area occupied by the production pad. Regulated hydrocarbons are not present in ground water or the vadose zone.

Three additional wells are proposed to refine our estimate of the vertical and horizontal extent of ground water impairment at the site. MW-1 medium and deep are, 2-inch monitoring wells located near the center of mass of ground water chloride and are screened below a low-permeability quartzite horizon. MW-2 and MW-3 are 2-inch monitoring well clusters located about 200 feet down gradient from the former drilling pits.

The proposed ground water remedy is natural restoration with an on-demand pump-and-use contingency plan that recovers brackish ground water for drilling oil and gas wells in the area.

The proposed drilling pit excavation closure is construction of an infiltration barrier to minimize the transport of salt from the vadose zone to ground water. Because the open excavation allows infiltration of precipitation through the impacted vadose zone and may represent an ongoing safety threat to stock, we ask NMOCD to review the vadose zone remedy as soon as possible. We are prepared to meet with you to resolve any outstanding issues associated with this vadose zone remedy – as it is the same design for other Pride sites. We will prepare a Public Notice for your review upon your request.

Sincerely, R.T. Hicks Consultants, Ltd.

Randall T. Hicks Principal

Copy: Pride Energy NMOCD District II New Mexico State Land Office

Table of Contents	
1 Summary	2
2 Description of the Site	
2.1 Location	
2.2 Site Map – Plate 1	د د
2.5 Field Flogram May-Julie 2006	3 4
3 May 2008 Deep Sampling Program – Field Protocols and Modification of the Stage 1	
Abatement Plan	
4 Results of Deep Sampling Program	5
4.1 Soil Boring SB-01 – Plate 3	5
4.2 Soil Boring SB-02 – Plate 4	6
4.3 Analysis of Ground Water from Borings – Table 2 and Plate 5	6
4.4 Ground water Monitoring well sampling – rable 3 and Appendix A	/7 7
5 Ground Water Flow is East-Southeast	7
5.2 The Extent of Brine Impact is Consistent with a 1962 Release	
5.3 The Vertical Extent of Brine Impact is Limited by the Quartzite at 52 Feet below Gr	ade 8
5.4 The Magnitude of Ground Water Impairment is 5700 mg/L TDS	8
5.5 Natural Dilution and Dispersion Will Effectively Abate the Ground Water Impairme	ent 8
6 Stage 2 Abatement Plan	
6.2 Vadose Zone Remedy	9 Q
6.3 Schedule of Activities	
List of Plates	
Plate 1 Site Map	
Plate 2 1966 Aerial Photograph with Site Features	
Plate 3 SB-01 Boring Log	
Plate 4 SB-02 Boring Log	
Plate 5 Map Showing Chemistry of Ground Water Samples from Borings	
Plate 6 June 2008 Water Table Elevation Map	
Plate 7 Potential Extent of Chloride Impacted Ground Water	
Plate 8 Proposed Boring/Well Location	
Plate 9 Proposed Construction of Deep Well MW-01m and MW-02d	
Plate 10 - Proposed Construction of Deep Wells MW-03 (s, m and d) and MW-04 (s, m and d)
Plate 11 – Reserve Pit Excavation Closure	
List of Appendices	
Appendix A – Laboratory Analysis Reports	
R.T. HICKS COMSULTANTS, LTD	

. •

September, 2008

1 Summary

- 1. Humble Oil and Refining (Humble) drilled South Four Lakes Unit #1 at this location in 1961. The cover of this plan shows a 1964 air photo of the area and the site is located in the upper right corner of the photograph.
- 2. In 2004, Pride Energy constructed a drilling pit for South Four Lakes #14 at the same location as the 1961 drilling pit
- 3. Evidence collected to date permits a conclusion that the horizontal extent of ground water impairment (chloride concentrations greater than 250 mg/L) is restricted to the area of the production pad.
- 4. Evidence collected to date permit a conclusion that the vertical extent of ground water impairment (chloride concentrations greater than 250 mg/L) is restricted to the ground water zone above a well-cemented quartzite horizon that exists at a depth of 52 feet below grade.
- 5. At MW-1, which is drilled through the legacy Humble drilling pit and is about 10-feet down gradient from the Pride drilling pit, chloride in ground water exceeds 2,500 mg/L.
- 6. Evidence collected to date permits a conclusion that the documented impairment of ground water is wholly or primarily due to seepage associated with the 1961 drilling pit.
- 7. Construction of a deep monitoring well using the mud-rotary method is proposed to test the hypothesis that the vertical extent of ground water impairment is restricted to the the aquifer that lies above the local quartzite horizon.
- 8. Construction of two down gradient monitoring wells is proposed to refine our estimate of the horizontal extent of ground water impairment
- 9. The proposed ground water remedy program is natural restoration and monitoring with a contingency plan to implement an on-demand pump-and-use program to remove impaired ground water for use in oil and gas well drilling.
- 10. Six months after NMOCD approval of this plan Pride will provide a report to NMOCD that presents
 - a. The borehole data from the proposed monitoring wells,
 - b. the ground water monitoring and sampling data,
 - c. our analysis of contaminant fate and transport and
 - d. a recommendation to continue with the proposed remedy of natural restoration or to implement an on-demand pump-and-use ground water restoration program as a contingency.

R.T. HICKS CONSULTANTS, LTD September, 2008

STAGE 2 WORKPLANS

2.4 Site History – Table 1 and Plate 2

Our examination of historic aerial photographs show that the drilling pit used by Pride Energy was located at the same location as the drilling pit used for the drilling of the Humble Oil and Refining Company well South Four Lakes Unit #1 originally drilled in 1961. Plate 2 is a 1966 aerial photo that shows the scar from the 1961 drilling event with the configuration of the Pride Energy activities superimposed. Prior to the mid 1960s, the State of New Mexico did not require lining of drilling pits, therefore it is probable that the 1961 unlined drilling pit released brine to the subsurface. Table 1 presents the Site History.

	Table 1: Site History
Date	Description
March 3, 1961	Humble Oil and Refining Company submits Notice of Intent to Drill
	South Four Lakes Unit #1 (API – 30-025-01828) well at this location
	to a depth of 10,600 feet
July 16, 1961	Humble completes well
July 18, 1967	Humble submits plugging and abandonment Form C-103 to NMOCD
August 30, 2004	Pride submits APD (C-101) for South Four Lakes Unit #14
September 8, 2004	Well spudded
October 25, 2004	Well drilled to total depth
March 10, 2005	Set pump in well
August 21, 2007	C-144 Pit Closure Form submitted to NMOCD
December 10,	Revised C-144 submitted by Elke Environmental to NMOCD
2007	
January 30, 2008	C-141 submitted by Elke Environmental to NMOCD
February 12, 2008	NMOCD requires submission of Abatement Plan
April 14, 2008	Stage 1 Abatement Plan submitted by R.T. Hicks Consultants to
analaise diseatandi ar antananana is promonen ar promonen ar san a	NMOCD
May 13, 2008	Soil boring program to define vertical and horizontal extent of any
	impairment to ground water
June 19, 2008	Sampling and monitoring event
September, 2008	Stage 2 Abatement Plan submitted by R.T. Hicks Consultants to
	NMOCD

3 May 2008 Deep Sampling Program – Field Protocols and Modification of the Stage 1 Abatement Plan

On May 13, 2008, Hicks Consultants mobilized to the site to perform soil boring activities. Hicks Consultants selected Atkins Engineering (Atkins), from Roswell, NM, as the drilling contractor. Using a Foremost Mobile 58 drilling rig and a 7 ¹/₄- inch O.D. hollow stem auger, we installed two soil borings at the site (see Plate 1).

After examination of historic air photos and a close examination of the site, we modified the location of the soil borings shown in Plate 6 of the Stage 1 Abatement Plan. The first boring was drilled adjacent to MW-1 (see Plate 1), and is basically the same location as the proposed boring SB-1 shown on Plate 6 of the Stage 1 Abatement Plan. We drilled the second boring midway between the

R.T. HICKS CONSULTANTS, LTD September, 2008

proposed borings SB-2 and SB-3 shown on Plate 6 of the Stage 1 Abatement Plan. The relatively low chloride concentrations in this boring obviated the need for additional borings.

Because each boring encountered a hard quartzite horizon at 52-feet below grade, we ceased drilling to avoid creating a vertical pathway between the documented impaired ground water and potentially unimpaired ground water beneath the quartzite. Furthermore, we observed flowing sands under lithostatic or hydrostatic pressure during soil boring activities at another Pride Energy site, State X #1. With the knowledge that flowing sands exist in the area, penetration of the quartzite layer without a mud column in the hole could allow flowing sand to rise in the auger hole, causing the loss of the hole and creation of a permanent conduit through the quartzite.

At each boring location, we

- 1. Created a borehole log.
- 2. Measured specific conductance (SC) of ground water collected through the auger using a trip bailer. SC was measured using a Hanna Combo pH & EC meter (Model No. HI 98130). We used the SC measurements to a.) determine the vertical and horizontal extent of any ground water impairment and b.) determine the location of additional boreholes.
- 3. Complete soil boring as a monitoring well if drilled outside of the deadman (well anchor) zone. The Association of Energy Service Companies (AESC) recommended safe procedures and guidelines for oil and gas well servicing² states "During operations, all wireline units, other vehicles, or portable houses and equipment should be placed outside the guylines of the well service unit and outside the fall zone (lane) of the derrick". The standpipe for a monitoring well would create a hazard during well servicing if placed within the deadman zone.
- 4. When borehole conditions allowed, we obtained ground water samples for laboratory analysis for SC, chloride, and total dissolved solids (TDS) to correlated field measurements with laboratory measurements. We submitted the ground water samples to Hall Environmental Laboratories in Albuquerque, NM. Laboratory Certificates of Analysis are in Appendix A:

Because ground water analysis of samples from MW-1 did not detect regulated hydrocarbons and deep soil samples from within the former pit did not detect volatile hydrocarbon vapors above 20 ppm using a PID, we did not collect samples from the auger borings for analysis of regulated hydrocarbons.

4 Results of Deep Sampling Program

4.1 Soil Boring SB-01 – Plate 3

SB-01 is located approximately 70-feet east of the southeast corner of the former drilling pit. The borehole log is shown on Plate 3.

R.T. HICKS CONSULTANTS, LTD September, 2008

² Association of Energy Service Companies (AESC) Recommended Safe Procedures and Guidelines for Oil and Gas Well Servicing. Available: <u>http://www.aesc.net/Safety/index.cfm?action=view&pdfid=27</u> and <u>http://www.aesc.net/Safety/index.cfm</u>. Accessed July 3, 2008.

Total depth of this borehole is 53.2-feet. The upper 15-feet consist of caliche. Fifteen to 52-feet below ground surface (bgs) is composed of fine sand with interbedded quartzite between 15 and 23-feet bgs. Quartzite (well indurated fine sandstone) exists from 52 to total depth.

Ground water was encountered at 27-feet bgs. We were unable to obtain field measurements at 38 and 43-feet bgs due to fine sands clogging the trip bailer. However, we obtained a ground water sample at total depth. Field measurements indicate SC is 7.33 mS/cm. We were unable to obtain sufficient sample volume for laboratory analysis.

4.2 Soil Boring SB-02 – Plate 4

SB-02 is located down-gradient approximately 65-feet southeast of the southeast corner of the former drilling pit. The borehole log is shown on Plate 4.

Total depth of this borehole is 52-feet. The upper 18-feet consist of caliche. Eighteen to 51-feet below ground surface (bgs) is composed of fine sand. Quartzite exists from 51 to total depth. We ceased drilling at 52-feet to avoid creating a vertical pathway for any impaired ground water.

Ground water was encountered at 23-feet bgs. Field measurements indicate the SC of ground water remained relatively consistent. We obtained sufficient sample volume for laboratory analysis of ground water at 28.3 and 38.2-feet bgs.

4.3 Analysis of Ground Water from Borings – Table 2 and Plate 5

	T:	able 2: Analysis of g	ground water	samples	
Boring ID	Depth	Field Measured Values	L. Constraints	alues	
	- (11 Ogs) -	SC (mS/cm)	SC (mS/cm)	Chloride (mg/L)	TDS (mg/L)
SB-01	52.2	7.33 ·		·	
SB-02	28.3	1.66	1.60	280	1,100
SB-02	38.2	1.55	1.50	270	1,400
SB-02	48.2	1.65			

Field and laboratory analysis of ground water samples are shown in Table 2.

--- indicates insufficient sample volume for lab analysis

SB-01 shows the highest SC measurement; 7.33 mS/cm at 53.2 feet bgs. SC measurements at SB-02 remained relatively consistent with increasing depth ranging from 1.55 to 1.65 mS/cm (see Plate 5 and Table 2).

Plate 5 shows the soil boring data spatially. Included on Plate 5 is laboratory and field data. Field TDS values were calculated from field SC measurements by correlating the ratio between lab measured conductivity and lab analyzed TDS concentrations (a 0.72 factor, see Table3). Maximum

R.T. HICKS CONSULTANTS, LTD September, 2008

calculated field TDS is 5,058 mg/L which occurred at SB-01, exceeding New Mexico Quality Control Commission's (WQCC) standards of 1,000 mg/L for domestic water supplies.

Calculated and actual TDS measurements at SB-02 range from 1,100 to 1,447 mg/L TDS. Actual chloride concentrations ranged from 270 to 280 mg/L; which only slightly exceeds the WQCC standard of 250 mg/L.

4.4 Ground Water Monitoring Well Sampling – Table 3 and Appendix A

Table 4, below, summarizes recent and historic ground water chemistry and ground water elevation measurements at MW-01. The Certificate of Analysis for the June 19th sampling event is in Appendix A.

June 2008 ground water monitoring data indicates chloride and TDS concentrations (2,600 and 5,700 mg/L, respectively) are above the WQCC standard at MW-01.

Sample Date	GW Elevation (ft)	DTW (ft)	Cl (mg/L)	TDS (mg/L)	Specific Conductance (mS/cm) (field measured)
1/24/2008	4123.70	25.10	1910	NA	6.32
3/13/2008	4123.58	25.22	1700	4260	6.74
6/19/2008	4123.45	25.35	2600	5700	6.89

able 4:	Summary of	f ground water	chemistry at	MW-01

NA indicates not analyzed for this constituent

Although MW-01 is the only monitoring well at the site, data from nearby monitoring wells and data from USGS allow a reasonable assessment of the water table elevation in the area. Plate 6 shows ground water gauging data collected at four nearby Pride Energy sites and a water table elevation map. Ground water flows east-southeast at a gradient of approximately 0.002. Depth to water at the site is approximately 25-feet bgs. Plate 6 agrees with regional data¹ from USGS gauging stations for 1996.

5 Discussion and Conclusions

Т

All of the conclusions listed below will be proved or disproved by the data collection program proposed in the Stage 2 Abatement Plan described in this submission.

5.1 Ground Water Flow is East-Southeast

Regional ground water data suggest a southeast ground water flow direction in much of the South Four Lakes area. Data from the gauging of the newly-installed monitor wells at the various sites in the area now suggest an east-southeast direction of ground water flow at the South Four Lakes #14 site (Plate 6).

K.T. HICKS CONSULTANTS, LTD September, 2008

5.2 The Extent of Brine Impact is Consistent with a 1962 Release

The lithologic data presented in Plates 4 and 5 show that the upper portion of the aquifer above the quartzite is composed of fine sand. The hydraulic conductivity of fine sand could be as low as 0.1 ft/day or as high as 10 ft/day. Plate 6 shows that the hydraulic gradient in the area of the site is 0.0015. Assuming a porosity of 25% for fine sand, a hydraulic conductivity of 1 ft/day, and use of Darcy's equation, the average linear velocity of ground water at the site is 2 feet/year. In the absence of site-specific hydraulic testing, this calculation must be considered an estimate.

Plate 7 shows our estimate of the extent of chloride impact from the release(s) from the drilling pit area. The distance from the edge of the 1962 reserve pit to the down gradient 250 mg/L chloride isoconcentration line is about 95 feet. We believe that the maximum extent of chloride impact (where chloride concentration exceeds background) could be 200 feet down gradient from the edge of the 1962 pit. The distance from the edge of the 2004-05 Pride Energy drilling pit to the down gradient of chloride impact is about 245 feet.

With a measured hydraulic gradient of 0.0015 and an assumed porosity of 25% for the fine sand, the hydraulic conductivity value required for the average linear velocity to equal 245 feet/4 years (61.25 feet/year) is 28 ft/day. We believe it possible but not probable that chloride molecules from the Pride drilling pit materially contributed to the impact observed as SB-1 and MW-1.

5.3 The Vertical Extent of Brine Impact is Limited by the Quartzite at 52 Feet below Grade

Soil borings SB-01 and SB-02 partially penetrated a very hard quartzite layer at 52-feet bgs. We believe this well-cemented horizon creates a permeability barrier between the uppermost portion of the Ogallala Aquifer and the lower section of the aquifer, which is typically screened for water supply wells.

5.4 The Magnitude of Ground Water Impairment is 5700 mg/L TDS

MW-1 was drilled through the area of the 1962 Humble drilling pit and is 10-feet down gradient of the 2004-05 Pride drilling pit. We conclude that MW-1 lies within the center of mass of the brine release at the site. The TDS of the most recent ground water sample at MW-1 is 5700 mg/L and the chloride concentration is 2600 mg/L.

5.5 Natural Dilution and Dispersion Will Effectively Abate the Ground Water Impairment

At this site, we believe the ground water flux is relatively small due to the low hydraulic gradient and fine-grained sediments that comprise the uppermost ground water zone. While this condition will minimize migration of the documented ground water impairment, natural restoration of ground water due to dilution and dispersion will require decades. Due to the location of the site, we believe it highly unlikely that the area of the production pad will be a site of ground water use in the foreseeable future. Therefore, rapid restoration of ground water quality is not warranted.

R.T. HICKS CONSULTAMTS, LTD September, 2008

6 Stage 2 Abatement Plan

Data collected to date indicates a highly localized area of impaired ground water beneath the site. Data from the Elke Environmental report shows that chloride above 1,000 mg/kg exists in the vadose zone below the former drilling pit (1961 and 2004). The source of the chloride in the vadose zone at the Elke Environmental boring TP-5 is probably leakage from the Pride drilling pit. The other borings conducted by Elke Environmental are 10 times lower in chloride concentration and have relatively low moisture content; the source of this chloride is probably the Humble drilling pit (1961). The source of the chloride detected in SB-2 is probably leakage from the Humble drilling pit. Because MW-1 is located within the footprint of the 1962 drilling pit, the source of chloride in ground water at this location is probably the Humble pit.

6.1 Ground Water Remedy

Although the impairment of ground water was probably caused by the legacy drilling pit originally operated by Humble Oil and Refining, Pride Energy is considered a "responsible party" with Humble. Pride Energy proposes to

- 1. Conduct three additional quarterly ground water sampling events and several slug (recovery) tests to provide data that will assist in creating a better estimate the rate of natural ground water restoration and the rate of contaminant migration
- 2. Compare the results of the slug testing to the results from an aquifer pumping test at a nearby site then create an estimate of the fate and transport of impaired ground water at this site.
- 3. After NMOCD approval of the Stage 1 and 2 Abatement Plan:
 - a. use mud rotary drilling and install MW-1 Middle and Deep (Plate 8 and Plate 9) to define the vertical extent of ground water impairment,
 - b. use mud rotary drilling and install MW-2 Shallow, Middle and Deep and MW-3 Shallow, Middle and Deep (Plates 8 and Plate 10) to further define the horizontal and vertical extent of ground water impairment.
- 4. Six months after NMOCD approval of this plan, Pride will provide a report to NMOCD that presents
 - a. The borehole data from the proposed monitoring wells,
 - b. the ground water monitoring and sampling data,
 - c. our analysis of contaminant fate and transport and
 - d. our recommendation to continue with the proposed remedy of natural restoration or to implement an on-demand pump-and-use ground water restoration program as a contingency.

6.2 Vadose Zone Remedy

1. Expand the existing pit excavation as necessary to create a 3-foot wide area where subsurface impact of pit leakage does not exist (Plate 11, step 1).

R.T. HICKS CONSULTANTS, LTD

September, 2008

- 2. Use the material from the pit expansion or deepen the excavation as necessary to create a sloping surface on the bottom of the excavation as suggested in Plate 11, step 2.
- 3. Over the sloping surface, place "shingles" of recycled or new 20-mil, reinforced liner material with a permeability of less than 10⁻⁹ cm/sec. The shingles are laid to shed any infiltrated water from the pit area to native soil and to prevent any upward migration of chloride into the root zone.
- 4. Backfill the excavation with clean material, beginning with caliche and/or sand and finishing the top of the backfill with about 6-inches of soil that is capable of supporting native vegetation.
- 5. The new grade is a 3-5% slope that drains to a "ponding area". The final grade of the surface over the former pit should blend with the surroundings as much as possible. Plate
 - 11, step 3, which shows a 5% slope that resembles a large "pitchers mound", is one example of a final surface that allows for drainage of stormwater away from the former drilling pit.
- 6. Seed the reclaimed pit with a mixture acceptable to the State Land Office.

6.3 Schedule of Activities

We will perform two additional ground water monitoring and sampling events at MW-1 to complete a full year of quarterly monitoring at the site. We will analyze the ground water for the following:

- Chloride
- TDS
- BTEX

Upon OCD approval of the Abatement Plan, Pride will commence the proposed work elements.

PLATES

STAGE 2 WORKPLANS

AP - 077

STAGE 2 WORKPLANS

.

r .

APPENDIX A

. • . • .

.

PLATES

STAGE 2 WORKPLANS

.

APPENDIX A

•



COVER LETTER

Wednesday, May 28, 2008

Andrew Parker R.T. Hicks Consultants, LTD 901 Rio Grande Blvd. NW Suite F-142

Albuquerque, NM 87104

TEL: (505) 266-5004 FAX (505) 266-0745

RE: Pride Energy-S4L #14

Dear Andrew Parker:

Order No.: 0805247

Hall Environmental Analysis Laboratory, Inc. received 2 sample(s) on 5/16/2008 for the analyses presented in the following report.

These were analyzed according to EPA procedures or equivalent.

Reporting limits are determined by EPA methodology. No determination of compounds below these (denoted by the ND or < sign) has been made.

Please don't hesitate to contact HEAL for any additional information or clarifications.

Sincerely,

Andy Freeman, Business Manager Nancy McDuffie, Laboratory Manager

NM Lab # NM9425 AZ license # AZ0682 ORELAP Lab # NM100001



4901 Hawkins NE ■ Suite D ■ Albuquerque, NM 87109 505.345.3975 ■ Fax 505.345.4107 www.hallenvironmental.com

Hall Environmental Analysis Laboratory, Inc.

Date: 28-May-08

CLIENT: Lab Order: Project: Lab ID:	R.T. Hicks Consultants, 0805247 Pride Energy-S4L #14 0805247-01	LTD		Client Sample ID Collection Date Date Received Matrix	: SB-02@ : 5/13/200 : 5/16/200 : AQUEO	38.2 fbgs 8 12:45:00 PM 8 US
Analyses		Result	PQL	Qual Units	DF	Date Analyzed
EPA METHOD Chloride	300.0: ANIONS	270	1.0	mg/L	10	Analyst: SLB 5/20/2008 4:32:09 PM
EPA 120.1: SPI Specific Condu		1500	0.010	µmhos/cm	1	Analyst: TAF 5/20/2008
SM 2540C TOT Total Dissolved	AL DISSOLVED SOLIDS Solids	1400	400	m o/L	. 1	Analyst: KMS 5/19/2008

Qualifiers:

- Value exceeds Maximum Contaminant Level * Value above quantitation range
- Ε Analyte detected below quantitation limits J
- ND
- Not Detected at the Reporting Limit S
 - Spike recovery outside accepted recovery limits
- ·В Analyte detected in the associated Method Blank
- Н Holding times for preparation or analysis exceeded
- MCL Maximum Contaminant Level

- RL Reporting Limit

1

Page 1 of 2

Hall Envi	ronmental Analysi	s Labor:	atory, In	c. D	ate: 28-M	lay-08							
CLIENT:	R.T. Hicks Consultants,	, LTD	Client Sample ID: SB-02@28.3 fbgs										
Lab Order:	0305247			Collection Date	: 5/13/200	8 12:38:00 PM							
Project:	Pride Energy-S4L #14			Date Received	: 5/16/200	8							
Lab ID:	0805247-02			Matrix	AQUEO	US							
Analyses		Result	PQL	Qual Units	DF	Date Analyzed							
EPA METHOD Chloride	300.0: ANIONS	280	1.0	mg/L	10	Analyst: SLB 5/20/2008 5:06:59 PM							
EPA 120.1: SP Specific,Condu		1600	0.010	µmhos/cm	1	Analyst: TAF 5/20/2008							
SM 2540C TOT Total Dissolved	AL DISSOLVED SOLIDS	1100	100	/ mg/L	1	Analyst: KNIS 5/19/2008							

Qualifiers:

*

Value exceeds Maximum Contaminant Level

- E Value above quantitation range
- J Analyte detected below quantitation limits
- ND Not Detected at the Reporting Limit
- S Spil:e recovery outside accepted recovery limits
- В Analyte detected in the associated Method Blank
- Н Holding times for preparation or analysis exceeded
- MCL Maximum Contaminant Level
- RL Reporting Limit

2

Page 2 of 2

Hall Environmental Analysis Laboratory, Inc.

Client: Project:	R.T. Hicks C Pride Energy	onsultants -S4L #14	, LTD					Wor	k Order: 0805247
Analyte		Result	Units	PQL	%Rec	LowLimit I	-lighLimit	%RPD RI	PDLimit Qual
Method: EPA M	ethod 300.0: Ani	ons							
Sample ID: MB			MBLK			Batch ID	R28613	Analysis Date:	5/20/2008 11:36:14 AM
Chloride		ND	mg/L	0.10					
Sample ID: LCS			LCS	•		Batch ID	: R28613	Analysis Date:	5/20/2008 11:53:38 AM
Chloride		4.853	mg/L	0.10	97.1	90	110		
Method: SM 264	OC Total Dissol	ed Solids							
Sample ID: MB-18	5979		MBLK			Batch ID	15979	Analysis Date:	5/19/2008
Total Dissolved Soli	ds	ND	mg/L	20					
Sample ID: LCS-1	5979		LCS			Batch ID	15979	Analysis Date:	5/19/2008
Total Dissolved Soli	ds	1012	mg/L	20	99.7	80	120		

QA/QC SUMMARY REPORT

Qualifiers:

- E Value above quantitation range
- J Analyte detected below quantitation limits
- R RPD outside accepted recovery limits

- H Holding times for preparation or analysis exceeded
 - Not Detected at the Reporting Limit
- S Spike recovery outside accepted recovery limits

3

ND

Hall Environmental Analysis Laboratory, Inc.

•	Sample	e Rece	eipt Ch	necklist				
Client Name RT HICKS				Date Receive	d: .		5/16/2008	
Work Order Number 0805247		•	,	Received by	: AMF		A .7	
	AL			Sample ID la	bels checked	by:	KS	
Checklist completed by:	<u>~</u>	<u> </u>		afor			initials	
				·				
Matrix:	Carrier name	<u>Clier</u>	<u>nt drop-o</u>	ſfſ				
Shipping container/cooler in good condition?		Yes			Not Present	<u> </u>		
Custody seals intact on shipping container/co	oler?	Yes		. No 🗔	Not Present		Not Shipped	
Custody seals intact on sample bottles?		Yes		No 🗔	N/A			
Chain of custody present?		Yes		No 🗋				
Chain of custody signed when relinquished ar	nd received?	Yes		No 🗌				
Chain of custody agrees with sample labels?		Yes		No 🗌				
Samples in proper container/pottle?		Yes		No 🗔				
Sample containers intact?		Yes		No 🗔				
Sufficient sample volume for indicated test?		Yes		No 🗍			*	
All samples received within holding time?		Yes		No 🗔				
Water - VOA vials have zero headspace?	No VOA vials sub	mitted		Yes 🗌	No 🗍			
Water - Preservation labels on bottle and cap	match?	Yes		No 🗔	N/A 🗹			
Water - pH acceptable upon receipt?		Yes	•	No 🗔	N/A 🗹			
Container/Temp Blank temperature?		11	6°	<6° C Acceptabl	θ			
COMMENTS:				If given sufficient	time to cool.			
			1					
			===					
Client contacted	Date contacted:			Pore	, on contacted			•
Contacted by:	Regarding:	· ·						
Comments:								
	•					_		
· · · ·				· · ·				
····								
· · · · · · · · · · · · · · · · · · ·								
Corrective Action								
······································								

4

Date:	Date: 716/08									5/13	51/9	Date	Fax #:	Phone #:				Address:		Client:	CHAI
Time:	Time: ا()خ	-								12:38	12:45	Time		505						27 Hid	N-OF
Relinquist	Relinquist									Aq.	Aq	Matrix		-266				Ľ		S S	CUSI
ned By: (Signature)	hed By: (Signature)									58-02.@ 20.3 Aus	58-02 @ 38.2 fbgs	Sample I.D. No.		- 5004-						nsultants	TODY RECORD
Heceived	Received									625mL	625 ML	Number/Volume	Sample Temperat	Sampler: A. F	ANDRE	Project Manager		Project #:	PRIDE	Project Name:	Other:
Burrosgnature)	98y: (Signature)											Preservative HgCl ₂ HNO ₃	-9 :aur	ARKER	W PARKER				ENERGY-S		QA/QC Package: Std C Level 4
·	5/16/08									2	-	0805247							54 7 # 7 4		
	Remark			 	 		 	-				BTEX + M	itbe +	TMB	's (802 Gasolin	1) e (1alı					
	ţ,			 				<u> </u>				TPH Metho	nd 801	5B (G	as/Dies	e Only el)					
				 								TPH (Meth	nod 41	8.1)							
				 			1				•	EDB (Meth	nod 50	4.1)		<u> </u>					L.,
												EDC (Meth	nod 80	21)		_		A		빅 Þ	4 b T
			·	 			 ·			·		8310 (PN4	or PA	(H)				AL	ww.h	1. 50	
				 			 					RCRA 8 Me	etals			<u>. </u>		VSI	allen	5.34	
		<u> </u>		 			 ļ	<u> </u>				Anions (F, C	CI, NO ₃	. NO ₂ .	P0 _{4'} S0]₄]		SR	viron	5, 39	
	ŀ			 		•••	 	<u> </u>	ļ			8081 Pest	icides ,	PCB'	s (8082	2)		EQU	ment	975 975	in Γ Π ω Σ Ο
	ł		_	 		·	 					8260B (VC	JA)					JES	cal.co	Fax	
	·		$ \rightarrow $	 i			 	 				8270 (Serr	ni-VOA)	•			-	В	505	- A F
	ŀ			 -			 	<u> </u>		×	×	TDS								109	₽ ₽
	ł			 			 	┞		$\hat{\mathbf{x}}$	Ĵ	SPECIF	-10	LONI	DUCT	<u>4N(</u>	E			<u>5</u> .410	 ζ'
	┝	-+	-+	 						-	1	CHUR	DE							7	
	ł			 -+						{		Air Ruhhler	or He		e (Y or	 M1					
	L			 l			 	I	L												•

Analytical Report 299691

for

R.T. Hicks Consultants, LTD

Project Manager: Randy Hicks

Pride Energy Company South Four Lakes #14

20-MAR-08



12600 West I-20 East Odessa, Texas 79765

Texas certification numbers: Houston, TX T104704215

Florida certification numbers: Houston, TX E871002 - Miami, FL E86678 - Tampa, FL E86675 Norcross(Atlanta), GA E87429

> South Carolina certification numbers: Norcross(Atlanta), GA 98015

> North Carolina certification numbers: Norcross(Atlanta), GA 483

Houston - Dallas - San Antonio - Austin - Tampa - Miami - Latin America Midland - Corpus Christi - Atlanta

Page 1 of 14



20-MAR-08



Project Manager: Randy Hicks R.T. Hicks Consultants, LTD 901 Rio Grande Blvd. NW, Suite F-142 Albuquerque, NM 87104

Reference: XENCO Report No: 299691 Pride Energy Company Project Address: T11S-R34E, Section 35, Unit Letter I

Randy Hicks:

We are reporting to you the results of the analyses performed on the samples received under the project name referenced above and identified with the XENCO Report Number 299691. All results being reported under this Report Number apply to the samples analyzed and properly identified with a Laboratory ID number. Subcontracted analyses are identified in this report with either the NELAC certification number of the subcontract lab in the analyst ID field, or the complete subcontracted report attached to this report.

Unless otherwise noted in a Case Narrative, all data reported in this Analytical Report are in compliance with NELAC standards. Estimation of data uncertainty for this report is found in the quality control section of this report unless otherwise noted. Should insufficient sample be provided to the laboratory to meet the method and NELAC Matrix Duplicate and Matrix Spike requirements, then the data will be analyzed, evaluated and reported using all other available quality control measures.

The validity and integrity of this report will remain intact as long as it is accompanied by this letter and reproduced in full, unless written approval is granted by XENCO Laboratories. This report will be filed for at least 5 years in our archives after which time it will be destroyed without further notice, unless otherwise arranged with you. The samples received, and described as recorded in Report No. 299691 will be filed for 60 days, and after that time they will be properly disposed without further notice, unless otherwise arranged with you. We reserve the right to return to you any unused samples, extracts or solutions related to them if we consider so necessary (e.g., samples identified as hazardous waste, sample sizes exceeding analytical standard practices, controlled substances under regulated protocols, etc).

We thank you for selecting XENCO Laboratories to serve your analytical needs. If you have any questions concerning this report, please feel free to contact us at any time.

Respectfully,

Brent Barron, II Odessa Laboratory Manager

Recipient of the Prestigious Small Business Administration Award of Excellence in 1994. Certified and approved by numerous States and Agencies. A Small Business and Minority Status Company that delivers SERVICE and QUALITY Houston - Dallas - San Antonio - Austin - Tampa - Miami - Atlanta - Corpus Christi - Latin America





Sample Cross Reference 299691

R.T. Hicks Consultants, LTD, Albuquerque, NM

Pride Energy Company

Sample Id	Matrix	Date Collected	Sample Depth	Lab Sample Id
MW-1	W	Mar-13-08 10:10		299691-001
• •				
		·		
. · · ·				
	<i>r</i>			
		٠		
				,
· .				



Certificate of Analysis Summary 299691 R.T. Hicks Consultants, LTD, Albuquerque, NM

Project Name: Pride Energy Company

Project Id: South Four Lakes Contact: Randy Hicks	#14	3		Date Receiv Re	ved in Lab: port Date:	Mar-14- 20-MAI	08 05:16 pn R-08	n
Project Location: T11S-R34E, Section	on 35, Unit Let	tter I		Project	Manager:	Brent B	arron, II	
	Lab Id:	299691-(001					·····
Analysis Requested	Field Id:	MW-I			ſ			
	Depth:							
	Matrix:	WATE	R					
	Sampled:	Mar-13-08	10:10					
Anions by EPA 300/300.1	Extracted:							
· · · · · · · · · · · · · · · · · · ·	Analyzed:	Mar-15-08	10:29					
	Units/RL:	mg/L	RL					
Chloride		1710	25.0					
Sulfate		390	25.0					
BTEX by EPA 8021B	Extracted:	Mar-19-08	10:00					:
	Analyzed:	Mar-19-08	17:44					
	Units/RL:	mg/L	RL					
Benzene	<u>-</u>	ND	0.0010					
Toluenc		ND	0.0020					
Ethylbenzene		ND	0.0010				_	
m,p-Xylenes		ND	0.0020					
o-Xylene		ND	0.0010				L	
Xylenes, Total		ND						
Total BTEX	·	ND		•				
Metals per ICP by SW846 6010B	Extracted:							
•	Analyzed:	Mar-17-08	16:36					
· · · · · · · · · · · · · · · · · · ·	Units/RL:	. mg/L	RL					
Calcium		. 585	0.100					
Magnesium		112	0.010					
Potassium		5.05	0.500					
Sodium ·		511	0.500		· -		_	
TDS by SM2540C	Extracted:							
	Analyzed:	Mar-17-08	16:00					
	Units/RL:	mg/L	RL					
Total dissolved solids	- <u></u>	4260	5.00		<u> </u>			<u></u>
Total Alkalinity by EPA 310.1	Extracted: Analyzed:	Mar-17-08	14:15					
	Units/RL:	mg/L	RL					
Alkalinity, Total (as CaCO3)		230	4.00			·		

This analytical report, and the entire data package it represents, has been made for your exclusive and confidential use. The interpretations and results expressed throughout this analytical report represent the best judgment of XENCO Laboratories. XENCO Laboratories assumes no responsibility and makes no warranty to the end use of the data hereby presented. Our liability is limited to the amount invoiced for this work order unless otherwise agreed to in writing.

Since 1990

Brent Barron

Odessa Laboratory Director

Houston - Dallas - San Antonio - Austin - Tampa - Miami - Latin America - Atlanta - Corpus Christi





- X In our quality control review of the data a QC deficiency was observed and flagged as noted. MS/MSD recoveries were found to be outside of the laboratory control limits due to possible matrix /chemical interference, or a concentration of target analyte high enough to effect the recovery of the spike concentration. This condition could also effect the relative percent difference in the MS/MSD.
- **B** A target analyte or common laboratory contaminant was identified in the method blank. Its presence indicates possible field or laboratory contamination.
- **D** The sample(s) were diluted due to targets detected over the highest point of the calibration curve, or due to matrix interference. Dilution factors are included in the final results. The result is from a diluted sample.
- E The data exceeds the upper calibration limit; therefore, the concentration is reported as estimated.
- F RPD exceeded lab control limits.
- J The target analyte was positively identified below the MQL(PQL) and above the SQL(MDL).
- U Analyte was not detected.
- L The LCS data for this analytical batch was reported below the laboratory control limits for this analyte. The department supervisor and QA Director reviewed data. The samples were either reanalyzed or flagged as estimated concentrations.
- H The LCS data for this analytical batch was reported above the laboratory control limits. Supporting QC Data were reviewed by the Department Supervisor and QA Director. Data were determined to be valid for reporting.
- K Sample analyzed outside of recommended hold time.

* Outside XENCO'S scope of NELAC Accreditation

Recipient of the Prestigious Small Business Administration Award of Excellence in 1994. Certified and approved by numerous States and Agencies. A Small Business and Minority Status Company that delivers SERVICE and QUALITY

Houston - Dallas - San Antonio - Austin - Tampa - Miami - Atlanta - Corpus Christi - Latin America

	Phone	Fax
11381 Mcadowglen Lane Suite L Houston, Tx 77082-2647	(281) 589-0692	(281) 589-0695
9701 Harry Hines Blvd , Dallas, TX 75220	(214) 902 0300	(214) 351-9139
5332 Blackberry Drive, Suite 104, San Antonio, TX 78238	(210) 509-3334	(210) 509-3335
2505 N. Falkenburg Rd., Tampa, FL 33619	(813) 620-2000	(813) 620-2033
5757 NW 158th St, Miami Lakes, FL 33014	(305) 823-8500	(305) 823-8555
6017 Financial Dr., Norcross, GA 30071	(770) 449-8800	(770) 449-5477



Form 2 - Surrogate Recoveries



Project Name: Pride Energy Company

/ork Order #: 299691	147-003 S / MS Ba	Project I	D: South Fou	r Lakes #14	4
Units: mg/L	SL	RROGATE R	ECOVERY	STUDY	
BTEX by EPA 8021B Analytes	Amount Found [A]	True Amount [B]	Recovery %R [D]	Control Limits %R	Flags
I,4-Difluorobenzene	0.0307	0.0300	102	80-120	
4-Bromofluorobenzene	0.0320	0.0300	107	80-120	
Lab Batch #: 717610 Sample: 2994	147-003 SD / MSD Ba	tch: 1 Matr	ix: Water		
	SU	RROGATE R	ECOVERY	STUDY	
BTEX by EPA 8021B Analytes	Amount Found [A]	True Amount [B]	Recovery %R [D]	Control Limits %R	Flags
1,4-Difluorobenzene	0.0309	0.0300	103	80-120	
4-Bromofluorobenzene	0.0322	0.0300	107	80-120	
Lab Batch #: 717610 Sample: 2996	591-001 / SMP Ba	tch: 1 Matr	ix: Water		
Units: mg/L	SU	RROGATE R	ECOVERY S	STUDY	·····
BTEX by EPA 8021B	Amount Found [A]	True Amount [B]	Recovery %R [D]	Control Limits %R	Flags
1.4-Difluorobenzene	0.0325	0.0300	108	80-120	
4-Bromofluorobenzene	0.0329	0.0300	110	80-120	·
Lah Batch #. 717610	50-1-BKS/BKS Ba	teh: 1 Matr	iv. Water		
Units: mg/L		RROGATE R	ECOVERY S	STUDY	
BTEX by EPA 8021B Analytes	- Amount Found [A]	True Amount [B]	Recovery %R [D]	Control Limits %R	Flags
1,4-Difluorobenzene	0.0336	0.0300	112	80-120	
4-Bromofluorobenzene	0.0353	0.0300	118	80-120	
Lab Batch #: 717610 Sample: 5061	50-1-BLK / BLK Ba	tch: 1 Matr	ix: Water		
Units: mg/L	SU	RROGATE R	ECOVERY S	STUDY	·
BTEX by EPA 8021B Analytes	Amount Found [A]	True Amount [B]	Recovery %R [D]	Control Limits %R	Flags
1,4-Difluorobenzene	0.0327	0.0300	109	80-120	
4-Bromofluorobenzene	0.0328	0.0300	109	80-120	

** Surrogates outside limits; data and surrogates confirmed by reanalysis

*** Poor recoveries due to dilution

Surrogate Recovery [D] = 100 * A / BAll results are based on MDL and validated for QC purposes.

1



Form 2 - Surrogate Recoveries



Project Name: Pride Energy Company

Work Order #: 299691

Project ID: South Four Lakes #14

Lab Batch #: 717610 Sample: 506150-1-BSD / 1 Units: mg/L	BSD BA	atch: 1 Matr JRROGATE R	ix: Water ECOVERY S	STUDY	
BTEX by EPA 8021B Analytes	Amount Found [A]	True . Amount [B]	Recovery %R [D]	Control Limits %R	Flags
1,4-Difluorobenzene	0.0306	0.0300	102	80-120	
4-Bromofluorobenzene	0.0331	0.0300	110	80-120	

** Surrogates outside limits; data and surrogates confirmed by reanalysis
 *** Poor recoveries due to dilution
 Surrogate Recovery [D] = 100 * A / B
 All results are based on MDL and validated for QC purposes.





Project Name: Pride Energy Company

Work Order #: 299691			P	roject ID:	So	uth Four L	akes #14	
Lab Batch #: 717368	Sa	ample: 717368	-1-BKS	Matri	ix: Water	•		
Date Analyzed: 03/17/2008	Date Prep	pared: 03/17/2	008	Analy	st: WRU			
Reporting Units: mg/L	Ba	atch #: 1	BLANK /BLANK SPIKE RECOVERY S					
Total Alkalinity by EPA 310.1		Blank Result	Spike Added	Blank Spike Posult	Blank Spike	Control Limits	Flags	
Analytes		[4]	[D]	[C]	[D]			
Alkalinity, Total (as CaCO3)		ND	200	172	86	80-120		
Lab Batch #: 717419	Sa	mple: 717419	-1-BKS	Matri	ix: Water			
Date Analyzed: 03/15/2008	Date Prep	pared: 03/15/2	008	Analy	st: LATCO	OR		
Reporting Units: mg/L	Ba	1.1.1 ttch #: 1	BLANK /	BLANK SPI	KE REC	OVERYS	STUDY	
Anions by EPA 300/300.1		Blank Result	Spike Added	Blank Spike	Blank Spike	Control Limits	Flags	
Analytes		[A]	[B]	Result [C]	%R [D]	%R		
Chloride		ND	10.0	9.45	95	85-115		
Sulfate		ND	10.0	8.71	87	90-110	L	

Blank Spike Recovery [D] = 100*[C]/[B]All results are based on MDL and validated for QC purposes.





Project Name: Pride Energy Company

Work Order #: 299691 Analyst: SHE	Project ID: South Four Lakes #14Date Prepared:03/19/2008Date Analyzed:03/19/2008										
Lab Batch ID: 717610 Sample: 506150-1-B	KS	Batch	1#: 1			Matrix: Water					
Units: mg/L	BLANK /BLANK SPIKE / BLANK SPIKE DUPLICATE RECOVERY STUDY										
BTEX by EPA 8021B	Blank Sample Result [A]	Spike Added (B]	Blank Spike Result [C]	Blank Spike %R [D]	Blank Spike Blank Blk. Spk Control C Spike Added Spike Dup. RPD Limits I %R Duplicate %R % %R 9 [D] [E] Result [F] [G]						Flag
Benzene	ND	0.1000	0.0867	87	0.1	0.0848	85	2	70-125	25	
Toluene	ND	0.1000	0.0868	87	0.1	0.0848	. 85	2	70-125	25	
Ethylbenzene	ND	0.1000	0.0916	92	0.1	0.0885	89	3	71-129.	25	
m.p-Xylenes	ND	0.2000	0.1841	92	0.2	0.1774	89	4	70-131	25	
o-Xylene	ND	0.1000	0.0998	100	0.1	0.0959	96	4	71-133	25	

Relative Percent Difference RPD = 200*[(D-F)/(D+F)] Blank Spike Recovery [D] = 100*(C)/[B] Blank Spike Duplicate Recovery [G] = 100*(F)/[E] All results are based on MDL and Validated for QC Purposes



Form 3 - MS Recoveries



Project Name: Pride Energy Company

Work Order #: 299691 Lab Batch #: 717419

Project ID: South Four Lakes #14 Analyst: LATCOR

Date Analyzed: 03/15/2008	Date Prepared:	03/15/2008	. 3	Analyst:	LATCOR	•		
QC- Sample ID: 299690-001 S	Batch #:	1		Matrix:	Water			
Reporting Units: mg/L	MAT	MATRIX / MATRIX SPIKE RECOVERY STUDY						
Inorganic Anions by EPA 300	Parent Sample Result [A]	Spike Added [B]	Spiked Sample Result [C]	%R [D]	Control Limits %R	Flag		
Chloride	4150	1000	5250	110	85-115			
Sulfate	415	1000	1400	99	90-110			

Matrix Spike Percent Recovery [D] = 100*(C-A)/BRelative Percent Difference [E] = 200*(C-A)/(C+B)All Results are based on MDL and Validated for QC Purposes



Form 3 - MS / MSD Recoveries

Project Name: Pride Energy Company



Project ID: South Four Lakes #14

Work Order #: 299691

Lab Batch ID: 717610 Date Analyzed: 03/19/2008 Reporting Units: mg/L	QC- Sample ID: Date Prepared:	299447 03/19/2	-003 S 008 IATRIX SPIK	Ba An E / MAT	tch #: alyst: RIX SPI) Matrix SHE - KE DUPEICA	: Water	OVERY	STUDY		
BTEX by EPA 8021B Analytes	Parent Sample Result [A]	Spike Added [B]	Spiked Sample Result [C]	Spiked Sample %R [D]	Spike Added [E]	Duplicate Spiked Sample Result [F]	Spiked Dup. %R [G]	RPD %	Control Limits %R	Control Limits %RPD	Flag
Benzene	ND	0.1000	0.1038	104	0.1000	0.1121	112	7	70-125	25	
Tohiene	ND	0.1000	0.1030	103	0.1000	0.1122	112	8	70-125	2.5	
Ethylbenzene	ND	0.1000	0.1055	106	0.1000	0.1161	116	9	71-129	25	
m,p-Xylenes	ND	0.2000	0.2079	104	0.2000	0.2291	115	10	70-131	25	
o-Xylene	ND	0.1000	0.1095	110	0.1000	0.1212	121	10	71-133	25	

Matrix Spike Percent Recovery [D] = 100*(C-A)/B Relative Percent Difference RPD = 200*(D-G)/(D+G) Matrix Spike Duplicate Percent Recovery [G] = 100*(F-A)/E

ND = Not Detected, J = Present Below Reporting Limit, B = Present in Blank, NR = Not Requested, I = Interference, NA = Not ApplicableN = See Narrative, EQL = Estimated Quantitation Limit



Sample Duplicate Recovery



Project Name: Pride Energy Company

Work Order #: 299691

Lab Batch #: 717419 Date Analyzed: 03/15/2008 Date H	repared: 03/	15/2008	Project I Analy	(D: South For	our Lakes #1 R -
QC- Sample ID: 299690-001 D	Batch #:	1	Mati	rix: Water	
Reporting Units: mg/L	SAMPLE	/ SAMPLE	DUPLIC	CATE REC	OVERY
Anions by EPA 300/300.1 Analyte	Parent Sample Result [A]	Sample Duplicate Result [B]	RPD	Control Limits %RPD	Flag
Chloride	4150	4140	0	20	
Sulfate	415	406	2	20	
Lab Batch #: 717329				1.	·
Date Analyzed: 03/17/2008 Date I	repared: 03/	17/2008	Analy	st: LATCO	R
QC- Sample ID: 299654-001 D	Batch #:	l	Matr	ix: Water	
Reporting Units: mg/L	SAMPLE	/ SAMPLE	DUPLIC	ATE REC	OVERY
Metals per ICP by SW846 6010B Analyte	Parent Sample Result [A]	Sample Duplicate Result [B]	RPD	Control Limits %RPD	Flag
Calcium	45.1	45.8	2	25	
Magnesium	22.6	21.8	4	25	
Potassium	8.64	8.45	2	25	[]
Sodium	172 -	172	0	25	
Lab Batch #: 717538 Date Analyzed: 03/17/2008 Date F QC- Sample ID: 299683-002 D D Reporting Units: mg/L D	repared: 03/ Batch #:	17/2008	Analy Matr DUPLIC	vst: RBA ix: Water	OVERY
TDS by SM2540C Analyte	Parent Sample Result [A]	Sample Duplicate Result [B]	RPD	Control Limits %RPD	Flag
Total dissolved solids	978	972	1	30	
Lab Batch #: 717368 Date Analyzed: 03/17/2008 Date P QC- Sample ID: 299680-001 D Reporting Units: mg/L	repared: 03/1 Batch #: 1 SAMPLE	7/2008 / SAMPLE	Analy Matr DUPLIC	st: WRU ix: Water ATE REC	OVERY
Total Alkalinity by EPA 310.1 Analyte	Parent Sample Result [A]	Sample Duplicate Result [B]	RPD	Control Limits %RPD	Flag
Alkalinity, Total (as CaCO3)	228	236	3	20	
Alkalinity, Carbonatc (as CaCO3)	ND	ND	NC	20	
Alkalinity, Bicarbonate (as CaCO3)	ND	ND	NC	20	

Spike Relative Difference RPD 200 * | (B-A)/(B+A) | All Results are based on MDL and validated for QC purposes.

12600 West I-20 East Odessa, Texas 79765	Phone: 432-563-1800 Fax: 432-563-1713										Сни	ain C	FCL	USTC	or.	RÉCI	ORD	<u>ÀND</u>	ANAL	Y SI S	REQI	UES	r
Project Ma	anager: <u>Randy Hicks</u>		·	_								Ρ	rojec	t Nar	ne: _	Prid	e Er	nergy	Co	mpar	<u>ıy</u>		
Company	Name R. T. Hicks Consultants, Ltd.												Р	rojec	t#:_	Sou	th F	our l	ake	s #14	<u> </u>		
Company Ac	dress: 901 Rio Grandè Blvd NW								_			Proj	act L	ocati	on: _	T11:	S-R	34E.	Sec	tion (35. L	Jnit	Letter
City, State, Zi	Code Albuquerque NM 87104													cọc	:#	- 5	ЧL	14	1-1	030	<u>2 C</u>	<u>)</u>	
Telepho	ne No: 505-266-5004		Fax No	: <u>50</u>	5-26	6-07	45																
Sa	ampier: Gil Van Deven	ter		_		_																	
	Printed				Sign	ature							F		TC	LP:	Â	nalyz	For:	ТТ		Т	
					r	Pre	servi	ative		T	Mai	rix	F		TOT	AL:	-	$\left\{ -\right\}$	ឆ្នា				
		Pet	Sled	ainers	s-iv				2				0154/ 1005 1001	lg. Na. K, F)	4, CO3, HCO3)	EC.			SUBD or BIEX 9 8		1 Solids (150.1)	(0 ¹)	d Mn (Pre-Schedule
299691	FIELD CODE	Date Samp	Time Samp	No. o' Conte	1 - 1 - 1	HNU, HCI BTEX on	NaDH	н ₂ SO.	Other (Specif	Water	Sludge	Sol Diher (specify	TPH: 418.1 84	Cations (Ca. M	Anons (Cl. SO	SAR : ESP / C	Violatées	Semivolatdes	ALLEXN MO218	4 O.R.M.	SPI P 1312	Nilrate (N.N	Total Fe an RUSH TAT
	MW-1	3/3/08	1010	3	X	X	\square	·	1-	Х			ſ	X	X	1	Ť	ŀ	$\langle]$	T.	x	T	
									Τ	\Box								П	T		\Box	T	
	· ·			1					\downarrow	\square		_	1		_		1		4-	\downarrow	+	4	╞╌┠╌┥
	<u> </u>			_	┞╌┼	-			+	\square	_		-	\vdash		+	+	$\left \right $	+	╞╌┤	+	+	┟╌┟╾┥
				+	\vdash	- <u>+-</u> -			+-	$\left\{ \cdot \right\}$	-	+-	┢	┝╌┤	-+	-	+	+	+-	++	+	╋	┼╂╼┥
			·	+	$\left \cdot \right $	+	\vdash	\square	+	+	-	+	╀	$\left \right $	+	+-	+-	++	+	$\left\{ \right\}$		÷	┝╌┠╌┦
			· · · ·	1-	+				+	$^{+}$		+-	┢		+	+	+		+-			+	
				1							T	+	t		+	· ·	T	†-†				T	
						Τ																T	
Special Instructions:	Email results to: r@rthicksconsult.co	om and gilber	rtvandeven	ter@	sudd	lenlir	ık.ņ	et							Sam Tem Labo	ple C perat prator	iontai ure L y Co	iners I Jpan F mmer	ntact' leceip lts:	? xt:	is Is	ر	N
Relinquished by	Date Time	Received by:	01	r			_			Da	ite		Tim	• 									
Preinquished by:	. Date Time	Received by EL	va J	Į,	۰. 				3	114	ae اړی	٢.	iim Lig	5	'n	11,	àn	وانح	ξ.	Scal	ت رئ		(colicy

•

1

.(*).)

al la

计准定

κ.

Environmental Lab of Texas

Variance/ Corrective Action Report- Sample Log-In

Client:	P.T. Hichs
Date/ Time:	3.14.08
Lab ID # :	2996

Initials

14 08 415 299691 ۵L

Sample Receipt Checklist

					ont mittais
#1	Temperature of container/ cooler?	(eg	No	-1.5 °C	
#2	Shipping container in good condition?	Yes	No		
#3	Custody Seals intact on shipping container/ cooler?	Yes	No	Not Present	
#4	Custody Seals intact on sample bottles/ container?	Yes	No	Not Present	
#5	Chain of Custody present?	Yes	No		
#6	Sample instructions complete of Chain of Custody?	Ye	No		
#7	Chain of Custody signed when relinquished/ received?	69	No		
#8	Chain of Custody agrees with sample label(s)?	Yes	No	ID written on Cont./ Lid	
#9	Container label(s) legible and intact?	(es	No	Not Applicable	
#10	Sample matrix/ properties agree with Chain of Custody?	Yes	No		
#11	Containers supplied by ELOT?	Yes	No		
#12	Samples in proper container/ bottle?	Yes	No	See Below	
#13	Samples properly preserved?	Yes	No	See Below	
#14	Sample bottles intact?	Yes	No		
#15	Preservations documented on Chain of Custody?		No		
#16	Containers documented on Chain of Custody?	Yes	No		
#17	Sufficient sample amount for indicated test(s)?	Yes	No	See Below	
#18	All samples received within sufficient hold time?	Yes	No	See Below	
#19	Subcontract of sample(s)?	Yes	No	Not Applicable	
#20	VOC samples have zero headspace?	Yes	No	Not Applicable	

Variance Documentation

Date/ Time:

Contacted by:

Contact:

Regarding:

Corrective Action Taken:

Check all that Apply:

See attached e-mail/ fax Client understands and would like to proceed with analysis Cooling process had begun shortly after sampling event

- 63 - 12 C Q., ... 15. 赤

age 5 B

1-154 清白 PHIL: 10.11

Analytical Report 306329

for

R.T. Hicks Consultants, LTD

Project Manager: Andrew Parker

Pride Energy Company South Four Lakes # 14

27-JUN-08



12600 West I-20 East Odessa, Texas 79765

Texas certification numbers: Houston, TX T104704215

Florida certification numbers: Houston, TX E871002 - Miami, FL E86678 - Tampa, FL E86675 Norcross(Atlanta), GA E87429

> South Carolina certification numbers: Norcross(Atlanta), GA 98015

> North Carolina certification numbers: Norcross(Atlanta), GA 483

Houston - Dallas - San Antonio - Austin - Tampa - Miami - Latin America Midland - Corpus Christi - Atlanta





27-JUN-08

Project Manager: Andrew Parker R.T. Hicks Consultants, LTD 901 Rio Grande Blvd. NW, Suite F-142 Albuquerque, NM 87104

Reference: XENCO Report No: **306329 Pride Energy Company** Project Address: T11S-R34E, Section 35, Unit Letter I

Andrew Parker:

We are reporting to you the results of the analyses performed on the samples received under the project name referenced above and identified with the XENCO Report Number 306329. All results being reported under this Report Number apply to the samples analyzed and properly identified with a Laboratory ID number. Subcontracted analyses are identified in this report with either the NELAC certification number of the subcontract lab in the analyst ID field, or the complete subcontracted report attached to this report.

Unless otherwise noted in a Case Narrative, all data reported in this Analytical Report are in compliance with NELAC standards. Estimation of data uncertainty for this report is found in the quality control section of this report unless otherwise noted. Should insufficient sample be provided to the laboratory to meet the method and NELAC Matrix Duplicate and Matrix Spike requirements, then the data will be analyzed, evaluated and reported using all other available quality control measures.

The validity and integrity of this report will remain intact as long as it is accompanied by this letter and reproduced in full, unless written approval is granted by XENCO Laboratories. This report will be filed for at least 5 years in our archives after which time it will be destroyed without further notice, unless otherwise arranged with you. The samples received, and described as recorded in Report No. 306329 will be filed for 60 days, and after that time they will be properly disposed without further notice, unless otherwise arranged with you. We reserve the right to return to you any unused samples, extracts or solutions related to them if we consider so necessary (e.g., samples identified as hazardous waste, sample sizes exceeding analytical standard practices, controlled substances under regulated protocols, etc).

We thank you for selecting XENCO Laboratories to serve your analytical needs. If you have any questions concerning this report, please feel free to contact us at any time.

Respectfully,

Brent Barron, II Odessa Laboratory Manager

Recipient of the Prestigious Small Business Administration Award of Excellence in 1994. Certified and approved by numerous States and Agencies. A Small Business and Minority Status Company that delivers SERVICE and QUALITY Houston - Dallas - San Antonio - Austin - Tampa - Miami - Atlanta - Corpus Christi - Latin America





Sample Cross Reference 306329

R.T. Hicks Consultants, LTD, Albuquerque, NM Pride Energy Company

Sample Id MW-1	Matrix W	Date Collected Jun-20-08 08:55	Sample Depth	Lab Sample Id 306329-001
· · ·				
		•		
		· ·		
· · · · · · · · · · · · · · · · · · ·				



Certificate of Analysis Summary 306329 R.T. Hicks Consultants, LTD, Albuquerque, NM

-	P	roject Nam	e: Pride	Energy Compa	iny		
Project Id: South Four Lakes #	Date Receiv	ed in Lab:	Jun-20-08 05:00 pm				
Contact: Andrew Parker				Re	oort Date:	27-JUN	-08
Project Location: THS-R34E, Section	n 35, Unit Let	ter I		Project	Manager:	Brent B	arron, Il
	Lab Id:	306329-0	01		•		
Analysis Requested	Field Id:	MW-1					
		•	•				
	Matrix:	WATER	L	ĺ			
	Sampled:	Jun-20-08 0	8:55				
Alkalinity by SM2320B	Extracted:	.`					
	Analyzed:	Jun-26-08 1	0:45				
	Units/RL:	mg/L	`RL				
Alkalinity, Total (as CaCO3)		190	4.00				
Alkalinity, Bicarbonate (as CaCO3)		190	4.00				
Alkalinity, Carbonate (as CaCO3)		ND	4.00		_		
Inorganic Anions by FPA 300 Extracted:							
· · · · · · · · · · · · · · · · · · ·	Analyzed:	Jun-23-08 0	8:50				
	Units/RL:	mg/L	RL				
Chloride		2600	25.0				
Sulfate		477	25.0				\
Metals per ICP by SW846 6010B	Extracted:					•	
	Analyzed:	Jun-23-08 1	1:59				
·	mg/L	RL		•			
Calcium	ND						
Magnesium	120	0.010					
Potassium	4.41	0.500					
Sodium		564	0.500			,	
TDS by SM2540C	Extracted:						· ·
	Analyzed:	Jun-23-08 10	6:30				
· · · · · · · · · · · · · · · · · · ·	Units/RL:	mg/L	RL	'n			·
Total dissolved solids	5700	5.00					

This analytical report, and the entire data package it represents, has been made for your exclusive and confidential use. The interpretations and results expressed throughout this analytical report represent the best judgment of XENCO Laboratories. XENCO Laboratories assumes no responsibility and makes no warranty to the end use of the data hereby presented. Our liability is limited to the amount invoiced for this work order unless otherwise agreed to in writing.

Houston - Dallas - San Antonio - Austin - Tampa - Miami - Latin America - Atlanta - Corpus Christi

Since 1990

Brent Barron

Odessa Laboratory Director



Flagging Criteria

- X In our quality control review of the data a QC deficiency was observed and flagged as noted. MS/MSD recoveries were found to be outside of the laboratory control limits due to possible matrix /chemical interference, or a concentration of target analyte high enough to effect the recovery of the spike concentration. This condition could also effect the relative percent difference in the MS/MSD.
- **B** A target analyte or common laboratory contaminant was identified in the method blank. Its presence indicates possible field or laboratory contamination.
- **D** The sample(s) were diluted due to targets detected over the highest point of the calibration curve, or due to matrix interference. Dilution factors are included in the final results. The result is from a diluted sample.
- E The data exceeds the upper calibration limit; therefore, the concentration is reported as estimated.
- F RPD exceeded lab control limits.
- J The target analyte was positively identified below the MQL(PQL) and above the SQL(MDL).
- U Analyte was not detected.
- L The LCS data for this analytical batch was reported below the laboratory control limits for this analyte. The department supervisor and QA Director reviewed data. The samples were either reanalyzed or flagged as estimated concentrations.
- **H** The LCS data for this analytical batch was reported above the laboratory control limits. Supporting QC Data were reviewed by the Department Supervisor and QA Director. Data were determined to be valid for reporting.
- K Sample analyzed outside of recommended hold time.

* Outside XENCO'S scope of NELAC Accreditation

Recipient of the Prestigious Small Business Administration Award of Excellence in 1994. Certified and approved by numerous States and Agencies. A Small Business and Minority Status Company that delivers SERVICE and QUALITY

Houston - Dallas - San Antonio - Austin - Tampa - Miami - Atlanta - Corpus Christi - Latin America

	Phone	Fax
11381 Meadowgien Lane Suite L Houston, Tx 77082-2647	(281) 589-0692	(281) 589-0695
9701 Harry Hine; Blvd, Dallas, TX 75220	(214) 902 0300	(214) 351-9139
5332 Blackberry Drive, Suite 104, San Antonio, TX 78238	(210) 509-3334	(210) 509-3335
2505 N. Falkenburg Rd., Tampa, FL 33619	(813) 620-2000	(813) 620-2033
5757 NW 158th St, Miami Lakes, FL 33014	(305) 823-8500	(305) 823-8555
6017 Financial Dr., Norcross, GA 30071	(770) 449-8800	(770) 449-5477





Project Name: Pride Energy Company

Work Order #: 306329			P	roject ID:	Sou	South Four Lakes #		
Lab Batch #: 726566	Sample: 726566-1-BKS			Matr	ix: Water			
Date Analyzed: 06/26/2008	Date Prepared: 06/26/2008			Analyst: WRU				
Reporting Units: mg/L	Batch #: 1 BLANK			K /BLANK SPIKE RECOVERY STI				
Alkalinity by SM2320B	· <u>·</u> ··	Blank Result	Spike Added	Blank Spike	Blank Spike	Control Limits	Flags	
Analytes		(A)	[D]	[C]	(D)	761		
Alkalinity, Bicarbonate (as CaCO3)		ND	200	176	88	80-120		
Lab Batch #: 726337	Sample: 726337-1-BKS Matrix: Water							
Date Analyzed: 06/23/2008	Date Prepared: 06/23/2008 Analyst: LATCOR				OR			
Reporting Units: mg/L	Batch #: 1 BLANK /BLANK SPIKE RECOVER				COVERY S	STUDY		
Inorganic Anions by EPA 300		Blank Result [A]	Spike Added [B]	Blank Spike Result	Blank Spike %R	Control Limits %R	Flags	
Analytes		(),		[C]	[D]			
Chloride		ND	10.0	11.6	116	80-120		
Sulfate		ND	10.0	12.0	120	80-120		

Blank Spike Recovery [D] = 100*[C]/[B] All results are based on MDL and validated for QC purposes.



Form 3 - MS Recoveries



Project Name: Pride Energy Company

Work Order #: 306329 Lab Batch #: 726337 Date Analyzed: 06/23/2008

Project ID: South Four Lakes # 14 Date Prepared: 06/23/2008 Analyst: LATCOR QC- Sample ID: 306329-001 S Batch #: 1 Water Matrix: Reporting Units: mg/L MATRIX / MATRIX SPIKE RECOVERY STUDY Parent **Inorganic Anions by EPA 300** Spiked Sample Control Sample Spike Result %R Limits Flag Result Added [C] [D] %R [A] [B] Analytes Chloride 2600 500 3270 134 80-120 х Sulfate 477 500 1080 121 80-120 x

Matrix Spike Percent Recovery [D] = 100*(C-A)/B Relative Percent Difference [E] = 200*(C-A)/(C+B)All Results are based on MDL and Validated for QC Purposes



Sample Duplicate Recovery



Project Name: Pride Energy Company

Work Order #: 306329

Lab Batch #: /26066					
Date Analyzed: 06/26/2008 Date	Prepared: 06/2	26/2008	Analy	yst: WRU	
QC- Sample ID: 306329-001 D	Batch #:	. <u> </u>	Mati	rix: Water	
Reporting Units: mg/L	SAMPLE	/ SAMPLE	DUPLIC	CATE REC	OVER
Alkalinity by SM2320B	Parent Sample Result [A]	Sample Duplicate Result [B]	RPD	Control Limits %RPD	Flag
Alkalinity Total (as CaCO3)	190	180	20	20	
Alkalinity, Bicarbonate (as CaCO3)	190	180	20	20	<u></u>
Alkalinity, Carbonate (as CaCO3)	ND	ND	20	20	
Lab Batch #: 726337				4	L
Date Analyzed: 06/23/2008 Date	Prepared: 06/2	23/2008	Analy	st: LATCO	ર
QC- Sample ID: 306329-001 D	Batch #: 1		Matr	ix: Water	
Reporting Units: mg/L	SAMPLE	SAMPLE	DUPLIC	ATE REC	OVER
Inorganic Anions by EPA 300 Analyte	Parent Sample Result [A]	Sample Duplicate Result [B]	RPD	Control Limits %RPD	Flag
		2500	20	20	
Chloride	2600	2,590	20	1 20	
Chloride Sulfate Lab Batch #: 726094	2600 477	463	20	20	
Chloride Sulfate Lab Batch #: 726094 Date Analyzed: 06/23/2008 Date QC- Sample ID: 306329-001 D Reporting Units: mg/L	2600 477 Prepared: 06/2 Batch #: 1 SAMPLE	463 3/2008	20 20 Analy Matr	20 20 vst: LATCOI ix: Water	R OVER
Chloride Sulfate Lab Batch #: 726094 Date Analyzed: 06/23/2008 Date QC- Sample ID: 306329-001 D Reporting Units: mg/L Mctals per ICP by SW846 6010B Analyte	2600 477 Prepared: 06/2 Batch #: 1 SAMPLE / Parent Sample Result [A]	463 463 3/2008 / SAMPLE Sample Duplicate Result [B]	20 20 Analy Matr DUPLIC RPD	20 20 vst: LATCOl ix: Water ATE REC Control Limits %RPD	COVER Flag
Chloride Sulfate Lab Batch #: 726094 Date Analyzed: 06/23/2008 Date QC- Sample ID: 306329-001 D Reporting Units: mg/L Mctals per ICP by SW846 6010B Analyte Calcium	2600 477 Prepared: 06/2 Batch #: 1 SAMPLE / Parent Sample Result [A]	463 463 3/2008 / SAMPLE Sample Duplicate Result [B] 603	Analy Matr DUPLIC RPD	20 20 20 20 20 21 22 25 25	OVER' Flag
Chloride Sulfate Lab Batch #: 726094 Date Analyzed: 06/23/2008 Date QC- Sample ID: 306329-001 D Reporting Units: mg/L Metals per ICP by SW846 6010B Analyte Calcium Magnesium	2600 477 Prepared: 06/2 Batch #: 1 SAMPLE / Parent Sample Result [A] ND	463 463 3/2008 / SAMPLE Sample Duplicate Result [B] 603 116	Analy Matr DUPLIC RPD NC	20 20 20 21 22 25 25 25	{ OVER Flag
Chloride Sulfate Lab Batch #: 726094 Date Analyzed: 06/23/2008 Date QC- Sample ID: 306329-001 D Reporting Units: mg/L Mctals per ICP by SW846 6010B Analyte Calcium Magnesium Potassium	2600 477 Prepared: 06/2 Batch #: 1 SAMPLE / Parent Sample Result [A] ND 120 4.41	463 463 3/2008 / SAMPLE Sample Duplicate Result [B] 603 116 4.85	Analy Matr DUPLIC RPD NC 3 10	20 20 vst: LATCOI ix: Water ATE REC Control Limits %RPD 25 25 25 25	COVER'
Chloride Sulfate Lab Batch #: 726094 Date Analyzed: 06/23/2008 Date QC- Sample ID: 306329-001 D Reporting Units: mg/L Mctals per ICP by SW846 6010B Analyte Calcium Magnesium Potassium Sodium	2600 477 Prepared: 06/2 Batch #: 1 SAMPLE / Parent Sample Result [A] ND 120 4.41 564	463 463 3/2008 / SAMPLE Sample Duplicate Result [B] 603 116 4.85 575	Analy Matr DUPLIC RPD NC 3 10 2	20 20 20 21 22 25 25 25 25 25 25 25	CVER
Chloride Sulfate Lab Batch #: 726094 Date Analyzed: 06/23/2008 Date QC- Sample ID: 306329-001 D Reporting Units: mg/L Mctals per ICP by SW846 6010B Calcium Magnesium Potassium Sodium Lab Batch #: 726342 Date Analyzed: 06/23/2008 Date I QC- Sample ID: 306329-001 D	2600 477 Prepared: 06/2 Batch #: 1 SAMPLE / Parent Sample Result [A] ND 120 4.41 564 Prepared: 06/2 Batch #: 1	463 463 3/2008 / SAMPLE Sample Duplicate Result [B] 603 116 4.85 575 3/2008	Analy Matr DUPLIC RPD NC 3 10 2 Analy Matr	20 20 20 21 20 25 25 25 25 25 25 25 25 25 25	CVER Flag
Chloride Sulfate Lab Batch #: 726094 Date Analyzed: 06/23/2008 Date QC- Sample ID: 306329-001 D Reporting Units: mg/L Mctals per ICP by SW846 6010B Calcium Magnesium Potassium Sodium Lab Batch #: 726342 Date Analyzed: 06/23/2008 Date I QC- Sample ID: 306329-001 D Reporting Units: mg/L	2600 477 Prepared: 06/2 Batch #: 1 SAMPLE / Parent Sample Result [A] 120 4.41 564 Prepared: 06/2 Batch #: 1 SAMPLE /	463 463 3/2008 / SAMPLE Sample Duplicate Result [B] 603 116 4.85 575 3/2008	Analy Matr DUPLIC RPD NC 3 10 2 Analy Matr DUPLIC	20 20 20 21 20 25 25 25 25 25 25 25 25 25 25	COVER
Chloride Sulfate Lab Batch #: 726094 Date Analyzed: 06/23/2008 Date QC- Sample ID: 306329-001 D Reporting Units: mg/L Mctals per ICP by SW846 6010B Analyte Calcium Magnesium Potassium Sodium Lab Batch #: 726342 Date Analyzed: 06/23/2008 Date I QC- Sample ID: 306329-001 D Reporting Units: mg/L TDS by SM2540C Analyte	2600 477 Prepared: 06/2 Batch #: 1 SAMPLE / Parent Sample Result [A] 120 4.41 564 Prepared: 06/2 Batch #: 1 SAMPLE / Parent Sample Result [A]	463 463 3/2008 / SAMPLE Sample Duplicate Result [B] 603 116 4.85 575 3/2008 / SAMPLE Sample Duplicate Result [B]	Analy 20 20 Analy Matr DUPLIC NC 3 10 2 Analy Matr DUPLIC RPD	20 20 20 21 20 22 25 25 25 25 25 25 25 25 25	VER Flag

Spike Relative Difference RPD 200 * | (B-A)/(B+A) | All Results are based on MDL and validated for QC purposes.



Environmental Lab of Texas Variance/ Corrective Action Report- Sample Log-In

Client:	RT HICKS								
Date/ Time:	67000 1700								
Lab iD # :	304329								
Initiais:	aL								

Sample Receipt Checklist

				Client Initial
#1	Temperature of container/ cooler?	Yes)	No	5.2 0
#2	Shipping container in good condition?	des)	No	
#3	Custody Seals intact on shipping container/ cooler? .	Yes	No	Not Present >
#4	Custody Seals intact on sample bottles/ container?	(es)	No	Not Present
#5	Chain of Custody present?	(es)	No	
#6	Sample instructions complete of Chain of Custody?	Yes	No	
#7	Chain of Custody signed when relinquished/ received?	69	No	
#8	Chain of Custody agrees with sample label(s)?	(es)	No	ID written on Cont./ Lid
#9	Container label(s) legible and intact?	(es	No	Not Applicable
#10	Sample matrix/ properties agree with Chain of Custody?	Yes?	No	
#11	Containers supplied by ELOT?	(es)	No	
#12	Samples in proper container/ bottle?	(es	No	See Below
#13	Samples property preserved?	Yes	No	See Below
#14	Sample bottles intact?	Ves	No	T
#15	Preservations documented on Chain of Custody?	Kes	No	
#15	Containers documented on Chain of Custody?	Yes	No	
#17	Sufficient sample amount for indicated test(s)?	Yes	No	See Below
#18	All samples received within sufficient hold time?	Yes	No	See Below
#19	Subcontract of sample(s)?	Yes	No	Not Applicable
#20	VOC samples have zero headspace?	Yes	No	Oct Applicable

Variance Documentation

Date/ Time:

٠

. ·

Contact:

Regarding:

Corrective Action Taken:

Check all that Apply:

Contacted by:

See attached e-mail/ tax Client understands and would like to proceed with analysis Cooling process had begun shortly after sampling event

			(Da-g	1819 (J	9	- ige 10 -111		the second	5210	242	1	J.Y
51 (1 (02) C 1 (C 1	1. la	 81	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	and the second		a first and the second present strates and the second second second second second second second second second s	the second second second second second	53 er:			<u> </u>	_